

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 2956T

DATE 18/12/2017 15:52

Jumani

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Grille (LH) ?			\$ 17.60
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Protector (LH) ✓			\$ 29.20
	Headlamp (LH) ✓			\$ 797.90
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) ?			\$ 86.00
	Front Fender Retainer ?			\$ 9.20
	Frt Wheel Hub Cap ✓			\$ 145.00
	SUB TOTAL			\$ 2,879.50
	LESS 20%			\$ 575.90
	DISCOUNTED TOTAL			\$ 2,303.60
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			\$ 400
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 3,543.60

Ka/210064

19/12/17 11006

2071

45

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
 • To survey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.