

Our Ref: SLE2746A Your Ref: GV8001X

January 31, 2018

QBE INSURANCE (INTERNATIONAL) LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583 Attention: Motor Claims

Dear Sir/Madam.

Repair Services Rendered to Vehicle Reg. No.SLE2746A – Accident on 15/12/2017 Along SERANGOON NORTH AVE 1 CARPARK.

We are pleased to enclose our invoice number 77358144 dated 27/01/2018 amounting as follows:

Cost of Repair S\$ 7524.45
Loss of Use 04dayxS\$80.00/DAY S\$ 320.00
LTA Search Fee S\$ 2.00
Grand Total S\$ 7846.45

In addition, attached are the supporting documents of repair services rendered to the abovementioned vehicle.

Please acknowledge receipt of the same.

Take Notice, the agreed settlement and acceptance for this case is subject to the understanding that we must receive your payment for the agreed sum within 30 days herein. Failing to, the above-mentioned agreed settlement and acceptance is considered void and nil and we will proceed to forward this case to our solicitors to proceed accordingly without further notices to you. To avoid unnecessary legal fees, kindly let us have your payment as stipulated above

Thank you.

Yours sincerely

Cycle & Carriage –Fulco Motor Dealer Pte Ltd Eunos Service Centre

Encs.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **TAX INVOICE**

Co Reg No : 199707303Z

GST Reg No : 19-9707303-Z

Invoice Name & Address	Owner Name & Vehicle Info			
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Contact No 64771154	Cust No/Name	/Mr Seah Cho Heng		
	Reg No/Reg Date	SLE2746A / 15/07/2016		
	Date In/Mileage	16/12/2017/ 16249		
	Chassis/Package	JMYSRCY1AGU005672 /1F		
	Engine No	4A92CJ5369		
	Make/Model	MIT/CY1AE21		
	Colour/Trim	UO1 / BK		

			e Printed	CSE	Operator		WIP No		Credit Note No
00056	Credit	27/01/20	18/ 08:25	DS	218 / MarsLer		49172	77358144	1
		Descrip	tion of Good	s / Service	es	Qty	Unit Price	Disc%	Amount
									60.00
	LIGHTING	G & WIRING	S SYSTEM ON	FRONT AC	CCIDENT AFFECTED				
	5								180.00
		TEDIZE 144	TI ALTONME	NT					100.00
		IERIZE WHI	EEL ALIGNME	IN I					1200.00
		RIIMDED II	HE FENDER R	ONNET ETC	,				1200101
									v
		ii, nerait oi	TEN SIDE A	OOIDENT /	11 20 120 1				100.00
		KIT ON N	EW PANEL					1.	
						~			1260.00
SPRAY PAI	NTING OF	N LH SIDE	ACCIDENT A	FFECTED /	AREAS				de materiale in constitue
SUNDRY						6			130.00
	Œ								100.00
								· ·	180.00
	TYRE 20	5/60R16						100	-36.00
		000 O T			· # · · 2				-30.00
	ion ut a	20% Unity	re					10.00	14.40
	10 I H RI	DVCKET E	D RIIMDER ST	DE					
	ra Lii bi	MACKET, I	K DOM EK 31	. DL				10.00	13.50
	9 LH PRO	OTECTOR F	R FENDER						
SUNDRY								10.00	117.00
JJ5370B83	37 FRT	LH SPLASH	SHIELD						
JJ6400H43	38							SECTION CONTRACTOR AND ADDRESS.	927.00
									552.60
			the second second second second		R				13.50
									27.00 27.00
									754.20
				331,LH					1512.0
	LI		MUEEF DI2C			1.00	1000.00	10.00	F20.C
	ON 15/1	2/2017 AI	ONG NORTH	AVF 1 CAR	PARK				
VCCIDEIII	011 13/1	L/LUIT AL	ONG NORTH /	TIL I ONK	THIS				
	TO CHECK AREAS MIPNT8808 TO CONDUC MIPNT8808 TO REPLAC STRAIGHTE MIPNT8808 TO APPLY MIPNT9808 SPRAY PAI SUNDRY TOWING FE SUNDRY JOKOHAMA CON Contribut SUNDRY JJ6400F54 SUNDRY JJ5220D79 SUNDRY JJ5220D79 SUNDRY JJ5220C64 JJMR32898 JJMB25396	AREAS MIPNT88088 TO CONDUCT COMPU MIPNT88088 TO REPLACE FRONT STRAIGHTEN, REFOR MIPNT88088 TO APPLY SEALANT MIPNT98088 SPRAY PAINTING O SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 20 CON Contribution Of SUNDRY JJ6400F549 LH B SUNDRY JJ5220D799 LH PR SUNDRY JJ5370B837 FRT JJ6400H438 JJ5220C649 JJMR328954 JJMR328954 JJMR328954 JJMB253964 JJ8301C341 JJ4250D611 NOTES	MIPNT88088 TO CHECK LIGHTING & WIRING AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHE MIPNT88088 TO REPLACE FRONT BUMPER, LESTRAIGHTEN, REFORM, ALIGN OF MIPNT88088 TO APPLY SEALANT KIT ON NEMIPNT98088 SPRAY PAINTING ON LH SIDE SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 205/60R16 CON Contribution Of 20% On Ty SUNDRY JJ6400F549 LH BRACKET, F SUNDRY JJ5220D799 LH PROTECTOR F SUNDRY JJ5370B837 FRT LH SPLASH JJ6400H438 JJ5220G041 JJ5220C649 JJMR328954 JJMR328954 JJMR328954 JJMB253964 JJ8301C341 JJ4250D611 NOTES	MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNME MIPNT88088 TO REPLACE FRONT BUMPER, LHF FENDER, B STRAIGHTEN, REFORM, ALIGN ON LH SIDE AMIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT98088 SPRAY PAINTING ON LH SIDE ACCIDENT A SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 205/60R16 CON Contribution Of 20% On Tyre SUNDRY JJ6400F549 LH BRACKET, FR BUMPER SI SUNDRY JJ5220D799 LH PROTECTOR FR FENDER SUNDRY JJ5370B837 FRT LH SPLASH SHIELD JJ6400H438 FACE, FR BL JJ5220G041 FENDER, FR LL JJ5220C649 LH BRACKET, JJMR328954 CLIP, SPLASH JJMR328954 CLIP, BUMPER JJ8301C341 HEADLAMP AS JJ4250D611 WHEEL DISC NOTES	MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACT AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT MIPNT88088 TO REPLACE FRONT BUMPER, LHF FENDER, BONNET, ETC STRAIGHTEN, REFORM, ALIGN ON LH SIDE ACCIDENT ACT MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT98088 SPRAY PAINTING ON LH SIDE ACCIDENT AFFECTED ACCIDENT ACC	TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT MIPNT88088 TO REPLACE FRONT BUMPER, LHF FENDER, BONNET, ETC STRAIGHTEN, REFORM, ALIGN ON LH SIDE ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT98088 SPRAY PAINTING ON LH SIDE ACCIDENT AFFECTED AREAS SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 205/60R16 CON Contribution Of 20% On Tyre SUNDRY JJ52200799 LH PROTECTOR FR FENDER SUNDRY JJ5370B837 FRT LH SPLASH SHIELD JJ6400H38 FACE, FR BUMPER JJ5220G041 FENDER, FR LH JJ5220C649 LH BRACKET, FR FENDER JJMR328954 CLIP, SPLASH SHIELD JJMR328954 CLIP, SPLASH SHIELD JJMB253964 CLIP, BUMPER JJ8301C341 HEADLAMP ASSY, LH JJ4250D611 WHEEL DISC	MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT MIPNT88088 TO REPLACE FRONT BUMPER,LHF FENDER,BONNET,ETC STRAIGHTEN,REFORM,ALIGN ON LH SIDE ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT98088 SPRAY PAINTING ON LH SIDE ACCIDENT AFFECTED AREAS SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 205/60R16 CON Contribution Of 20% On Tyre SUNDRY JJ5400F549 LH BRACKET, FR BUMPER SIDE SUNDRY JJ5220D799 LH PROTECTOR FR FENDER SUNDRY JJ5370B837 FRT LH SPLASH SHIELD JJ5400H438 FACE, FR BUMPER JJ5400H438 FACE, FR BUMPER JJ5220G041 FENDER,FR LH 1.00 JJM828954 CLIP,SPLASH SHIELD JJM828954 CLIP,SPLASH SHIELD JJM8253964 CLIP,BUMPER 10.00 JJM8253964 CLIP,BUMPER 10.00 JJM82530611 HEADLAMP ASSY,LH 1.00 NOTES	MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED  AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT MIPNT88088 TO REPLACE FRONT BUMPER, LHF FENDER, BONNET, ETC STRAIGHTEN, REFORM, ALIGN ON LH SIDE ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT98088 SPRAY PAINTING ON LH SIDE ACCIDENT AFFECTED AREAS SUNDRY TOWING FEE SUNDRY TOWING FEE SUNDRY OKOHAMA TYRE 205/60R16 CON Contribution Of 20% On Tyre SUNDRY JJ5220D799 LH PROTECTOR FR FENDER SUNDRY JJ5220D799 LH PROTECTOR FR FENDER SUNDRY JJ5370B837 FRT LH SPLASH SHIELD JJ6400H438 FACE, FR BUMPER JJ5220G041 FENDER, FR LH LOO 614.00 JJ5220C649 LH BRACKET, FR FENDER LUD JJ5220G649 LH BRACKET, FR FENDER LUD JJ5220G49 LH BRACKET, FR FENDER LUD JJMR328954 CLIP, SPLASH SHIELD LUD JJMR328954 CLIP, SPLASH SHIELD LUD JJMR328954 CLIP, SPLASH SHIELD LUD JJB301C341 HEADLAMP ASSY, LH LOO 838.00 LUD 838.0	MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS MIPNT88088 TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT MIPNT88088 TO REPLACE FRONT BUMPER, LHF FENDER, BONNET, ETC STRAIGHTEN, REFORM, ALIGN ON LH SIDE ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL MIPNT88088 SPRAY PAINTING ON LH SIDE ACCIDENT AFFECTED AREAS SUNDRY TOWING FEE SUNDRY YOKOHAMA TYRE 205/60R16 CON CONTTIBUTION OF 20% ON TYPE SUNDRY JJ6400F549 LH BRACKET, FR BUMPER SIDE SUNDRY JJ52200799 LH PROTECTOR FR FENDER SUNDRY JJ53708837 FRT LH SPLASH SHIELD JJ6400H438 FACE, FR BUMPER JJ5220G041 FENDER, FR LH JJ5220C649 LH BRACKET, FR FENDER JJ620C649 LH BRACKET, FR FENDER JJ620C640 LH BRACKET, FR FENDER JJ62



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### TAX INVOICE

Co Reg No : 199707303Z

GST Reg No : 19-9707303-Z

Invoice Name & Address	Owner Name & Vehicle Info			
ODE Incurance (Singapone) Dto Ltd	Cust No/Name	/Mr Seah Cho Heng		
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10	Reg No/Reg Date	SLE2746A / 15/07/2016		
South Tower	Date In/Mileage	16/12/2017/ 16249		
Singapore 048583	Chassis/Package	JMYSRCY1AGU005672 /1F		
	Engine No	4A92CJ5369		
<b>Contact No</b> 64771154	Make/Model	MIT/CY1AE21		
	Colour/Trim	U01 / BK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Invoice/C	redit Note No
F0000056	Credit	27/01/2018/ 08:25	DS	218 / MarsLer		49172	77358144	
		Description of Goods	/ Services		Qty U	nit Price	Disc%	Amount
		HIRD PARTY	20					
LOSS OF TP : GV		S x S\$80.00 = S\$320.0 TP INS : QBE	00					
IF : di	VOOOIX	TE INS . QUE						
							6.	
								-
			N 19 2					
	ir							
								Y
			#		· · · · · · · · · · · · · · · · · · ·	N		7,032.20
Parts		3,813			7% GST on	Net 7032.2		492.25
Labour Standard	Menu		.00			. 30=11		
Specialis		2,800			Tota	1 Payab		7,524.45
Others(Li		-36	.00			Par Total D		0.00 7,524.45
Sundry	- CCT)	454			- Bala	nce B/FI		0.00
Total (w/	0 (31)	7,068	.20	Ť	otal Payable			7,524.45



### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No:

GR-17-190426

Date of Request:

18/12/2017

Your Ref No:

Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd 330 Ubi Road 3 Singapore 408650

Dear Sir/Madam,

**Enquiry Date** 

18/12/2017

**Enquiry By** 

Mars Ler

TP Vehicle No.

GV8001X

Accident Date

15/12/2017

**Enquiry Result** 

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GV8001X	QBE Insurance (Singapore) Pte Ltd	15/11/2017-14/11/2018	62246633

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



#### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

#### TAX INVOICE

Our Ref No:

GR-17-190426

Date of Request:

18/12/2017

Your Ref No:

Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd 330 Ubi Road 3 Singapore 408650

Dear Sir/Madam,

**Enquiry Date** 

18/12/2017

**Enquiry By** 

Mars Ler

TP Vehicle No. Accident Date

GV8001X 15/12/2017

DESCRIPTION	AMOUNT (S\$)	44.1
TP Insurer Enquiry		1.87
GST Amount		0.13
Total Amount Due (GST Inclusive)		2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque