

## ASSIGNMENT (Officer)

CWS

From (Person)

Karen Tan

of

FCI

Date/Time

4:10pm @ 20/12/17

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKP 5263K

Insured

SHB 4346X

at Workshop in/

Think One Autocare

Tel

G5553360 / 68443300 Karen

of

No. 18 Defu Ave 2

Policy No.

Claim No.

D17011592MFSH

Sum Insured

Excess

Make of Veh.

D.O.A

14/12/17

(Client's Record)

21/12/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

5:17pm @ 20/12/17

Person Contacted

Karen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 5263K - NA / AIG / 6013081 / h4

D.O.A: 13/07/2016

SHB 4346X - NA / III / 2015243 / 92

D.O.A: 3/08/2012

21/12/17 @ 5:09pm revised to Karen Tan via Memo.

03-11-17  
03/11/17

XML

REF: FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: 21/12/17  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKP 5263K  
at Workshop m/s Think One Autocare  
of No. 18 Defu Ave 2  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 6 days Res.: Yes or No  
Lum Sum: 20 % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS w/p  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKP 5263K Yr Regn: 26 Nov 2009  
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: BMW 318i C.C. 1995  
Colour: Brown A/C: Insured / Std / NI / NA  
Sp. Reading: 131856 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WBA PF 720 X GA 143466  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A Rim or  
Tyre Size: F: 205/55 R16  
R: 1  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front Rear  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. \_\_\_\_\_ D.O.I. 21-12-17  
Survey held at w/s 3:30pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/3	w/s withdraw the claim, <del>veh did not repair</del>
14/3/19	submit Preli - Report

RECEIVED 14 MAR 2019

Date/Time. File Pass to? ☒ : Preli. Report  
14/3/19 ☐ : Final Report  
Date/Time. File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ☐ : S + RS (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_) ☐ : Photos  
☐ : Tech. Invs (\$ \_\_\_\_\_) ☐ : Charts  
☐ : Weekend (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

6x15=90
90+170
50
43
353

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024168/Gqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2017	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 4346X		Veh. Inspected	SKP 5263K
Policy No.			Coverage (\$)	0.00
Claim No.	D17011592MFSH		Excess (\$)	0.00
Assign From	CWS (KAREN TAN)		Assign Date	20/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	14/12/2017		Inspection Date	
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date	16-12-2017	Our Ref No. D17011592MFSH
Accident Date	14-12-2017	Claim Type. Third Party
Insured Vehicle	SHB4346X	Third Party Vehicle. SKP5263K
Survey Location	NO.18 DEFU AVENUE 2	
Contact Person.	KAREN TAN	
Contact No.	65553300/ 91288488	Fax No. 68424988
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	THINK ONE AUTOCARE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231999)



PRI Documents



Close



## PRI Header Details

Claim No	D17011592MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & THINK ON
Workshop Name	THINK ONE AUTOCARE PTE LTD (Contact Person : KAREN TAN)	Survey Location & Contact Details	NO.18 DEFU AVENUE 2 Mobile: 91288488 , Phone: 65553300 , Fax: 68424988 EmailId: KARENTAN@THINKONE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4346X	TP Vehicle No	SKP5263K
PRI Recieved Date	18-12-2017 01:58:06 PM	Surveyor Appointed Date	20-12-2017 04:09:15 PM	Surveyor Accept Date	20-12-2017 0

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	20-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

## Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 22 December, 2017 5:09 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** KARENTAN@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17011592MFSH/1  
**Attachments:** CSFCI17024168Gqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKP 5263K.

*Wishes you a Merry Christmas & Happy New Year 2018*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 20 December, 2017 5:20 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D17011592MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Wednesday, 20 December, 2017 4:09 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [KARENTAN@FIRST-INSURANCE.COM.SG](mailto:KARENTAN@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17011592MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011592MFSH  
Our Ref: CS/FCI17024168/Gqd3

Date: 22 December 2017

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKP 5263K**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/12/2017 at the premises of M/s THINK ONE AUTOCARE and have the following to report:-

Workshop Estimate Amount	: S\$ 16,406.60 .
Revised Estimate Amount	: S\$ 3,732.25 .
"Check" Items Amount	: S\$ 2,999.70 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

**Description of Damage:**

The vehicle sustained damages at the o/s body. The undercarriage affected due to collision.



Yours faithfully

Guo Qiang  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

MT/0974553  
AR201712-0329

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/12/2017 13:43
Date Of Accident	14/12/2017 06:55
Exact Location Of Accident	ALONG AIRPORT ROAD TWD DEFU LANE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP5263K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THINK ONE AUTOMOBILE PTE LTD
Co Reg No	200508965H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

### Vehicle Particulars

Manufacturer	BMW
Model	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	506961189-03
Cover Note Number	

### Driver

Name of Driver	MARTIN SONG JIANQIAO
NRIC No	S9574581D
Date Of Birth	01/07/1995
Occupation	OUTDOOR
Date Of Driving Pass	17/03/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94594387
Fax Number	
Contact Number	OFFICE-65553300
Email Address	NOEMAIL



Address	APT BLK 333 ANG MO KIO AVENUE 1 #04-1925
Postcode	560333
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 60 HOUGANG AVE 9 , <b>POSTCODE:</b> 538775 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4890999 - <b>FAX NO:</b> 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SHB4346X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	LEONG YEW WAH EDWARD
NRIC/Passport Number	S0063637A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	

SKETCH PLAN

Approach Road toward Left lane



A - SKP5263K  
B - SHB4346X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 4.12.17 at about 6.55 hr. I was driving (SKP5263K) from Airport Road toward left lane. I was at the most extreme left lane, I signal & saw the middle lane to be clear. When I safely moved to the middle lane, completely a taxi (SHB4346X) was there at my rear side of my vehicle. The impact caused me to swerve and was given 3 days MC

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Police Officer's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time 10:14 AM

15/12/2017

Think One Autocare Pte Ltd  
18 D'Almeida Avenue  
Singapore 110022  
Tel: 6644 3300 Fax: 6642 4988

Investigating Officer's Signature  
Name: [Signature]  
NRIC/PIN No: S1825241

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8965H
Vehicle Details	
Vehicle No.:	SKP5263K
Vehicle to be Exported:	No
Intended De-registration Date:	22 Dec 2017
Vehicle Make:	B.M.W.
Vehicle Model:	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR
Primary Colour:	Brown
Manufacturing Year:	2009
Engine No.:	B041I563N46B20BZ
Chassis No.:	WBAPF720X0A143466
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$35,470.00
Original Registration Date:	26 Nov 2009
First Registration Date:	26 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$35,470.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2019
PARF Rebate Amount:	\$19,508.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2019
COE Category:	B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$18,002.00
COE Rebate Amount:	\$3,465.00
<b>Total Rebate Amount:</b>	<b>\$22,973.00</b>

The information contained herein is correct as at 22 Dec 2017

OK

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

## SKP5263K BMW 318i

No.	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy X Repair	\$ 1,083.00 X
2	2	Rear bumper side bracket X NN	\$ 126.00 X
3	2	Rear bumper side retainer X NN	\$ 182.00 X
4	1	Rear right fender assy X Repair	\$ 1,877.00 X
5	1	Rear right fender inner cowling X NN	\$ 226.00 X
6	1	Rear right door panel assy - Buc	\$ 1,655.00 / 1152.6
7	1	Rear right door lock mechanism X	\$ 285.00 X
8	1	Rear right door lock catch X	\$ 76.00 X
9	1	Rear right door regulator with motor X NN	\$ 488.00 X
10	2	Rear right door hinges X	\$ 166.00 X
11	1	Rear right door checker linkage X	\$ 209.00 X
12	1	Rear right door weatherstrip X	\$ 387.00 X
13	1	Rear right door handle X	\$ 188.00 X
14	1	Rear right side rocker panel X Garnish - CHA	\$ 1,900.00 ? 1218.95
15	1	Rear right lower arm carrier X	\$ 496.00 X
16	1	Rear right strut link X	\$ 221.00 X
17	1	Rear right strut arm X NN	\$ 179.00 X
18	1	Rear right camber arm X	\$ 423.00 X
19	1	Rear right trailing link X	\$ 223.00 X
20	1	Rear right shock absorber X	\$ 593.00 X
21	1	Rear right fender inner garnish X	\$ 445.00 X
		Rear right wheel bearing - Ac.	\$ 11,428.00 2371.55
		Less 5%	\$ 571.40
			<u>\$ 10,856.60</u> 2252.97

Special Nett Items

1	12	Rear bumper clips X NN	\$ 60.00 X
2	8	Rear right fender inner garnish clips X	\$ 30.00 X
3	6	Rear right fender inner cowling clips X NN	\$ 30.00 X
4	1	Rear windscreen glass sealant X NN	\$ 80.00 X
5	1	Rear right fender sealant X	\$ 80.00 X
6	1	Rear right sport rim - Gut	\$ 950.00 X 650.
7	1	Rear right tyre - sup	\$ 350.00 150.
			<u>\$ 1,580.00</u> 800

Total parts

\$ 12,436.60

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

## SKP5263K BMW 318i

No.	Description	Labour Charge	
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,200.00	750
2	To putty and spray painting accident portion.	\$ 1,200.00	1000
3	To remove and install rear right inner garnish and trim to facilitate the repair.	\$ 180.00	60
4	To remove and install rear right undercarriage parts.	\$ 300.00	x NN
5	To apply anti rust proofing to accident affected area.	\$ 120.00	60
6	To balance rear right wheel.	\$ 50.00	20
7	To conduct wheel alignment.	\$ 80.00	60
8	To remove and install rear right door lock mechanism.	\$ 80.00	60
9	To remove and install rear right door glass.	\$ 80.00	x
10	To check door centre locking for function.	\$ 80.00	x
11	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00	x NN
12	To remove and install rear windscreen to facilitate the repair.	\$ 140.00	x
13	Towing service.	\$ 100.00	x
14	To repair, straighten and re-align front right door panel.	\$ 180.00	x
		<b>\$ 3,970.00</b>	2010

6 Days.

lumpsum repair.

After repair photos.

Gua Qi: mp - 82880282

21/12/17

Total parts : \$ 12,436.60  
Total labour : \$ 3,970.00  
Total repair cost : \$ 16,406.60

5062.97

20% 4050

Lump Sum

Li & Co Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024168/Gqd3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-03-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 4346X	Veh. Inspected	SKP 5263K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011592MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	20/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W 318i	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WBAPF720X0A143466	Colour	BROWN	
Odometer	131856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	GOODYEAR	5 mm	
L/H Front Tyre	205/55R16	GOODYEAR	5 mm	
R/H Rear Tyre	205/55R16	GOODYEAR	5 mm	
L/H Rear Tyre	205/55R16	GOODYEAR	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/12/2017	Inspection Date	21/12/2017	
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 5263K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER ASSY	TO REPAIR SEE LABOUR	1,083.00	-
2	REAR BUMPER SIDE BRACKET	NOT NECESSARY	126.00	-
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	182.00	-
1	REAR RIGHT FENDER ASSY	TO REPAIR SEE LABOUR	1,877.00	-
1	REAR RIGHT FENDER INNER COWLING	NOT NECESSARY	226.00	-
1	REAR RIGHT DOOR PANEL ASSY	BUCKLED	1,655.00	1,152.60
1	REAR RIGHT DOOR LOCK MECHANISM	NOT NECESSARY	285.00	-
1	REAR RIGHT DOOR LOCK CATCH	NOT NECESSARY	76.00	-
1	REAR RIGHT DOOR REGULATOR WITH MOTOR	NOT NECESSARY	488.00	-
2	REAR RIGHT DOOR HINGES	NOT NECESSARY	166.00	-
1	REAR RIGHT DOOR CHECKER LINKAGE	NOT NECESSARY	209.00	-
1	REAR RIGHT DOOR WEATHERSTRIP	NOT NECESSARY	387.00	-
1	REAR RIGHT DOOR HANDLE	NOT NECESSARY	188.00	-
1	REAR RIGHT SIDE ROCKER PANEL GARNISH	CRACKED	1,900.00	1,218.95
1	REAR RIGHT LOWER ARM CARRIER	NOT NECESSARY	496.00	-
1	REAR RIGHT STRUT LINK	NOT NECESSARY	221.00	-
1	REAR RIGHT STRUT ARM	NOT NECESSARY	179.00	-
1	REAR RIGHT CAMBER ARM	NOT NECESSARY	423.00	-
1	REAR RIGHT TRAILING LINK	NOT NECESSARY	223.00	-
1	REAR RIGHT SHOCK ABSORBER	NOT NECESSARY	593.00	-
1	REAR RIGHT FENDER INNER GARNISH	NOT NECESSARY	445.00	-
1	REAR RIGHT WHEEL BEARING (NPA)	NECESSARY	-	-
	LESS 5% DISCOUNT		-571.40	-118.58
			10,856.60	2,252.97
<b><u>SPECIAL NETT ITEMS</u></b>				
12	REAR BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
8	REAR RIGHT FENDER INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
6	REAR RIGHT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI17024168/Gqd3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RIGHT FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR RIGHT SPORT RIM (SN)	CUT	950.00	650.00
1	REAR RIGHT TYRE (SN)	SCRATCHED	350.00	150.00
			1,580.00	800.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN ACCIDENT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER ASSY AND REAR RIGHT FENDER ASSY.		1,200.00	750.00
	TO PUTTY AND SPRAY PAINTING ACCIDENT PORTION.		1,200.00	1,000.00
	TO REMOVE AND INSTALL REAR RIGHT INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		180.00	60.00
	TO REMOVE AND INSTALL REAR RIGHT UNDERCARRIAGE PARTS.	NOT NECESSARY	300.00	-
	TO APPLY ANTI RUST PROOFING TO ACCIDENT AFFECTED AREA.		120.00	60.00
	TO BALANCE REAR RIGHT WHEEL.		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND INSTALL REAR RIGHT DOOR LOCK MECHANISM.		80.00	60.00
	TO REMOVE AND INSTALL REAR RIGHT DOOR GLASS.	NOT NECESSARY	80.00	-
	TO CHECK DOOR CENTRE LOCKING FOR FUNCTION.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL REAR WINDSCREEN TO FACILITATE THE REPAIR.	NOT NECESSARY	140.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
	TO REPAIR, STRAIGHTEN AND RE-ALIGN FRONT RIGHT DOOR PANEL.	NOT NECESSARY	180.00	-
			-	-
			-	-
			-	-
			3,970.00	2,010.00
<b>GRAND TOTAL</b>			<b>16,406.60</b>	<b>5,062.97</b>

Report Ref No. CS/FCI17024168/Gqd3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)			4,050.00
---	--	--	----------

Report Ref No. CS/FCI17024168/Gqd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.