

ASS. REC. BY

REF cs/FCI17024170/Uqd3n2

S. J. V. / J. F.

Marcus

ASSIGNMENT (Office)

CWS

From/Person

Eileen Lee

FCI

Date/Time 3.49pm @ 20/12/17

Estimated Cost

Bill to

OD / TP / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLM 4772T

Insured

SHC 1838H

at Workshop in

Pegasus Engineering

Tel

6858 1846

of

51 Defu Lane 10

Policy No.

D-1507270114FSH

Claim No.

D17011604 MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A. 15/12/17

CA / REV / REP. / REV 24 HRS

1 wpl

R.O.D. Endorsement

Date/Time

5.32pm @ 20/12/17

Person Connected

Alvin

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 4772T - X

SHC 1838H - CC3/AIG 08007509/Ytn

D.O.A. : 25/02/2008

27/12/17 @ 3.55pm informed Eileen Lee, we are pending for estimate from repairer.
 7/1/18 @ 10.07am revised to Eileen Lee by email.

Surveys

REF:

Ref/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLM 47727
 at Workshop m/s Pegasus
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 1.41 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLM 47727 Yr Regn: 3 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or FA
 Make: Nissan Dashgait 1197
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 54603 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFEAJ1141917580
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kende

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/12/17 D.O.I. 26/12/17
 Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

MS Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

claims v13 also.

28/12/17 conf. with f. act for \$3519.97 with Sam.
(Lump \$6090.79, 63%)

RECEIVED 29 DEC 2017

Date/Time: File Pass to? ☐ : Preli. Report

1) 29/12 12:15 ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + P + S:

Photos:

Others:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format: 7P

Lump Sum / I.B.I.: (\$ 3519.97)

170
50
50
37
307



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024170/Uqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1838H	Veh. Inspected	SLM 4772T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011604MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/12/2017	Inspection Date		
Survey held at	51 DEFU LANE 10			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-12-2017	Our Ref No. D17011604MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SHC1838H	Third Party Vehicle. SLM4772T
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232040)



PRI Documents



Close



PRI Header Details

Claim No	D17011604MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1838H	TP Vehicle No	SLM4772T
PRI Recieved Date	18-12-2017 05:15:53 PM	Surveyor Appointed Date	20-12-2017 03:48:43 PM	Surveyor Accept Date	20-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 December, 2017 10:07 AM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011604MFSH/1
Attachments: CSFCI17024170Uqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLM 4772T.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 December, 2017 3:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011604MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SLM 4772T on 26/12/2017.

We are pending for estimate from repairer.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 December, 2017 5:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011604MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011604MFSH

Date: 29 December 2017

Our Ref: CS/FCI17024170/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 4772T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/12/2017 at the premises of M/s PEGASUS ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,610.76</u> .
Revised Estimate Amount	: S\$ <u>3,519.97</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s body.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 December, 2017 3:55 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011604MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SLM 4772T on 26/12/2017.

We are pending for estimate from repairer.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 December, 2017 5:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011604MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 20 December, 2017 3:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011604MFSH/1

Dear Sir/Mdm,

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : BRYCE TAM YIK MAN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

26/12/17
not signed
plp 4dy
LKK Munn
26/12/17 @ 1056h

Quotation No : QO17/12-1153	Quotation Date : 16/12/2017	Terms : 30 DAYS
Vehicle No : SLM4772T	Chassis No : SJNFEAJ11U1917580	Third Party Insurer :
Model : QASHQAI		Date of Accident :
marks : TP INSURER: FCI, INSURED VEH NO:SHC1838H, DATE OF ACCIDENT: 15.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	N/S FRONT DOOR <i>Subs. P</i>	1		
2	FRONT DOOR PROTECTOR <i>Sub</i>			
3	FRONT DOOR POWER WINDOW MOTOR <i>11X</i>			
4	FRONT DOOR REGULATOR <i>11X</i>			
5	FRONT DOOR INNER LOCK <i>11X</i>			
6	FRONT DOOR INNER LOCK STRIKER <i>11X</i>			
7	FRONT DOOR OUTER WEATHERSTRIP MOULDING <i>m</i>			
8	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11X</i>			
9	FRONT DOOR INNER TRIMBOARD <i>11X</i>			
10	FRONT DOOR WINDOW FRAME TOP CHROME GARNISH <i>11X</i>			
11	FRONT DOOR WINDOW FRAME MATT BLACK TAPE <i>m</i>	1		
12	FRONT DOOR WEATHERSTRIP <i>m</i>	1		
13	N/S REAR DOOR <i>2x</i>	1		
14	N/S REAR DOOR PROTECTOR <i>grand</i>	1		
15	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING <i>11X</i>	1		
16	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11X</i>	1		
17	N/S REAR WINDOW FRAME MATT TAPE BLACK FRONT <i>11X</i>	1		
18	N/S REAR WINDOW FRAME MATT TAPE BLACK REAR <i>11X</i>	1		
19	N/S REAR DOOR WEATHERSTRIP <i>11X</i>	1		
20	N/S ROCKER PANEL <i>2x</i>	1		
21	N/S REAR FENDER WHEEL ARC GARNISH <i>grand</i>	1		
22	N/S FRONT FENDER <i>2x</i>	1		
23	N/S FRONT FENDER WHEEL ARC GARNISH <i>11X</i>	1		

LKK Auto Car Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part during resurvey
- Parts prices are subject to information
- Third party survey is on a "Without Prejudice" basis
- 1 illeg. modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C/F

0.00

Page 1 of 2

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : BRYCE TAM YIK MAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/12-1153	Quotation Date : 16/12/2017	Terms : 30 DAYS
Vehicle No : SLM4772T	Chassis No : SJNFEAJ11U1917580	Third Party Insurer :
Model : QASHQAI	Date of Accident :	
marks : TP INSURER: FCI, INSURED VEH NO:SHC1838H, DATE OF ACCIDENT: 15.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	LESS 20%	1		
25	SUNDRIES CLIPS	1		
26	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1		
27	TO RUST PROOFING OF THE AFFECTED AREAS	1		
28	TO TRANSFER OF N/S FRONT AND REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1		

Sub Total	0.00
GST(7.00%)	0.00
Total (SGD)	0.00

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : BRYCE TAM YIK MAN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn : 28/12 - Confirmed
Tel :
Fax : PBP \$3519.97

26/12/17
not authorized
HKK
9/2/18 3519.97
HKK
Weight Security

Quotation No : QO17/12-1153	Quotation Date : 16/12/2017	Terms : 30 DAYS
Vehicle No : SLM4772T	Chassis No : SJNFEAJ11U1917580	Third Party Insurer :
Model : QASHQAI	Date of Accident :	
Remarks : TP INSURER: FCI, INSURED VEH NO:SHC1838H, DATE OF ACCIDENT: 15.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	N/S FRONT DOOR ✓ body m	1	1,169.8000	1,169.80 ✓
2	FRONT DOOR PROTECTOR ✓ Dis	1	323.6000	323.60 ✓
3	FRONT DOOR POWER WINDOW MOTOR ✗ 11	1	244.8400	244.84 ✗
4	FRONT DOOR REGULATOR ✗ 11	1	244.8400	244.84 ✗
5	FRONT DOOR INNER LOCK ✗ 11	1	275.2000	275.20 ✗
6	FRONT DOOR INNER LOCK STRIKER ✗ 11	1	36.0000	36.00 ✗
7	FRONT DOOR OUTER WEATHERSTRIP MOULDING ✓ me	1	188.9000	188.90 ✓
8	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP 11	1	186.4000	186.40 ✗
9	FRONT DOOR INNER TRIMBOARD ✗ 11	1	1,869.5000	1,869.50 ✗
10	FRONT DOOR WINDOW FRAME TOP CHROME GARNISH ✗ 11	1	111.1000	111.10 ✗
11	FRONT DOOR WINDOW FRAME MATT BLACK TAPE ✓ me	1	36.0000	36.00 ✓
12	FRONT DOOR WEATHERSTRIP ✓ me	1	132.2000	132.20 ✓
13	N/S REAR DOOR ✗ R	1	1,169.8000	1,169.80 ✗
14	N/S REAR DOOR PROTECTOR ✓ ground	1	323.6000	323.60 ✓
15	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING ✗ 11	1	188.9000	188.90 ✗
16	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP ✗ 11	1	186.4000	186.40 ✗
17	N/S REAR WINDOW FRAME MATT TAPE BLACK FRONT ✗ 11	1	36.0000	36.00 ✗
18	N/S REAR WINDOW FRAME MATT TAPE BLACK REAR ✗ 11	1	36.0000	36.00 ✗
19	N/S REAR DOOR WEATHERSTRIP ✗ 11	1	132.2000	132.20 ✗
20	N/S ROCKER PANEL ✗ R	1	945.0000	945.00 ✗
21	N/S REAR FENDER WHEEL ARC GARNISH ✓ ground	1	483.0000	483.00 ✓
22	N/S FRONT FENDER ✗ R	1	698.8000	698.80 ✗
23	N/S FRONT FENDER WHEEL ARC GARNISH ✗ 11	1	483.0000	483.00 ✗

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : BRYCE TAM YIK MAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/12-1153	Quotation Date : 16/12/2017	Terms : 30 DAYS
Vehicle No : SLM4772T	Chassis No : SJNFEAJ11U1917580	Third Party Insurer :
Model : QASHQAI		Date of Accident :
Remarks : TP INSURER: FCI, INSURED VEH NO: SHC1838H, DATE OF ACCIDENT: 15.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	LESS 30% (ITEM 1-23)	1	-2,850.3200	-2,850.32
25	SUNDRIES CLIPS	1	150.0000	150.00
26	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	180.0000	180.00
27	TO RUST PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00
28	TO TRANSFER OF N/S FRONT AND REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	250.0000	250.00
29	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,000.0000	1,000.00
30	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,200.0000	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1-2657.1
 302
 1859.97
 3519.97

Sub Total	9,610.76
GST(7.00%)	672.75
Total (SGD)	10,283.51

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024170/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1838H	Veh. Inspected	SLM 4772T	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011604MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SJNFEAJ11U1917580	Colour	SILVER	
Odometer	54603	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	KENDA	6 mm	
L/H Front Tyre	215/60 R17	KENDA	6 mm	
R/H Rear Tyre	215/60 R17	KENDA	6 mm	
L/H Rear Tyre	215/60 R17	KENDA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2017	Inspection Date	26/12/2017	
Survey held at	51 DEFU LANE 10			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 4772T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S FRONT DOOR	BADLY DENTED	1,169.80	1,169.80
1	FRONT DOOR PROTECTOR	DISTORTED	323.60	323.60
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	244.84	-
1	FRONT DOOR REGULATOR	NOT NECESSARY	244.84	-
1	FRONT DOOR INNER LOCK	NOT NECESSARY	275.20	-
1	FRONT DOOR INNER LOCK STRIKER	NOT NECESSARY	36.00	-
1	FRONT DOOR OUTER WEATHERSTRIP MOULDING	NECESSARY	188.90	188.90
1	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	186.40	-
1	FRONT DOOR INNER TRIMBOARD	NOT NECESSARY	1,869.50	-
1	FRONT DOOR WINDOW FRAME TOP CHROME GARNISH	NOT NECESSARY	111.10	-
1	FRONT DOOR WINDOW FRAME MATT BLACK TAPE	NECESSARY	36.00	36.00
1	FRONT DOOR WEATHERSTRIP	NECESSARY	132.20	132.20
1	N/S REAR DOOR	TO REPAIR SEE LABOUR	1,169.80	-
1	N/S REAR DOOR PROTECTOR	GRAZED	323.60	323.60
1	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	188.90	-
1	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	186.40	-
1	N/S REAR WINDOW FRAME MATT TAPE BLACK FRONT	NOT NECESSARY	36.00	-
1	N/S REAR WINDOW FRAME MATT TAPE BLACK REAR	NOT NECESSARY	36.00	-
1	N/S REAR DOOR WEATHERSTRIP	NOT NECESSARY	132.20	-
1	N/S ROCKER PANEL	TO REPAIR SEE LABOUR	945.00	-
1	N/S REAR FENDER WHEEL ARC GARNISH	GRAZED	483.00	483.00
1	N/S FRONT FENDER	TO REPAIR SEE LABOUR	698.80	-
1	N/S FRONT FENDER WHEEL ARC GARNISH	NOT NECESSARY	483.00	-
	LESS 30% DISCOUNT		-2,850.32	-797.13
			6,650.76	1,859.97
SPECIAL NETT ITEMS				
1	SUNDRIES CLIPS (SN)	NOT NECESSARY	150.00	-

Report Ref No. CS/FCI17024170/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR		150.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	180.00	-
	TO RUST PROOFING OF THE AFFECTED AREAS.		180.00	30.00
	TO TRANSFER OF N/S FRONT AND REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		250.00	80.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF N/S REAR DOOR, N/S ROCKER PANEL AND N/S FRONT FENDER.		1,000.00	750.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	800.00
			2,810.00	1,660.00
	GRAND TOTAL		9,610.76	3,519.97
RECOMMENDED COST OF REPAIRS				3,519.97

Report Ref No. CS/FC117024170/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.