



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
 Loyang Enterprise Building, Email: johnong@ethicarz.sg
 Tel: 63844404, FAX: 63840444

VEHICLE NUM:	SGL112P
MAKE & MODEL:	TOYOTA PICNIC
MILEAGE:	4911.6
TYRE:	FALKEN 205/66/R16
CHASSIS NUM:	JTEG23B400020909

ATTN:

QTY	DESCRIPTION - PARTS	PRICE
1	FRONT BUMPER ✓	
2	FRONT BUMPER BRACKET (L+R) LH x RH ✓	
2	FRONT BUMPER RETAINER (L+R) LH x RH ✓	
2	FRONT BUMPER CLIP (L+R) ✓	
1	FRONT BUMPER REINFORCEMENT BAR x	
1	FRONT BUMPER SPONGE x	
1	FRONT BUMPER FOG LIGHT (RH) x	
1	FRONT BUMPER FOG LIGHT GRILLE (RH) x	
1	HEADLAMP (RH) x	
1	HEADLAMP CLIP (RH) x	
1	HEADLAMP WEATHER STRIP (RH) x	
1	FRONT FENDER (RH) x repair	REPAIR
1	FRONT FENDER COWLING (RH) x	
1	FRONT FENDER COWLING CLIP (RH) x	
1	FRONT LOWER ARM (RH) x	
1	FRONT KNUCKLE (RH) x	
1	FRONT KNUCKLE BEARING (RH) x	
1	FRONT ABSORBER (RH) x	

QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	FRONT RIM (RH) x	500
1	FRONT TYRE (RH) x	300

QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT	400 800
1	TO PUTTY AND RESPRAY AFFIDENT AFFECTED FRONT	400 600
1	TO CHECK WIRING AND HEADLIGHT FOCUS FUNCTION	180 x
1	TO CHECK FRONT WHEEL ALIGNMENT	180 x

Calvin 12/12/14
 2 1/2 days 1400 hrs.
 2 Days
 LK Auto Repairs
 After Repair photo

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: