

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 237/IC/TCAC/CCR/2017
DATE : 19-DEC-2017

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : 1R CHEONG FEI KONG
ADDRESS : 35 PASIR RIS DRIVE 3
#08-06
S(519493)
TELEPHONE NO : 98513334/94567551

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100414621-02000
VEHICLE NO : SKT3258T
MODEL CODE : BDTARCZB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR16963429B
CHASSIS NO : MNTBBAB17Z0023317
MILEAGE : 72154 KM
DATE IN : 19/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 19/12/2017

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT3258T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	
4	ZZ/001	RENEW REAR LEFT DOOR, FENDER, BUMPER, RIM ETC PANELS & REPAIR	1140.00	
5	ZZ/002	TRANSFER REAR LEFT DOOR MECHANISMS TO FACILITATE REPAIR	120.00	
6	ZZ/003	RENEW REAR LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	
7	ZZ/004	INSTALL SOLAR FILM ON REAR LEFT QUARTER GLASS	32.00	
8	ZZ/005	RESPRAY REAR LEFT DOOR, FENDER, REAR BUMPER ETC	1000.00	
9	ZZ/006	QC, RETUNE & CONSULT CHECK		
10	ZZ/007	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	
		TOTAL LABOUR CHARGES	3057.00	

TC AUTOCLINIC PTE LTD
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKT3258T

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	LEFT QUARTER GLASS	83301-3SB1A			492.20
2	ALLOY RIM(G11/B17)16X6.5	40300-SSW166			230.00
3	SIDE MOULDING	G6840-3ST0A			247.00
4	REAR BUMPER	85022-3ST4H	607.00		
5	CENTRE DOOR MOULDING	82821-3SB0A	130.40		
6	C-PILLAR TAPE	82813-3SB0A	12.00		
7	TOP DOOR TAPE	82819-3SB0A	27.40		
8	B-PILLAR TAPE	82817-3SB0A	20.50		
9	REAR LEFT DOOR	H210A-3SBMA	930.60		
10	REAR LEFT FENDER	G8101-3SBMA	1387.40		
SUB TOTAL			3115.30	0.00	969.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			623.06	0.00	0.00
GRAND TOTAL			2492.24	0.00	969.20
OVERALL TOTAL			3461.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKT3258T

TOTAL LABOUR CHARGES	3057.00
TOTAL SPARE PARTS CHARGES	3461.44
GRAND TOTAL	6518.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.