



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 19/12/2017

TO : AXA INSURANCE

ATTN :

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL PANDAN

ATTN : ANDY OOI

OFFICE / MOBILE : 67730073

FAX NO. : 67730928

VEHICLE NO. : SJH9649J

MODEL NO. : HONDA STREAM 1.8L A

CHASSIS NO. : JHMRN68408S201206

ENGINE NO. : R18A12801139

REG. DATE : 29/8/2008

REF. NO. : GBE/SVC/SALES

D.O.A. : 11/12/2017

POLICY NO. : 5092752947

CLAIM TYPE : TP CLAIM - AXA INSURANCE

WORKSHOP : BLK K PANDAN LOOP IND EST
#01-12 SINGAPORE 128230

<u>S/N</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>QUANTITY</u>	<u>LIST PRICE</u>
1		FRONT FENDER LH ✓ DT	1	\$ 486.00
2		FRONT FENDER INNER SHIELD LH ?	1	\$ 79.00
3		FRONT FENDER SIGNAL LAMP LH ✓ ms	1	\$ 15.00
4		HEADLAMP LH ✓ CRK	1	\$ 650.00

SUB-TOTAL :	\$ 1,230.00
PART-20% :	\$ 246.00
BALANCE :	\$ 984.00



Certificate No: AJA(S)01/Q1243

Certificate No: AJA01/3054



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

SPECIAL-NETT ITEMS

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

PARTS TOTAL :

\$ 984.00

LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	1	\$ 800.00 400
2 TO CHECK FOR & RECTIFY WIRING FAULT ,ETC	1	\$ 30 100.00
3 TO PUTTY ,CLEAN ,SPRAY PAINT & POLISH ,ETC	1	\$ 400 700.00
4 RUST PROOFING	1	\$ 50 120.00
5 CONDUCT WHEEL ALIGHMENT ?	1	\$ 120.00

LABOUR TOTAL :

\$ 1,840.00

GRAND TOTAL :

\$ 2,824.00

PREPARED BY : ANDY OOI

DATE / TIME : 8/1/2018.

SURVEYOR : Sebastian.

MOBILE NO. : 90036121

OFFICE FAX NO. :

EMAIL ADDRESS : Sebastianyeang@lkkauto.com.

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

REMARKS :

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Lump Sum Repair.
- Question mark Item Photo
- Photo After Paint.



Certificate No: AJA(S)01/Q1243

Certificate No: AJA01/3054