



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5814Z  
 Ref. No : BUS/12/17/7023  
 Reg. Date : 04/07/2017  
 Vehicle Type : DOUBLE DECK  
 Make : MAN  
 Model : MAN A95  
 Name of Driver : Kwa Tian Ser  
 Type of Accident : OTHERS  
 Date / Time of Accident : 19/12/2017 09:00:00 AM  
 Accident Reported Date / Time : 19/12/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : China Tai Ping  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093703  
 Special Instruction to ARC, if any :



BC SAID ONLY THE FRONT MUDGUARD NEAR BOARDING DOOR IS SCRATCHED. TP IS CHINA TP SLR784J

Prepared Date : 19/12/2017 12:16:10 PM

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA95ZZ2G7003463

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	530.00
Total Spray Painting Charges	: 616.00	446.00
Total Material Charges	: 275.40	275.40
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 1,686.40</b>	<b>1,251.40</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00 /
Prepared / Adjusted By	: Goh Kok Khoo	Sebastian Yeang
Arc / Surveyor Sign Off Date	: 19/12/2017 04:45:51 PM	19/12/2017 04:47:58 PM



LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/12/2017 02:38:11 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	446.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>616.00</b>	<b>446.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			RUBBER DOOR PILLAR FRONT	1	306.00	10.00	275.40	Replace	Replace	No / Deform.
TOTAL MATERIALS							275.40	275.40		
TOTAL MATERIALS(Discounted)							275.40	275.40		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

275.40  
 530.00  
 + 446.00  
 -----  
 1251.40

Sebastian  
 28/12/2017