

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	795.00	530.00
Total Spray Painting Charges :	616.00	446.00
Total Material Charges :	275.40	275.40
Other Charges :	0.00	0.00
TOTAL :	1,686.40	1,251.40
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	2.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	19/12/2017 04:45:51 PM	19/12/2017 04:47:58 PM



LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/12/2017 02:38:11 PM


Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5814Z
Ref. No : BUS/12/17/7023
Reg. Date : 01/01/1900
Vehicle Type : DOUBLE DECK
Make : MAN
Model : MAN A95
Name of Driver : Kwa Tian Ser
Type of Accident : OTHERS
Date / Time of Accident : 19/12/2017 09:00:00 AM
Accident Reported Date / Time : 19/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : China Tai Ping
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :



BC SAID ONLY THE FRONT MUDGUARD NEAR BOARDING DOOR IS SCRATCHED. TP IS CHINA TP SLR784J

Prepared Date : 19/12/2017 12:16:10 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530.00
Total Labour	795.00	530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	446.00
Total Spray Painting & Panel Beating	616.00	446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			RUBBER DOOR PILLAR FRONT	1	306.00	10.00	275.40	Replace	Replace	No
TOTAL MATERIALS							275.40	275.40		
TOTAL MATERIALS(Discounted)							275.40	275.40		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									