

12/20/2017

ASS: REC. BY:

REF: CS/CT#17024203/Tivd302

Special Instructions:

Subject:

ASSIGNMENT (Office)

Maximen

From (Person):

Irene Tay

of

CTI

Date/Time: 21/12/17 @ 11:15am

Estimated Cost:

Bill to:

OD # IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 6285 Y

Insured:

SJZ 2406 U

at Workshop n/s

Vermogen Ace

Tel:

6694 1919 | 6904 4596

of

G Benoi Sector

Policy No:

DMHCSN169033/1606

Claim No:

SNM17D07127 C02

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A. 15/12/2017

CA / REV / REP. / REV 24 HRS

'wup'

R.O.D. Endorsement:

Date/Time:

12:22pm @ 21/12/17

Person Contacted:

Eera

Vehicle IN OUT

Date/Time

Action/Instruction:

(✓) Estimate

SLC 6285 Y - X

SJZ 2406 U - X

30/1/18

LS \$3350 confirmed by email (Ref 18,089.96, 8415)

Signature: *Toufik*

REF: CTI

ASSIGNMENT

From: _____ Date: 22/12/17
Estimated Cost: _____
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
To Inspect Vehicle No: SLC 6285Y
at Workshop mis Vermogen Ace
of Genot Seefor
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

wp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC 6285Y Yr Regn: 2016 may
Type: ☒ M Car ☐ M Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover /
Truck / Trailer or
Make: Honda Vezel o.c. 1496
Colour: Silver A/C: _____ Insured / Std / NI / NA
Sp. Reading: 15280 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: R41113937
Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt
Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
Modi: ☒ Nil ☐ S/Rim ☐ STD A/Rim or
Tyre Size: F: 215/60R16
R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 1 mm

D.O.A. _____

D.O.I. 22/12/17

Survey held at

Vermogen

Des. of Damages: Frt / Rear ☒ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Date/Time: File Return to?

2) 30/1 - typist

Add Fee: ☐ : Site Insp. (\$

☐ : Interview (\$

☐ : Techn. Insp. (\$

☐ : Weekend (\$

Photos

Others

Report Format :

merimen

Lump Sum / I.B.I. (\$

3350

220

220

Survey Department Check List (Case Handler)

Reference No.: CS/CTI17024203/TIVC3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 30/11/13
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17024203/R1vd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-12-2017



Code : CTI

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SJZ 2406U	Veh. Inspected	SLC 6285Y
Policy No.	DMHCSN1690331600	Coverage (\$)	0.00
Claim No.	SNM17D07127C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2017	Inspection Date	21/12/2017
Survey held at	6 BENOI FACTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	21 Dec 2017		21 Dec 2017 11:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	KIRALY PTE LTD, Co. Reg. No.: 201412081C								
Main Claimant:	LION CITY RENTALS PTE. LTD., Co. Reg. No.: 201504621K								
Vehicle Reg. No.:	SLC6285Y	Date of Loss:	15/12/2017 11:00 - :59						
Claim Type:	TP / SNM17D07127C02	Policy/Cover Note No.:	DMHCSN1690331600 (Comprehensive) Coverage: 21/12/2016 - 14/02/2018						
Vehicle Reg. No. (Insured):	SJZ2406U	Policy No. (Claimant):	1159890						
		Excess:	\$0.00						
Repairer:	Vermogen Ace Pte Ltd (benol) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2018]								
Adj. Asg. Remarks:	1) REQUESTED SURVEYOR: KENNETH KONG PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Susan

From: Lina Rosli <linavermogenace@gmail.com>
Sent: Monday, 18 December 2017 1:42 PM
To: Susan
Cc: group@ajaxmars.com; Eileen, May Hwee Yap; Insurance LCR SG; vmg.vermogenace; Yira Rahman; Nikolette Chong; edmondvermogenace; VERMOGEN ACE; Minoko Chan; pila.vermogenace@gmail.com
Subject: Re: SLC628SY- 15122017

Dear Susan,

Kindly assist on addendum GIA report.
Hirer have came down to workshop hence we have clarified.

1) Hirer video has been overwrite. Hence No video captured instead of Yes.

2) Name of passenger from unknown passenger to Agnes Choo

Thanks susan,

Best Regards,

Lina R.



Vermogen Ace Pte Ltd

Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6694 4919
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Weega Plaza Singapore 658064

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 17:49
Date Of Accident	15/12/2017 11:30
Exact Location Of Accident	HENDERSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6285Y
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE. LTD.
Co Reg No	201504621K
Email Address	ABDUL.MOTLIB@VOLIA.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97599472

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
--	------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	1159890
Cover Note Number	NA

Driver

Name of Driver	ABDUL MOTLIB S/O MOHADOS ALI
NRIC No	S0059975A
Date Of Birth	07/11/1953
Occupation	INDOOR
Date Of Driving Pass	08/02/1973
Driving Experience	44 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97599472
Fax Number	
Contact Number	
EMail Address	ABDUL.MOTLIB@VOLIA.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] BEDOK NORTH N P C
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NUMBER T/20171215/2093: ON 15/12/2017 AT ABOUT 11.30AM, I WAS DRIVING ALONG HENDERSON ROAD SUBSEQUENTLY THE TRAFFIC LIGHT TURN RED. THERE WERE A FEW VEHICLES IN FRONT OF ME. MY VEHICLE WAS IN THE STATIONARY POSITION. SUDDENLY I FELT A SUDDEN JERK ON THE REAR OF MY VEHICLE. I CHECKED ON MY PASSENGERS AND THEY SAID THEY WERE FINE BUT SAID THEY HAD PAIN ON THEIR NECK. I CALLED FOR THE AMBULANCE AND FEW MINUTES LATER THEY ARRIVED AT SCENE. THE SAID PASSENGERS WERE ASSESSED BY PARAMEDIC BUT REFUSED TO BE CONVEYED TO THE HOSPITAL. AFTER WHICH I ALIGHTED FROM MY VEHICLE. AND TALKED TO THE DRIVER (SJZ2460U) THAT HAD HIT ME. WE MANAGED TO EXCHANGE PARTICULARS. WE THEN WENT OUR SEPARATE WAYS. AFTER THAT I RECEIVED A CALL FROM TRAFFIC POLICE TO LODGE A POLICE REPORT REGARDING THE ACCIDENT THAT JUST OCCURRED. THE DAMAGES TO MY CAR ARE MY REAR BONNET AND REAR BUMPER IS DAMAGED. I AM NOT INJURED. THEY TOLD ME TO VISIT THE DOCTOR IF I START VOMITING. I WISH TO STATE THAT I ONLY HAVE FRONT IN-CAR CAMERA.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ2406U
 Vehicle Make/Model/Colour HONDA / CIVIC 1.8L A
 Details Of Properties NA
 Name of Driver SHAMSURIA BIN HANAFI
 NRIC/Passport Number S1713427B
 Contact Number 84242623
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

AGNES CHOO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLC6285Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

UNKNOWN PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLC6285Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident.
2. This form must be completed by the Police.
3. Information provided must be as truthful as possible to avoid insurance companies to repudiate the claim.
4. The issue and acceptance of this form is a legal document.
5. Any false reporting may be referred to the Police.
6. The report will be forwarded by the Ministry of Transport (MOT) to the Insurance Corporation of Singapore (ICA) for archiving and for the judgement of this report to be made available elsewhere.
7. Consent under the Personal Data Protection Act (PDPA) (a) My insurer, my workshop and I agree to process my personal data for the purpose of my insurer (collectively the "insurers"), the insured vehicle(s) involved in the accident, for the purpose of processing, handling, the claim.
- (b) Investigating the accident.
- (c) Settling the claim.
- (d) Settling the claim.
- (e) Settling the claim.
- (f) Settling the claim.
- (g) Settling the claim.
- (h) Settling the claim.
- (i) Settling the claim.
- (j) Settling the claim.
- (k) Settling the claim.
- (l) Settling the claim.
- (m) Settling the claim.
- (n) Settling the claim.
- (o) Settling the claim.
- (p) Settling the claim.
- (q) Settling the claim.
- (r) Settling the claim.
- (s) Settling the claim.
- (t) Settling the claim.
- (u) Settling the claim.
- (v) Settling the claim.
- (w) Settling the claim.
- (x) Settling the claim.
- (y) Settling the claim.
- (z) Settling the claim.

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bedok North N P C
30 Bedok North Road SINGAPORE 469676
Tel No 1800-2449999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made
15/12/2017 15:30

Vide Report No.:

Name of Informant: ABDUL MOTLIB S/O MOHADOS ALI		Address: APT BLK 544 BEDOK NORTH SINGAPORE 460544	
ID Type / ID No: NRIC NO / 50059875A		Contact No.:	
Nationality: SINGAPORE CITIZEN		Home/Office:	
Email:		Type of Informant: Driver	
Sex: Male	Age: 64	Date of Birth: 07/11/1953	Language:
Race: Pakistani		Driving Licence Information: Class: 2B, 2A, 3, 4, 5	
Occupation: UBER DRIVER			

Type of Accident:	Injury Others	Drink Drive:	Other
Location: Along Road 1 HENDERSON ROAD		No	
Weather: Clear		Road Surface: Dry	
Traffic Flow: Two Way		Traffic Sign:	
Type of Collision: Motor Vehicle Against - Pedestrian			

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469675
Tel No. 1800-2448889



Report No. T201712

CONTINUATION OF REPORT

Name	SHAMSURIA BIN HANAFI		ID No.	S1713427B
Related Vehicle	SJZ2408U (Car)		Contact No.	84242823
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Name	ABDUL MOTLIB S/O MOHADOS ALI		ID No.	S0010702
Related Vehicle	SLC8285Y (Car)		Contact No.	97600
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Name	AGNES CHOO		ID No.	S0010702
Related Vehicle	SLC8285Y (Car)		Contact No.	97600
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of
Bedok North N.P.C.
30 Bedok North Road SINGAPORE 40676
Tel No: 980-244999

COMMUNICATION

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469576
Tel No: 1800-2448889

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance certificate with you now, please do not leave it behind.

Signature Of Officer Recording
G /
Sgt 2 ANWAR MUSHADAD BILAL
RAHMAN

Signature Of Interpreter
Not applicable

Officer
TP /
SI /
Com

EMAIL ATTACHED

Susan

From: Lina Rosli <linavermogenace@gmail.com>
Sent: Monday, 18 December 2017 1:42 PM
To: Susan
Cc: group@ajaxmars.com; Eileen, May Hwee Yap; Insurance LCR SG; vmg.vermogenace; Yira Rahman; Nikolette Chong; edmondvermogenace; VERMOGEN ACE; Minoko Chan; pila.vermogenace@gmail.com
Subject: Re: SLC6285Y- 15122017

Dear Susan,


Kindly assist on addendum GIA report.
Hirer have came down to workshop hence we have clarified.

- 1) Hirer **video has been overwrite**. Hence No video captured instead of **Yes**.
- 2) Name of passenger from **unknown passenger** to **Agnes Choo**

Thanks susan,

Best Regards,

Lina R.




Vermogen Ace Pte Ltd

Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6694 4919
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Weega Plaza Singapore 658064

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Driving License

REPUBLIC OF SINGAPORE



Identification Card

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

		ISS DATE
Class 2B	Motorcycles not exceeding 200 cc	23 Feb 1964
Class 2A	Motorcycles between 201 cc and 400 cc	10 Jan 1966
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms	05 Feb 1972
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 3500 kilograms	10 Sep 1969
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 3500 kilograms	20 Nov 1966



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday 09:30 - 17:00
URN: 5665500200 / GST Reg. No. 84400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH17165244 Vehicle Registration No : SLC6285Y
Name (as shown in NRIC) : ABDUL MOTLIB S/O MOHADOS ALI NRIC/FIN/Passport No : S0059975A
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. 97599472
Email Address : abdul.motlib@voh.com
Date of Accident : 15/12/2017 Time of Accident : 11:30
Place of Accident : HENDERSON RD
Insurance Company : AIG ASIA PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND Was there any video captured by Car Camera? NO

DETAILS OF INJURED PERSON 1 Agnes Choo

Policyholder / Driver's Signature
Date:

SUSAN (e-filer)
Reporting Centre Personnel's Signature
Name: F S NEO
NRIC/FIN No :
Date 18/12/2017



SLC6285Y

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 15/12/2017

Vehicle Reg. No. : SLC6285Y
Vehicle Reg. Date: 20-May-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4033942
Chassis No. : RU11113937

COST OF CLAIMS

Parts Cost / List Items :	\$	19,243.70
Plus/Less <u>20%</u>	\$	3,848.74
Total Cost / List :	\$	15,394.96
Special Nett Items :	\$	825.00
Total Parts Amount :	\$	16,219.96
Total Labour Amount :	\$	5,220.00
Gross Total :	\$	21,439.96
GST % : <u>7%</u>	\$	1,500.80
Nett Amount :	\$	22,940.76

Surveyor Name and Company :

Tanjilun 97495749
Date of survey : 22/12/17
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@lkkank.com
Fax No :
HP No :

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental claims must be resurveyed and is subject to final approval from insurance

Acknowledged by Repairer:
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6285Y**
 Vehicle Reg. Date: **20/5/2016**
 Make / Model : **H. VEZEL 1.5X CVT**
 Engine No. : **L15B4033942**
 Chassis No. : **RU11113937**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bf ✓	\$ 1,860.00		
2	1	Tailgate outer garnish	x nn	\$ 285.00		
3	1 set	Tailgate outer garnish clips	x nn	\$ 40.00		
4	1	Tailgate logo	nd ✓	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	nd ✓	\$ 56.20		
6	2	Tailgate lamp LH/RH	x ✓	\$ 980.00		
7	2set	Tailgate lamp clips	x	\$ 50.00		
8	1	Tailgate outer handle switch	x	\$ 180.00		
9	2	Tailgate damper LH/RH	x	\$ 424.00		
10	1	Tailgate wiper motor	x	\$ 250.00		
11	1	Tailgate wiper blade	x	\$ 75.00		
12	1	Tailgate buzzer	x nn	\$ 150.00		
13	1	Tailgate inner handle	x	\$ 74.00		
14	1	Tailgate inner lock	x	\$ 245.00		
15	1	Tailgate lock sensor	x	\$ 220.00		
16	1	Tailgate striker	x	\$ 32.00		
17	1	Tailgate trimboard	x	\$ 295.00		
18	1 set	Tailgate trimboard clips	x	\$ 45.00		
19	1	Tailgate weatherstrip	cut ✓	\$ 145.00		
20	1 set	Tailgate windscreen moulding	nd ✓	\$ 164.00		
21	2	Tail lamp LH/RH	x nn	\$ 978.00		
22	1set	Tail lamp clips	x nn	\$ 36.00		
23	1	Rear bumper	de ✓	\$ 950.00		
24	1set	Rear bumper clips	nd ✓	\$ 50.00		
25	2	Rear bumper retainer LH/RH	x ✓	\$ 144.00		
26	2	Rear bumper bracket LH/RH	x x	\$ 116.00		
27	2	Rear bumper reflector LH/RH	x nn	\$ 334.00		
28	2	Rear bumper cover LH/RH	x	\$ 420.00		
29	1set	Rear bumper cover clips	x	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	x	\$ 84.00		
31	1	Rear end panel outer	Ry	\$ 585.00		
32	1	Rear end panel inner	x ✓	\$ 396.00		
33	1	Rear end panel top garnish	x	\$ 184.00		
34	1set	Rear end panel top garnish clips	x	\$ 25.00		
35	1	Spare tyre panel	x x	\$ 1,230.00		
36	1	Spare tyre panel insulator	x nn	\$ 240.00		
37	1	Spare tyre panel top board	x	\$ 420.00		
38	1	Spare tyre tool tray	x	\$ 430.00		
39	1	EDLC module	x	\$ 1,750.00		
40	2	Rear fender panel LH	x	\$ 1,900.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6285Y**
 Vehicle Reg. Date: **20/5/2016**
 Make / Model : **H. VEZEL 1.5X CVT**
 Engine No. : **L15B4033942**
 Chassis No. : **RU11113937**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2	Rear fender inner trim LH/RH	X	\$ 480.00		
42	2	Tail lamp panel LH/RH	X	\$ 550.00		
43	2	Rear fender arch garnish LH/RH	X	\$ 330.00		
44	2set	Rear fender arch garnish clips	X	\$ 60.00		
45	2	Rear fender inner water shield LH/RH	X	\$ 320.00		
46	2set	Rear fender inner water shield clips	X	\$ 60.00		
47	2	Rear fender Air duct LH/RH	X	\$ 150.00		
48	1	Exhaust muffler	X	\$ 855.00		
49	1	Exhaust muffler mounting	X	\$ 79.50		
50	1	Exhaust muffler heat shield	X	\$ 165.00		
51	2	Rear plate lamp LH/RH	X	\$ 250.00		
52	1	Rear number plate with frame	X		\$ 45.00	
53	1	Tailgate windscreen sealant	new		\$ 80.00	
54	1	Tailgate windscreen inner seal	new		\$ 80.00	
55	1	Rear end panel sealant	X un		\$ 80.00	
56	1	Reverse sensor	? X un	200	\$ 300.00	
57	1	Spare tyre panel sealant	X un		\$ 80.00	
58	1	Spare tyre panel padding	X un		\$ 100.00	
59	1	Sundries	✓	20	\$ 60.00	
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLC6285Y
Vehicle Reg. Date:	20/5/2016
Make / Model :	H. VEZEL 1.5X CVT
Engine No. :	L15B4033942
Chassis No. :	RU11113937

PAGE 1

Estimates on Labour

[illegible]



SLC6285Y

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING

Vehicle Reg. No. : SLC6285Y

OWN INSURER : AIG

Vehicle Reg. Date: 20-May-2016

CLAIM TYPE : TP

Make / Model : H. VEZEL 1.5X CVT

Date of Accident : 15/12/2017

Engine No. : L15B4033942

Chassis No. : RU11113937

COST OF CLAIMS

Parts Cost / List Items : \$ 19,243.70

Plus/Less 20% \$ 3,848.74

Total Cost / List : \$ 15,394.96

Special Nett Items : \$ 825.00

Total Parts Amount : \$ 16,219.96

Total Labour Amount : \$ 5,220.00

Gross Total : \$ 21,439.96

GST % : 7% \$ 1,500.80

Nett Amount : \$ 22,940.76

Surveyor Name and Company :

Tanjiu 97495749

Date of survey : 22/12/17

Part by Part / Lump Sum : 4 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@kkk.com

Fax No : _____

HP No : _____

This claim is handled by : PAULO BALDOZ

L/S = 3400

$$\begin{array}{r} P = 3277.20 \\ - 20 \\ \hline 2021.76 \\ SM = 220 \\ L = 1420 \\ \hline = 4201.76 \\ - 20 \\ \hline = 3409.408 \end{array}$$

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLC6285Y
 Vehicle Reg. Date: 20/5/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4033942
 Chassis No. : RU11113937

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bf ✓	\$ 1,860.00		
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1 set	Tailgate outer garnish clips	X	\$ 40.00		
4	1	Tailgate logo	new ✓	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	new ✓	\$ 56.20		
6	2	Tailgate lamp LH/RH	X	\$ 980.00		
7	2set	Tailgate lamp clips	X	\$ 50.00		
8	1	Tailgate outer handle switch	X	\$ 180.00		
9	2	Tailgate damper LH/RH	X	\$ 424.00		
10	1	Tailgate wiper motor	X	\$ 250.00		
11	1	Tailgate wiper blade	X	\$ 75.00		
12	1	Tailgate buzzer	X	\$ 150.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	X	\$ 245.00		
15	1	Tailgate lock sensor	X	\$ 220.00		
16	1	Tailgate striker	X	\$ 32.00		
17	1	Tailgate trimboard	X	\$ 295.00		
18	1 set	Tailgate trimboard clips	X	\$ 45.00		
19	1	Tailgate weatherstrip	new ✓	\$ 145.00		
20	1 set	Tailgate windscreen moulding	new ✓	\$ 164.00		
21	2	Tail lamp LH/RH	X	\$ 978.00		
22	1set	Tail lamp clips	X	\$ 36.00		
23	1	Rear bumper	de ✓	\$ 950.00		
24	1set	Rear bumper clips	new ✓	\$ 50.00		
25	2	Rear bumper retainer LH/RH	X	\$ 144.00		
26	2	Rear bumper bracket LH/RH	X	\$ 116.00		
27	2	Rear bumper reflector LH/RH	X	\$ 334.00		
28	2	Rear bumper cover LH/RH	X	\$ 420.00		
29	1set	Rear bumper cover clips	X	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	X	\$ 84.00		
31	1	Rear end panel outer	Ry	\$ 585.00		
32	1	Rear end panel inner	X	\$ 396.00		
33	1	Rear end panel top garnish	X	\$ 184.00		
34	1set	Rear end panel top garnish clips	X	\$ 25.00		
35	1	Spare tyre panel	X	\$ 1,230.00		
36	1	Spare tyre panel insulator	X	\$ 240.00		
37	1	Spare tyre panel top board	X	\$ 420.00		
38	1	Spare tyre tool tray	X	\$ 430.00		
39	1	EDLC module	X	\$ 1,750.00		
40	2	Rear fender panel LH	X	\$ 1,900.00		

P= 3277.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLC6285Y
 Vehicle Reg. Date: 20/5/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4033942
 Chassis No. : RU11113937

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2	Rear fender inner trim LH/RH	X	\$ 480.00		
42	2	Tail lamp panel LH/RH	X	\$ 550.00		
43	2	Rear fender arch garnish LH/RH	X	\$ 330.00		
44	2set	Rear fender arch garnish clips	X	\$ 60.00		
45	2	Rear fender inner water shield LH/RH	X	\$ 320.00		
46	2set	Rear fender inner water shield clips	X	\$ 60.00		
47	2	Rear fender Air duct LH/RH	X	\$ 150.00		
48	1	Exhaust muffler	X	\$ 855.00		
49	1	Exhaust muffler mounting	X	\$ 79.50		
50	1	Exhaust muffler heat shield	X	\$ 165.00		
51	2	Rear plate lamp LH/RH	X	\$ 250.00		
52	1	Rear number plate with frame	X		\$ 45.00	
53	1	Tailgate windscreen sealant	new		\$ 80.00	
54	1	Tailgate windscreen inner seal	new		\$ 80.00	
55	1	Rear end panel sealant	X		\$ 80.00	
56	1	Reverse sensor	X	200	\$ 300.00	
57	1	Spare tyre panel sealant	X		\$ 80.00	
58	1	Spare tyre panel padding	X		\$ 100.00	
59	1	Sundries	✓	20	\$ 60.00	
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

SN= 220

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6285Y**
Vehicle Reg. Date: **20/5/2016**
Make / Model : **H. VEZEL 1.5X CVT**
Engine No. : **L15B4033942**
Chassis No. : **RU11113937**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 2,000.00	500
	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,		
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,		
2	To putty, respray painting and polish accident area. Rear Portion.	\$ 1,800.00	500
	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,		
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,		
3	To remove and transfer tailgate components.	\$ 150.00	60
4	To remove and refit tailgate windscreen.	\$ 150.00	120
5	To remove and refit reverse sensor.	\$ 120.00	30
6	To rust proof affected areas.	\$ 250.00	30
7	To check and rectify wiring after disconnect and connect.	\$ 100.00	30
8	To remove and refit interior parts to give way the repair.	\$ 150.00	50
9	To remove and aligned exhaust pipe.	\$ 150.00	x
10	To resetting for "ELDC MODULE".	\$ 350.00	100

L = 1420

Veron Chen (LKKAuto)

From: ezelvermogenace@gmail.com
Sent: Tuesday, 30 January 2018 9:25 AM
To: Veron Chen (LKKAuto)
Cc: SUR; 'Eric Glorioso'; 'juan paulo baldoz'
Subject: RE: SLC6285Y DOA: 15/12/2017 TO FINALISE (CHINA TAIPING TP)

Dear Veron,

Confirmed COR L/S \$3350/- (4 days)

Thanks & Regards,
Ezel Tejano

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, January 29, 2018 5:45 PM
To: ezelvermogenace@gmail.com
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLC6285Y DOA: 15/12/2017 TO FINALISE (CHINA TAIPING TP)

Dear Ezel,

Kindly confirmed Lump Sum \$3350/- (Sundries should be \$20)

No of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ezelvermogenace@gmail.com [mailto:ezelvermogenace@gmail.com]
Sent: Monday, 29 January 2018 5:20 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SLC6285Y DOA: 15/12/2017 TO FINALISE (CHINA TAIPING TP)

Hi Veron,

As requested,

Thanks & Regards,
Ezel Tejano

From: juan paulo baldoz [mailto:paulovermogenace@gmail.com]
Sent: Thursday, January 11, 2018 3:56 PM
To: Taufikh (LKK Auto) <taufikh@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>

Cc: Éric Glorioso <ericvermogenace@gmail.com>; ezel tejano <ezelvermogenace@gmail.com>; Minoko <minokovermogenace@gmail.com>; pila.vermogenace <pila.vermogenace@gmail.com>; Edmond Lim jian zhi <edmondvermogenace@gmail.com>; Luis Tan <luis.vermogenace@gmail.com>; Paul <Paul@v-auto.com.sg>
Subject: SLC6285Y DOA: 15/12/2017 TO FINALISE (CHINA TAIPING TP)

Hi Taufikh,

Please check and confirm finalise COR @ \$3,400 bef gst (lump sum) 4 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you.

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2017		21 Dec 2017 11:15 Edit Adj Rpt	S\$4,221.76 Edit Estimates	S\$4,221.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]					
Insured:	KIRALY PTE LTD, Co. Reg. No.: 201412081C								
Main Claimant:	LION CITY RENTALS PTE. LTD., Co. Reg. No.: 201504621K								
Vehicle Reg. No.:	SLC6285Y	Date of Loss:	15/12/2017 11:00 - :59						
Claim Type:	TP / SNM17D07127C02	Policy/Cover Note No.:	DMHCSN1690331600 (Comprehensive) Coverage: 21/12/2016 - 14/02/2018						
Vehicle Reg. No. (Insured):	SJZ2406U	Policy No. (Claimant):	1159890						
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/01/2018]								
Adj Asg. Remarks:	1) REQUESTED SURVEYOR: KENNETH KONG PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC6285Y (SNM17D07127C02)
 [SJZ2406U]
 TP
 LION CITY RENTALS PTE. LTD.
 Dec 15 2017 11:00AM
 [KIRALY PTE LTD]
 Vermogen Ace Pte Ltd (benoi)

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	27/12/17 14:08	General View		Load JPG	☒		
2	27/12/17 14:08	General View		Load JPG	☒		
3	27/12/17 14:08	General View		Load JPG	☒		
4	27/12/17 14:08	General View		Load JPG	☒		
5	27/12/17 14:08	General View		Load JPG	☒		
6	27/12/17 14:08	General View		Load JPG	☒		
7	27/12/17 14:08	General View		Load JPG	☒		
8	27/12/17 14:08	General View		Load JPG	☒		
9	27/12/17 14:08	General View		Load JPG	☒		
10	27/12/17 14:08	General View		Load JPG	☒		
11	27/12/17 14:08	General View		Load JPG	☒		
12	27/12/17 14:08	General View		Load JPG	☒		
13	27/12/17 14:08	General View		Load JPG	☒		
14	27/12/17 14:08	General View		Load JPG	☒		
15	27/12/17 14:08	General View		Load JPG	☒		
16	27/12/17 14:08	General View		Load JPG	☒		
17	27/12/17 14:08	General View		Load JPG	☒		
18	27/12/17 14:08	General View		Load JPG	☒		
19	27/12/17 14:08	General View		Load JPG	☒		
20	27/12/17 14:08	General View		Load JPG	☒		
21	27/12/17 14:08	General View		Load JPG	☒		
22	27/12/17 14:08	General View		Load JPG	☒		
23	27/12/17 14:08	General View		Load JPG	☒		
24	27/12/17 14:08	General View		Load JPG	☒		
25	27/12/17 14:08	General View		Load JPG	☒		
26	27/12/17 14:08	General View		Load JPG	☒		
27	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
28	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
29	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
30	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
31	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
32	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
33	29/01/18 17:33	Reinspection Photo		Load JPG	☒		
Documentation						1 per page	☒

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/12/17 11:16	E-filed GIA report	 Load PDF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print	
1	15/12/17 21:01	Accident Statement	 Load HTM		
2	19/12/17 08:15	Addendum Sheet	 Load JPG		☒
3	19/12/17 08:16	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print	
1	15/12/17 17:57	Accident Photo	 Load JPG		☒
2	15/12/17 17:57	Accident Photo	 Load JPG		☒
3	15/12/17 17:57	Accident Photo	 Load JPG		☒
4	15/12/17 17:57	Accident Photo	 Load JPG		☒
5	15/12/17 17:57	Accident Photo	 Load JPG		☒
6	15/12/17 17:57	Accident Photo	 Load JPG		☒
7	15/12/17 17:57	Accident Photo	 Load JPG		☒
8	15/12/17 17:57	Accident Photo	 Load JPG		☒
9	15/12/17 17:57	Accident Photo	 Load JPG		☒
10	15/12/17 17:57	Driving License	 Load JPG		☒
11	15/12/17 17:57	Identification Card	 Load JPG		☒
Documentation				1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print	
1	15/12/17 17:55	Sketch Plan	 Load JPG		☒
2	15/12/17 17:56	POLICE REPORT	 Load JPG		☒
3	15/12/17 17:56	POLICE REPORT	 Load JPG		☒
4	15/12/17 17:56	POLICE REPORT	 Load JPG		☒
5	15/12/17 17:56	POLICE REPORT	 Load JPG		☒
6	19/12/17 08:15	EMAIL ATTACHED	 Load JPG		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117024203/R1VD3E2

Date: 02/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1690331600

Claimant Vehicle
No : SLC6285YInsured Vehicle
No : SJZ2406U

Date of Loss: 15/12/2017

Nature of Claim: TP

Claim
No: SNM17D07127C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC6285Y**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4033942

Reg. Date: 20/05/2016 (Man. Year: 2016)

Chassis No: RU11113937

Colour: Silver

Odometer: 15280 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Achilles 6 mm	Rear Left Side:	Achilles 6 mm
Front Right Side:	Achilles 6 mm	Rear Right Side:	Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,219.96	2,801.76	13,418.20	82.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	1,420.00	3,800.00	72.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,439.96	4,221.76	17,218.20	80.31
+ GST 7.00/7.00% (S\$)	1,500.80	295.52	1,205.28	80.31
Nett Amount (S\$)	22,940.76	4,517.28	18,423.48	80.31

INSPECTION

Date of Assignment: 21/12/2017

Date Inspected: 22/12/2017 Inspected At:

Vermogen Ace Pte Ltd (benoi) (HQ)
6 Benoi Sector
Singapore 629904

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2018)
Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC6285Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,860.00 FL	*1,860.00 FL
2	1	*TAILGATE OUTER GARNISH	Not Necessary	285.00 FL	*- FL
3	1	*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1	*TAILGATE LOGO	Necessary	52.00 FL	*52.00 FL
5	1	*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
6	2	*TAILGATE LAMP LH/RH	Not Necessary	980.00 FL	*- FL
7	2	*SET TAILGATE LAMP CLIPS	Not Necessary	50.00 FL	*- FL
8	1	*TAILGATE OUTER HANDLE SWITCH	Not Necessary	180.00 FL	*- FL
9	2	*TAILGATE DAMPER LH / RH	Not Necessary	424.00 FL	*- FL
10	1	*TAILGATE WIPER MOTOR	Not Necessary	250.00 FL	*- FL
11	1	*TAILGATE WIPER BLADE	Not Necessary	75.00 FL	*- FL
12	1	*TAILGATE BUZZER	Not Necessary	150.00 FL	*- FL
13	1	*TAILGATE INNER HANDLE	Not Necessary	74.00 FL	*- FL
14	1	*TAILGATE INNER LOCK	Not Necessary	245.00 FL	*- FL
15	1	*TAILGATE LOCK SENSOR	Not Necessary	220.00 FL	*- FL
16	1	*TAILGATE STRIKER	Not Necessary	32.00 FL	*- FL
17	1	*TAILGATE TRIMBOARD	Not Necessary	295.00 FL	*- FL
18	1	*SET TAILGATE TRIMBOARD CLIPS	Not Necessary	45.00 FL	*- FL
19	1	*TAILGATE WEATHERSTRIP	Cut	145.00 FL	*145.00 FL
20	1	*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
21	2	*TAIL LAMP LH / RH	Not Necessary	978.00 FL	*- FL
22	1	*SET TAIL LAMP CLIPS	Not Necessary	36.00 FL	*- FL
23	1	*REAR BUMPER	Deformed	950.00 FL	*950.00 FL
24	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
25	2	*REAR BUMPER RETAINER LH/RH	Not Necessary	144.00 FL	*- FL
26	2	*REAR BUMPER BRACKET LH/RH	Not Necessary	116.00 FL	*- FL
27	2	*REAR BUMPER REFLECTOR LH/RH	Not Necessary	334.00 FL	*- FL
28	2	*REAR BUMPER COVER LH/RH	Not Necessary	420.00 FL	*- FL
29	1	*SET REAR BUMPER COVER CLIPS	Not Necessary	50.00 FL	*- FL
30	2	*REAR BUMPER COVER RETAINER LH/RH	Not Necessary	84.00 FL	*- FL
31	1	*REAR END PANEL OUTER	Repair	585.00 FL	*- FL
32	1	*REAR END PANEL INNER	Not Necessary	396.00 FL	*- FL
33	1	*REAR END PANEL TOP GARNISH	Not Necessary	184.00 FL	*- FL
34	1	*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.00 FL	*- FL
35	1	*SPARE TYRE PANEL	Not Necessary	1,230.00 FL	*- FL
36	1	*SPARE TYRE PANEL INSULATOR	Not Necessary	240.00 FL	*- FL
37	1	*SPARE TYRE PANEL TOP BOARD	Not Necessary	420.00 FL	*- FL
38	1	*SPARE TYRE TOOL TRAY	Not Necessary	430.00 FL	*- FL
39	1	*EDLC MODULE	Not Necessary	1,750.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR FENDER PANEL LH	Not Necessary	1,900.00 FL	*- FL
41	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	480.00 FL	*- FL
42	2		*TAIL LAMP PANEL LH/RH	Not Necessary	550.00 FL	*- FL
43	2		*REAR FENDER ARCH GARNISH LH/RH	Not Necessary	330.00 FL	*- FL
44	2		*SET REAR FENDER ARCH GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
45	2		*REAR FENDER INNER WATER SHIELD LH/RH	Not Necessary	320.00 FL	*- FL
46	2		*SET REAR FENDER INNER WATER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
47	2		*REAR FENDER AIR DUCT LH/RH	Not Necessary	150.00 FL	*- FL
48	1		*EXHAUST MUFFLER	Not Necessary	855.00 FL	*- FL
49	1		*EXHAUST MUFFLER MOUNTING	Not Necessary	79.50 FL	*- FL
50	1		*EXHAUST MUFFLER HEAT SHIELD	Not Necessary	165.00 FL	*- FL
51	2		*REAR PLATE LAMP LH/RH	Not Necessary	250.00 FL	*- FL
52	1		*REAR NUMBER PLATE WTH FRAME	Not Necessary	45.00 FS	*- FS
53	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
54	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*80.00 FS
55	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
57	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*SPARE TYRE PANEL PADDING	Not Necessary	100.00 FS	*- FS
59	1		*SUNDRIES	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,068.70 3,457.20
 - List Item Discount on L Items 20.00/20.00% (\$\$) 3,848.74 655.44

Total Parts (\$\$) 16,219.96 2,801.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR PORTION. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH	New	2,000.00	500.00
2	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. REAR PORTION. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH	New	1,800.00	500.00
3	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
4	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	30.00
6	TO RUST PROOF AFFECTED AREAS	New	250.00	30.00
7	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
8	TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY THE REPAIR	New	150.00	50.00
9	TO REMOVE AND ALIGNED EXHAUST PIPE	New	150.00	0.00
10	TO RESETTING FOR EDLC MODULE	New	350.00	100.00
Gross Labour Cost (\$\$)			5,220.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >