

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1485 L

1 pc	Emblem I30	\$	27.80 <i>all</i>
1 pc	Emblem CRDI	\$	29.40 <i>all</i>
1 pc	Emblem Hyundai	\$	29.40 <i>all</i>
1 pc	Rear bumper	\$	811.11 <i>DE</i>
1 pc	Rear bumper sponge	\$	79.20 <i>?</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>?</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 <i>?</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>?</i>
1 pc	Tailgate	\$	2,292.30 <i>R</i>
1 pc	Tailgate lower garnish	\$	362.61 <i>CRA</i>
		\$	4,631.06
		\$	926.21 <i>Less 20%</i>
		\$	3,704.85
<b>S/NETT</b>			
1 set	Rear bumper clips	\$	48.00 ✓
1 set	Reverse sensor	\$	<del>280.00</del> 220 <i>?</i>
1 set	Tailgate sticker	\$	100.00 <i>na</i>
	Sundry	\$	50.00 <i>?</i>
	To dismantle and replace reverse sensor and test system	\$	<del>80.00</del> 60
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same	\$	<del>650.00</del> 450
	To putty and spray painting on the rear bumper, tailgate lower garnish	\$	400.00 ✓
	To apply rustproofing on the repaired and replaced panels	\$	<del>120.00</del> 20
<b>Total</b>		\$	5,432.85

Rasul  
Hp 90000068

5 days

P/P

20/12/17 @ 1115

Resurvey by paint

( ALL THE REPAIR COSTS ARE SUBJECT TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: