

Mainmen

Rasul

ASSIGNMENT (Office)

From (Name)

Gerald Poh

LPC

21/12/17 @ 8:25am

Estimated Cost

RM 10

01 / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

S/N 4651C

Insured

at Workshop in

Woon Meng Motor

Tel 6316 1131

of

50 Bukit Batok Street 23 #01-06

Policy No.

Z17VP05013207

Claim No.

17/17/17/VP05/020273

Sum Insured

Excess

Make of Vehi

(Client's Record)

D.O.A. 12/12/2017

CA / (REV)

/ REP. / REV 24 HRS

R.O.D. Endorsement

Date/Time 10:51am @

Person Connected

Mrs. Heng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

S/N 4651C - CC4/LPC17023759/Uua3

D.O.A. 12/12/17

22/12

revert via mainmen

22/12 @

12:50pm inform by Chew Beng Kee authorise repair

22/12 @

2:45pm inform me Heng authorise repair excess \$0.

Surveyor Farm


REF: CS/LPC17024216/R1/d3

5690 F

COE XPIRY: 2019/06/05

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
(OD) TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJN 4651C
at Workshop m/s Woon men
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: 38K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / (REV) / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJN 4651C Yr Regn: 2009 JCB
Type: (C) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: MERCEDES BENZ C200 Komp c/o 1796
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 112817 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2640412A226017
Gen. Cond: Good / (F) Fair / Poor / Burnt
Steering: (I) In order / Jammed / Leaked / Burnt or
Brake: (I) In order / Jammed / Leaked / Burnt or
Modi: Nil / (S) Rim / STD A/Rim or
Tyre Size: F: 225/45ZR17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / (M) MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 12/12/17 D.O.I. 21/12/17
Survey held at Woon men
Des. of Damages (F) Fr / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Part by Part \$8570.05 + (Red: 2546.10 '22%)

RECEIVED: 3 JAN 2018

Date/Time. File Pass to? ☐ Preli. Report
26/14 Typist ☒ Final Report
Date/Time. File Return to? _____

Days Of Repair: 8
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$ _____) ☐ 3-RS (\$ _____)
☐ Interview (\$ _____) ☐ Photos
☐ Tech. Insp (\$ _____) ☐ Others
☐ Weekend (\$ _____)

Report Format: 00
Lump Sum / I.S. 8570.05

Survey Fee:	170+15=185
Transportation	185 x 20% = 37
	185+37
	50
	50
	107
TOTAL	429+10
	439

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017 Sendback Est	20 Dec 2017 18:09 S\$11,116.15	21 Dec 2017 08:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	DAVID HO POH WAH, ID: S1545690F, Tel: +6596494859, Email: saabiho@singnet.com.sg		
Vehicle Reg. No.:	SJN4651C	Date of Loss:	12/12/2017 16:00 - :59
Claim Type:	OD / 17/17/17/VP05/020273	Policy/Cover Note No.:	Z17VP05013207 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2018]		
Driver/Custodian:	DAVID HO POH WAH (55 / Male), NRIC: S1545690F, Tel: +6596494859		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	5690F

Vehicle Details

Vehicle No.:	SJN4651C
Vehicle to be Exported:	No
Intended De-registration Date:	22 Dec 2017
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200 KOMPRESSOR
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	27195031131024
Chassis No.:	WDD2040412A220017
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$43,115.00
Original Registration Date:	17 Feb 2009
First Registration Date:	17 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$43,115.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Feb 2019
PARF Rebate Amount:	\$23,713.00

Intended COE Rebate Details

COE Expiry Date:	16 Feb 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$3,200.00
COE Rebate Amount:	\$23.00
Total Rebate Amount:	\$23,736.00

The information contained herein is correct as at 22 Dec 2017

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC17024216/R1td3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-12-2017		
		Code : LPC2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SJN 4651C	
Policy No.	Z17VP05013207	Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020273	Excess (\$)	0.00	
Assign From	MERIMEN (GERALD POH)	Assign Date	21/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/12/2017	Inspection Date	21/12/2017	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

View Received Message

This mail is associated with :

SJN4651C (17/17/17/VP05/020273)

OD

Dec 12 2017 4:00PM

[DAVID HO POH WAH]

Woon Meng Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 22/12/2017 12:56 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$7509.65) - SJN4651C - Claim Handler: Gerald Poh

Approved:7509.65.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2017 19:26
Date Of Accident	12/12/2017 16:40
Exact Location Of Accident	TPE TOWARDS BEDOK TOWN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN4651C
Insured/Policyholder	
Name Of Registered Owner	DAVID HO POH WAH
NRIC No	S1545690F
Email Address	SAABIHO@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96494859
Alternative Phone No	OFFICE-96494859

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200 KOMPRESSOR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05013207
Cover Note Number	

Driver

Name of Driver	DAVID HO POH WAH
NRIC No	S1545690F
Date Of Birth	03/08/1962
Occupation	INDOOR
Date Of Driving Pass	20/08/1980
Driving Experience	37 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96494859
Fax Number	
Contact Number	OFFICE-96494859
Email Address	SAABIHO@SINGNET.COM.SG

Address	BLK 17 # 14- 14 ANCHORVALE CRESCENT BELLEWATERS
Postcode	544652
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT TO POLICE REPORT NO : T/20171213/2100.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW5096P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	WANG KANG RONG
NRIC/Passport Number	S9309720C
Contact Number	94233343
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

13/12/17

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13/12/17

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

☒ Claim Own Damage ☐ Claim TP ☐ Reporting Only ☐ Claim OD/TP at other workshop

Workshop name

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment to Police report No.
T/2017/213/2100.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Damir

Policyholder's Signature
Date & Time:

13/12/17

Damir

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/12/17

[Signature]
Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: Lonpac Insurance Bhd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05013207	Date of Loss:	12/12/2017
Vehicle Reg. No.:	SJN4651C	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	DAVID HO POH WAH	Contact No:	+6596494859
Driver:	DAVID HO POH WAH		

Make/Model:	MERCEDES-BENZ 200, 2.0 (A)	Vehicle Reg. Date:	17/02/2009
Vehicle Colour:	BEIGE		
Engine No:	27195031131024	Chassis No:	WDD20404412A220017
Odometer:	112817 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	18

Description of Accident/Loss	REFER TO ATTACHMENT TO POLICE REPORT NO : T/20171213/2100.
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	7,476.15
Miscellaneous Items	670.00
Labour	1,570.00
Paintwork Labour	1,400.00
Towing	0.00
Gross Total (S\$)	11,116.15
+ GST 7.00% (S\$)	778.13
Nett Amount (S\$)	11,894.28

This claim is handled by: WOON MENG MOTOR PTE LTDGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

Estimates on Miscellaneous Items

No.	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	35.00
2	1	FRONT BUMPER SENSOR	600.00
3	1	FRONT NUMBER PLATE	35.00
Sub Total (S\$)			670.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING.	New	1,400.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, REPAIR & INSTALL DAMAGED PARTS.	New	1,200.00
3	TO R & R FRONT RADIATOR.	New	120.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	150.00
5	TO R & R WIRING/ SENSOR.	New	100.00
Gross Labour Cost (S\$)			2,970.00

Woon Meng Motor Pte Ltd/SJN4651C/20/12/2017 18:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 90010068

8 days

L/S

21/12/17 @ 1510

EXCESS : 0

Revers

Resurvey after repair

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: Lonpac Insurance Bhd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05013207	Date of Loss:	12/12/2017
Vehicle Reg. No.:	SJN4651C	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	DAVID HO POH WAH	Contact No:	+6596494859
Driver:	DAVID HO POH WAH		
Make/Model:	MERCEDES-BENZ 200, 2.0 (A)	Vehicle Reg. Date:	17/02/2009
Vehicle Colour:	BEIGE		
Engine No:	27195031131024	Chassis No:	WDD20404112A220017
Odometer:	112817 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Description of Accident/Loss	REFER TO ATTACHMENT TO POLICE REPORT NO : T/20171213/2100.		
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)		

COST OF CLAIMS

	Amount
Parts	7,476.15
Miscellaneous Items	670.00
Labour	1,570.00
Paintwork Labour	1,400.00
Towing	0.00
Gross Total (S\$)	11,116.15
+ GST 7.00% (S\$)	778.13
Nett Amount (S\$)	11,894.28

This claim is handled by: WOON MENG MOTOR PTE LTD

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Parts - 4887.00
 15% - 733.05
 5620.05
 Miscellaneous - 690.00
 Spray/labour - 2260.00
 8570.05

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Dec 2017)
 Parts: 143 MERCEDES-BENZ 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Woon Meng Motor Pte Ltd/SJN4651C/20/12/2017 18:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Rasul to repairer for 1.0
27/12/17

64 paint here taken photo
0.00 27/12/17

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	✓	*FRONT BUMPER	580	0.00	0.00 580.00 <i>580</i>
2	2		*FRONT BUMPER RETAINER	30	0.00	0.00 30.00 <i>30</i>
3	1	✓	*FRONT BUMPER REINFORCEMENT	155	0.00	0.00 155.00 <i>155</i>
4	1	✓	*FRONT BUMPER SPONGE	90 photo	0.00 90	0.00 90.00 <i>90</i>
5	1		*TOWING COVER	25	0.00	0.00 25.00 <i>25</i>
6	2	✓	*FRONT BUMPER SIDE MOULDING	96	0.00	0.00 96.00 <i>96</i>
7	1		*FRONT BUMPER LOWER CENTER GRILLE	0.00	0.00	0.00 50.00 <i>50</i>
8	1	✓	*FRONT NUMBER PLATE GARNISH	75	0.00	0.00 75.00 <i>75</i>
9	1		*FRONT RADIATOR	0.00	0.00	0.00 435.00 <i>435</i>
10	2	✓	*FRONT RAD SIDE GARNISH	48	0.00	0.00 48.00 <i>48</i>
11	1	✓	*FRONT CENTER GRILLE	375	0.00	0.00 375.00 <i>375</i>
12	2	✓	*FRONT HEADLAMP	1070	0.00	0.00 1,070.00 <i>1,070</i>
13	2	✓	*FRONT SUPPORT TOP PANEL	50	0.00	0.00 50.00 <i>50</i>
14	1	✓	*FRONT SUPPORT CENTER PANEL	90	0.00	0.00 90.00 <i>90</i>
15	1	✓	*AIR DUCT	0.00	0.00	0.00 70.00 <i>70</i>
16	1	✓	*AIR DUCT HOSE	60	0.00	0.00 60.00 <i>60</i>
17	1		*AIR CON CONDENSOR	0.00	0.00	0.00 620.00 <i>620</i>
18	1		*FAN MOTOR	0.00	0.00	0.00 550.00 <i>550</i>
19	1	✓	*FRONT BONNET	880	0.00	0.00 880.00 <i>880</i>
20	2		*FRONT BONNET SIDE LOCK	0.00	0.00	0.00 420.00 <i>420</i>
21	1	✓	*FRONT BONNET CENTER LOCK	50	0.00	0.00 50.00 <i>50</i>
22	2	✓	*FRONT FENDER	430	0.00	0.00 860.00 <i>860</i>
23	1		*FRONT BONNET EMBLEM	50	0.00	0.00 50.00 <i>50</i>

F=Franchise part.

Sub Total (\$\$) *4154* 6,501.00
 + Margin on L,N Items 15.00% (\$\$) 975.15

Total Parts (\$\$) 7,476.15

Woon Meng Motor Pte Ltd/SJN4651C/20/12/2017 18:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2017)**Parts:** 143 MERCEDES-BENZ 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Woon Meng Motor Pte Ltd/SJN4651C/26/12/2017 14:10**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CENTER GRILLE LOCK	0.00	12	0.00 <i>BAV</i> 12.00 F <i>12</i>
2	2		*FRONT BONNET SPRING	0.00	24	0.00 <i>MIS</i> 24.00 F <i>120</i>
3	2		*FRONT BUMPER BRACKET	0.00	50	0.00 <i>100</i> 50.00 F <i>100</i>
4	1		*FRONT BUMPER BRACKET O/S	0.00	14	0.00 <i>0.00</i> 14.00 F <i>14</i>
5	1		*FRONT BONNET LOCK CABLE	0.00	40	0.00 <i>Cut</i> 40.00 F <i>400</i>
6	1		*FRONT SUPPORT TOP GARNISH	0.00	65	0.00 <i>CPA</i> 65.00 F <i>65</i>
7	1		*FRONT HEADLAMP TOP GARNISH O/S	0.00	18	0.00 <i>CPA</i> 18.00 F <i>18</i>
8	1		*EMBLEM CLIPS	0.00	10	0.00 <i>20</i> 10.00 F <i>10</i>
9	2		*FRONT HEADLAMP PANEL	0.00	220	0.00 <i>220</i> 220.00 F <i>1100</i>
10	2		*FRONT BUMPER REINFORCEMENT BRACKET	0.00	280	0.00 <i>74</i> 280.00 F <i>1400</i>

F=Franchise part.

Sub Total (S\$) *733* 733.00 ✓
+ Margin on L,N Items 15.00% (S\$) 109.95

Total Parts (S\$) 842.95

Woon Meng Motor Pte Ltd/SJN4651C/26/12/2017 14:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 COOLANT	35.00
2	2 FRONT BUMPER SENSOR	600.00
3	1 FRONT NUMBER PLATE	35.00
Sub Total (S\$)		670.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING.	New	1,400.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, REPAIR & INSTALL DAMAGED PARTS.	New	1,200.00
3	TO R & R FRONT RADIATOR.	New	120.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	150.00
5	TO R & R WIRING/ SENSOR.	New	100.00
Gross Labour Cost (S\$)			2,970.00

Woon Meng Motor Pte Ltd/SJN4651C/20/12/2017 18:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 90010068
8 days
4/5 P/P
21/12/17 @ 1510

EXCESS : 0

Revers

Resony after repair
by paint




PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)

TEL NO : 64523938 (6 LINES) FAX NO : 64527936

A/C DEPT : 64590882

Business Reg & GST NO : 201512120M



D154331

TAX INVOICE

REPRINT

CASH DN

SN4651C

REMARK : WDD 2040412A220017

DELIVER TO :

WOON MENG MOTOR PTE LTD

50 BUKIT BATOR STREET 23

#01 -- 06 MIDVIEW BUILDING

SINGAPORE 653578

INV NO : I154331

DATE : 26/12/2017

A/C NO : 200005

TERM : C.O.D

PAGE : 1 OF 1

ISSUE : HONG

Printed on 26/12/2017 02:08:27

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	000 991 2595MB	RAD CLIP	SS2A25	1	PCS	10.00	10.00 ✓
2	204 500 0155MB	RAD TOP COVERING	3W3A02	1	PCS	65.00	65.00 ✓
3	204 505 0530MB	RAD AIR BAFFLE	3W3J05	1	PCS	48.00	48.00 ✓
4	204 620 0272MB	STIFFENING	3W3A05	1	PC	90.00	90.00 ✓
5	204 620 0991MB	HEAD LAMP PANEL LH	3W3A12	1	PC	110.00	110.00 ✓
6	204 620 0995MB	FRT BUMPER MEMBER RH	3W3A08	1	PC	140.00	140.00 ✓
7	204 620 1091MB	HEAD LAMP PANEL RH	3W3C11	1	PC	110.00	110.00 ✓
8	204 620 1195MB	FRT BUMPER MEMBER LH	3W3A08	1	PC	140.00	140.00 ✓
9	204 826 1424MB	COVERING RH,H/L TOP	SS2D30	1	PC	18.00	18.00 ✓
10	204 880 0059MB	BONNET CABLE	SS2C00	1	PC	40.00	40.00 ✓
11	204 880 0227MB	BONNET SPRING	SS2C18	2	PCS	12.00	24.00 ✓
12	204 885 0116MB	STIFFENING LH	SS2C10	1	PC	25.00	25.00 ✓
13	204 885 0136MB	GRILL STAY	SS2C04	1	PC	12.00	12.00 ✓
14	204 885 0216MB	STIFFENING RH	SS2C10	1	PC	25.00	25.00 ✓
15	218 880 0430MB	BRACKET	SS2C20	1	PC	14.00	14.00 ✓

RECEIVED BY

PICKED BY: JOHNSON 8514

SUB-TOTAL : S\$ 871.00

ADD 7% GST : S\$ 60.97

TOTAL : S\$ 931.97

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D154205

REPRINT

CASH DN

REMARK : WDD 2040412A087950

TAX INVOICE

DELIVER TO :
WOON MENG MOTOR PTE LTD
50 BUKIT BATOR STREET 23
#01 -- 06 MIDVIEW BUILDING
SINGAPORE 659578

INV NO : I154205
DATE : 23/12/2017
A/C NO : 200005
TERM : C.O.D
PAGE : 1 OF 1
ISSUE : HONG

Printed on 23/12/2017 12:42:41

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 817 0616MB	BONNET STAR	SS2D05	1	PC	50.00	50.00 X
2	204 880 0023 9744	GRILL SPORT 9744	3W2D07	1	PCS	375.00	375.00 X
3	204 880 0064MB	BONNET SAFETY LOCK	SS2C15	1	PCS	50.00	50.00 X
4	204 880 0164MB	RETAINING HOOK	SS2C15	1	PCS	50.00	50.00 X
5	204 906 5303MB	HEADLAMP LH	3W2A12	1	PCS	535.00	535.00 X
6	204 906 5403MB	HEADLAMP RH	3W2A12	1	PCS	535.00	535.00 X
7	271 090 0582MB	AIR CLEANER HOSE	SS1B33	1	PCS	60.00	60.00 X

SIN 46451C

RECEIVED BY

PICKED BY: JOHNSON 8514

SUB-TOTAL : S\$ 1,655.00

ADD 7% GST : S\$ 115.85

TOTAL : S\$ 1,770.85

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D154361

REPRINT

CASH DN

REMARK : WDD 2040412A220017

GW4651C

DELIVER TO :
WOON MENG MOTOR PTE LTD
50 BUKIT BATOR STREET 23
#01 -- 06 MIDVIEW BUILDING
SINGAPORE 653578

TAX INVOICE

INV NO : I154361
DATE : 26/12/2017
A/C NO : 200005
TERM : C.O.D
PAGE : 1 OF 1
ISSUE : HONG

Printed on 26/12/2017 2:50:27

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 880 1057MB	BONNET	3W1C16	1	PCS	880.00	880.00✓
2	204 880 1418MB	FRT FENDER RH	3W2J10	1	PCS	430.00	430.00✓

RECEIVED BY

PICKED BY: ALAN 2956

SUB-TOTAL : S\$ 1,310.00

ADD 7% GST : S\$ 91.70

TOTAL : S\$ 1,401.70

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D154547

REPRINT

CASH DN

REMARK : WDD 2040412A220017

TAX INVOICE

DELIVER TO :
WOON MENG MOTOR PTE LTD
50 BUKIT BATOR STREET 23
#01 -- 06 MIDVIEW BUILDING
SINGAPORE 659578

INV NO : 1154547
DATE : 27/12/2017
A/C NO : 200005
TERM : C.O.D
PAGE : 1 OF 1
ISSUE : HONG

Printed on 27/12/2017 12:57:02

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 885 0037MB	FRT BUMPER SPONG	3W3F03	1	PCS	90.00	90.00
2	221 542 0417MB	BUMPER SENSOR	SS2H03	4	PC	155.00	620.00

RECEIVED BY

PICKED BY: JOHNSON 8514

SUB-TOTAL : S\$ 710.00
ADD 7% GST : S\$ 49.70
TOTAL : S\$ 759.70

Goods sold are not returnable except Repairs/Service at authorized workshop.



GOLDENLINK AUTO PTE LTD

TAX INVOICE



Invoice To

WOON MENG MOTOR PTE LTD CASH
50 BUKIT BATOK STREET 23
#01-06 MIDVIEW BUILDING
WDD2040412A220017
CASH SALES

INVOICE NO: WC070934

DATE: 27-12-2017 19:09

PAGE: 1 / 1

SALESMAN: CWS

TERMS: CASH

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE (SGD)	AMOUNT (SGD)
1	204 881 0106	BUMPER RAIL FRT LH	1	15.00	15.00✓
2	204 880 0940	BUMPER FRT	1	580.00	580.00✓
3	204 881 0206	BUMPER RAIL FRT RH	1	15.00	15.00✓
4	207 620 1600	BUMPER CROSSMEMBER FRT	1	155.00	155.00✓
5	204 885 0124 9999	TOWING COVER	1	25.00	25.00✓
6	204 885 0721	BUMPER MLD FRT LH	1	48.00	48.00✓
7	204 885 0821	BUMPER MLD FRT RH	1	48.00	48.00✓
8	204 817 0378	LICENCE PLATE GARNISH	1	75.00	75.00✓

GOLDENLINK AUTO PTE LTD

Products received and checked to be
in good condition

SUB-TOTAL 961.00

ADD G.S.T 7% 67.27

TOTAL (SGD) 1,028.27

Authorised Signature

Customer's Signature / Company Stamp

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

Cheques to be made payable to GOLDENLINK AUTO PTE LTD.

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited.
Request for the return of any unused product (in original and good condition) may be considered on a case by case basis
and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged
within 14 days of delivery of your order.



bigSAFE₃

Goldenlink Auto Pte Ltd

Head Office: 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4700 / 6336 2030 (5.00p Chain) Fax: 6339 5618

www.goldenlink.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017 Sendback Est	20 Dec 2017 18:09 \$11,116.15	21 Dec 2017 08:25 Edit Adj Rpt	\$8,570.05 Edit Estimates	\$8,570.05 View Rpt		Pending for Survey Report Cancel Case
Supp #1	26 Dec 2017 13:35	26 Dec 2017 14:10 \$842.95	26 Dec 2017 14:10			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	DAVID HO POH WAH, ID: S1545690F, Tel: +6596494859, Email: saabiho@singnet.com.sg		
Vehicle Reg. No.:	SJN4651C	Date of Loss:	12/12/2017 16:00 - :59 [105 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/17/17/VP05/020273	Policy/Cover Note No.:	Z17VP05013207 (Comprehensive)
		Excess:	\$0.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/01/2018]		
Driver/Custodian:	DAVID HO POH WAH (55 / Male), NRIC: S1545690F, Tel: +6596494859		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (26/04/2018): Alert - Adj Mandate Approved (\$8570.05) - SJN4651C - Claim Handler: Gerald Poh
- LONPAC_HQ (22/12/2017): Alert - Adj Mandate Approved (\$7509.65) - SJN4651C - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN4651C (17/17/17/VP05/020273)

OD

Dec 12 2017 4:00PM

[DAVID HO POH WAH]

Woon Meng Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ☐	
Assessment Reports			1 per page ☐	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail Print
1	20/12/17 18:09	Repairer Estimates		Load HTM
2	26/12/17 14:10	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/12/17 10:50	Adjuster Immediate Advice		Load HTM
2	25/04/18 13:33	Adjuster Immediate Advice		Load HTM
Photos/Images				
			3 per page ☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/04/18 13:17	General View		Load JPG ☒
2	25/04/18 13:17	General View		Load JPG ☒
3	25/04/18 13:17	General View		Load JPG ☒
4	25/04/18 13:17	General View		Load JPG ☒
5	25/04/18 13:17	General View		Load JPG ☒
6	25/04/18 13:17	General View		Load JPG ☒
7	25/04/18 13:17	General View		Load JPG ☒
8	25/04/18 13:17	General View		Load JPG ☒
9	25/04/18 13:17	General View		Load JPG ☒
10	25/04/18 13:17	General View		Load JPG ☒
11	25/04/18 13:17	General View		Load JPG ☒
12	25/04/18 13:17	General View		Load JPG ☒
13	25/04/18 13:17	General View		Load JPG ☒
14	25/04/18 13:17	General View		Load JPG ☒
15	25/04/18 13:17	General View		Load JPG ☒
16	25/04/18 13:17	General View		Load JPG ☒
17	25/04/18 13:17	General View		Load JPG ☒
18	25/04/18 13:17	General View		Load JPG ☒
19	25/04/18 13:17	General View		Load JPG ☒
20	25/04/18 13:17	General View		Load JPG ☒
21	25/04/18 13:17	General View		Load JPG ☒
22	25/04/18 13:17	General View		Load JPG ☒
23	25/04/18 13:17	General View		Load JPG ☒
24	25/04/18 13:17	General View		Load JPG ☒
25	25/04/18 13:17	General View		Load JPG ☒
26	25/04/18 13:17	General View		Load JPG ☒
27	25/04/18 13:17	General View		Load JPG ☒
28	25/04/18 13:17	General View		Load JPG ☒
29	25/04/18 13:17	General View		Load JPG ☒
30	25/04/18 13:17	General View		Load JPG ☒
31	25/04/18 13:17	General View		Load JPG ☒
32	25/04/18 13:17	General View		Load JPG ☒

Assessment Reports			1 per page	☒	
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail	Print
33	25/04/18 13:17	General View		Load JPG	☒
34	25/04/18 13:17	General View		Load JPG	☒
35	25/04/18 13:17	General View		Load JPG	☒
36	25/04/18 13:17	General View		Load JPG	☒
37	25/04/18 13:17	General View		Load JPG	☒
38	25/04/18 13:17	General View		Load JPG	☒
39	25/04/18 13:17	General View		Load JPG	☒
40	25/04/18 13:17	General View		Load JPG	☒
41	25/04/18 13:17	General View		Load JPG	☒
42	25/04/18 13:17	General View		Load JPG	☒
43	25/04/18 13:17	General View		Load JPG	☒
44	25/04/18 13:17	General View		Load JPG	☒
45	25/04/18 13:17	General View		Load JPG	☒
46	25/04/18 13:17	General View		Load JPG	☒
47	25/04/18 13:17	General View		Load JPG	☒
48	25/04/18 13:17	General View		Load JPG	☒
49	25/04/18 13:17	General View		Load JPG	☒
50	25/04/18 13:17	General View		Load JPG	☒
51	25/04/18 13:17	General View		Load JPG	☒
52	25/04/18 13:17	General View		Load JPG	☒
53	25/04/18 13:17	General View		Load JPG	☒
54	25/04/18 13:17	General View		Load JPG	☒
55	25/04/18 13:17	General View		Load JPG	☒
56	25/04/18 13:17	General View		Load JPG	☒
57	25/04/18 13:17	General View		Load JPG	☒
58	25/04/18 13:17	General View		Load JPG	☒
59	25/04/18 13:17	General View		Load JPG	☒
60	25/04/18 13:17	General View		Load JPG	☒
61	25/04/18 13:17	General View		Load JPG	☒
62	25/04/18 13:17	General View		Load JPG	☒
63	25/04/18 13:17	General View		Load JPG	☒
64	25/04/18 13:19	Reinspection Photo		Load JPG	☒
65	25/04/18 13:19	Reinspection Photo		Load JPG	☒
66	25/04/18 13:19	Reinspection Photo		Load JPG	☒
67	25/04/18 13:19	Reinspection Photo		Load JPG	☒
68	25/04/18 13:19	Reinspection Photo		Load JPG	☒
69	25/04/18 13:19	Reinspection Photo		Load JPG	☒
70	25/04/18 13:19	Reinspection Photo		Load JPG	☒
71	25/04/18 13:19	Reinspection Photo		Load JPG	☒
72	25/04/18 13:19	Reinspection Photo		Load JPG	☒
73	25/04/18 13:19	Reinspection Photo		Load JPG	☒
74	25/04/18 13:19	Reinspection Photo		Load JPG	☒
75	25/04/18 13:19	Reinspection Photo		Load JPG	☒
76	25/04/18 13:19	Reinspection Photo		Load JPG	☒
77	25/04/18 13:19	Reinspection Photo		Load JPG	☒
78	25/04/18 13:19	Reinspection Photo		Load JPG	☒
79	25/04/18 13:19	Reinspection Photo		Load JPG	☒
80	25/04/18 13:19	Reinspection Photo		Load JPG	☒
81	25/04/18 13:19	Reinspection Photo		Load JPG	☒
82	25/04/18 13:19	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
83	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
84	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
85	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
86	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
87	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
88	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
89	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
90	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
91	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
92	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
93	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
94	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
95	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
96	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
97	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
98	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
99	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
100	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
101	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
102	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
103	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
104	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
105	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
106	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
107	25/04/18 13:19	Reinspection Photo	 Load JPG	☒
108	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
109	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
110	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
111	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
112	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
113	25/04/18 13:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/12/17 10:51	ESTIMATE	 Load PDF	
2	25/04/18 13:16	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	13/12/17 20:15	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	13/12/17 19:59	Accident Photo	 Load JPG	☒
2	13/12/17 19:59	Accident Photo	 Load JPG	☒
3	13/12/17 19:59	Accident Photo	 Load JPG	☒
4	13/12/17 19:59	Accident Photo	 Load JPG	☒
5	13/12/17 19:59	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
6	13/12/17 19:59	Accident Photo	 Load JPG	☒
7	13/12/17 19:59	Accident Photo	 Load JPG	☒
8	13/12/17 19:59	Accident Photo	 Load JPG	☒
9	13/12/17 20:14	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	13/12/17 20:00	POLICE REPORT	 Load TIF	
2	13/12/17 20:00	POLICE REPORT	 Load TIF	
3	13/12/17 20:00	Driver's Driving License/NRIC	 Load TIF	
4	13/12/17 20:12	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lompac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC17024216/R1TD3E2

Date: 30/04/2018

REFERENCE

Insured/Claimant: DAVID HO POH WAH Policy No: Z17VP05013207
Date of Loss: 12/12/2017 Nature of Claim: OD Claim No: 17/17/17/VP05/020273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN4651C**
Make & Model: MERCEDES-BENZ 200, 2.0 (A) Engine No: 27195031131024
Reg. Date: 17/02/2009 (Man. Year: 2008) Chassis No: WDD2040412A220017
Colour: Grey Odometer: 112817 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$38,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,319.10	5,620.05	2,699.05	32.44
Miscellaneous Items	670.00	690.00	-20.00	-2.99
Labour	1,570.00	1,260.00	310.00	19.75
Paintwork Labour	1,400.00	1,000.00	400.00	28.57
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,959.10	8,570.05	3,389.05	28.34
+ GST 7.00/7.00% (S\$)	837.14	599.90	237.24	28.34
Nett Amount (S\$)	12,796.24	9,169.95	3,626.29	28.34

INSPECTION

Date of Assignment: 21/12/2017 Present Location: Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected: 21/12/2017 Inspected At: 50 Bukit Batok Street 23,, #01-06 Midview Building
Singapore 659578

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Apr 2018)
Parts: 143 MERCEDES-BENZ 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN4651C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	580.00 F	*580.00 F
2	2		*FRONT BUMPER RETAINER (WCP)	Necessary	30.00 F	*30.00 F
3	1		*FRONT BUMPER REFORCEMENT (WCP)	Bent	155.00 F	*155.00 F
4	1		*FRONT BUMPER SPONGE (WCP)	Cracked	90.00 F	*90.00 F
5	1		*TOWING COVER (WCP)	Cut	25.00 F	*25.00 F
6	2		*FRONT BUMPER SIDE MOULDING (WCP)	Necessary	96.00 F	*96.00 F
7	1		*FRONT BUMPER LOWER CENTER GRILLE (WCP)	Serviceable	50.00 F	*- F
8	1		*FRONT NUMBER PLATE GARNISH (WCP)	Cracked	75.00 F	*75.00 F
9	1		*FRONT RADIATOR (WCP)	Serviceable	435.00 F	*- F
10	2		*FRONT RAD SIDE GARNISH (WCP)	Cracked	70.00 F	*48.00 F
11	1		*FRONT CENTER GRILLE (WCP)	Cracked	375.00 F	*375.00 F
12	2		*FRONT HEADLAMP (WCP)	Cracked	1,070.00 F	*1,070.00 F
13	2		*FRONT SUPPORT TOP PANEL (WCP)	Cracked	100.00 F	*50.00 F
14	1		*FRONT SUPPORT CENTER PANEL (WCP)	Bent	90.00 F	*90.00 F
15	1		*AIR DUCT (WCP)	Serviceable	70.00 F	*- F
16	1		*AIR DUCT HOSE (WCP)	Cut	60.00 F	*60.00 F
17	1		*AIR CON CONDENSOR (WCP)	Serviceable	620.00 F	*- F
18	1		*FAN MOTOR (WCP)	Serviceable	550.00 F	*- F
19	1		*FRONT BONNET (WCP)	Bent	880.00 F	*880.00 F
20	2		*FRONT BONNET SIDE LOCK (WCP)	Serviceable	120.00 F	*- F
21	1		*FRONT BONNET CENTER LOCK (WCP)	Cracked	50.00 F	*50.00 F
22	1		*FRONT FENDER (2PCS)(WCP)	Bent-1pc only	860.00 F	*430.00 F
23	1		*FRONT BONNET EMBLEM (WCP)	Necessary	50.00 F	*50.00 F

Supplementary #1

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*CENTER GRILLE LOCK (WCP)	Broken	12.00 F	*12.00 F
25	2		*FRONT BONNET SPRING (WCP)	Missing	24.00 F	*24.00 F
26	2		*FRONT BUMPER BRACKET (WCP)	Necessary	50.00 F	*50.00 F
27	1		*FRONT BUMPER BRACKET O/S (WCP)	Necessary	14.00 F	*14.00 F
28	1		*FRONT BONNET LOCK CABLE (WCP)	Cut	40.00 F	*40.00 F
29	1		*FRONT SUPPORT TOP GARNISH (WCP)	Cracked	65.00 F	*65.00 F
30	1		*FRONT HEADLAMP TOP GARNISH O/S (WCP)	Cracked	18.00 F	*18.00 F
31	1		*EMBLEM CLIPS (WCP)	Necessary	10.00 F	*10.00 F
32	2		*FRONT HEADLAMP PANEL (WCP)	Bent	220.00 F	*220.00 F
33	2		*FRONT BUMPER REFORCEMENT BRACKET (WCP)	Bent	280.00 F	*280.00 F

F=Franchise part.

Sub Total (\$\$)	7,234.00	4,887.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,085.10	733.05
Total Parts (\$\$)	8,319.10	5,620.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	35.00	35.00
2	4	FRONT BUMPER SENSOR (NOT WORKING)	600.00	620.00
3	1	FRONT NUMBER PLATE (MISSING)	35.00	35.00
Sub Total (S\$)			670.00	690.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & SPRAY PAINTING.	New	1,400.00	1,000.00
Labour Items				
2	TO REMOVE, REPLACE, REPAIR & INSTALL DAMAGED PARTS.	New	1,200.00	1,000.00
3	TO R & R FRONT RADIATOR.	New	120.00	80.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	150.00	120.00
5	TO R & R WIRING/ SENSOR.	New	100.00	60.00
Gross Labour Cost (S\$)			2,970.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >