

CS/MSG1702422/R1qdbz

Signature

Rasul

ASSIGNMENT (OFFICE)

Merimen

From (Person)

Christina Wong

MSIG

To (Time)

2/12/17 @ 9.08am

Estimated Cost

RM

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLB 5893D

Insured

SJY 7407P

at Workshop in

Hitachi Capital Asia

Tel

9336 6862

of

No. 8 Fourth Lok Yang Road

Policy No.

80263532 SMP

Claim No.

541446

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

16/12/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Entemen.com

Date/Time

9.29am @ 2/12/17

Person Contacted

Gwen

Vehicle IN/OUT

Date/Time

Action/Instruction ( ) Estimate

SLB 5893D - X

SJY 7407P - X

27/12/17 @ 4.37pm revised to Christina Wong via Merimen.

07/5/18 @ 2.11M confirmed with Jaailah final fig \$6779, 7 days.  
(CRN @ 4509.25, 40%)

2/5/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD	Ref : CS/MSG17024221/R1qd3
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581	Date : 21-12-2017
	Code : MSG



### 1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SJY 7407P	Veh. Inspected	SLB 5893D
Policy No.	80263532SMP	Coverage (\$)	0.00
Claim No.	541446	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	21/12/2017

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	16/12/2017	Inspection Date	21/12/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Refiled	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017 13:46 <a href="#">Sendback Est</a>	20 Dec 2017 14:03 <b>S\$11,213.50</b>	21 Dec 2017 09:08 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>KHOO LAY GHEE ANTHONY</b> , ID: S1726399D, Email: KHOO_ANTHONY@HOTMAIL.COM								
Main Claimant:	<b>HITACHI CAPITAL ASIA PACIFIC PTE LTD</b> , Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	<b>SLB5893D</b>	Date of Loss:	16/12/2017 22:00 - :59						
Claim Type:	<b>TP / 541446</b>	Policy/Cover Note No.:	80263532SMP (Comprehensive) Coverage: 28/09/2017 - 27/09/2018						
Vehicle Reg. No. (Insured):	<b>SJY7407P</b>	Policy No. (Claimant):	MSD/VPCP/17-000784-00						
		Excess:	S\$1,500.00						
Repairer:	<b>Hitachi Capital Asia Pacific Pte. Ltd (HQ)</b> No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Imm.Advice due 22/12/2017</b> ]								
Driver/Custodian (Insured):	<b>KHOO LAY GHEE ANTHONY (52 / Male)</b> , NRIC: S1726399D								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 2 May 2018 2:11 PM  
**To:** Jamilah, Binte MohdKassim; SUR; Admin A; Admin-D (LKKAuto); Taufikh (LKKAuto); Rasul (LKKAuto); Guo Qiang (LKKAuto); Asher Sng (LKKAuto); Vic (LKKAuto)  
**Cc:** Kevin, MJ Leong  
**Subject:** RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Jamilah,

SLB 5893D – confirm final fig \$6,779.00 before GST and 7 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Jamilah, Binte MohdKassim [mailto:jamilahbegum@hcspl.com.sg]  
**Sent:** Monday, 30 April 2018 12:42 PM  
**To:** SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Cc:** Kevin, MJ Leong <kevinleong@hcspl.com.sg>  
**Subject:** RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear All,

Good Afternoon.

Please take note Grant has resigned.

Only 3 cases closed since (in red).

Appreciate your immediate action to close the balance cases before Mid May 2018.

Thank you & regards,

Jamilah

Admin Assistant

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6265

e: [jamilahbegum@hcspl.com.sg](mailto:jamilahbegum@hcspl.com.sg)

w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 27 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: SJY7407P	Accident Date	: 16/12/2017
TP Vehicle No	: SLB5893D	Assignment Date	: 21/12/2017
Make	: TOYOTA LEXUS	Est. Duration of Repair	: 7.00
Date of Inspection	: 21/12/2017		
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,213.50
Revised Amount	:S\$	7,147.00
Check Items (Estimated)	:S\$	1,472.00
Total	:S\$	8,619.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/12/2017 17:09
Date Of Accident	16/12/2017 21:45
Exact Location Of Accident	MD.SULTAN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5893D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	LEXUS-4.6 LS460L (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCL/17-000784-00
Cover Note Number	
<b>Driver</b>	
Name of Driver	MAK SHAH BIN ABU SAMAH
NRIC No	S2169821J
Date Of Birth	13/10/1958
Occupation	OUTDOOR
Date Of Driving Pass	04/06/1980
Driving Experience	37 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98277669
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - LESSEE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJY7407P  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver KHOO LAY GHEE ANTHONY  
 NRIC/Passport Number S1726399D  
 Contact Number 93683481  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)  
**Details of Witness**  
 Name AKETA  
 Phone Number 91451442  
 Email Address

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**HITACHI**  
Inspire the Next

**TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**  
**HITACHI CAPITAL ASIA PACIFIC PTE LTD**  
NO.8 FOURTH LOK YANG ROAD  
Singapore 629705

**Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.**

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/12/2017
Vehicle Reg. No.:	SLB5893D	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	MAK SHAH BIN ABU SAMAH	Driver (Insured):	MAK SHAH BIN ABU SAMAH
Make/Model:	TOYOTA LEXUS, 4.6 LS460L (M)	Vehicle Reg. Date:	15/04/2016
Vehicle Colour:	BLACK		
Engine No:	1UR0594174	Chassis No:	JTHBL46F205142158
Odometer:	10000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

**Description of REFER TO ATTACHMENT**

**Accident/Loss**  
Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

**COST OF CLAIMS**

	<b>Amount</b>
Parts	7,553.50
Miscellaneous Items	0.00
Labour	3,660.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>11,213.50</b>
<b>+ GST 7.00% (S\$)</b>	<b>784.95</b>
<b>Nett Amount (S\$)</b>	<b>11,998.45</b>

**This claim is handled by: GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11 788.05

**REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 20 Dec 2017)  
 Parts: N/A TOYOTA LEXUS 4.6 LS460L (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/20/12/2017 14:03  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bootlid Repair	0.00	0.00	-
2	1		*Bootlid lower garnish cover	0.00	0.00	*450.00 F CPA
3	1		*Bootlid inner LED lamp LH	0.00	0.00	*350.00 F XSVL
4	1		*Rear bumper	0.00	0.00	*360.00 F SCR
5	10		*Rear bumper clips	0.00	0.00	*15.00 F
6	2		*Rear bumper side retainer inner LH/RH	0.00	0.00	*110.00 F SS
7	2		*Rear bumper side retainer outer LH/RH	0.00	0.00	*110.00 F SS
8	2		*Rear bumper bolt cover LH/RH	0.00	0.00	*20.00 F XSVL
9	1		*Rear bumper reflector lamp LH	0.00	0.00	*20.00 F XSVL
10	1		*Rear bumper lower spoiler	0.00	0.00	*125.00 F CPA
11	2		*Rear bumper lower chrome cover LH/RH	0.00	0.00	*230.00 F XSVL
12	1		*Rear reinforcement	0.00	0.00	*230.00 F XSVL
13	1		*Rear bumper sponge	0.00	0.00	*85.00 F XSVL
14	1		*Rear bumper undercover LH	0.00	0.00	-
15	1		*Taillamp outer LH	0.00	0.00	*450.00 F XSVL
16	1		*Rear fender shield LH	0.00	0.00	*120.00 F cut
17	10		*Rear fender shield clips	0.00	0.00	*15.00 F
18	1		*Rear fender LH Repair	0.00	0.00	-
19	1		*Rear original RIM LH 19	0.00	0.00	*3,400.00 F SCR
20	1		*Rear tyre LH 245/45R19	0	0.00	*550.00 FS XSVL
21	1		*Rear door LH Repair	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,640.00
+ Margin on L,N Items 15.00% (S\$)	913.50
<b>Total Parts (S\$)</b>	<b>7,553.50</b>

Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/20/12/2017 14:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	<del>1,400.00</del> 700
2	Putty, blend and paint affected area	New	<del>1,200.00</del> 800
3	Check Wiring and ensure proper function	New	<del>80.00</del> 30
4	Remove & reinstall bumper sensors	New	<del>120.00</del> 60
5	Cavity Treatment on New Parts	New	<del>80.00</del> 40
6	Remove & reinstall Rear reverse camera	New	<del>120.00</del> 60
7	Remove, replace & balance rim / tire	New	<del>50.00</del> 30
8	Conduct four wheel alignment / side slip test	New	<del>150.00</del> 80
9	Remove and refix door lock & mechanism	New	200.00 X11
10	Conduct water seepage test	New	80.00 X11
11	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	<del>180.00</del> 80
<b>Gross Labour Cost (S\$)</b>			<b>3,660.00</b>

Hitachi Capital Asia Pacific Pte. Ltd./SLB5893D/20/12/2017 14:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N**

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835  
 www.hitachi-capital.com.sg

**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
 8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

*Panel*  
*HP 90010068*  
*7 days*  
*P/P*  
*21/12/17 @ 1650*  
*Resy by panel*

*[Signature]*  
*5/1/18*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 20 Dec 2017)  
 Parts: N/A TOYOTA LEXUS 4.6 LS460L (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/20/12/2017 14:03  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bootlid Repair	0.00	0.00	-
2	1		*Bootlid lower garnish cover	0.00	0.00	✓ *450.00F <i>CPA</i>
3	1		*Bootlid inner LED lamp LH	X 0.00	0.00	X *350.00F <i>?</i>
4	1		*Rear bumper	0.00	0.00	✓ *360.00F <i>SCR</i>
5	10		*Rear bumper clips	0.00	0.00	✓ *15.00F <i>SCR</i>
6	2		*Rear bumper side retainer inner LH/RH	0.00	0.00	✓ *110.00F <i>SCR</i> \$55
7	2		*Rear bumper side retainer outer LH/RH	0.00	0.00	✓ *110.00F <i>SCR</i> \$55
8	2		*Rear bumper bolt cover LH/RH	0.00	0.00	X *20.00F <i>?</i>
9	1		*Rear bumper reflector lamp LH	0.00	0.00	X *20.00F <i>?</i>
10	1		*Rear bumper lower spoiler	→ 0.00	0.00	✓ *125.00F <i>?</i>
11	2		*Rear bumper lower chrome cover LH/RH	0.00	0.00	X *230.00F <i>X</i>
12	1		*Rear reinforcement	0.00	0.00	X *230.00F <i>?</i>
13	1		*Rear bumper sponge	0.00	0.00	X *85.00F <i>?</i>
14	1		*Rear bumper undercover LH	0.00	0.00	- <i>?</i>
15	1		*Taillamp outer LH	0.00	0.00	X *450.00F <i>?</i>
16	1		*Rear fender shield LH	0.00	0.00	✓ *120.00F <i>cut</i>
17	10		*Rear fender shield clips	0.00	0.00	✓ *15.00F <i>SCR</i>
18	1		*Rear fender LH Repair	0.00	0.00	-
19	1		*Rear original RIM LH 19	\$3000 0.00	0.00	<del>*3,400.00F</del> <i>SCR</i>
20	1		*Rear tyre LH 245/45R19	0	0.00	X *550.00FS <i>X</i>
21	1		*Rear door LH Repair	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,640.00
+ Margin on L,N Items 15.00% (\$\$)	913.50
<b>Total Parts (\$\$)</b>	<b>7,553.50</b>

Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/20/12/2017 14:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

Supplementary \$ 65 + 15% = \$ 74.75  
 parts \$ 4195 + 15% = \$ 4824.25  
 labour \$ 1880

\* Total PIP \$ 6779 @ 7 day \*

<b>REPAIR DETAILS</b>	
<b>Reference</b>	
Part Source:	(Last Synchronised: 21 Mar 2018)
Parts:	N/A TOYOTA LEXUS 4.6 LS460L (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/21/03/2018 22:03
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear wheel arch moulding Rear LH	0.00	0.00	*50.00 F
2	3		*Rear bumper white clip	0.00	0.00	*15.00 F
Sub Total (S\$)						65.00
+ Margin on L,N Items 15.00% (S\$)						9.75
Total Parts (S\$)						74.75

*creat*  
*UP re*

Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/21/03/2018 22:03. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	<del>1,480.00</del> 700
2	Putty, blend and paint affected area	New	<del>1,200.00</del> 800
3	Check Wiring and ensure proper function	New	<del>80.00</del> 30
4	Remove & reinstall bumper sensors	New	<del>120.00</del> 60
5	Cavity Treatment on New Parts	New	<del>80.00</del> 90
6	Remove & reinstall Rear reverse camera	New	<del>120.00</del> 60
7	Remove, replace & balance rim / tire	New	<del>50.00</del> 30
8	Conduct four wheel alignment / side slip test	New	<del>150.00</del> 80
9	Remove and refix door lock & mechanism	New	200.00 X
10	Conduct water seepage test	New	80.00 X
11	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	<del>180.00</del> 80
Gross Labour Cost (S\$)			3,660.00

Hitachi Capital Asia Pacific Pte. Ltd/SLB5893D/20/12/2017 14:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835  
 www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

*Rasmel*  
*Hy 90010068*  
*7 days*  
*P/P*  
*21/12/17 @ 1650*  
*Resy by punkt*

**HITACHI**  
Inspire the Next

## (SUPPLEMENTARY)

**TP INSURER:** MSIG Insurance (Singapore) Pte. Ltd. (HQ)  
**KHOO LAY GHEE ANTHONY**  
72 HTYHE ROAD  
SINGAPORE 557561  
Singapore

**Claimant Insurer:** MSIG Insurance (Singapore) Pte. Ltd.

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	80263532SMP	Date of Loss:	16/12/2017
Vehicle Reg. No.:	SLB5893D	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	MAK SHAH BIN ABU SAMAH	Driver (Insured):	KHOO LAY GHEE ANTHONY
Make/Model:	TOYOTA LEXUS, 4.6 LS460L (M)	Vehicle Reg. Date:	15/04/2016
Vehicle Colour:	BLACK		
Engine No:	1UR0594174	Chassis No:	JTHBL46F205142158
Odometer:	48977 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

## Description of REFER TO ATTACHMENT

Accident/Loss

Present HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

Location:

**COST OF CLAIMS****Amount**

Parts	74.75
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>74.75</b>
<b>+ GST 7.00% (S\$)</b>	<b>5.23</b>
<b>Nett Amount (S\$)</b>	<b>79.98</b>



# 合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

## TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

LEXUS LS460

GRANT

NO: DLI9197462 ✓

PAGE: 1

DATE: 22/12/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLB5893D

Part No	Description	Location	Qty	Unit Price	Amount	
				<u>SIN</u>	<u>SIN</u>	
1	T76802-50020-A0 GARNISH SUB ASSY LEX	DU2HI	1	450.00	450.00	
2	T52159-50932 BUMPER RR	DB2G	1	360.00	360.00	
3	T52161-16010 CLIP BUMPER	DUIAD11-3	10	1.50	15.00	
4	T52156-50060 BUMPER RETAINER RR LH	DUIAD49-1	1	55.00	55.00	
5	T52568-50040 RR BUMPER RET LH	DUIAD44-7	1	55.00	55.00	
6	T65638-50040 RR FENDER LINER LH	DU2C2	1	120.00	120.00	
7	T90189-06065 CLIP RR FENDER	DUIAD11-7	10	1.50	15.00	
TOTAL QUANTITY:			25	TOTAL	SIN 1,070.00	
					ADD GST @ 7%	74.90
					<b>GRAND TOTAL</b>	<b>SIN 1,144.90</b>

J/R: 104074

LU GEN


Print / LSK / 22/12/2017 9:32:43 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY 



# 合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

## TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

LS460

GRANT

NO: DLI9197479

PAGE: 1

DATE: 22/12/2017

A/C CODE: LDHC008


TERMS: CR

VEH NO: SLB5893D

Part No	Description	Location	Qty	Unit Price	Amount
1	T75874-50050	WHEEL ARCH MLG RR LH	DUIG18-4	1 / 50.00	SIN 50.00
TOTAL QUANTITY:			1	TOTAL	SIN 50.00
				ADD GST @ 7%	3.50
				GRAND TOTAL	<b>SIN 53.50</b>

O/R: 104074

MR GEN



Print / LSK / 22/12/2017 11:43:27 AM


SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

E. & O.E.





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /  
DAIHATSU / KIA / SUZUKI / HONDA  
TEL: 6291 2827 FAX: 6296 4390  
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S : HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

LS460

GRANT

NO: DLI9197484

PAGE: 1

DATE: 22/12/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLB5893D

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	T52197-30040	DD1A188	2	5.00	10.00	
		DD1A191	1	5.00	5.00	
TOTAL QUANTITY:			3	TOTAL	SIN 15.00	
					ADD GST @ 7%	1.05
					GRAND TOTAL	<b>SIN 16.05</b>

O/R: 104074

MR GEN

Reprint:2 / LSK / 22/12/2017 2:46:33 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

LS460

GRANT

NO: DL19197504

PAGE: 1

DATE: 22/12/2017

A/C CODE: LDHC008


TERMS: CR

VEH NO: SLB5893D

Part No	Description	Location	Qty	Unit Price	Amount
1	T52169-50050 (spoiler)	RR BUMPER LWR CVR	1	SIN 125.00	SIN 125.00
TOTAL QUANTITY:			1	TOTAL	SIN 125.00
				ADD GST @ 7%	8.75
				GRAND TOTAL	<b>SIN 133.75</b>

O/R: 104074

MR GEN



Print / LSK / 22/12/2017 4:48:44 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

\_\_\_\_\_  
 GOODS RECEIVED BY

E. & O. E.



# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

LEXUS

GRANT

NO: DLI9197601

PAGE: 1

DATE: 27/12/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLB5893D

Part No	Description	Location	Qty	Unit Price	Amount	
1	T4261A-50161	RIM	1	3,000.00	3,000.00	
TOTAL QUANTITY:			1	TOTAL	SIN 3,000.00	
					ADD GST @ 7%	210.00
					<b>GRAND TOTAL</b>	<b>SIN 3,210.00</b>

O/R: 104074

MR GEN

Print / LSK / 27/12/2017 9:48:55 AM

SALESMAN: LSK


This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

*Grant Gen*



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017 13:46 <a href="#">Sendback Est</a>	20 Dec 2017 14:03 <b>\$11,213.50</b>	21 Dec 2017 09:08 <a href="#">Edit Adj Rpt</a>	<b>\$6,779.00</b> <a href="#">Edit Estimates</a>	<b>\$6,779.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	21 Mar 2018 21:58	21 Mar 2018 22:03 <b>\$74.75</b>	21 Mar 2018 22:03			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>KHOO LAY GHEE ANTHONY</b> , ID: S1726399D, Email: KHOO_ANTHONY@HOTMAIL.COM								
Main Claimant:	<b>HITACHI CAPITAL ASIA PACIFIC PTE LTD</b> , Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	<b>SLB5893D</b>	Date of Loss:	16/12/2017 22:00 - :59 <b>[20 Months and 1 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 541446</b>	Policy/Cover Note No.:	80263532SMP (Comprehensive) Coverage: 28/09/2017 - 27/09/2018						
Vehicle Reg. No. (Insured):	<b>SJY7407P</b>	Policy No. (Claimant):	MSD/VPCP/17-000784-00						
		Excess:	<b>\$1,500.00</b>						
Repairer:	<b>Hitachi Capital Asia Pacific Pte. Ltd (HQ)</b> No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 20/01/2018]</b>								
Driver/Custodian (Insured):	KHOO LAY GHEE ANTHONY (52 / Male), NRIC: S1726399D								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**SLB5893D (541446)**  
**[SJY7407P]**  
**TP**  
**HITACHI CAPITAL ASIA PACIFIC PTE LTD**  
**Dec 16 2017 10:00PM**  
**[KHOO LAY GHEE ANTHONY]**  
**Hitachi Capital Asia Pacific Pte. Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>		
<b>Assessment Reports</b>		1 per page <input type="checkbox"/>		
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/12/17 19:17	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
2	20/12/17 14:03	<b>Repairer Estimates</b>	Load HTM	<input type="checkbox"/>
3	21/03/18 22:03	<b>Repairer Estimates Suppl. #1</b>	Load HTM	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/12/17 09:09	<b>Accident Statement</b> <small>From: OD - Reg. No: SJY7407P, Claimant: KHOO LAY GHEE ANTHONY</small>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/17 16:37	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>		3 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 14:23	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	02/05/18 14:23	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
3	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	02/05/18 14:23	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
29	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
30	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
31	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
32	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
33	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
34	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
35	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
36	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
37	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
38	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
39	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
40	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
41	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
42	02/05/18 14:23	General View		Load JPG <input checked="" type="checkbox"/>
43	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	02/05/18 14:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 17:10	Parts Invoice		Load PDF <input type="checkbox"/>
2	09/05/18 17:20	Supplementary		Load PDF <input type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/12/17 19:17	Accident Statement		Load HTM <input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/12/17 17:37	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	18/12/17 17:37	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	18/12/17 17:37	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	18/12/17 17:37	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	18/12/17 17:37	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
6	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	18/12/17 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/12/17 18:16	Sketch Plan	 Load TIF	<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024221/R1QD3E2

Date: 09/05/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 80263532SMP
Claimant Vehicle No: SLB5893D	Insured Vehicle No: SJY7407P
Date of Loss: 16/12/2017	Nature of Claim: TP
	Claim No: 541446

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLB5893D</b>	Engine No: 1UR0594174
Make & Model: TOYOTA LEXUS, 4.6 LS460L (M)	Chassis No: JTHBL46F205142158
Reg. Date: 15/04/2016 (Man. Year: 2016)	Odometer: 48977 km
Colour: Black	
Engine Capacity: 4608 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size: 245/45 R19	Rear Tyre Size: 245/45 R19
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,628.25	4,899.00	2,729.25	35.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,880.00	1,780.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,288.25</b>	<b>6,779.00</b>	<b>4,509.25</b>	<b>39.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>790.18</b>	<b>474.53</b>	<b>315.65</b>	<b>39.95</b>
<b>Nett Amount (S\$)</b>	<b>12,078.43</b>	<b>7,253.53</b>	<b>4,824.90</b>	<b>39.95</b>

#### INSPECTION

Date of Assignment: 21/12/2017	Present Location: Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected: 21/12/2017	Inspected At: No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair: 7.0 days	

**Adjuster: MOHD RASUL**

**Manager: SHIAU CHAN**

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 09 May 2018)  
**Parts:** N/A TOYOTA LEXUS 4.6 LS460L (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLB5893D)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bootlid (NPA)(WCP)	Repair	-	-
2	1		*Bootlid lower garnish cover (WCP)	Cracked	450.00 F	*450.00 F
3	1		*Bootlid inner LED lamp LH (WCP)	Serviceable	350.00 F	*- F
4	1		*Rear bumper (WCP)	Scratched	360.00 F	*360.00 F
5	10		*Rear bumper clips (WCP)	Necessary	15.00 F	*15.00 F
6	1		*Rear bumper side retainer inner LH/RH (WCP)	N/S Necessary	110.00 F	*55.00 F
7	1		*Rear bumper side retainer outer LH/RH (WCP)	N/S Necessary	110.00 F	*55.00 F
8	2		*Rear bumper bolt cover LH/RH (WCP)	Serviceable	20.00 F	*- F
9	1		*Rear bumper reflector lamp LH (WCP)	Serviceable	20.00 F	*- F
10	1		*Rear bumper lower spoiler (WCP)	Cracked	125.00 F	*125.00 F
11	2		*Rear bumper lower chrome cover LH/RH (WCP)	Serviceable	230.00 F	*- F
12	1		*Rear reinforcement (WCP)	Serviceable	230.00 F	*- F
13	1		*Rear bumper sponge (WCP)	Serviceable	85.00 F	*- F
14	1		*Rear bumper undercover LH (NPA)(WCP)	Serviceable	-	*- F
15	1		*Taillamp outer LH (WCP)	Serviceable	450.00 F	*- F
16	1		*Rear fender shield LH (WCP)	Cut	120.00 F	*120.00 F
17	10		*Rear fender shield clips (WCP)	Necessary	15.00 F	*15.00 F
18	1		*Rear fender LH (NPA)(WCP)	Repair	-	*- F
19	1		*Rear original RIM LH 19 (WCP)	Scratched	3,400.00 F	*3,000.00 F
20	1		*Rear tyre LH 245/45R19	Serviceable	550.00 FS	*- FS
21	1		*Rear door LH (NPA)(WCP)	Repair	-	*- F
<b>Supplementary #1</b>						
22	1		*Rear wheel arch moulding Rear LH (WCP)	Cut	50.00 F	*50.00 F
23	3		*Rear bumper white clip (WCP)	Necessary	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Sub Total (\$\$)</b>	<b>6,705.00</b>	<b>4,260.00</b>
					<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	<b>923.25</b>	<b>639.00</b>
					<b>Total Parts (\$\$)</b>	<b>7,628.25</b>	<b>4,899.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,400.00	700.00
2	Putty, blend and paint affected area	New	1,200.00	800.00
3	Check Wiring and ensure proper function	New	80.00	30.00
4	Remove & reinstall bumper sensors	New	120.00	60.00
5	Cavity Treatment on New Parts	New	80.00	40.00
6	Remove & reinstall Rear reverse camera	New	120.00	60.00
7	Remove, replace & balance rim / tire	New	50.00	30.00
8	Conduct four wheel alignment / side slip test	New	150.00	80.00
9	Remove and refix door lock & mechanism	New	200.00	0.00
10	Conduct water seepage test	New	80.00	0.00
11	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	180.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,660.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >