



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT17004571	Page	1
Registration No	: SLB4840M	Date	: 8. Nov 2017		
Chassis No	: JHMRC1890GC203574	Customer No.	: WZE011		
Model	: ODYSSEY2.4 EXV-S 16YM NAVI-RES	Svc Advisor	: PATRICK MOK LIP KAY		
Owner's Name	: NORADLINAH BTE ADAM	Engine No	: K24W72011688		
Ins Policy No.	:	Date Time	: 8. Nov 2017 5:32:43 PM		
Date of Accident	:	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NORADLINAH BINTE ADAM OWNER INSURER: AVIVA LTD ACC DATE: 06/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: EQ INSURANCE CO. LTD TP VEH: GY1282G						
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BOJSE	SEALANT FOR BONNET	1	100.00		100.00	7.00	107.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	2240.00	1400	2240.00	156.80	2396.80
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1575.00	1350	1575.00	110.25	1685.25
	Sum Labor				4195.00	293.65	4488.65
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00	X	45.00	3.15	48.15
60100-T6A-000ZZ	HOOD COMP	1	658.30	PH	658.30	46.08	704.38
74120-T6A-003	LOCK ASSYHOOD	1	104.20	X	104.20	7.29	111.49
71121-T6A-003	BASEFR.GRILLE	1	165.70	?	165.70	11.60	177.30
71122-T6A-003	MOLDINGFR.GRILLE	1	258.10	CRA	258.10	18.07	276.17
75700-TA0-A00	EMBLEMFR.	1	25.30	neu	25.30	1.77	27.07
91505-TM8-003	CLIPBUMPER	6	2.00	neu	12.00	0.84	12.84
04711-T6A-900ZZ	FACEFR.BUMPER	1	686.30	DE	686.30	48.04	734.34
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	65.80	?	65.80	4.61	70.41
71108-T6A-P00	LOWER PLATEFR.BUMPER	1	144.20	?	144.20	10.09	154.29
71110-T6A-000	AIR SPOILERFR.BUMPER	1	90.60	?	90.60	6.34	96.94
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	291.80	?	291.80	20.43	312.23
71151-T6A-911	BASEMID GRILLE	1	182.80	?	182.80	12.80	195.60



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLK MND BUILDING
 SINGAPORE 069110

Registration No : SLB4840M

Chassis No : JHMRC1890GC203574

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : NORADLINAH BTE ADAM

Ins Policy No. :

Date of Accident :

Document No. : SQT17004571 Page 2

Date : 8. Nov 2017

Customer No. : WZE011

Svc Advisor : PATRICK MOK LIP KAY

Engine No : K24W72011688

Date | Time : 8. Nov 2017 5:32:43 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	150.60	CRA ✓	150.60	10.54	161.14
71153-T6A-921	MID MOLDINGMID GRILLE	1	144.20	CRA ✓	144.20	10.09	154.29
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	38.70	?	38.70	2.71	41.41
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	38.70	?	38.70	2.71	41.41
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2237.30	?	2237.30	156.61	2393.91
33150-T6A-Q11	HEADLIGHT ASSYL.WITH LED	1	2237.30	?	2237.30	156.61	2393.91
Sum Item					<u>7576.90</u>	<u>530.38</u>	<u>8,107.28</u>

Survey By RAbul - Hp 90010068

Date & Time 11/11/18 @ 11:10

Excess _____

Status _____

Signature [Signature]

6 days

Resurvey b4 paint

Total Amount 11,771.90 824.03 12,595.93

Total (Inclusive of GST) 12,595.93

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 14/11/2017 4:31:08 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)