

ASS. REC BY: Kenneth REF: CS/FCI17024225 / Ktd302

SUBMIT: cws ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 11:23am @ 21/12/17

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / GS

To Inspect Vehicle No: SKS 5851 Y Insured: SHD 4026 J

at Workshop to: Tong Luck Auto Tel: 6250 0088

of 160 Sing Ming Drive #07-01/06

Policy No: \_\_\_\_\_ Claim No: D17011714 MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 18/12/2017

(Client's Record) (wp) 22/12/17

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 1209pm @ 21/12/17 Person Consulted: Candy Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKS 5851 Y - X</u>
	<u>SHD 4026 J - CS/FCI15016126 / T1/bc2</u> D.O.A: <u>20/09/2015</u>
	<u>Part by Part \$56561 (Red: 1387.7: 25%)</u>

## ASSIGNMENT

From: \_\_\_\_\_ Date: 22/12/17

Estimated Cost: \_\_\_\_\_

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 5851Y

at Workshop m/s Tong Luck Auto  
of 160 Sin Ming Drive #07-01/106

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKS 5851Y Yr Regn: \_\_\_\_\_Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Audi A6 TFSColour: M. Black A/C: Insured / Std / NI / NASp. Reading: 233163 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W AU 77846 5EN 203479Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: \_\_\_\_\_ R: 245/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 18/12/17D.O.I. 22/12/17

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

for o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
26/12 File sent to Customer

RECEIVED 03 JAN 2018

Date/Time File Pass to?

1) 31 Typist

Date/Time File Return to?

2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: \_\_\_\_\_

Photos:

Others:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / (B): (\$ 5656)

TOTAL

150
50
50
15
265

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date	20-12-2017	Our Ref No. D17011714MFSH
Accident Date	18-12-2017	Claim Type. Third Party
Insured Vehicle	SHD4026J	Third Party Vehicle. SKS5851Y
Survey Location	160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY	
Contact Person.	YU CHING	
Contact No.	6250 0088/ 0	Fax No. 6250 5545
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	TONG LUCK AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232183)



PRI Documents



Close



## PRI Header Details

Claim No	D17011714MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TONG LUC
Workshop Name	TONG LUCK AUTO PTE LTD (Contact Person : YU CHING)	Survey Location & Contact Details	160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY Mobile: 0 , Phone: 6250 0088 , Fax: 6250 5545 EmailId: OPERATION@TLAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4026J	TP Vehicle No	SKS5851Y
PRI Recieved Date	20-12-2017 08:19:56 PM	Surveyor Appointed Date	21-12-2017 11:22:39 AM	Surveyor Accept Date	21-12-2017 1

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024225/Ktd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-12-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4026J	Veh. Inspected	SKS 5851Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17011714MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	21/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

4.

## 5. General Information

5.

Accident Date	18/12/2017	Inspection Date
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722	

## Remarks

5a.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2017 15:27
Date Of Accident	18/12/2017 05:30
Exact Location Of Accident	ESSO JURONG WEST SERVICE STATION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS5851Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WOLERO PTE LTD
Co Reg No	NA (2009003226)
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63965376
<b>Vehicle Particulars</b>	
Manufacturer	AUDI
Model	A6
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V09021/VPL/R03
Cover Note Number	

### Driver

Name of Driver	MOHAMED SAHLI BIN SALIM
NRIC No	S1662223J
Date Of Birth	18/11/1964
Occupation	OUTDOOR
Date Of Driving Pass	21/12/1984
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90502474
Fax Number	
Contact Number	
Email Address	NOEMAIL

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : WOLERO PTE LTD (TP)

65 AIRPORT BOULEVARD

CHANGI AIRPORT TERMINAL 3 #B1-36A

SINGAPORE 819663

ATTN :

TEL : 6396 5376

FAX : 6243 3400

YOUR REF NO : SHD4026J

CLAIM TYPE : D17011714MPSH

TP INS. CO. : FIRST CAPITAL INSURANCE LTD

ACCIDENT DATE : 18/12/2017

## ESTIMATE

NO : QUOT201712-0064(00)

DATE : 20/12/2017

POLICY NO : SD17V09021/VPL/R03

VEH REG NO : SKS5851Y

MAKE/MODEL : AUDI A6 2.0 TFSI MU

CHASSIS NO : WAUZZZ4G5EN203479

ENGINE NO : CDN417144

REG. DATE : 2014

## Estimate Repair Cost to Vehicle No : SKS5851Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>LIST PRICE</b>			
1 Headlamp assy - RH	1	2,150.00	2,150.00
2 Headlamp barcket - RH	1	95.00	95.00
3 Front bumper	1	1,660.00	1,660.00
4 Front bumper reinforcement	1	490.00	490.00
5 Front bumper side retainer - RH	1	45.00	45.00
6 Front bumper fog lamp cover - RH	1	103.00	103.00
7 Front bumper headlamp nozzle - RH	1	188.00	188.00
8 Front bumper headlamp nozzle cover - RH	1	52.00	52.00
9 Front bumper sensor	1	158.00	158.00
10 Front bumper sensor seals	4	6.00	24.00
11 Front bumper clips (set)	1	128.00	128.00
			5,093.00
			Less 10%
			509.30
			4,583.70
<b>LABOUR</b>			
12 To remove and refit front bumper sensor and reset faulty code	1	100.00	100.00
13 To check and rectify wiring system	1	80.00	80.00
14 To panel beat and straighten RH front chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
15 To spray same on affected areas	1	1,200.00	1,200.00
16 To re-programme and coding of headlamp	1	580.00	580.00
			2,960.00
			1300
			Not Authorise
			1. B1
			Reusing B4 parts
			22/12/17 (4 days)
			TOTAL
			S\$ 7,543.70
			ADD GST @ 7%
			528.06
			GRAND TOTAL
			S\$ 8,071.76

SINGAPORE DOLLAR EIGHT THOUSAND SEVENTY-ONE AND CENTS SEVENTY-SIX ONLY

\$ 5,656.00

4 days

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# GT CONTINENTAL PTE. LTD.

160 Sin Ming Drive #08-20/21  
Sin Ming Autocity Singapore 575722  
Tel : 6457 7763  
Fax: 6457 0355  
UEN/GST Reg No. 201612356H



## Tax Invoice

Invoice Name & Address	Invoice No.
Tong Luck Auto Pte Ltd 160 Sin Ming Drive #07-01 Sin Ming Autocity Singapore 575722 Terence Tan Hp: 9623 5378 Tel: 6453 5104	GT17-0216
	Date 29/12/2017
	Done by Fat
	Terms 30 Days

Vehicle No.	Model	Chassis No.	Mileage
SKS 5851 Y	Audi A6		233163

Description	Quantity	U/M	Unit Price	Amount
Labour charge for re programming headlamp faulty code (online)			250.00	250.00

E. & O.E.

Sub Total	\$250.00
Add 7% GST	\$17.50
<b>Total (SGD)</b>	<b>\$267.50</b>

Payment by cheque to be crossed and made payable to GT Continental Pte Ltd  
Any dispute to the invoice must be made within 3 days.  
This is a computer generated document, no signature is required.

[www.gtcontinental.sg](http://www.gtcontinental.sg)



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : WOLERO PTE LTD (TP)

65 AIRPORT BOULEVARD  
CHANGI AIRPORT TERMINAL 3 #B1-36A  
SINGAPORE 819663

ATTN :

TEL : 6396 5376

FAX : 6243 3400

YOUR REF NO : SHD4026J

CLAIM TYPE :

TP INS. CO. : FIRST CAPITAL INSURANCE LTD

ACCIDENT DATE : 18/12/2017

## ESTIMATE

NO : QUOT201712-0064(00)

DATE : 20/12/2017

POLICY NO : SD17V09021/VPL/R03

VEH REG NO : SKS5851Y

MAKE/MODEL : AUDI A6 2.0 TFSI MU

CHASSIS NO : WAUZZZ4G5EN203479

ENGINE NO : CDN417144

REG. DATE : 2014

## Estimate Repair Cost to Vehicle No : SKS5851Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>LIST PRICE</b>			
1 Headlamp assy - RH	1	2,150.00	2,150.00 ✓
2 Headlamp barcket - RH	1	95.00	95.00 ?
3 Front bumper	1	1,660.00	1,660.00 ✓
4 Front bumper reinforcement	1	490.00	490.00 ?
5 Front bumper side retainer - RH	1	45.00	45.00 ✓
6 Front bumper fog lamp cover - RH	1	103.00	103.00 ✓
7 Front bumper headlamp nozzle - RH	1	188.00	188.00 ✓
8 Front bumper headlamp nozzle cover - RH	1	52.00	52.00 ✓
9 Front bumper sensor	1	158.00	158.00 ?
10 Front bumper sensor seals	4	6.00	24.00 ?
11 Front bumper clips (set)	1	128.00	128.00 ✓
			5,093.00
		Less 10%	509.30
			4,583.70
<b>LABOUR</b>			
12 To remove and refit front bumper sensor and reset faulty code	1	100.00	100.00 800
13 To check and rectify wiring system	1	80.00	80.00 200
14 To panel beat and straighten RH front chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 4500
15 To spray same on affected areas	1	1,200.00	1,200.00 5000
16 To re-programme and coding of headlamp	1	580.00	580.00 ?
			2,960.00
		<b>TOTAL</b>	<b>S\$ 7,543.70</b>
		ADD GST @ 7%	528.06
		<b>GRAND TOTAL</b>	<b>S\$ 8,071.76</b>

SINGAPORE DOLLAR EIGHT THOUSAND SEVENTY-ONE AND CENTS SEVENTY-SIX ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024225/Ktd3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-01-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4026J	Veh. Inspected	SKS 5851Y
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17011714MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	21/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	AUDI A6 TFSI (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WAUZZZ4G5EN203479	Colour	METALLIC BLACK
Odometer	233163	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R17	HANKOOK	9 mm
L/H Front Tyre	245/45 R17	HANKOOK	9 mm
R/H Rear Tyre	245/45 R17	HANKOOK	9 mm
L/H Rear Tyre	245/45 R17	HANKOOK	9 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	18/12/2017	Inspection Date	22/12/2017
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 5851Y**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HEADLAMP ASSY-RH	CUT	2,150.00	2,150.00
1	HEADLAMP BRACKET-RH	SERVICEABLE	95.00	-
1	FRONT BUMPER	BUCKLED	1,660.00	1,660.00
1	FRONT BUMPER REINFORCEMENT	BENT	490.00	490.00
1	FRONT BUMPER SIDE RETAINER-RH	DISTORTED	45.00	45.00
1	FRONT BUMPER FOG LAMP COVER-RH	MISSING	103.00	103.00
1	FRONT BUMPER HEADLAMP NOZZLE-RH	CRACKED	188.00	188.00
1	FRONT BUMPER HEADLAMP NOZZLE COVER-RH	DENTED	52.00	52.00
1	FRONT BUMPER SENSOR	SERVICEABLE	158.00	-
4	FRONT BUMPER SENSOR SEALS @\$6.00	NECESSARY	24.00	24.00
1	SET FRONT BUMPER CLIPS	NECESSARY	128.00	128.00
	LESS 10% DISCOUNT		-509.30	-484.00
			4,583.70	4,356.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT FRONT BUMPER SENSOR AND RESET FAULTY CODE.		100.00	80.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN RH FRONT CHASSIS FRAME INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME.		1,000.00	450.00
	TO SPRAY SAME ON AFFECTED AREAS.		1,200.00	500.00
	TO RE-PROGRAMME AND CODING OF HEADLAMP.		580.00	250.00
			2,960.00	1,300.00
<b>GRAND TOTAL</b>			<b>7,543.70</b>	<b>5,656.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,656.00</b>

Report Ref No. CS/FCI17024225/Ktd3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.