

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

19-Dec-17

Our ref : TP/4439/17

See Yen Fern

RE : estimate cost for vehicle no :SJT 5176U

1 pc	bootlid	\$	1,690.87 <i>bt</i>
1 pc	Jetta emblem		99.70 <i>new</i>
1 pc	Tsi emblem		90.79 <i>new</i>
2 pcs	bootlid reflectors		801.86 <i>cut</i>
1 pc	bootlid lock		288.70 <i>X</i>
1 pc	bootlid w/strip		388.90 <i>X</i>
2 pcs	taillamp		1000.74 <i>cut</i>
1 pc	rear bumper		1,630.71 <i>de</i>
1 pc	bootlid lower spoiler		799.87 <i>de</i>
2 pcs	rear bumper reflectors		181.94 <i>LH-rt, RM-X</i>
1 pc	rear bumper centre holder		197.87 <i>?</i>
2 pcs	rear bumper retainers		195.74 <i>new</i>
2 pcs	rear bumper side holder		195.74 <i>new</i>
1 pc	rear bumper reinforcement		488.78 <i>?</i>
1 pc	end panel		1,490.79 <i>?</i>
1 pc	end panel inner garnish		388.70 <i>?</i>
1 pc	exhaust pipe		1,200.93 <i>Ry</i>
			11,132.63
		less 10%	1,113.26
			10,019.37
1 pc	rear no plate		40.00 <i>snett</i>
1 pc	reverse sensor		250.00 <i>200 new</i>
	Panel beating,		1000.00 <i>700</i>
	Spray painting.		1000.00 <i>700</i>
	Wiring.		30.00 <i>✓</i>
	Rust proofing.		80.00 <i>40</i>
	Remove & refit exhaust pipe.		80.00 <i>50</i>
			12499.37
		Plus 7% GST	874.96
			13374.32

SD : thirteen thousand three hundred seventy-four & cents thirty-two only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
wp
20/12/17 @ 12pm
humpun
Ream after opiv.
6 days
sur@lkkauto.com
taufik@lkkauto.com