

DING AUTO PTE LTD

Blk 10, #01-20
 Sin Ming Industrial Est. Sec C
 Singapore 575645
 Tel: 6452 1208
 Fax: 6452 0614

Vehicle:	PC4743H
Model:	TOYOTA HIACE COMMUTER GL 3.0A
Chassis:	KDH2230027787

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	DOOR SLIDING LH	1	\$ 1,757.90	10%	\$ 1,582.11	✓
2	DOOR RUBBER-BEADING LH	1	\$ 322.70	10%	\$ 290.43	✓
3	SLIDING DOOR GLASS LH	1	\$ 1,232.40	10%	\$ 1,109.16	✓
4	DOOR INNER LOCK LH	1	\$ 344.75	10%	\$ 310.28	✓
TOTAL:					\$ 3,291.98	

NO	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
5	DOOR GLASS SEALANT	1	\$ 60.00	✓
6	DOOR EXCURSION	1	\$ 60.00	✓
SPECIAL NETT			\$ 120.00	

NO	LABOUR	PRICE	SURVEYOR MARKING
7	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	\$ 700.00	300
8	R & R SLIDING DOOR COMPONENTS LH	\$ 120.00	80
9	R & R SLIDING DOOR GLASS LH	\$ 150.00	80
10	R & R ELECTRICAL WIRINGS, CHECK & REPAIR WIRING	\$ 80.00	30
11	CHECK & RESETTING ECU SYSTEM	\$ 180.00	X
12	SPRAY PAINTING SLIDING DOOR LH, ROCKER PANEL LH, FRONT PILLAR LH & REAR FENDER LH	\$ 1,000.00	600
TOTAL:		\$ 2,230.00	

PARTS	\$	3,291.98
LABOUR	\$	2,230.00
SPECIAL NETT	\$	120.00
TOTAL	\$	5,641.98
GST 7%	\$	394.94
FINAL TOTAL	\$	6,036.91

LKK Auto Consultants hence notify the Insurer of the following:

- To not pay before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Handwritten:
 4/5 \$2000
 4w days

Handwritten:
 Not Authorised
 4/5 Repair
 After Paha Pashu
 L&L Auto (M)
 Holidays
 21/12/2012
 67412034