

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9543K - AXA**AAD1712-185***Not Authorised
21 Sep 8340d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9543K - CANDY

KL1LA69RJB123946

CHEVROLET

CHEVROLET EPICA 2.0

18.12.2017

AXA**PART****LIST**

1	1	Front Fender RH	\$	R	837.60X
2	1	Front Fender Liner RH	\$	SL	47.00 X
3	1	Front Door RH	\$	nd/way	1,133.00 ✓
4	1	Front Door Glass Guide RH Chrome Moulding	\$	SL	60.00 X
5	1	Front Door Outer Handle RH	\$	SL	125.00 X
6	1	Front Door Hinge Upper RH	\$	R	65.00 X
7	1	Front Door Hinge Lower RH	\$	R	65.00 X
8	1	Front Side View Mirror RH	\$	SL	939.00 X
9	1	Side Rocker Panel Garnish RH	\$	way/nd	236.40 ✓
10	1	Rear Door RH	\$	nd/way	1,133.00 ✓
11	1	Rear Door Guide RH Chrome Moulding	\$	SL	60.00
12	1	Rear Door Outer Handle RH	\$	SL	125.00
13	1	Rear Door Weatherstrip RH	\$	SL	138.79
14	1	Rear Fender RH	\$	R	1,145.00
15	1	Rear Fender Inner Cowling RH	\$	SL	298.00
16	1	Rear Tail Lamp RH	\$	SL	479.30
17	1	Rear Bumper	\$	SL	1,202.00
18	1	Rear Bumper Beam	\$	R	239.94
19	1	Rear Bumper Centre Absorber	\$	SL	260.00
20	1	Rear Bumper Side Retainer RH	\$	SL	68.76
21	1	Rear Bumper Reflectors RH	\$	SL	119.74

TOTAL	\$	8,777.53
10%	\$	877.75
	\$	7,899.78

Special Nett

1	1 Set	Front Fender Liner Clip RH	\$	nn	30.00 X
2	1	Door Sticker "Trans-cab" RH	\$	nn	80.00 bosn
3	1	Door Sticker "6555-3333" RH	\$	nn	80.00 bosn

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-185**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9543K - AXA

4	1set	Side Rocker Panel Garnish Clip RH	\$	<i>nn</i> 60.00	
5	1	Rear Tyre RH	\$	<i>sn</i> 360.00	} <i>X</i>
6	1	Rear Wheel Rim RH	\$	<i>sn</i> 254.00	
7	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00	
9	1Set	Rear Bumper Parking Sensor	\$	<i>sn</i> 300.00	
10	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 30.00	
11	1Set	Rear Fender inner cowling clip RH	\$	<i>nn</i> 30.00	

TOTAL	\$	1,404.00
TOTAL PARTS	\$	9,303.78

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *500*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *60*

Putty and Spray Painting Of The Affected
Portion.

\$ 3,000.00 *1100*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

Towing Fees

\$ *nn* 120.00 *X*

To transfer of door fittings, attachment and
perform water seepage test.

\$ 170.00 *120*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 *X*

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 *X*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-185**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9543K - AXA

TOTAL	\$	7,210.00
Over All Total	\$	16,513.78

REPAIR DAYS~~10 DAYS~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6232.16