



CC3 / CTI170 74234, Kpa3

LKK:

IDAC:

INS. CASE OWNER:

ASSIGNMENT

20/12/17

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE

SLE 1565 L



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II : S\$

Is driver the owner? ( YES / NO )

D.O.A :

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHD 9913R



INSRS:

WSP:

Tel :

Liability :

RMKS:

Trans Cab



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
16-01-2018 2:10:30pm	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	( days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :
Repair Cost:	S\$	
Loss of Rental (LOR):	S\$	( days)
Loss of Use (LOU):	S\$	(\$ x days)
Loss of Income (LOI):	S\$	(\$ x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	S\$	
Medical:	S\$	
Disbursement:	S\$	(e.g. Tow/ Independent)
Legal Cost	S\$	
Total:	S\$	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/CTI17024234/Kqb

20 MCCALLUM STREET #09-01  
TOKIO MARINE CENTRESINGAPORE 069046

Date : 21-12-2017



Code : TMI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 1565L	Veh. Inspected	SHD 9913R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	18/12/2017	Inspection Date	20/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/CTI17024234/Kpa3

Date: 21.12.2017

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHD 9913R**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/12/2017 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	43,354.21
Revised Estimate Amount	: S\$	7,414.91
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Cenneth): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler Date 9/1/18

\*C: Critical \*N: Non-Critical

21/05/201

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 18 January 2018 3:09 PM  
**To:** Too Joon Hwa  
**Cc:** Priscilla Tan; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 18/12/2017, SHD 9913R (TP VEHICLE), SLE 1565L (OI VEHICLE)  
**Attachments:** SHD9913 ESTIMATE.pdf; SHD9913 GIA REPORT.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHD 9913R M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 20/12/2017

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9913R
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Dec 2017
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001177
Chassis No.:	VF1ABL15AUC277441
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$31,966.00
<b>Total Rebate Amount:</b>	<b>\$41,339.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Dec 2017

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2017 10:59
Date Of Accident	18/12/2017 15:40
Exact Location Of Accident	COMMONWEALTH AVENUE X HOLLAND AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9913R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	SOH KOK MENG
NRIC No	S1688247Z
Date Of Birth	23/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1985
Driving Experience	32 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98256665
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 226 TAMPINES STREET 23 #06-235
Postcode	521226
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Name	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Address	TEL NO: 1800-5529999 - FAX NO: 65561905
Police Station Contact	NO
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT : T/20171218/2153

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE1565L
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name

SOH KOK MENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD9913R

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police report -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171218/2153

1 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20171218/2153

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/12/2017 18:58	Vide Report No.:	Station Diary No.: 99
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: SOH KOK MENG			Address: APT BLK 226 TAMPINES STREET 23 #06-235 SINGAPORE 521226	
ID Type / ID No.: NRIC NO / S1688247Z			Contact No.: Home/Office:	Mobile: 98256665
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 52	Date of Birth: 23/04/1965	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B, 3, 4, 5	Date of Expiry:

## General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/12/2017 15:40	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 COMMONWEALTH AVENUE HOLLAND AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD9913R	Car					2
SLE1565L	Car					0

## Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

## POLICE REPORT Pg. 1



POLICE FORCE

T/20171218/2153

2 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20171218/2153

## CONTINUATION OF REPORT

Driver		ID No.		S1688247Z	
Name	SOH KOK MENG		Contact No.	98256665	
Related Vehicle	SHD9913R (Car)		Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL	
Hospital/Clinic	Unihealth 24 Hr Clinic (Ang Mo Kio)		Date Treatment	18/12/2017	
			Date Discharge	NIL	
			No. of Days granted Medical Leave	05	
			Degree of Injury	NIL	
Driver		ID No.		S8131109I	
Name	LIEW CHEE WAI		Contact No.	96994540	
Related Vehicle	SLE1565L (Car)		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Hospital/Clinic	NIL		Date Treatment	NIL	
			Date Discharge	NIL	
			No. of Days granted Medical Leave	NIL	
			Degree of Injury	NIL	

**Brief Details.**

On 18/12/2017 at about 3.40pm, I was driving my vehicle (SHD 9913 R) along Commonwealth Ave. When I was at the cross-junction of Holland Ave, in front of my vehicle, there was a bus. When the traffic light was in my favour, the bus turned right into Holland Ave. Hence, I moved gradually. Suddenly, there was one e-scooter just dashed in front of me. I managed to brake in time, however the vehicle at the rear (SLE 1565 L) unable to stop in time and hit my vehicle at the rear portion.

Due to the accident, I sustained some injury and went to see doctor. Then, I was given 5 days MC by the doctor. There was no in-built car camera inside my vehicle.



POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171218/2153

3 of 3

Report No. T/20171218/2153

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sr Staff Sgt SHAHRULWIJAYA BIN  
SAMSUDEEN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
Sr Staff Sgt LEE SOON LYE  
Contact No.: 65476239

Authentication Stamp  
NP168

Signature Of Informant:

*[Signature]*

Date/Time:  
18/12/2017 18:58

Classification Of Case:

*[Signature]*

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD9913R - CHINA TAIPING**

*Not Authorised*  
*21 Sep 8*  
**AAD1712-190**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD9913R - JHOW**  
**VF1ABL15AUC277441**  
**RENAULT**  
**LATITUDE**  
**18.12.2017**  
**CHINA TAIPING**

		<b>PART</b>		<b>LIST</b>
1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>B</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>D</i> 113.47 ✓
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>S</i> 135.97 X
5	1	BUMEP R RETAINER RH REAR	\$	<i>S</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>S</i> 43.61 X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>S</i> 135.97 X
8	1	BUMEP R RETAINER LH REAR	\$	<i>S</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>S</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>A</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>D</i> 225.95 ✓
13	1	BOOT REAR	\$	<i>R</i> 2,872.68 X
14	1	BOOT FINISHER	\$	<i>S</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>S</i> 323.05 ✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>S</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>S</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>R</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>S</i> 276.08
21	1	BOOT STRUT RH	\$	<i>S</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>S</i> 586.45
25	1	BOOT SWITCH	\$	<i>S</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>S</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>S</i> 221.81
30	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
31	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
32	1	TAILLAMP RH	\$	<i>S</i> 552.55
33	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
34	1	TAILLAMP LH	\$	<i>S</i> 552.55

X

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD9913R - CHINA TAIPING**

AAD1712-190

35	1	TAILLAMP PANEL LH	\$	R 986.70 X
36	1	OUTER PANEL REAR (End Panel)	\$	B 1,471.77 ✓
37	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm 404.56 ✓
38	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88 X
39	1	SPARE WHEEL PANEL TRIM	\$	su 612.21 X
40	1	EXHAUST REAR	\$	R 7,489.05 X
41	1	EXHAUST CAP REAR	\$	R 230.49 X

<b>TOTAL</b>	\$	<b>33,439.09</b>
<b>10%</b>	\$	<b>3,343.91</b>
	\$	<b>30,095.19</b>

**Specical Nett**

1	1SET	PARKING AID	\$	Shon 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	na 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	su 17.82 X
11	1SET	BOOT FINISHER CLIP	\$	na 24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	na 30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	na 30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	na 45.00 } X
15	1	TAILLAMP CLIP RH	\$	na 5.00 }
16	1	TAILLAMP CLIP LH	\$	na 5.00 }
17	2	REAR WINDSCREEN SELANT	\$	na 80.00 }
18	1	WINDSCREEN MOULDING	\$	na 100.00 }
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 }
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su 385.00 }
21	1	SPARE TYRE	\$	su 330.00 }

<b>TOTAL</b>	\$	<b>2,099.02</b>
<b>TOTAL PARTS</b>	\$	<b>32,194.21</b>

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 6601
To Rust-Proofing Of The Affected Areas.	\$	170.00 301

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD9913R - CHINA TAIPING**

AAD1712-190

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>600</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } <i>60</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

**TOTAL \$ 11,160.00**

**Over All Total \$ 43,354.21**

**(PARTS BY PARTS)**

**Repair Days**

- KKK Auto Consultants hence notify  
the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**15-Days**

*4 days*

*29.14.91*

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI17024234/KQBN2  
Date: 19/01/2018

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MH001023  
Claimant: SHD9913R Insured Vehicle No: SLE1565L  
Vehicle No: SHD9913R Nature of Claim: TP Claim No: M1706401  
Date of Loss: 18/12/2017

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD9913R Engine No: M9R8839C001177  
Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Chassis No: VF1ABL15AUC277441  
Reg. Date: 05/06/2014 (Man. Year: 2014) Odometer: 327531 km  
Colour: Metallic White/Red  
Engine Capacity: 1995 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Falken 6 mm Rear Left Side: Falken 8 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	32,194.19	6,004.91	26,189.28	81.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,160.00	1,410.00	9,750.00	87.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,354.19	7,414.91	35,939.28	82.90
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	43,354.19	5,950.00	37,404.19	86.28
+ GST 7.00/7.00% (S\$)	3,034.79	416.50	2,618.29	86.28
Nett Amount (S\$)	46,388.98	6,366.50	40,022.48	86.28

## INSPECTION

Date of Assignment: 19/01/2018  
Date Inspected: 20/12/2017 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111  
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9913R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Bent	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1	*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1	*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Cut	323.05 FL	*323.05 FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
31	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
32	1	*TAILLAMP RH	Serviceable	552.55 FL	*- FL
33	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
34	1	*TAILLAMP LH	Serviceable	552.55 FL	*- FL
35	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
36	1	*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
37	1	*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
38	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
39	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
40	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL
41	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
42	1	*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
43	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
44	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS

Report was unsubmitted during this print-out.



No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
46	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
47	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
48	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
49	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
50	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
51	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
52	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
53	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
54	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
55	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
56	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
57	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
58	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
59	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
60	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
61	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
62	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>35,538.10</b>	<b>6,569.34</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>3,343.91</b>	<b>564.43</b>
<b>Total Parts (\$\$)</b>	<b>32,194.19</b>	<b>6,004.91</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TOWING FEES	New	120.00	-
13	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (S\$)			11,160.00	1,410.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;