

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9913R - CHINA TAIPING*Not Authored*
*21 Sep 8***AAD1712-190**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9913R - JHOW

VF1ABL15AUC277441

RENAULT

LATITUDE

18.12.2017

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>B</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Dir</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>S</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>S</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>S</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>S</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>S</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>S</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>A</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Dir</i> 225.95 ✓
13	1	BOOT REAR	\$	<i>R</i> 2,872.68 X
14	1	BOOT FINISHER	\$	<i>S</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>S</i> 323.05 ✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>S</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>S</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>R</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>S</i> 276.08
21	1	BOOT STRUT RH	\$	<i>S</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>S</i> 586.45
25	1	BOOT SWITCH	\$	<i>S</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>S</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>S</i> 221.81
30	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
31	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
32	1	TAILLAMP RH	\$	<i>S</i> 552.55
33	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
34	1	TAILLAMP LH	\$	<i>S</i> 552.55

X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-190**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9913R - CHINA TAIPING

35	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 <i>X</i>
36	1	OUTER PANEL REAR (End Panel)	\$	<i>B</i> 1,471.77 <i>✓</i>
37	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm</i> 404.56 <i>✓</i>
38	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88 <i>X</i>
39	1	SPARE WHEEL PANEL TRIM	\$	<i>sn</i> 612.21 <i>X</i>
40	1	EXHAUST REAR	\$	<i>R</i> 7,489.05 <i>X</i>
41	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49 <i>X</i>

TOTAL	\$	33,439.09
10%	\$	3,343.91
	\$	30,095.19

Specical Nett

1	1SET	PARKING AID	\$	<i>Shan</i> 700.00 <i>✓</i>
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>✓</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>✓</i>
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 <i>✓</i>
10	1	EXHAUST MOUNTING REAR	\$	<i>sn</i> 17.82 <i>X</i>
11	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20 <i>X</i>
12	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 <i>✓</i>
13	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 <i>✓</i>
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00 <i>✓</i>
15	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00 <i>✓</i>
16	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00 <i>✓</i>
17	2	REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 <i>✓</i>
18	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00 <i>✓</i>
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 <i>✓</i>
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00 <i>✓</i>
21	1	SPARE TYRE	\$	<i>sn</i> 330.00 <i>✓</i>

TOTAL	\$	2,099.02
TOTAL PARTS	\$	32,194.21

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *669*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *301*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-190

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9913R - CHINA TAIPING

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	600
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	nn X
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 60
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	nn X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
Towing Fees	\$	120.00	nn X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X

TOTAL \$ 11,160.00**Over All Total \$ 43,354.21****(PARTS BY PARTS)****Repair Days**KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15-Days

4 days

24.4.91