



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2005 TOYOTA WISH 1.8 (SGA2823R)

Date of Loss

15 December 2017

Time of Loss

11.40

Loss Description

SGA2823R (INSD) HIT REAR OF SJS6900U (TP)

Comment

Workshop Details

Total Rebate Amount

47672

Nett Loss Amount

\$9,328.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

09/05/2018



Days of work completion *

138



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SGA2823R

Registration State

SINGAPORE

Mileage

201889

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2005

ASSESSMENT INFO...

2005

Purchase Date

dd/mm/yyyy



Registration Date *

12/11/2005



Age of Vehicle

12

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LIM KWEE KHENG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... WISH 1.8

ASSESSMENT INFO... WISH 1.8 A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... ZNE100272223

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... ZNE100272223

CATEGORY Engine No

POLICY INFORMAT... 1ZZ2405793

ASSESSMENT INFO... 1ZZ2405793

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1794

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 57000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1292916A



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

22/12/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/65R15

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

195/65R15

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts															
Add Approve Deny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BONNET			Damaged	0				0	Reviewing
		2	1			BONNET INNER RUBBER STRIP			Necessary	0				0	Reviewing
		3	2			BONNET HINGE			Serviceable	0	0	0	0	0	Deny
		4	1			BONNET MOULDING			Necessary	0				0	Reviewing
		5	1			BONNET TOYOTA EMBLEM			Serviceable	0	0	0	0	0	Deny
		6	1			BONNET LOCK			Bent	0				0	Reviewing
		7	2			BONNET RUBBER STOPPER			Necessary	0				0	Reviewing
		8	2			HEADLAMP (RHS&LHS)			Cracked	0				0	Reviewing
		9	1			FRONT BUMPER			Cracked	0				0	Reviewing
		10	1			FRONT BUMPER UPPER RETAINER			Necessary	0				0	Reviewing
		11	10			FRONT BUMPER CLIPS			Necessary	0				0	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			FRONT BUMPER SPONGE			Cracked	0				0	Reviewing
		13	2			FRONT BUMPER SIDE RETAINER			Necessary	0				0	Reviewing
		14	1			FRONT BUMPER LOWER GRILLE			Deformed	0				0	Reviewing
		15	10			FRONT BUMPER LOWER GRILLE CLIPS			Necessary	0				0	Reviewing
		16	10			FRONT BUMPER GRILLE CLIPS			Bent	0				0	Reviewing
		17	1			FRONT GRILLE UPPER COVER			Bent	0				0	Reviewing
		18	1			FRONT SUPPORT PANEL			Serviceable	0	0	0	0	0	Deny
		19	2			RADIATOR UPPER MOUNTING			Serviceable	0	0	0	0	0	Deny
		20	2			RADIATOR UPPER MOUNTING BRACKET			Serviceable	0	0	0	0	0	Deny
		21	1			RADIATOR			Serviceable	0	0	0	0	0	Deny
		22	1			RADIATOR FAN COWLING			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		23	1			RADIATOR ELECTRIC FAN ASSY			Serviceable	0	0	0	0	0	Deny
		24	1			RADIATOR OVER FLOW TANK			Serviceable	0	0	0	0	0	Deny
		25	1			WINDSCREEN WASHER TANK			Serviceable	0	0	0	0	0	Deny
		26	1			BONNET INSULATION			Serviceable	0	0	0	0	0	Deny
		27	1			BONNET INSULATION CLIPS			Necessary	0				0	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		1		LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS AND FITTINGS TO ENABLE REPAIRS; TO CUT & WELD FRONT END PANEL; }	400	0	0	Reviewing		
		2		TO STRAIGHTEN & REPAIRS BOTH HEADLAMPS SUPPORT PANELS, FRONT LHS & RHS FENDERS & INNER SUPPORT PANELS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE }	0	0	0	Reviewing		
		3		TO SPRAY PAINT ON: BONNET (INNER & OUTER), BOTH FRONT FENDERS & INNER PANELS, FRONT SUPPORT PANEL & HEADLAMP PANELS, FRONT BUMPER AND BONNET HINGES	400	0	0	Reviewing		
		4		TO REMOVE & REPLACE A/C CONDENSER C/W RECEIVER DRYER & REFIT A/C HOSES; TO VACUUM & CHARGE UP GAS	100	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		5		TO REMOVE & REPLACE RADIATOR & REFIT HOSES; TO PRESSURIZE RADIATOR & CHECK FOR LEAKAGE	40	0	0	Reviewing		
		6		TO REMOVE & REPLACE HEADLAMPS; TO CHECK ELECTRICAL WIRINGS & FOCUS HEADLIGHTS	30	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
☐		2	PARTS SUPPLIED BY AXAS SUPPLIER \$1471.00	Reviewing			
☐		3	FRONT NUMBER PLATE C/W HOLDER	Reviewing	45	DENTED	
☐		4	RADIATOR COOLANT	Reviewing	40	NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$1,055.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$970.00	\$970.00
Miscellaneous	\$85.00	\$85.00

Submit for Review