21-12-17;11:31 ;

1/ 10



<u>To</u>; Cq: LONPAC INSURANCE BHD

Bcc.

Subject.

SLS5773C CLAIMING AGAINST PC3958L DOA17122017 CHECK LIABILITY & ARRANGE SURVEY


Dear Sir/Madam,

Kindly assist to check liability for this case and arrange survey at CDGE braddell. Your insured vehicle number is PC3958L

Please see attached and reply as soon as possible.

Thanks.

Best Regards William Wang External Business | ComfortDelGro Engineering Pte Ltd Off: 6383 8115 | Fax: 6281 5767 www.SPARKcarcare.com



1st

21/12/2017



205 Braddell Road S(579701)

		ACC	IDENT F	REPAIR ESTIMATE	
Our Ref:					
Type of Claim:		TP		Vahiçle No.	: SLS5773C
			1000	Make & Model	NISSAN QASHQAI 1,2 DIG-T C
				Year of Manufacture	: 2017
				Chassis No.	: SJNFEAJ11U2009282
Ins Company : _	IIIVs	LONPA	<u> </u>	Engine No.	HRA2477688A
Excess ; _		-		Policy No.	
Date of Accident :	17.1	2.2017		Time of Accident	: 15:30
Suggested Days of Re	pair :			In-house Vehicle Asses	103
Repair Estimat	e			Case Owner	WILLIAM
Parts (a) Cost / List Pilus/Less Total of Cos (b) Nett Price its Loss Total of Nett (c) Special Nett Total Parts Cost (App Labour (Appendix B) Total Ropair Cost The above total will be	30% it / List ims 10% Item Items iondix A)	\$ 4 \$ 5 \$ 1,	,501.60 460,16 ,051.44 ,051.44 ,140.00 ,191.44	Signature Contact No Frt Counter Operation 63837466 – Patrick Tia 63837730 - Brenda Ng 63837890 – Rohani braddell_cr@sparkcarcarc Workshop Operation 63837656 - Ngo Toh Wee 63837362 - 63838115 - William Wang 63838115 - Andrew Go braddell_operation@spark	2.com : i h
Name of Surveyor Company Survey conducted o	п	: _		at	
Remarks By Survey	<u>or</u>				
	vehicle is au			norized until further notice,	
(с) Resurvey	,opc		equired / No		
(d) Excess		· S			

Date:

vacedent hepan estimatesys

(e) Signature of surveyor

Page 1

Spark Car Care ComfortDelGro Engineering Pte Ltd 205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLS5773C	Case Owner	:	WILLIAM
Make & Model	:	NISSAN QASHQAI 1.2 DIG	Year Manufacture	;	2017
Chassis No	:	SJNFEAJ11U2009282	Engine No	:	HRA2477688A
Sales Order	:		Supplier	;	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost	List	Nott	<u></u>	Disposition By
1	0	1	Prico	Price	Prico	SIN	Surveyor
2	Front bumper	1			\$ 614.60		
	Front bumper cover RH	1			\$ 614.60 \$ 102.00	***************************************	
4	Front bumper fog lamp RH	1			\$ 258.00	V	
	Front bumper retainer LH	1			\$ 21.00		
	Front bumper retainer RH	1					
7	Front bumper clips	1			\$ 21.00 \$ 41.00		
	RH headlamp	1			\$ 2,961.00		
	RH front fender arch garnish	1			\$ 483.00		
	0	1			3 463.00		
	0	1					
	0	1					
_	0	1					
	0	1					
	0	1	***************************************				
	0	1					
	0						
	0	1					
	0	1				.,	
	0	1	····				
	0	1					
	0	1					
	0	1					
	0	1					
	0	1					
	0	1					
	0	1			 		
	0	1					
	0	1		<u></u>			
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No.	:	SLS5773C	Case Owner	4	WILLIAM
Make & Model	;	SAN QASHQAI 1.2 DIG-T CVT	Year of Manufacture	•	2017

		-	2017
S/No	Labour Description	Esimated Price	Adjusted Price
1	Labour charges to repair and panel beat the RH front fender	\$600.00	
	and replace damaged parts. (per day \$240.00)		
2	To check wiring functions and focus headlamps.	\$40.00	
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
3	To putty, apply primer & spray-paint the front bumper, RH front	\$500.00	
	fender and affected areas, (per panel \$250.00)		
			<u></u>
······································			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

21-12-17;11:31 ;

MDHH17100440-01 / AJAX MARC PTE LTD - BURK MOTOR ENTRY DATE & TIME: 18/12/2017 21:20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to space up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Orlyon
- 3. Information provided must be an truthful and accurate as possible. Any wilful migrepresentation or witholding of material facts may taken insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any folse reporting may be referred to the Police for investigation.
- 6 This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the ledgement of this report to the insurars, you hereby consent to the trohiving of this report at the centre and to copies of the report being made available aforosald

ACCIDENT STATEMENT

Date Of Report 18/12/2017 21:25 Date Of Accident 17/12/2017 15:30

Exact Location Of Accident ALONG QUEEN STREET

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS5773C

Insured/Policyholder

Name Of Registered Owner COMFORTDELGRO RENT-A-CAR PTE LTD

Co Rog No 198105775H

Email Address DANNYNG@CDGRENTACAR.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-68820807

Vehicle Particulars

Manufacturer NISSAN

Model QASHQAI 1.2 DIG

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD Typo Of Coverage COMPREHENSIVE

Floot Policy YES Policy Number M460802 Cover Note Number NA

Driver

Name of Driver CHENG POEY HING

NRIC No S1424704A Date Of Birth 25/01/1960 Occupation INDOOR Date Of Driving Pass 01/01/2017

Driving Experience 0 YEAR AND 11 MONTH

Gender MALE

Mobile Number (LOCAL) +65-88692966

Fax Number Contact Number

EMpil Address MAXWINFMG@GMAIL,COM 21-12-17;11:31 ; # 6/ 10

Address

Postcode

Was driver an employee of the insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

.

NO

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance,

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If You against whom?

Circumstances of Accident

On 17 December 2017 at about 1530 hours my vehicle SLS5773C was approaching the exit of car park adjacent to Queen Stroot. After the traffic coming from my right was clear, I slowly moved onto Queen Street and slowly filter into the outer lane on the right(Intention to turn right at junction of Queen Street and Rocher Road). As I already move onto the lane 2, the outer most lane of YELLOW BOX JUNCTION, my car suddenly hit by vehicle no pC3958L on the right side front fender. The said vehicle was behind me at the exit of the carpark(footage from my video camera). The accident is recorded by my vehicle camera(front and back).

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Repsons: WILL FORWARD TO LEASING COMPANY

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC3958L

Vehicle Make/Model/Colour TOYOTA /HIACE COMMUTER

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Nanto

21-12-17;11:31 ; ; # 7/ 10

Phone Number Email Address 21-12-17;11:31 ;

Sketch Plan

SKETCH PLAN 雷强。

important notice

- The serve of the state of the serve of the s

VEHILL DY AJAK MARS reporting officer


Multarement (strail

isservindales indesputa (1976 de coma esconara, bugadous illumanta esconara por encepta de coma esconara por e

Air Pacille Volgasasa by Kapadang Cocus

SERVER OF

Skoten Rian



Common Statement

ACCIDEM	STATEMENT	(2000	characters)
---------	-----------	-------	-------------

clear, a slowly moved onto Queen Street in Gueen Street in the street of	nours my vehicle SLS5773C was approaching Street. After the traffic coming from my right was and slowly filter into the outer lane on the of Queen Street and Rochor Road). As i already ane of YELLOW BOX JUNCTION, my car the right side front lender. The said vehicle was stage from my video camera). The accident is not back).
‡axi Voyaner teg	
DECLARATION	
We declare that the above particulars & information prov	
The state of the s	aled above are true in overy anises
VERIFIED BY AJAX MARS REPORTING OPPICER MUHAMAMA FAIZAL GIN PABILA	akid abang aro true in overy anpena
VERIFIED BY AJAX MARS REPORTING OFFICER	aked above and true in divery ampieca
VERIFIED BY AJAX MARS REPORTING OPPICER MUHAMAMO FAIZAL GIN PABILA	Peophesial Corne or Covers Segundaria
VERIFIED BY AJAX MARS REPORTING OPPICER MUHAMMAD FAIZAL GIN PABILA	

21-12-17;11:31 ; # 10/ 10

Individual Statement

On 17 December 2017 at about 15 300 hours my vibide SIS5773C was approaching the exit of car. parkadjaceta to Queen's Street ofter the traffic coming from my right was clear; I slowly moved onto Cruner Street and slowly litter into the outer lane on the right (intention to sure right at Junction of Queen Street and Rother Road. As I already move onto the lane? (see diagram), the outer most lane of Yellow Box (Unction, my carwas sufficiently his by vehicle no) $\frac{\partial \mathcal{L}}{\partial \mathcal{L}} = \frac{\partial \mathcal{L}}{\partial \mathcal{L}}$ on the right side from funder. The said vehicle was behind me at the exit of the carpack (footage from my video camera). the accident is incorded by my value is eamera (front and back).