

Surveyor

REF: CS/LAW/7024261/Uthn2

Special Instruction:

45: \$9000.00

## ASSIGNMENT (Office)

From (Person): Igene Lim of M Nedumaran Date/Time: 15-12-2017

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: MC-COY Appraiser

Workshop: Blumel Automotive

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: SJT 5541Z Insured: SJL 1441Y

at Workshop m/s Blumel Automotive Tel: 6745 2088

of Blk 1 Kaki Bukit Ave 6 #01-28

Policy No: Claim No: MN-76-B1-1711606

Sum Insured: Excess:

Make of Veh: D.O.A. 11-05-2017

(Client's Record)

27.12.2017 (Wednesday) @ 5pm

SJE

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 14 days)

Date/Time: 16/1/2018 Submit Final Fig 7200, 12 days (Red \$ 800 / 20 %; Original 14 days)

Date/Time	Action/Instruction
	SJT 5541Z - X Alu
	SJT 1441Y - X
	Sum 457200 12/1/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 16 JAN 2018

## Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

Basic &amp; Add

Transport

Photos

Others

Total

Date:

1000

- 1) Date/Time File Pass to 2) Date/Time File Return to
- 3) Date/Time File Pass to 4) Date/Time File Return to
- 5) Date/Time File Pass to 6) Date/Time File Return to

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 51TS3412 Yr Regn: 10 / 09  
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Nissan 2410 d.c. 1498  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 18422 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JN1FAAC112 0010692  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 205/50R16  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or FALKEN  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. \_\_\_\_\_ D.O.I. 27/12/17  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_

) \$ - RS \$

) Photos

) Other

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
M NEDUMARAN & CO*			Ref : CS/LAW17024261/Utb	
No. 11 SIN MING ROAD #B2-09 (UNIT 2), THOMSON V TWO SINGAPORE 575629			Date : 22-12-2017	
			Code : L134	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	SJL 1441Y	Veh. Inspected	SJT 5541Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	MN.IG.B1.1711606	Excess (\$)	0.00	
Assign From	IGENE LIM	Assign Date	15/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	11/05/2017	Inspection Date	27/12/2017	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Catherine Chong (LKK Auto)**

---

**From:** Igene Lim <igene.lim@mneduco.com.sg>  
**Sent:** Friday, 15 December, 2017 5:45 PM  
**To:** Celine Fong (LKKAuto); Catherine Chong (LKK Auto); 'SUR'; 'assignments'  
**Cc:** info@kepartnership.com  
**Subject:** RE: APPOINTMENT OF SINGLE JOINT EXPERT // ACCIDENT ON 11/5/2017 INVOLVING VEHICLE NOS. SJT 5541Z, SLF 9607S & SJL 1441Y // KELVIN CHIA PARTNERSHIP'S REF NO. : AK/SK/zi/2017002792.AIG (mpd)

27.12.2017 @ 5pm

WITHOUT PREJUDICE

**MC SUIT NO. 14250/2017**

Our Ref : MN.IG.B1.1711606

Dear Sir/Mdm,

Further to our email below, in compliance with the Court's direction, we have made an arrangement for the Plaintiff's motor vehicle **SJT 5541Z** to be available for re-inspection on:

**Date** : 21<sup>st</sup> December 2017 (Thursday)  
**Time** : 9.00 a.m.  
**Venue** : 1 Kallang Way, 2A Car park  
**Contact** : Mr Leong @ 9727-5845

Kindly ensure that the appointed surveyor, Chua Kang Seng attends to the above without fail.

**Please also let us have your written confirmation on the above arrangement soon.**

With thanks & regards,

**IGENE LIM (MS)**

*(For and on behalf of Mr Nedumaran Muthukrishnan)*

**M NEDUMARAN & CO**

**Advocates & Solicitors**

**Commissioner for Oaths**

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

**From:** Igene Lim

**Sent:** Friday, December 15, 2017 12:15 PM

**To:** 'Celine Fong (LKKAuto)' <celinefong@lkkauto.com>; 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

**Cc:** 'info@kepartnership.com' <info@kepartnership.com>

**Subject:** APPOINTMENT OF SINGLE JOINT EXPERT // ACCIDENT ON 11/5/2017 INVOLVING VEHICLE NOS. SJT 5541Z, SLF 9607S & SJL 1441Y // KELVIN CHIA PARTNERSHIP'S REF NO. : AK/SK/zi/2017002792.AIG (mpd)

WITHOUT PREJUDICE

**MC SUIT NO. 14250/2017**

Our Ref : MN.IG.B1.1711606

Dear Sir/Mdm,

We refer to the above-captioned matter.

We act for the Plaintiff (motor vehicle no. SJT 5541Z) and M/s Kelvin Chia Partnership acts for the Defendant (motor vehicle no. SLF 9607S) in the abovementioned suit arising out of a road traffic accident on 11 May 2017.

Please be informed that by consent of all parties, **CHUA KANG SENG** is appointed as a Single Joint Expert ("hereinafter referred to as SJE") for this action to provide an independent assessment in respect of the costs of repairs for vehicle no. SJT 5541Z. Mr Chua Kang Seng is to determine the issue on quantum and to draw up an Affidavit of Evidence in Chief (AEIC) annexing a copy of the re-inspection report on the Plaintiff's vehicle SJT 5541Z.

Kindly note that as a Single Joint Expert appointed by the Court, your primary duty is to the Court and you are required to give a fair and reasonable assessment of costs for the Plaintiff's motor vehicle SJT 5541Z.

We enclose herewith relevant document as follows:

- (1) The Plaintiff's GIA report;
- (2) Plaintiff's final repair bill;
- (3) Plaintiff's surveyor's report by Mc-Coy Appraiser Pte Ltd;
- (4) 150 coloured photos depicting damage to the Plaintiff's vehicle; and
- (5) Defendant's surveyor's adjustment on the cost of repairs during pre-repair inspection.

We would be grateful if your surveyor Mr Chua Kang Seng could let us know whether you will be available to conduct a re-inspection on the Plaintiff's motor vehicle SJT 5541Z.

Thereafter, you are required to produce your re-surveyed report, inter alia, the estimated cost of repairs and number of days for repairs to the Plaintiff's motor vehicle, as well as the reason for the same.

Meanwhile, please also let us know the fees/costs chargeable for the re-inspection, preparation of the re-inspection report and affirmation of the Affidavit of Evidence in Chief with regard to the Plaintiff's motor

vehicle SJT 5541Z. We would also like to know the fees chargeable for the surveyor's attendance in Court should this matter proceed for a half day hearing.

Should you require further clarification on the above, please do not hesitate to call our Ms Igene Lim at 66509-8480.

With thanks & regards,

**IGENE LIM (MS)**

*(For and on behalf of Mr Nedumaran Muthukrishnan)*

**M NEDUMARAN & CO**

**Advocates & Solicitors**

**Commissioner for Oaths**

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/05/2017 16:43
Date Of Accident	11/05/2017 13:15
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT5541Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEONG SAI MUN
NRIC No	S8400297F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97275845
Alternative Phone No	OFFICE-97275845

### Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO-1.5 L (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3059591600
Cover Note Number	

### Driver

Name of Driver	LEONG SAI MUN
NRIC No	S8400297F
Date Of Birth	10/01/1984
Occupation	INDOOR
Date Of Driving Pass	28/04/2010
Driving Experience	7 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97275845
Fax Number	
Contact Number	OFFICE-97275845
Email Address	NOEMAIL



Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION- CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJL1441Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address



#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLF9607S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

# Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan

A - SJ75541Z  
B - SLF9607S  
C - SJL1441Y

Geylang Road

Describe Circumstances of the Accident

Handwritten text: *Police Report*

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time: *[Signature]*  
Driver's Signature (If driver is not the policyholder) / Date & Time: *12/5/17, 1240PM*  
Witnessed by Reporting Centre Personnel: *[Signature]*



Insurance Co. \_\_\_\_\_  
Vehicle NO. \_\_\_\_\_ Date Of Accident \_\_\_\_\_  
☐ Reporting Only  
☐ Own Damage Claim  
☐ Third Party Claim



**SINGAPORE  
POLICE FORCE**



T/20170512/2048

1 of 4

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

Report No. T/20170512/2048

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 12/05/2017 12:07	Vide Report No.:	Station Diary No.: 34
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: LEONG SAI MUN			Address: APT BLK 625 ANG MO KIO AVENUE 9 #09-102 SINGAPORE 560625		
ID Type / ID No.: NRIC NO / S8400297F			Contact No.: Home/Office: Mobile: 97275845		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 10/01/1984	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: FACILITY MANAGEMENT SALES MANAGER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/05/2017 13:15	Type of Location: Straight Road
Location: Along Road 1 GEYLANG ROAD				
lane 2		Road Surface: Dry	Road Speed Limit:	
Weather: Clear		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Traffic Flow: One Way				Anyone conveyed by ambulance: No
Type of Collision: Moving Vehicle Against - Stopped Vehicle				

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL1441Y	Car	SUBARU			Slightly Damaged	0
SJT5541Z	Car	NISSAN	LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D	Grey	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20170512/2048

2 of 4

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

Report No. T/20170512/2048

**CONTINUATION OF REPORT**

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLF9607S	Car	HONDA		Grey	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJT5541Z	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30329817 01	19/04/2017	18/04/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LEO ANN WUANG		ID No.	S7640188H
Related Vehicle	SJL1441Y (Car)		Contact No.	96392753
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	LEONG SAI MUN		ID No.	S8400297F
Related Vehicle	SJT5541Z (Car)		Contact No.	97275845
Hospital/Clinic	KHO CLINIC		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	12/05/2017		Date Discharge	12/05/2017
No. of Days granted Medical Leave		04	Degree of Injury	Slight



**SINGAPORE  
POLICE FORCE**



T/20170512/2048

3 of 4

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

Report No. T/20170512/2048

**CONTINUATION OF REPORT**

Driver			
Name	LIM KEN MING	ID No.	S7663869A
Related Vehicle	SLF9607S (Car)	Contact No.	96936786
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 11/05/2017 @ 1315hrs, I was in my stationary car, SJT5541Z, in lane 2 of Geyland Road as there was a traffic jam. Just as I was about to move off, I felt a hard impact coming from the rear of my car. The impact was so hard that it pushed my car forward and hit the car in front of mine, SJL1441Y. I went down from my car and realized that a car, SLF9607S had collided onto the rear of my car. At that point of time, no one seems injured and after exchanging particulars, all three of us left the scene. On 12/05/2017, I did not feel well and went to see a doctor where I was given 4 days of medical leave. I have an in-car camera installed in my car, both forward and rear facing. The footages from my in-car camera shows how the accident happened. That's all.



**SINGAPORE  
POLICE FORCE**



T/20170512/2048

4 of 4

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

Report No. T/20170512/2048

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt MOHAMMAD FADZLI BIN JAMALUDIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

12/05/2017 12:07

Officer In Charge Of Case:

TP / AEIT /

TAN SIEW GEK

Contact No.: 65476230

Classification Of Case:

SELF

Authentication Stamp

NP168



**Enquire Transfer Fee****Vehicle Details**

Vehicle No. : SJT5541Z  
 Vehicle Type : P10 - Passenger Motor Car  
 Vehicle Attachment 1 : No Attachment  
 Vehicle Scheme : Normal  
 Vehicle Make : NISSAN  
 Vehicle Model : LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D  
 Chassis No. : JN1FAAC11Z0010692  
 Propellant: Petrol  
 Engine No. : HR15138992B  
 Engine Capacity : 1498 cc  
 Maximum Power Output: 80.0 kW (107 bhp)  
 Maximum Laden Weight: 1455 kg  
 Unladen Weight: 1150 kg  
 Year Of Manufacture: 2009  
 Original Registration Date: 19 Oct 2009  
 Lifespan Expiry Date : -  
 COE Category : A - Car (1600cc & below)  
 Quota Premium : \$16,201.00  
 COE Expiry Date : 18 Oct 2019  
 Road Tax Expiry Date : 18 Oct 2017  
 PARF Eligibility Expiry Date : 18 Oct 2019  
 Inspection Due Date : 18 Oct 2018  
 Intended Transfer Date : 11 May 2017  
 CO2 Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
<b>Total Amount Payable :</b>			<b>11.00</b>

You may print this page for reference.

OK

Print

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-51/53/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: [www.bluwel.com.sg](http://www.bluwel.com.sg) Email: [bluwel2088@yahoo.com.sg](mailto:bluwel2088@yahoo.com.sg)  
Co. Reg. No.: 200704951N  
GST Reg. No.: 200704951N

Vehicle No : SJT 5541 Z  
Make/Model : Nissan Latio  
Name : Leong Sai Mun  
Address : c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

Date : 21-Jul-17

QTY	ITEM	AMT (\$\$)
-----	------	------------

Lump sum repair costs

	\$	9,000.00
GST 7 %	\$	630.00
Grand-total	\$	<u>9,630.00</u>

Dollars : Nine Thousand Six Hundred And Thirty Only

# MC-COY

## APPRAISER PTE LTD

No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017  
Registration No.: 200723252D

Invoice No 17017-05/MY

Billing Name & Address

Date 21 Jul 2017

Leong Sai Mun  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

Vehicle No : SJT 5541 Z

Model : Nissan Latio

Item	Descriptions	Amount S\$
1	Date of inspection : <u>12 May 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>150</u> copies	
3	Transportation Charges	
4	2nd Inspection <span style="float: right;">Total</span>	<u>\$ 770.00</u>
	SDLS : SEVEN HUNDRED AND SEVENTY ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017  
Registration No.: 200723252D

Report Reference : TP / 17017-05/MY / 2017  
Date of Report : 21 Jul 2017

Leong Sai Mun  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

**THIRD PARTY SURVEY  
ACCIDENT HAPPENED ON 11 May 2017**

Workshop Address : Bluwel Automotive Service Pte Ltd  
No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

As per your instruction dated **12 May 2017** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SJT 5541 Z**. We enclosed herewith our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: SJT 5541 Z	Engine No	: HR15138992B
Model	: Nissan Latio	Mileage	: 173724
Year / Capacity	: 2009/1498	Colour	: Grey
Chassis No	: JN1FAAC11Z0010692		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 205/50 R16	Falken	4.00	mm	Sport
REAR O/S	: 205/50 R16	Falken	6.00	mm	Sport
FRONT N/S	: 205/50 R16	Falken	4.00	mm	Sport
REAR N/S	: 205/50 R16	Falken	6.00	mm	Sport

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete.
5. Enclosed number of photograph : 150 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJT 5541 Z  
 Report No: TP/ 17017-05/MY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

Spare Parts Sub Total c/f \$ 8043.83 \$ 6698.15

Special Nett Items

1	Front bumper clip (1 set)	Necessary	\$ 35.00	\$ 35.00 ✓
1	Front bumper fog lamps	Intact	\$ 559.00	\$ <i>Nil</i>
1	Rear windscreen seal	Necessary	\$ 85.00	\$ 85.00 <i>40</i>
1	Rear windscreen sealant	Necessary	\$ 50.00	\$ 50.00 ✓
1	Rear bumper clip (1 set)	Necessary	\$ 35.00	\$ 35.00 ✓
1	Rear number plate	Damage	\$ 50.00	\$ 50.00 <i>40</i>
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00 <i>200</i>
1	Rear spare tyre insulator (1 set)	Necessary	\$ 150.00	\$ 150.00 <i>100</i>
			<u>\$ 1244.00</u>	<u>\$ 685.00</u>

*860*

Spare Parts Total \$ 9287.83 \$ 7383.15

Vehicle No: SJT 5541 Z  
Report No: TP/ 17017-05/MY / 2017

# SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet	Damage	\$ 972.70	\$ 972.70 ✓
1	Front bumper	Damage	\$ 436.00	\$ 436.00 ✓
1	Front bumper inner sponge	Damage	\$ 207.20	\$ 207.20 ✓
1	Front bumper reinforcement	Intact	\$ 444.90	\$ 444.90 ✓
2	Front bumper side retainers	Necessary	\$ 57.60	\$ 57.60 ✓
1	Rear tailgate	Damage	\$ 1314.80	\$ 1314.80 ✓
1	Rear end panel	Damage	\$ 442.60	\$ 442.60 ✓
1	Rear bumper	Damage	\$ 551.00	\$ 551.00 ✓
1	Rear bumper bracket	Damage	\$ 91.70	\$ 91.70 ✓
2	Rear bumper side retainers	Damage	\$ 65.40	\$ 65.40 ✓
1	Rear number plate bracket	Damage	\$ 61.70	\$ 61.70 ✓
1	Rear spare tyre panel	Damage	\$ 771.40	\$ 771.40 ✓
1	Rear fender	Repair	\$ 1052.70	\$ 1052.70 ✓
			\$ 6469.70	\$ 4972.10
	Discount	30.0%	\$ 1940.91	\$ 1491.63
			\$ 4528.79	\$ 3480.47
<u>Nett Items</u>				
2	Front headlamps	Damage	\$ 599.20	\$ 599.20 ✓
1	Front grille	Damage	\$ 161.20	\$ 161.20 ✓
2	Rear tailgate dampers	Intact	\$ 330.40	\$ 330.40 ✓
1	Rear tailgate inner board	Damage	\$ 219.70	\$ 219.70 ✓
1	Rear tailgate inner lock	Damage	\$ 48.60	\$ 48.60 ✓
1	Rear tailgate outer handle	Damage	\$ 135.70	\$ 135.70 ✓
1	Rear tailgate rubber	Necessary	\$ 98.60	\$ 98.60 ✓
1	Rear tailgate 'NISSAN' emblem	Necessary	\$ 42.80	\$ 42.80 ✓
1	Rear tailgate 'LATIO' emblem	Necessary	\$ 52.70	\$ 52.70 ✓
1	Rear wiper motor	Damage	\$ 405.40	\$ 405.40 ✓
2	Rear taillamps	Damage	\$ 438.80	\$ 438.80 ✓
1	Rear end panel inner garnish	Damage	\$ 73.10	\$ 73.10 ✓
1	Rear end panel smart sensor	Damage	\$ 188.50	\$ 188.50 ✓
1	Rear bumper inner sponge	Damage	\$ 35.60	\$ 35.60 ✓
1	Rear number plate lamp	Damage	\$ 42.60	\$ 42.60 ✓
1	Rear exhaust silencer	Damage	\$ 464.40	\$ 464.40 ✓
3	Rear exhaust silencer mountings	Necessary	\$ 172.80	\$ 172.80 ✓
1	Rear fender inner trim board	Necessary	\$ 395.50	\$ 395.50 ✓
			\$ 3905.60	\$ 3575.20
	Discount	10.0%	\$ 390.56	\$ 357.52
			\$ 3515.04	\$ 3217.68
	Spare Parts Sub Total		\$ 8043.83	\$ 6698.15



Vehicle No: **SJT 5541 Z**  
 Report No: **TP/ 17017-05/MY / 2017**


**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9287.83	\$ 7383.15
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00 <i>20</i>
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00 <i>20</i>
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 200.00	\$ 140.00 <i>60</i>
4	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00 <i>50</i>
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 <i>✓</i>
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1900.00	\$ 1540.00 <i>1200</i>
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1900.00	\$ 1760.00 <i>1600</i>
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 150.00 <i>60</i>
<b>Total</b>		<u>\$ 13857.83</u>	<u>\$ 11253.15</u> <i>3050</i>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9000.00

SDLS: NINE THOUSAND ONLY

  
 Qualified Appraiser

Vehicle No: **SJT 5541 Z**  
 Report No: **TP/ 17017-05/MY / 2017**

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

<u>List Items</u>				
1	Bonnet	Damage	\$ 972.70	\$ 972.70 X
1	Front bumper	Damage	\$ 436.00	\$ 436.00 /
1	Front bumper inner sponge	Damage	\$ 207.20	\$ 207.20 X
1	Front bumper reinforcement	Intact	\$ 444.90	\$
2	Front bumper side retainers	Necessary	\$ 57.60	\$ 57.60 X
1	Rear tailgate	Damage	\$ 1314.80	\$ 1314.80 /
1	Rear end panel	Damage	\$ 442.60	\$ 442.60 /
1	Rear bumper	Damage	\$ 551.00	\$ 551.00 /
1	Rear bumper bracket	Damage	\$ 91.70	\$ 91.70 /
2	Rear bumper side retainers L <sup>1</sup>	Damage	\$ 65.40	\$ 65.40 32.70
1	Rear number plate bracket	Damage	\$ 61.70	\$ 61.70 /
1	Rear spare tyre panel	Damage	\$ 771.40	\$ 771.40 R
1	Rear fender	Repair	\$ 1052.70	\$
			\$ 6469.70	\$ 4972.10
Discount 30.0%			\$ 1940.91	\$ 1491.63
			\$ 4528.79	\$ 3480.47
				1741.53
<u>Nett Items</u>				
2	Front headlamps	Damage	\$ 599.20	\$ 599.20 X
1	Front grille	Damage	\$ 161.20	\$ 161.20 /
2	Rear tailgate dampers	Intact	\$ 330.40	\$
1	Rear tailgate inner board	Damage	\$ 219.70	\$ 219.70 X
1	Rear tailgate inner lock	Damage	\$ 48.60	\$ 48.60 X
1	Rear tailgate outer handle	Damage	\$ 135.70	\$ 135.70 X
1	Rear tailgate rubber	Necessary	\$ 98.60	\$ 98.60 /
1	Rear tailgate 'NISSAN' emblem	Necessary	\$ 42.80	\$ 42.80 /
1	Rear tailgate 'LATIO' emblem	Necessary	\$ 52.70	\$ 52.70 /
1	Rear wiper motor	Damage	\$ 405.40	\$ 405.40 X
2	Rear taillamps L <sup>1</sup>	Damage	\$ 438.80	\$ 438.80 219.40
1	Rear end panel inner garnish	Damage	\$ 73.10	\$ 73.10 /
1	Rear end panel smart sensor	Damage	\$ 188.50	\$ 188.50 X
1	Rear bumper inner sponge	Damage	\$ 35.60	\$ 35.60 /
1	Rear number plate lamp	Damage	\$ 42.60	\$ 42.60 /
1	Rear exhaust silencer	Damage	\$ 464.40	\$ 464.40 X
3	Rear exhaust silencer mountings	Necessary	\$ 172.80	\$ 172.80 X
1	Rear fender inner trim board	Necessary	\$ 395.50	\$ 395.50 X
			\$ 3905.60	\$ 3575.20
Discount 10.0%			\$ 390.56	\$ 357.52
			\$ 3515.04	\$ 3217.68
Spare Parts Sub Total			\$ 8043.83	\$ 6698.15
				652.40

Vehicle No: **SJT 5541 Z**  
 Report No: **TP/17017-05/MY / 2017**

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

Spare Parts Sub Total c/f      \$      8043.83      \$      6698.15

Special Nett Items

1	Front bumper clip (1 set)	Necessary	\$      35.00	\$      35.00 20/=
1	Front bumper fog lamps	Intact	\$      559.00	\$
1	Rear windscreen seal	Necessary	\$      85.00	\$      85.00 40/=
1	Rear windscreen sealant	Necessary	\$      50.00	\$      50.00 -
1	Rear bumper clip (1 set)	Necessary	\$      35.00	\$      35.00 20/=
1	Rear number plate	Damage	\$      50.00	\$      50.00 45
1	Rear reverse sensor (1 set)	Damage	\$      280.00	\$      280.00 200
1	Rear spare tyre insulator (1 set)	Necessary	\$      150.00	\$      150.00 100/=
			<u>\$      1244.00</u>	<u>\$      685.00</u>

475/=

Spare Parts Total      \$      9287.83      \$      7383.15

Vehicle No: **SJT 5541 Z**  
 Report No: **TP/ 17017-05/MY / 2017**

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9287.83	\$ 7383.15
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00 30/=
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00 30/=
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 200.00	\$ 140.00 100/=
4	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00 30/=
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 -
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. <i>4 day</i>	\$ 1900.00	\$ 1540.00 1400/=
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1900.00	\$ 1760.00 1000/=
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 150.00 60/=

**Total**    \$ 13857.83    \$ 11253.15


*2770/=*

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9000.00

*Total: 5639. 93, 7 day*

SDLS: NINE THOUSAND ONLY

  
 Qualified Appraiser



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

M NEDUMARAN & CO\*

Ref : CS/LAW17024261/Utbn2

No. 11 SIN MING ROAD  
#B2-09 (UNIT 2), THOMSON V TWO  
SINGAPORE 575629

Date : 17-01-2018



Code : L134

## 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SJL 1441Y	Veh. Inspected	SJT 5541Z
Policy No.		Coverage (\$)	0.00
Claim No.	MN.IG.B1.1711606	Excess (\$)	0.00
Assign From	IGENE LIM	Assign Date	15/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1FAAC11Z0010692	Colour	GREY
Odometer	184221	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	5 mm
L/H Front Tyre	205/50 R16	FALKEN	5 mm
R/H Rear Tyre	205/50 R16	FALKEN	5 mm
L/H Rear Tyre	205/50 R16	FALKEN	5 mm

## 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

## 5. General Information

Accident Date	11/05/2017	Inspection Date	27/12/2017
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5541Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	REPAIRED SEE LABOUR	972.70	-
1	FRONT BUMPER	REPLACED	436.00	436.00
1	FRONT BUMPER INNER SPONGE	REPLACED	207.20	207.20
1	FRONT BUMPER REINFORCEMENT	NOT CHANGED	444.90	-
2	FRONT BUMPER SIDE RETAINERS	REPLACED	57.60	57.60
1	REAR TAILGATE	REPLACED	1,314.80	1,314.80
1	REAR END PANEL	REPLACED	442.60	442.60
1	REAR BUMPER	REPLACED	551.00	551.00
1	REAR BUMPER BRACKET	REPLACED	91.70	91.70
2	REAR BUMPER SIDE RETAINERS	REPLACED	65.40	65.40
1	REAR NUMBER PLATE BRACKET	REPLACED	61.70	61.70
1	REAR SPARE TYRE PANEL	REPAIRED SEE LABOUR	771.40	-
1	REAR FENDER	REPAIRED SEE LABOUR	1,052.70	-
	LESS 30% DISCOUNT		-1,940.91	-968.40
			4,528.79	2,259.60
<b>NETT ITEMS</b>				
2	FRONT HEADLAMPS (N)	REPLACED	599.20	599.20
1	FRONT GRILLE (N)	REPLACED	161.20	161.20
2	REAR TAILGATE DAMPERS (N)	NOT CHANGED	330.40	-
1	REAR TAILGATE INNER BOARD (N)	REPLACED	219.70	219.70
1	REAR TAILGATE INNER LOCK (N)	REPLACED	48.60	48.60
1	REAR TAILGATE OUTER HANDLE (N)	NOT NECESSARY	135.70	-
1	REAR TAILGATE RUBBER (N)	REPLACED	98.60	98.60
1	REAR TAILGATE "NISSAN" EMBLEM (N)	REPLACED	42.80	42.80
1	REAR TAILGATE "LATIO" EMBLEM (N)	REPLACED	52.70	52.70
1	REAR WIPER MOTOR (N)	REPLACED	405.40	405.40
2	REAR TAILLAMPS (N)	REPLACED	438.80	438.80
1	REAR END PANEL INNER GARNISH (N)	REPLACED	73.10	73.10

Report Ref No. CS/LAW17024261/Utn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SMART SENSOR (N)	REPLACED	188.50	188.50
1	REAR BUMPER INNER SPONGE (N)	REPLACED	35.60	35.60
1	REAR NUMBER PLATE LAMP (N)	REPLACED	42.60	42.60
1	REAR EXHAUST SILENCER (N)	REPLACED	464.40	464.40
3	REAR EXHAUST SILENCER MOUNTINGS (N)	REPLACED	172.80	172.80
1	REAR FENDER INNER TRIM BOARD (N)	REPLACED	395.50	395.50
	LESS 10% DISCOUNT		-390.56	-343.95
			3,515.04	3,095.55
	<b>SPECIAL NETT ITEMS</b>			
1	SET FRONT BUMPER CLIP (SN)	REPLACED	35.00	35.00
1	FRONT BUMPER FOG LAMPS (SN)	NOT CHANGED	559.00	-
1	REAR WINDSCREEN SEAL (SN)	REPLACED	85.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	REPLACED	50.00	50.00
1	SET REAR BUMPER CLIP (SN)	REPLACED	35.00	35.00
1	REAR NUMBER PLATE (SN)	REPLACED	50.00	40.00
1	SET REAR REVERSE SENSOR (SN)	REPLACED	280.00	200.00
1	SET REAR SPARE TYRE INSULATOR (SN)	REPLACED	150.00	100.00
			1,244.00	500.00
	<b>LABOUR</b>			
	TO REMOVE AND REFIT DAMAGE PARTS,TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		60.00	20.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING,REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		60.00	20.00
	TO REMOVE AND REFIT INNER TRIMS,INNER GARNISHES,TO FACILITATE THE REPAIRS.		200.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		120.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BONNET,REAR SPARE TYRE PANEL AND REAR FENDER.		1,900.00	1,200.00

Report Ref No. CS/LAW17024261/Utn2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,900.00	1,600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	60.00
			4,570.00	3,150.00
GRAND TOTAL			13,857.83	9,005.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,200.00

Report Ref No. CS/LAW17024261/Utbn2

  
CHUA KANG SENG  
Licensed Appraiser

  
K.K.LAU CPT(RET)  
BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE  
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.