

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5463D - AIG

Not Authorised
LLP \$137000

AAD1712-213

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5463D - JHOW
 VF1ABL15AUC280948
 RENAULT
 LATITUDE
 20.12.2017
AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	Bu 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	SL 181.75 X
3	1	BUMPER ABSORBER FRT	\$	SL 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	Dir 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	SL 123.88
6	1	BUMPER RETAINER FRT RH	\$	SL 150.77
7	1	BUMPER SUPPORT FRT	\$	SL 123.88
8	1	BUMPER UNDERTRAY FRT	\$	SL 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	SL 266.80 } X
10	1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21
12	1	BUMPER BEAM FRT	\$	R 914.08
13	1	TOW COVER FRT	\$	SL 28.61
14	1	RADAITOR GRILLE	\$	CM 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36 ✓
16	1	RADAITOR GRILLE FRAME	\$	CM 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	CM 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
19	1	FRONT BRACE PANEL	\$	R 177.22
20	1	HORN	\$	SL 314.17
21	1	HORN BRACKET	\$	R 40.45
22	1	HEADLALMP LH	\$	SL 1,184.43
23	1	HEADLALMP RH	\$	SL 1,184.43
24	1	HEADLAMP PANEL FRT LH	\$	R 152.15
25	1	HEADLAMP PANEL FRT RH	\$	R 152.15 } X
26	1	BONNET	\$	R 1,941.63
27	1	BONNET INSULATOR	\$	SL 405.73
28	1	BONNET STRUT LH	\$	SL 88.61
29	1	BONNET STRUT RH	\$	SL 88.61
30	1	BONNET HINGE LH	\$	R 348.31
31	1	BONNET HINGE RH	\$	R 348.31
32	1	BONNET LOCK	\$	R 305.48
33	1	BONNET CABLE	\$	SL 119.19
34	1	BONNET CABLE COVER	\$	SL 161.03

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-213

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5463D - AIG

35	1	BONNET SEAL OUTER	\$	<i>Pr</i>	92.36	
36	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	
37	1	FENDER PANEL FRT RH	\$	<i>R</i>	783.83	
38	1	WHEELARCH FRT LH	\$	<i>Pr</i>	278.84	
39	1	WHEELARCH FRT RH	\$	<i>Pr</i>	278.84	
40	1	FENDER BRACKET LOWER LH	\$	<i>Pr</i>	15.79	
41	1	FENDER BRACKET LOWER RH	\$	<i>Pr</i>	15.79	
42	1	FENDER INSULATOR LH	\$	<i>Pr</i>	130.84	
43	1	FENDER INSULATOR RH	\$	<i>Pr</i>	130.84	
44	1	BUMPER COVER REAR	\$	<i>B</i>	1,108.46	✓
45	1	BUMPER LOWER REAR	\$	<i>B</i>	768.84	✓
46	1	BUMPER BRACKET CTR REAR	\$	<i>Di</i>	113.47	✓
47	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Pr</i>	135.97	X
48	1	BUMEP R BRACKET CTR LH REAR	\$	<i>Pr</i>	44.99	X
49	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Pr</i>	135.97	X
50	1	BUMEP R BRACKET CTR RH REAR	\$	<i>Pr</i>	44.99	X
51	1	BUMPER BEAM REAR	\$	<i>B</i>	777.52	✓
52	1	BUMPER BEAM BRACKET LH REAR	\$	<i>B</i>	225.95	✓
53	1	BUMPER BEAM BRACKET RH REAR	\$	<i>B</i>	225.95	✓
54	1	BUMPER REFLECTOR LH	\$	<i>CR</i>	43.61	✓
55	1	BUMPER REFLECTOR RH	\$	<i>CR</i>	43.61	✓
56	1	BOOT REAR	\$	<i>B</i>	2,872.68	✓
57	2	BOOT RUBBER PLUG	\$	<i>Pr</i>	221.81	X
58	1	BOOT FINISHER	\$	<i>Pr</i>	470.06	X
59	1	BOOT SWITCH	\$	<i>Pr</i>	168.13	X
60	1	BOOT TRIM BOARD	\$	<i>Pr</i>	914.87	X
61	1	BOOT LOCK	\$	<i>Pr</i>	202.67	✓
62	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40	X
63	1	BOOT LOCK LINKAGE	\$	<i>Pr</i>	34.53	X
64	1	BOOT LOCK LINKAGE HOLDER	\$	<i>Pr</i>	154.52	✓
65	1	BOOT LOCK CATCH TRIM BOARD	\$	<i>Pr</i>	249.24	X
66	1	BOOT WHEATERSTRIP	\$	<i>Pr</i>	323.05	✓
67	1	BOOT REFLECTOR LAMP LH	\$	<i>Pr</i>	493.35	X
68	1	BOOT REFLECTOR LAMP RH	\$	<i>Pr</i>	493.35	X
69	1	BOOT BADGE 'RENAULT'	\$	<i>Pr</i>	225.36	✓
70	1	BOOT BADGE	\$	<i>Pr</i>	225.36	✓
71	1	BOOT STRUT LH	\$	<i>Pr</i>	276.08	X
72	1	BOOT STRUT RH	\$	<i>Pr</i>	276.08	X
73	1	BOOT HINGE LH	\$	<i>R</i>	367.84	X
74	1	BOOT HINGE RH	\$	<i>R</i>	367.84	X
75	2	LICENCE PLATE LAMP	\$	<i>Pr</i>	50.52	X
76	1	TAILLAMP LH	\$	<i>Pr</i>	552.55	✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-213

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5463D - AIG

77	1	TAILLAMP PANEL LH	\$	R	986.70	}	X
78	1	TAILLAMP RH	\$	Sn	552.55		
79	1	TAILLAMP PANEL RH	\$	R	986.70		
80	1	FENDER PANEL REAR LH	\$	R	3,299.13		
81	1	FENDER PANEL REAR RH	\$	R	3,299.13		
82	1	WHEELARCH REAR LH	\$	Sn	543.47		
83	1	WHEELARCH REAR RH	\$	Sn	543.47		
84	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
85	1	SPARE WHEEL PANEL TRIM (Luggage Floor Pane	\$	Sn	612.21		
86	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73		
87	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	}	
88	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77		
89	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	401.02	}	X
90	1	EXHAUST REAR	\$	R	7,489.05		
91	1	EXHAUST CAP REAR	\$	R	230.49		
92	1	EXHAUST MOUNTING REAR	\$	Sn	31.97		
93	1	EXHAUST BRACKET REAR	\$	R	39.86		
94	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06		
95	1	SHIELD - HEAT - TUNNEL	\$	R	225.16		
96	1	DOOR PANEL REAR LH	\$	R	2,844.66		
97	1	DOOR SEAL REAR LH	\$	Sn	187.08		
98	1	DOOR PANEL REAR RH	\$	R	2,844.66		
99	1	DOOR SEAL REAR RH	\$	Sn	162.02		

TOTAL	\$	59,966.76
10%	\$	5,996.68
	\$	53,970.09

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	R	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	R	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	R	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	R	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	R	12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	R	10.50	X
7	1	TOW COVER FRT	\$	Sn	14.50	X
8	1SET	RADAITOR GRILLE SCREW	\$	R	16.00	X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	R	69.00	✓
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	R	70.00	X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	Sn	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	Sn	30.00	X
13	1SET	WHEELARCH CLIP FRT LH	\$	R	30.50	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-213**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5463D - AIG

14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	sn	35.00	
16	1	RIM LH FRT	\$	sn	385.00	
17	1	TYRE LH FRT	\$	sn	330.00	
18	1	CAP HUB RH FRT	\$	sn	35.00	
19	1	RIM RH FRT	\$	sn	385.00	
20	1	TYRE RH FRT	\$	sn	330.00	
21	1SET	BUMPER RR CLIP	\$	nn	66.00	
22	1SET	BUMPER BEAM BOLT	\$	nn	22.22	X
23	1SET	PARKING AID	\$	shom	600.00	
24	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	
25	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
26	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
27	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
28	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
29	1	CAP HUB LH RR	\$	sn	35.00	
30	1	RIM LH RR	\$	sn	385.00	
31	1	TYRE LH RR	\$	sn	330.00	
32	1	CAP HUB RH RR	\$	sn	35.00	
33	1	RIM RH RR	\$	sn	385.00	
34	1	TYRE RH RR	\$	sn	330.00	
35	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
36	1	SPARE TYRE	\$	sn	330.00	
37	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
38	1	Rear boots sticker "trans-cab"	\$	nn	30.00	
39	1	Rear boots sticker "6555-3333"	\$	nn	30.00	
40	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
41	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
42	2	Rear windscreen sealant	\$	nn	80.00	X
43	1	Windscreen moulding	\$	nn	100.00	X
44	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	X
45	1	EXHAUST MOUNTING REAR	\$	sn	65.50	X
46	1	EXHAUST BRACKET REAR	\$	n	22.22	X
47	1SET	Front licence plate with holder	\$	nn	80.00	45n
48	1SET	Rear licence plate with holder	\$	sn	80.00	X
49	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
50	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TOTAL	\$	5,742.92
TOTAL PARTS	\$	59,713.01

Towing Fees.	\$	nn 120.00	X
--------------	----	-----------	---

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-213**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5463D - AIG

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	1300
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	4,500.00	1100
To rust-proofing of the affected areas.	\$	170.00	60
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	40
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	Byow 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	h 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	nn 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-213**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5463D - AIG

To reinstall rear bumper parking sensor.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 601
To repair and realign rear exhaust pipe.	\$	170.00	
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X
TOTAL	\$	13,180.00	
Over All Total	\$	72,893.01	

< parts by parts > Repair Days

~~15~~ DAYS

7 days