

SMRT Accident Vehicle Repair Estimates

EQ

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4492B
 Ref. No : TAX/12/17/2118
 Reg. Date : 13/05/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHEW ANN KIAT
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 20/12/2017 02:30:00 PM
 Accident Reported Date / Time : 21/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093740
 Special Instruction to ARC, if any :
 SLL2604P - EQ - LKK
 Prepared Date : 21/12/2017 09:44:14 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian
21/12/2017.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint

90036121

sebastian.yeang@lkkauto.com.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105768059

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 7,299.40	7,299.40
Other Charges	: 460.00	0.00
TOTAL	: 10,278.40	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 21/12/2017 02:46:02 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/12/2017 02:46:02 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/21/2017 2:48:17 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00 500
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 50
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
TO RESPRAY FRONT DOOR RH	378.00	0.00 X
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	460.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>CRK</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>ME</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>?</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>?</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>?</i>	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>✓</i>	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace <i>?</i>	No
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace <i>✓ NEC</i>	No
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Replace <i>✓ NEC</i>	No
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace <i>✓ NEC</i>	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace <i>X</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>?</i>	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>✓</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>?</i>	No
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace <i>?</i>	No
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace <i>?</i>	No
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace <i>?</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>✓</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>✓ NEC</i>	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>✓</i>	No
53851-47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace <i>✓</i>	No
12611-17140 Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>R</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>X</i>	No
17001-17070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>X</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>X</i>	No
13410-17070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								7,299.44	7,299.40	
TOTAL MATERIALS(Discounted)							7,299.40	7,299.40		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									