

SMRT Accident Vehicle Repair Estimates

China Taiping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5387X
 Ref. No : TAX/12/17/2121
 Reg. Date : 10/09/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN CHIN LEONG (CHEN ZHENLONG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 20/12/2017 06:00:00 PM
 Accident Reported Date / Time : 21/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093753
 Special Instruction to ARC, if any :
 DROVE IN / SLM1686D - CHINA TAIPING - LKK
 Prepared Date : 21/12/2017 11:58:08 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.

21/12/2017.

- Lump Sum Repair.

- Question mark Item Photo

- Photo After Paint.

90036121

sebastian.yang@lkkauto.com.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB134469

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 6,989.33	6,989.33
Other Charges	: 1,080.00	0.00
TOTAL	: 10,926.33	0.00
Lum Sum Total	: 10,950.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	5 days
Arc / Surveyor Sign Off Date	: 21/12/2017 01:09:15 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/12/2017 01:09:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/21/2017 1:09:22 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 600
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00 50
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,080.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓ Defm	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓ OT	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ?	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓ CRK	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ omg	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace ✓ cut	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓ OT	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓ NEC	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace R	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓ OT	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace ?	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ NEC	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓ NEC	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓ NEC	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace ?	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ? ✓ cut	No
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace ✓ TN	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓ TN	No
96327155	REAR		REAR BOOT ACTUATOR LOCK	1	75.00	10.00	67.50	Replace	Replace ?	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓ Defm.	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ?	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓ NEC	No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace ✓ Defm.	No
94503739			CLIP,TRIM	10	1.00	10.00	9.00	Replace	Replace ✓ NEC	No
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace ✓ CRK.	No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ?	No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace R	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace X	No
TOTAL MATERIALS							8,736.66	8,736.66		
TOTAL MATERIALS(Discounted)							6,989.33	6,989.33		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									