

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Keefe Kendrick Lee

Accident Date : 11-Dec-17

Vehicle No : FS 6694 L

Vehicle Model : Honda NSR150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Top cowl	165.00
1	Windshield	75.00
1	Headlamp	165.00
1	Front fender	68.00
2	Fork inner tubes	420.00
2	Fork outer tubes	430.00
1	Fork under bracket	125.00
1	Fork under bracket	175.00
1	Front brake disc	155.00
1	Front sport rim	280.00
1	Front rim shaft	38.00
2	Side mirrors	70.00
2	Handle bars	210.00
2	Handle bar ends	36.00
1	Hand grip (1 set)	40.00
1	Clutch lever	15.00
1	Brake lever	18.00
2	Front signals	84.00
2	Centre fairings	170.00
2	Lower fairings	230.00
2	Air intake tubes	76.00
1	Centre inner fairing	75.00
2	Inner panels	40.00
1	Radiator	210.00
1	Radiator grille	38.00
1	Lampstay	75.00
1	Fuel tank	385.00
2	Rear footrests	80.00
2	Rear footrest brackets	130.00
1	Exhaust pipe	380.00
2	Rear tailboards	250.00
1	Rear centre cowl	28.00
1	Chain guard	48.00
1	Rear sport rim	280.00
1	Swing arm	980.00
		6,044.00
	Less 10%	604.40
		5,439.60

Not Acknd
mk
24/12/17
2/SS
take photo after up in
Sch.

Resp \$ 647 165.00
\$ 500 75.00
\$ 17 165.00
\$ 647 68.00
\$ 2 420.00
\$ 2 430.00
\$ 17 125.00
\$ 17 175.00
\$ 17 155.00
\$ 17 280.00
\$ 17 38.00
\$ 0/500 70.00
\$ 50 210.00
\$ 50 36.00
\$ 70 40.00
\$ 17 15.00
\$ 50 18.00
\$ 00 84.00
\$ 00 170.00
\$ 600 230.00
\$ 00 76.00
\$ 00 75.00
\$ 70 40.00
\$ 200 210.00
\$ 70 38.00
\$ 17 75.00
\$ 00 385.00
\$ 50 80.00
\$ 50 130.00
\$ 50 380.00
\$ 00 250.00
\$ 00 28.00
\$ 00 48.00
\$ 0/20 280.00
\$ 2 980.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Keefe Kendrick Lee

Accident Date : 11-Dec-17

Vehicle No : FS 6694 L

Vehicle Model : Honda NSR150

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ <i>Net</i>	28.00/0
2	Fork oils	\$ <i>Net</i>	30.00 ✓
2	Fork oil seals	\$ <i>Net</i>	56.00 ✓
1	Steering cone (1 set)	\$ <i>Net</i>	75.00 ✓
1	Racing footrest (1 set)	\$ <i>7m</i>	250.00 150
1	Front tyre	\$ <i>11</i>	120.00 x
1	Rear tyre	\$ <i>11</i>	120.00 x
		\$	679.00

S/No.


Labour

1	To provide towing service.	\$ <i>30</i>	45.00
2	To check wiring and reset headlamp focusing.	\$ <i>11</i>	80.00 x
3	To provide labour.	\$ <i>280</i>	380.00
4	To respray painting.	\$ <i>300</i>	450.00
5	To repair body frame.	\$ <i>200</i>	400.00
		\$	1,355.00

Grand Total

\$ 7,473.60

Dollars: Seven Thousand Four Hundred Seventy-Three And Sixty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: