

\* Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

not allocated  
LKK  
2/5 8 3500/2  
22/12/17  
4 days  
whip photo office  
rep

**ABWIN** 諭輝

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Date : 22/12/2017  
TP Vehicle No. : SGW-9775-J  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department  
Owner : WELLBUILT CONSTRUCTION PTE LTD  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5083032272-01  
Vehicle No. : GBD-2982-H  
Make & Model : TOYOTA DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Accident Date: 21/12/2017

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

#### List Item

1	FRONT BUMPER	1 pc \$698.50	—
1	FRONT BUMPER FOG LAMP COVER RH	1 pc \$311.62	X
1	RH FRONT BUMPER FOG LAMP	1 pc \$265.00	X
1	RH HEADLAMP	1 pc \$973.30	—
1	RH HEADLAMP LOWER MOULDING	1 pc \$65.60	—
1	RH FRONT DOOR	1 pc \$1,588.65	—
1	RH FRONT DOOR HINGE BOTTOM	1 pc \$79.81	—
1	RH FRONT DOOR HINGE TOP	1 pc \$83.62	X
1	RH FRONT DOOR SIGNAL LAMP	1 pc \$58.90	—
1	RH CORNER PANEL	1 pc \$282.20	—
1	FRONT GRILLE	1 pc \$511.20	X
1	FRONT GRILLE MOULDING	1 pc \$65.80	X
1	RH FRONT WIPER GARNISH RH	1 pc \$95.60	—
1	FRONT LOGO	1 pc \$95.60	X
1	RH FRONT STEP PANEL GARNISH	1 pc \$348.50	—
Sub Total		\$5,523.95	4191.06
Discount 25% on Parts		(\$1,380.99)	3143.21
		\$4,142.96	

#### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	600
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	850
TO CHECK ALL NECESSARY WIRINGS	\$150.00	30
Sub Total	\$3,150.00	4423.29

Sub Total	\$7,292.96
GST 7%	\$510.51
Total	\$7,803.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875

Company Registration No. 201318685G