

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1712-111

DATE : 22-Dec-2017

POLICY NO. : AVIVA 10735708

VEHICLE REG. NO. : SJG5573A

VEHICLE MAKE : MITSUBISHI LANCER 1.6 A

TO Motor Claim Department

EQ Insurance Company Limited

22 Gemmill Lane, Singapore 069257

Tel: 6223 9433

Fax: 6224 3903

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper ✓ Deform	1	\$ 720.00	\$ 720.00
2	Front Bumper Clips ✓ NEC	10	\$ 4.00	\$ 40.00
3	Front Retainer RH ✓ NEC	1	\$ 40.00	\$ 40.00
4	Front Fender RH ✓ DT	1	\$ 480.00	\$ 480.00
5	Front Fender Shield RH ✓ TN	1	\$ 120.00	\$ 120.00
6	Front Fender Signal RH ?	1	\$ 40.00	\$ 40.00
7	Front Fender Clip ✓ NEC	10	\$ 4.00	\$ 40.00
8	Front Head lamp RH ✓ CRK	1	\$ 480.00	\$ 480.00
9	Front Foglamp RH ?	1	\$ 380.00	\$ 380.00
10	Front Foglamp Garnish RH ✓ CRK	1	\$ 40.00	\$ 40.00
11	Front Undercover RH ?	1	\$ 60.00	\$ 60.00
12	Front Undercover Clip ?	10	\$ 4.00	\$ 40.00
Total Spare Parts				\$ 2,480.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
13	S-painting Frt Bumper&Skirt, Fender RH, Door RH & Support	1	\$ 800.00	\$ 800.00
14	Repair, Replace and Refill Affected Accident Area & Support	1	\$ 800.00	\$ 800.00
15	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,630.00
Amount Before Excess				\$ 4,110.00
Add GST @ 7%				287.70
Total Amount Payable				\$ 4,397.70

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Sebastian 22/12/2017.

- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint.

90036121

sebastianyeang@lkkauto.com

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: