Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C GST Reg. No.: 201312913C

Estimate

38 Woodlands Industrial Park E1 #05-18, Singapore 757700 Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO.: EST1712-111 DATE: 22-Dec-2017 POLICY NO.: AVIVA 10735708

VEHICLE REG. NO.: SJG5573A

VEHICLE MAKE: MITSUBISHI LANCER 1.6 A

TO Motor Claim Department **EQ Insurance Company Limited** 22 Gemmill Lane, Singapore 069257

> Tel: 6223 9433 Fax: 6224 3903

FOR SURVEYOR		

ESTIMATE REPAIR COST

ESTIMATE REPAIR COST						
NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST		
	SPARE PARTS					
1	Front Bumper	1	\$ 720.00	\$ 720.00		
2	Front Bumper Clips	10	\$ 4.00	\$ 40.00		
3	Front Retainer RH	1	\$ 40.00	\$ 40.00		
4	Front Fender RH	1	\$ 480.00	\$ 480.00		
5	Front Fender Shield RH	1	\$ 120.00	\$ 120.00		
6	Front Fender Signal RH	1	\$ 40.00	\$ 40.00		
7	Front Fender Clip	10	\$ 4.00	\$ 40.00		
8	Front Head lamp RH	1	\$ 480.00	\$ 480.00		
9	Front Foglamp RH	1	\$ 380.00	\$ 380.00		
10	Front Foglamp Garnish RH	1	\$ 40.00	\$ 40.00		
11	Front Undercover RH	1	\$ 60.00	\$ 60.00		
12	Front Undercover Clip	10	\$ 4.00	\$ 40.00		
	Total Spare Parts					
	SPECIAL NETT					
	\$ -					
	<u>LABOUR</u>					
13	S-painting Frt Bumper&Skirt, Fender RH, Door RH & Support	1	\$ 800.00	\$ 800.00		
14	Repair, Replace and Refill Affected Accident Area & Support	1	\$ 800.00	\$ 800.00		
15	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00		
Estima	Estimate prepared by: Raymond Tan Total Labour					
The abo	\$ 4,110.00					
parts o worn o	287.70					
inspect and lab	\$ 4,397.70					

Please arrange this vehicle to be surveyed soonest possible. Thank you.