

Superior

REF:

CS/TP17024278/Altbn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD1290J Yr Regn: 2016 Line
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Altis d.o 1598
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 112496 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MROS3REH104533376
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 22/12/17.
 Survey held at: First Autowork
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Great American Independent

Part by Part \$8638.55 (Red: 7896.78 :47%)

RECEIVED 19 Jan 2017

Date/Time, File Pass to? ☐ : Preli. Report

1) 19/1 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

____ \$ - PG. ____ \$

Photos

Sketch

TOTAL:

6x15=90
170+90
50
50+50+50
104
80
644

Report Format :

Lump Sum / I.E. (\$) 8638.55

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 11:24
Date Of Accident	15/12/2017 08:35
Exact Location Of Accident	ANG MO KIO AVE 9 JUNCTION ST 62
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1290J
Insured/Policyholder	
Name Of Registered Owner	ALPINE CAR RENTAL PTE LTD
Co Reg No	199003483E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65113043

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	RENTAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5093613878
Cover Note Number	

Driver

Name of Driver	KOH TENG CHUAN
NRIC No	S1270033D
Date Of Birth	02/10/1957
Occupation	OUTDOOR
Date Of Driving Pass	07/03/1979
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97832023
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

SEE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP4239B

Vehicle Make/Model/Colour TOYOTA

Details Of Properties

Name of Driver FONG THIAM WAI

NRIC/Passport Number

Contact Number 91773236

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date time & place, I was driving along Amk Ave 9. I was making a right turn into Amk st 64. Suddenly, a vehicle (B) hit me at the rear.


I am making this report to claim loss of income and damages of the car for the car.


(A) - SLD 1290J.

(B) - SLP 4239B.

DECLARATION

We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1270033D



Name
KOH TENG CHUAN



Race
CHINESE

Date of Birth
02-10-1957

Sex
M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Identity Card No. S1270033D

Name
KOH TENG CHUAN



Birth Date: **02 Oct 1957**


Issue Date: **26 Jan 2003**



000154875K

Land Transport Authority

VOCATIONAL LICENCE



Licence No. **S1270033D**

Name **KOH TENG CHUAN**

Issue Date **10/5/2011**

Please visit www.lta.gov.sg to check the status of this vocational licence

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5093613878

Cover : drive PREMIUM

1. Index mark and Registration Number of Vehicle : **SLD1290J**
Chassis Number : MR053REH104535376
2. Name of Policyholder : ALPINE CAR RENTAL PTE LTD
3. Effective Date of Insurance : 01 Sep 2017
4. Expiry Date of Insurance : 31 Aug 2018
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$1,400
EXCESS (SECTION 2)	: S\$1,400
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALPINE CREDIT PTE LTD (00000615424)
Date of Issue : 21 Aug 2017 12:23 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Finalisation A/c

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

Great American Insurance Company

GST Ref. No: 20-0000274-Z

Vehicle No: SLD1290J

Invoice No:

Chassis No: MR053REH104535376

Engine No: IZR519433

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	Bootlid	\$ 755.00
2	1	Toyota Emblem	\$ 60.00
3	1	Lettering Corolla	\$ 40.00
4	1	Lettering Altis	\$ 40.00
5	1	Rear Bootlid Chrome	\$ 230.70
6	2	Number Plate Lamp	\$ 128.20
7	1	LHR Bootlid Lamp	\$ 395.00
8	1	RHR Bootlid Lamp	\$ 395.00
9	1	Bootlid Latch	\$ 382.50
10	1	LHR Taillamp	\$ 385.00
11	1	RHR Taillamp	\$ 385.00
12	1	Rear Bumper	\$ 495.00
13	1	LHR Bumper Retainer	\$ 120.00
14	1	RHR Bumper Retainer	\$ 120.00
15	1	Bar	\$ 395.00
16	1	Rear End Panel	\$ 590.00
17	1	Rear End Panel Trim	\$ 240.00
18	1	LHR Fender Inner Trim	\$ 320.00
19	1	RHR Fender Inner Trim	\$ 320.00
20	1	Board	\$ 254.00
21	1	Rear Exhaust Pipe	\$ 929.00

Total: \$ 6,979.40

Less 25%: \$ 1,744.85

Parts Total : \$ 5,234.55

Labour

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 15/12/2017

Reference: SLD1290J
TOYOTA
COROLLA
ALTIS CLASSIC
Make: 1.6 CVT

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLD1290J
CHASSIS NO.: MR053REH104535376
ENGINE NO.: 1ZR519433

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 15/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Bootlid <i>Dented</i>	\$ 755.00 ✓
2	1	Toyota Emblem <i>2</i>	\$ 60.00 ✓
3	1	Lettering Corolla <i>1 set</i>	\$ 40.00 ✓
4	1	Lettering Altis	\$ 40.00 ✓
5	1	Rear Bootlid Chrome <i>lot</i>	\$ 230.70 ✓
6	2	Number Plate Lamp <i>new</i>	\$ 128.20 ✓
7	1	LHR Bootlid Lamp <i>new</i>	\$ 395.00 ✓
8	1	RHR Bootlid Lamp <i>new</i>	\$ 395.00 ✓
9	1	LHR Bootlid Hinge <i>new</i>	\$ 68.00 ✓
10	1	RHR Bootlid Hinge <i>new</i>	\$ 68.00 ✓
11	1	Bootlid Inner Trim <i>new</i>	\$ 320.00 ✓
12	1	Bootlid Latch <i>new</i>	\$ 382.50 ✓
13	1	Bootlid Striker <i>new</i>	\$ 55.00 ✓
14	1	LHR Fender <i>3 parts</i>	\$ 1,095.00 ✓
15	1	RHR Fender <i>3 parts</i>	\$ 1,095.00 ✓
16	1	LHR Fender Liner <i>3 parts</i>	\$ 54.00 ✓
17	1	RHR Fender Liner <i>3 parts</i>	\$ 54.00 ✓
18	1	LHR Taillamp <i>2 parts</i>	\$ 385.00 ✓
19	1	RHR Taillamp <i>2 parts</i>	\$ 385.00 ✓
20	1	Rear Windscreen <i>new</i>	\$ 611.70 ✓
22	1	Rear Bumper <i>2 parts</i>	\$ 495.00 ✓
23	1	LHR Bumper Reflector <i>new</i>	\$ 58.00 ✓
24	1	RHR Bumper Reflector <i>new</i>	\$ 58.00 ✓
25	1	LHR Bumper Centre Bracket <i>new</i>	\$ 68.00 ✓

26	1	RHR Bumper Centre Bracket <i>plan</i>	\$ 68.00	+
27	1	LHR Bumper Retainer <i>2 per</i>	\$ 120.00	✓
28	1	RHR Bumper Retainer	\$ 120.00	✓
29	1	Rear Bumper Reinforcement Bar <i>Best</i>	\$ 395.00	✓
30	1	Rear End Panel <i>Replaced</i>	\$ 590.00	✓
31	1	Rear End Panel Trim <i>Replaced</i>	\$ 240.00	✓
32	1	LHR Fender Inner Trim <i>Replaced</i>	\$ 320.00	✓
33	1	RHR Fender Inner Trim <i>Replaced</i>	\$ 320.00	✓
34	1	Rear Spare Tyre Panel Board <i>Replaced</i>	\$ 254.00	✓
35	1	Rear Spare Tyre Panel <i>Replaced</i>	\$ 797.00	X
36	1	Rear Exhaust Pipe <i>Best</i>	\$ 929.00	✓
37	1	Fuel Tank <i>Ren</i>	\$ 790.00	+
38	1	RHR Door Panel <i>2</i>	\$ 1,185.00	+
39	1	RHR Door Latch <i>Ren</i>	\$ 400.00	+
40	1	RHR Door Striker	\$ 55.00	+

69794
5134 SS

Parts Total: \$ 13,879.10
Less 25%: \$ 3,469.78
Total : \$ 10,409.33

Labour

Labour Description

No.

Price (SGD)

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,000.00	1300
2	Carry out spray painting on accident affected area	\$ 1,600.00	1200
3	To conduct anti rust of under carriage tuff coat	\$ 120.00	60
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	100
6	To remove and refix reverse sensor and conduct test	\$ 80.00	60
7	Conduct chasis alignment of vehicle	\$ 250.00	+
8	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	✓
9	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
10	To remove and replace exhaust pipe	\$ 80.00	✓
11	To remove and replace fuel tank	\$ 200.00	+
12	To remove and refit rear windscreen due to replacement of rear fender	\$ 150.00	+

2910

Labour Total : \$ 4,920.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	1	Rear number plate <i>Bert</i>	\$ 45.00	✓
2	10	Bootlid Inner Trim Clips <i>me</i>	\$ 65.00	30
3	10	Rear bumper clip <i>me</i>	\$ 65.00	30
4	6	Rear fender liner clips <i>me</i>	\$ 39.00	✓
5	6	Rear end panel trim clip <i>me</i>	\$ 39.00	10
6	1	Rear end panel insulation seal <i>me</i>	\$ 80.00	60
7	1	Rear floor panel insulation seal <i>me</i>	\$ 150.00	+
8	12	Rear fender inner trim clip <i>me</i>	\$ 78.00	60
9	10	RHR Door Inner Trim Clip <i>me</i>	\$ 65.00	+
10	1	Reverse sensor (2pcs) <i>2ygd</i>	\$ 280.00	220
11	2	Rear exhaust mounting <i>me</i>	\$ 180.00	+
12	1	Rear windscreen sealant <i>me</i>	\$ 120.00	+

494

Other Total: \$ 1,206.00

GRAND TOTAL: \$ 16,535.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian Lj

22/12/17.

P/P 08 Days

total: 8638.55 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

1ST AUTOWORKS PTE LTD

Ref : CS/TP17024278/Atbn2

23 KAKI BUKIT AVE 4 #04-01
(SOUTH WING) SINGAPORE 415933

Date : 22-01-2018



ON BEHALF OF ALPINE CAR RENTAL PTE LTD

Code : TP480

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLD 1290J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104535376	Colour	WHITE
Odometer	112496	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/12/2017	Inspection Date	22/12/2017
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1290J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	DENTED	755.00	755.00
1	TOYOTA EMBLEM	NECESSARY	60.00	60.00
1	LETTERING COROLLA	NECESSARY	40.00	40.00
1	LETTERING ALTIS	NECESSARY	40.00	40.00
1	REAR BOOTLID CHROME	CUT	230.70	230.70
2	NUMBER PLATE LAMP	CRACKED	128.20	128.20
1	LHR BOOTLID LAMP	CRACKED	395.00	395.00
1	RHR BOOTLID LAMP	CRACKED	395.00	395.00
1	LHR BOOTLID HINGE	NOT NECESSARY	68.00	-
1	RHR BOOTLID HINGE	NOT NECESSARY	68.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	320.00	-
1	BOOTLID LATCH	DAMAGED	382.50	382.50
1	BOOTLID STRIKER	NOT NECESSARY	55.00	-
1	LHR FENDER	TO REPAIR SEE LABOUR	1,095.00	-
1	RHR FENDER	TO REPAIR SEE LABOUR	1,095.00	-
1	LHR FENDER LINER	NOT NECESSARY	54.00	-
1	RHR FENDER LINER	NOT NECESSARY	54.00	-
1	LHR TAILLAMP	CRACKED	385.00	385.00
1	RHR TAILLAMP	CRACKED	385.00	385.00
1	REAR WINDSCREEN	NOT NECESSARY	611.70	-
1	REAR BUMPER	DISTORTED	495.00	495.00
1	LHR BUMPER REFLECTOR	NOT NECESSARY	58.00	-
1	RHR BUMPER REFLECTOR	NOT NECESSARY	58.00	-
1	LHR BUMPER CENTRE BRACKET	NOT NECESSARY	68.00	-
1	RHR BUMPER CENTRE BRACKET	NOT NECESSARY	68.00	-
1	LHR BUMPER RETAINER	NECESSARY	120.00	120.00
1	RHR BUMPER RETAINER	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT BAR	BENT	395.00	395.00
1	REAR END PANEL	DENTED	590.00	590.00
1	REAR END PANEL TRIM	CRACKED	240.00	240.00
1	LHR FENDER INNER TRIM	DEFORMED	320.00	320.00
1	RHR FENDER INNER TRIM	DEFORMED	320.00	320.00

Report Ref No. CS/TP17024278/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL BOARD	DEFORMED	254.00	254.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	797.00	-
1	REAR EXHAUST PIPE	BENT	929.00	929.00
1	FUEL TANK	NOT NECESSARY	790.00	-
1	RHR DOOR PANEL	NOT NECESSARY	1,185.00	-
1	RHR DOOR LATCH	NOT NECESSARY	400.00	-
1	RHR DOOR STRIKER	NOT NECESSARY	55.00	-
	LESS 25% DISCOUNT		-3,469.77	-1,744.85
			10,409.33	5,234.55
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	45.00	45.00
10	BOOTLID INNER TRIM CLIPS (SN)	NECESSARY	65.00	30.00
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
6	REAR FENDER LINER CLIPS (SN)	NECESSARY	39.00	39.00
6	REAR END PANEL TRIM CLIP (SN)	NECESSARY	39.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	80.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
12	REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	78.00	60.00
10	RHR DOOR INNER TRIM CLIP (SN)	NOT NECESSARY	65.00	-
1	REVERSE SENSOR (2 PCS)(SN)	DAMAGED	280.00	220.00
2	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
			1,206.00	494.00
	<u>LABOUR</u>			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF LHR FENDER,RHR FENDER AND REAR SPARE TYRE PANEL.		2,000.00	1,300.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,600.00	1,200.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		120.00	60.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.		250.00	100.00

Report Ref No. CS/TP17024278/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	60.00
	CONDUCT CHASSIS ALIGNMENT OF VEHICLE.	NOT NECESSARY	250.00	-
	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOLTID TO NEW BOOTLID.		80.00	80.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.		80.00	80.00
	TO REMOVE AND REPLACE FUEL TANK.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER.	NOT NECESSARY	150.00	-
			4,920.00	2,910.00
GRAND TOTAL			16,535.33	8,638.55
RECOMMENDED COST OF REPAIRS				8,638.55

Report Ref No. CS/TP17024278/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.