

INS. CASE OWNER:

Jowyn

CC 3 / CTI17024280 / K1633N2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KALVIN

DOI:

20/12/17

Date / Time:

20/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PA 7881H

Claim No.:

SNM17D07241/002/1

Name of Insured:

SIN ANN TRAVEL & COACH SERVICES PTE LTD

Policy No.:

DMB15N162178101

Insured Tel No.:

HP: 9669 8666

Make / Model:

ISUZU LT134L - 7.80 (M)

Excess Sec II :SS

D.O.A.: 20/12/17

Place of Accident:

JOO CHEAT ROAD TOWARDS CRANE ROAD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ZHANG BEN

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

8319 7888

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHC 6016E



INSRS:

WSP: Premier Auto (Chang)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHC 6016E - CC3/III16000422/K16332 DOA: 29/12/15
 - CC3/MSG15016830/H16402 DOA: 02/10/15
 - CC4/PA16001794/H16432 DOA: 26/01/16
 - CF/MEGUT04267/1 DOA: 07/11/07
 PA 7881H - CC3/CTE16011031/K16332 DOA: 11/04/16

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 03/01/18 VLO-OK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time: 26/12/17

Sent By:

Shirley Hsu

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,600.00 (A days) Reduction: A1 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ GST) S\$ 3,852.00

COLD TURNING TOO WIDE @ WRONG LANE

Loss of Rental (LOR):

S\$ 672.77 (7 days) X\$96.11

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$ -

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

S\$ -

3) Survey fee:

\$400.00

Total:

S\$ 4,526.77

Global Sum S\$:

4,520.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 4,520.00

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17024280/K1hs3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 22-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PA 7881H	Veh. Inspected	SHC 6016E
Policy No.		Coverage (\$)	0.00
Claim No.	SNM17D07241/C02/1	Excess (\$)	0.00
Assign From		Assign Date	22/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/12/2017	Inspection Date	20/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CT117024280/K1hs3

Date: 26.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 6016E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report:-

Workshop Estimate Amount	: S\$	6,144.20
Revised Estimate Amount	: S\$	4,545.80
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	13 Jun 2014 / 09:15:55	Receipt No.:	AACCK001-AX239-140613-000008
Asset Type:	Vehicle	Transaction Amount:	\$70,018.00
Asset ID:	SHC6016E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140613091555045868		

Vehicle No.:	SHC6016E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	13 Jun 2014
Original Registration Date:	13 Jun 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5463516
Engine No.:	D4FDDH308971
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$20,028.00
Minimum PARF Benefit:	\$7,524.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	13 Jun 2014 09:15:55
COE No.:	2014061301001199W
COE Expiry Date:	12 Jun 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$57,338.00
Lifespan Expiry Date:	12 Jun 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6016 E

1 pc	Front n/s fender inner shield	X see	\$	120.00
1 pc	Front n/s wheel cover	— horizontal	\$	116.00
1 pc	Front n/s fender	— horizontal	\$	384.00
1 pc	Rear n/s door	— horizontal	\$	791.00
2 pcs	Rear n/s door hinges	@\$34.00 X see	\$	68.00
1 pc	Front n/s door	— horizontal	\$	765.00
2 pc	Front n/s door hinges	@\$34.00 X see	\$	68.00
1 pc	Rear n/s wheel cover	— horizontal	\$	116.00
1 pc	n/s mirror assy	— Bro Ken	\$	590.00
			\$	3,018.00
			Less 10%	\$ 301.80
			\$	2,716.20

S/NETT

1 pc	Rear n/s fender sticker — me	\$	60.00 —
1 set	n/s door sticker — me	\$	100.00 —
1 set	Front n/s fender inner shield clips X m	\$	28.00
1 pc	Front n/s fender sticker X m	\$	30.00
Sundry		\$	50.00 20
To check wheel alignment		\$	160.00 X m
To dismantle and refit the inner component of front o/s door into new shell door		\$	150.00 50
To dismantle and refit the inner component of rear o/s door into new shell door		\$	150.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, rear n/s fender, rear bumper,		\$	1,000.00 600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, front n/s door, n/s side mirror, front n/s fender, front bumper, bonnet		\$	1,500.00 1130
To apply rustproofing on the repaired and replaced panels		\$	200.00 50
		\$	6,144.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

REPAIR D

Signature: _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6016 E

1 pc	Front n/s fender inner shield ✕	\$	120.00
1 pc	Front n/s wheel cover —	\$	116.00
1 pc	Front n/s fender —	\$	384.00
1 pc	Rear n/s door —	\$	791.00
2 pcs	Rear n/s door hinges @\$34.00 ✕	\$	68.00
1 pc	Front n/s door —	\$	765.00
1 pc	Front n/s door hinges @\$34.00 ✕	\$	68.00
1 pc	Rear n/s wheel cover —	\$	116.00
1 pc	n/s mirror assy —	\$	590.00
		\$	3,018.00
Less 10%		\$	301.80
		\$	2,716.20

S/NETT

1 pc	Rear n/s fender sticker —	\$	60.00
1 set	n/s door sticker —	\$	100.00
1 set	Front n/s fender inner shield clips ✕	\$	28.00
1 pc	Front n/s fender sticker ✕	\$	30.00
Sundry		\$	50.00 20
To check wheel alignment		\$	160.00 ✕
To dismantle and refit the inner component of front o/s door into new shell door		\$	150.00 50
To dismantle and refit the inner component of rear o/s door into new shell door		\$	150.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, rear n/s fender, rear bumper,		\$	1,000.00 600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, front n/s door, n/s side mirror, front n/s fender, front bumper, bonnet		\$	1,500.00 1130
To apply rustproofing on the repaired parts and replaced panels		\$	200.00 50
		\$	6,144.20

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Inspected by Repairer
Signature: _____
Date: _____

ORIGINAL

R

THE SCHEDULE

Agency	AN0580A	Class of Policy	MOTOR PRIVATE BUS	Policy Number DMB1SN1621781701
Account	AN0580A	Issued on 11/04/2017 in SINGAPORE	Replacing Policy no.	DMB1SN1621781600
Client	3167064	Acceptance Date	11/04/2017		

Period of Insurance from 13/04/2017 to 19/06/2018 , both dates inclusive

Insured's Name....	SIN ANN TRAVEL & COACH SERVICES PTE LTD
Address.	520B TAMPINES CENTRE 8
	#15-51
	SINGAPORE 522520

Business/Occupn... TRANSPORTATION

Risk No. 001	MOTOR PRIVATE BUS			
	ORIGINAL REGISTRATION DATE: 28/8/2008			
1. Registration	PA7881H	Make/Model ..	ISUZU LT134P	
Type of Cover	Comprehensive	No. of seats	49	Body Type BUS
Engine No. ..	6HK1466832	Capacity cc's	0	Yr of Manuf/Regn 2008/2008
Chassis No...	JALLT134P87000050			
	Tonnage	4.31		Certificate Ref. MZ601
Sum Insured..	Market value at the time of loss			
Excess Sect I			S\$2,000.00	
Excess Sect. II			S\$1,000.00	
EX ON WINDSCREEN			S\$800.00	

RESTRICTION TO USE:

1. USE FOR TRANSPORTING OF PASSENGERS, SCHOOL CHILDREN OR WORKERS. BUS IS ALSO ALLOWED TO TRANSPORT TOURISTS WITHIN SINGAPORE ONLY.
2. THE COMPANY SHALL NOT BE LIABLE FOR ANY CLAIMS WHEN:
 - A. THE BUS IS USED AS PUBLIC SERVICE TRANSPORT

The geographical limit of this Policy is restricted to Singapore only and not as otherwise stated.

Other terms and conditions remain unchanged.

The following clauses and endorsements apply to this policy

Subject to Endts. 1, 2, Y, 25, 57, 72 & W(\$6,000/-).

AUTOSAFE SCHEME (W)

In consideration of a premium discount given, the insured, in the event of any accident/windscreen

Continued on page 2

Issued on 11/04/2017 in SINGAPORE

Policy No. DMB1SN1621781701

damage, must send his/their vehicle to the Company's authorised workshop for repairs if he/they wish to seek indemnity under Section I of this Policy.

Subject otherwise to the terms, conditions and exceptions of this policy.

MODIFIED VEHICLES (FOR COMMERCIAL VEHICLES/BUSES/RENTAL VEHICLES)

It is hereby declared and agreed that the Company shall not be liable for any claims under SECTION I or II or both if the vehicle has been modified without prior notice/declaration to the Company.

Subject otherwise to the terms, exceptions and conditions of the Policy.

MEMORANDUM : CONDITION NO. 4 - NOTIFICATION OF ACCIDENTS

It is hereby noted and agreed that Condition No. 4 of the Policy is amended to read as follows:-

Notification Clause

- a) In the event of any accident involving the Motor Vehicle, irrespective of whether it would give rise to a claim, the Insured shall, together with the Motor Vehicle, call at the Company's Approved Authorised Workshop and/or Reporting Centre and report the accident within 24 hours of the accident or by the next working day thereof.
- b) In case of theft or other criminal act which may give rise to a claim under this policy the Insured shall give immediate notice of the occurrence to the Company and the police and co-operate with the Company in securing the conviction of the offender.
- c) Every letter, claim, writ, summons and process shall be notified or forwarded unanswered to the Company immediately upon receipt. Notice shall also be given to the Company immediately after the Insured or any person claiming to be indemnified shall have knowledge of any impending prosecution, inquest, inquiry, or offer of composition in connection with any such accident and/or occurrence.

This condition in its entirety is a condition precedent to liability and failure to comply with any of the above requirements in respect of any accident and/or occurrence will result in the Insured being denied indemnity under both Section 1 and Section 2 of the Policy in respect of that particular accident and/or occurrence. Notwithstanding the No Claim Discount provisions set out herein, failure to comply with this condition precedent will additionally result in the Insured losing all or part of his No Claim Discount as set out below.

NCD - COMMERCIAL VEHICLES

CURRENT	UPON RENEWAL (NON-REPORTING)
20%	15%
15%	10%
10%	0%
0%	0%

* The Accident NCD to be applied first before the Non-Reporting NCD.

Issued on 11/04/2017 in SINGAPORE

Policy No. DMB1SN1621781701

In the context of this clause, the following terms have the following meanings assigned to them:

- * Accident NCD - Refers to the loss of percentage of No Claim Discount entitlement as a result of claims arising from an accident.
- * Non-Reporting NCD - Refers to the loss of percentage of No Claim Discount as a result of not reporting or late reporting of an accident as set out under the Policy.

Subject otherwise to the terms, conditions and exceptions of the Policy.

Authorised Drivers for vehicle(s) with Certificate Ref. MZ601

Persons or Classes of Persons entitled to drive*

Any person provided he is in the Policyholder's employ and is driving on their order or with their permission or any person driving with policyholder's permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to use*

Use only for the carriage of passengers or goods in connection with the Policyholder's business as specified in the Schedule.

The Policy does not cover

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer, except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

Signed for and on behalf of the Company

Authorised Signature

Vic (LKKAUTO)

From: Gary Shi <gary.shi@premiertaxi.com>
Sent: Tuesday, 3 April, 2018 9:29 AM
To: Vic (LKKAUTO)
Cc: AccReport; Admin A; Asher Sng (LKKAUTO)
Subject: RE: LOD / Accident involving SHC6016E & PA7881H on 20.12.17 (China Taiping case) LKK REF CC3/CTI17024280/K1hs3
Attachments: SHC6016E - DV.pdf

WITHOUT PREJUDICE

Dear Vic,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6016E, our client agreed to direct settle the above claims at \$4520.00

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$4520.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Monday, 26 March, 2018 3:31 PM
To: Gary Shi
Cc: AccReport; Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: RE: LOD / Accident involving SHC6016E & PA7881H on 20.12.17 (China Taiping case) LKK REF CC3/CTI17024280/K1hs3

Without Prejudice

Dear Gary,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we propose a global sum of **\$4,520.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the enclosed **DV and ATA** then forward back to us the original signed copy together with the LOD and supporting documents for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Tuesday, 16 January, 2018 2:14 PM

To: Gary Shi

Cc: AccReport; Admin A; Vic (LKKAuto); Asher Sng (LKKAuto)

Subject: RE: LOD / Accident involving SHC6016E & PA7881H on 20.12.17 (China Taiping case) LKK REF CC3/CTI17024280/K1hs3

Without Prejudice

Dear Gary,

We refer to your below email and the contents were noted.

We will get back to you for an update/offer in due course.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Gary Shi [<mailto:gary.shi@premiertaxi.com>]

Sent: Monday, 15 January, 2018 2:24 PM

To: Asher Sng (LKKAuto); Vic (LKKAuto)

Cc: AccReport; CS A Team

Subject: LOD / Accident involving SHC6016E & PA7881H on 20.12.17 (China Taiping case)

WITHOUT PREJUDICE

Dear Asher & Vic,

Your Ref: PA7881H

Our Ref: SHC6016E/GS

Date of accident: 20/12/2017

We refer to the above mentioned accident.

Hereby we would like to append our losses from China Taiping Insurance (S) Pte Ltd, as insurers of vehicle number PA7881H which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Regards

Gary Shi

Senior Executive, Claims

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443

Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17024280/K1hb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 06-04-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PA 7881H	Veh. Inspected	SHC 6016E	
Policy No.	DMB1SN1621781701	Coverage (\$)	0.00	
Claim No.	SNM17D07241/C02/1	Excess (\$)	0.00	
Assign From		Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5463516	Colour	SILVER	
Odometer	340680	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/12/2017	Inspection Date	20/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6016E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	FRONT N/S WHEEL COVER	GRAZED	116.00	116.00
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	REAR N/S DOOR	DENTED	791.00	791.00
2	REAR N/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	-
1	FRONT N/S DOOR	DENTED	765.00	765.00
2	FRONT N/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	-
1	REAR N/S WHEEL COVER	GRAZED	116.00	116.00
1	N/S MIRROR ASSY	BROKEN	590.00	590.00
	LESS 10% DISCOUNT		-301.80	-276.20
			2,716.20	2,485.80
SPECIAL NETT ITEMS				
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			268.00	180.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT .	NOT NECESSARY	160.00	-
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHELL DOOR .		150.00	50.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR O/S DOOR INTO NEW SHELL DOOR .		150.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE FRONT BUMPER ,REAR N/S FENDER ,REAR BUMPER .		1,000.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,REAR N/S FENDER ,REAR N/S DOOR ,FRONT N/S DOOR,N/S SIDE MIRROR ,FRONT N/S FENDER FRONT BUMPER ,BONNET .		1,500.00	1,130.00

Report Ref No. CC3/CTI17024280/K1hb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS .		200.00	50.00
			3,160.00	1,880.00
GRAND TOTAL			6,144.20	4,545.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC3/CTI17024280/K1hb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.