

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6016 E

1 pc	Front n/s fender inner shield X	\$	120.00
1 pc	Front n/s wheel cover —	\$	116.00
1 pc	Front n/s fender —	\$	384.00
1 pc	Rear n/s door —	\$	791.00
2 pcs	Rear n/s door hinges @\$34.00 X	\$	68.00
1 pc	Front n/s door —	\$	765.00
1 pc	Front n/s door hinges @\$34.00 X	\$	68.00
1 pc	Rear n/s wheel cover —	\$	116.00
1 pc	n/s mirror assy —	\$	590.00
		\$	3,018.00
		Less 10%	\$ 301.80
			\$ 2,716.20

S/NETT

1 pc	Rear n/s fender sticker —	\$	60.00
1 set	n/s door sticker —	\$	100.00
1 set	Front n/s fender inner shield clips X	\$	28.00
1 pc	Front n/s fender sticker X	\$	30.00
		\$	50.00 20
Sundry		\$	160.00 X
To check wheel alignment		\$	150.00 50
To dismantle and refit the inner component of front o/s door into new shell door		\$	150.00 50
To dismantle and refit the inner component of rear o/s door into new shell door		\$	150.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, rear n/s fender, rear bumper,		\$	1,000.00 600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, front n/s door, n/s side mirror, front n/s fender, front bumper, bonnet		\$	1,500.00 1130
To apply rustproofing on the repaired and replaced panels		\$	200.00 50
		\$	6,144.20

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer

Signature:

Date: