

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 27 December 2017

Third Party Insurer: AIG

Vehicle No: SLS8878P

Third Party Veh No: SJQ73G

Model: HONDA FREED HYBRID 1.5G

Date of Accident: 19/12/2017

Chassis: GB7-1030047

## ESTIMATE

| QTY         | DESCRIPTION                     | UNIT S\$        | AMOUNT S\$           |
|-------------|---------------------------------|-----------------|----------------------|
| 1           | FRONT BUMPER                    | <i>Per item</i> | \$1,570.80 ✓         |
| 1           | FRONT BUMPER SIDE RETAINER RH   |                 | <i>Per</i> \$35.20 X |
| 10          | FRONT BUMPER CLIPS              | \$3.90          | <i>Per</i> \$39.00 ✓ |
| 1           | FRONT HEADLAMP LOWER BRACKET RH |                 | \$54.10 ?            |
| SUB TOTAL   |                                 |                 | \$1,699.10           |
| Less 20%    |                                 |                 | -\$339.82            |
| PARTS TOTAL |                                 |                 | \$1,359.28           |

## LABOUR CHARGES:

TO REMOVE & REPLACE WITH PANEL BEATING ALL ACCIDENT PORTION

\$500.00 *2000*

TO PUTTY & SPRAY PUTTING WITH SEALANT ALL ACCIDENT PORTION

\$400.00 *2200*

TO TUFF KOTE / ANTI-RUST

*Per* \$40.00 X

LABOUR TOTAL \$940.00

WINSON

TOTAL \$2,299.28

*Not Authorized  
1. B1  
Resurvey B4 paint  
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: