

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 27 December 2017

Third Party Insurer: AIG

Vehicle No: SLS8878P

Third Party Veh No: SJQ73G

Model: HONDA FREED HYBRID 1.5G

Date of Accident: 19/12/2017

Chassis: GB7-1030047

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER <i>1437.70</i>	<i>Auto/1M</i>	\$1,570.80 ✓
1	FRONT BUMPER SIDE RETAINER RH		<i>R</i> \$35.20 X
10	FRONT BUMPER CLIPS	\$3.90	<i>10</i> \$39.00 ✓
1	FRONT HEADLAMP LOWER BRACKET RH		<i>R</i> \$54.10 XX
		SUB TOTAL	\$1,699.10
		Less 20%	-\$339.82
		PARTS TOTAL	\$1,359.28

1609.80
321.20
1287.84

LABOUR CHARGES:

TO REMOVE & REPLACE WITH PANEL BEATING ALL ACCIDENT PORTION

\$500.00 *2000*

TO PUTTY & SPRAY PUTTING WITH SEALANT ALL ACCIDENT PORTION

\$400.00 *2200*

TO TUFF KOTE / ANTI-RUST

22 \$40.00 X

LABOUR TOTAL \$940.00

42200

WINSON

TOTAL

\$2,299.28

Not Authorized
1.B1
Runny B4 paint
2 days

81601-36

2 days.

P- 1287.84

42200

\$ 1707.84 - p/p

X 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: