

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD426P - CHINA TAIPING**AAD1712-203***Not Notarized**Henry B4 paint**83493-82*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 426P - JHOW

VF1ABL15AUC278273

RENAULT

LATITUDE

19.12.2017

CHINA TAIPING

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>CM</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
7	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
8	1	BUMPER REFLECTOR LH	\$	<i>Bu</i> 43.61 ✓
9	1	BUMPER BEAM REAR	\$	<i>N</i> 777.52
10	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95
11	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95
12	1	BOOT REAR	\$	<i>N</i> 2,872.68
13	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
14	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
15	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
16	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
17	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36 X
18	1	BOOT BADGE	\$	<i>nn</i> 225.36
19	1	BOOT SWITCH	\$	<i>Sn</i> 168.13
20	1	BOOT LOCK	\$	<i>N</i> 202.67
21	1	BOOT LOCK CATCH	\$	<i>N</i> 74.40
22	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
23	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
24	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45
25	1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13
26	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
27	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
28	1	TAILLAMP PANEL LH	\$	<i>N</i> 986.70
29	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77
30	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56

TOTAL	\$	17,376.10
10%	\$	1,737.61
	\$	15,638.49

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-203**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD426P - CHINA TAIPING**Specical Nett**

1	1SET	PARKING AID	\$	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1SET	BOOT FINISHER CLIP	\$	24.20	X
11	1	BOOT STICKER "Trans-cab"	\$	30.00	} X
12	1	BOOT STICKER "6555-3333"	\$	30.00	
13	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
14	1	FENDER INNER TRIM CLIP LH	\$	28.00	
15	1	TAILLAMP CLIP LH	\$	5.00	
16	2	REAR WINDSCREEN SELANT	\$	80.00	
17	1	WINDSCREEN MOULDING	\$	100.00	
18	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	} X
19	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
20	1	SPARE TYRE	\$	330.00	

TOTAL	\$	2,094.20
TOTAL PARTS	\$	17,732.69

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	401
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-203**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD426P - CHINA TAIPING

To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
Towing Fees	\$	<i>nn</i> 120.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>

TOTAL \$ 7,710.00**Over All Total \$ 25,442.69****(PARTS BY PARTS)****Repair Days****~~10~~ Days***2 1/2 days*