



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

FIRE MAINTENANCE PTE LTD

26/12/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 401

Xiao Chan.

Accident date: 21/12/2017

Estimated repair cost for vehicle no: GBE8583G NISSAN NV200 1.6 A '16

CHASSIS: VM20088245

S/N	QTY	ITEMS / Nett	U/PRICE	AMOUNT
L 1	1	Rear Boot Lid <i>Dented</i>		\$1,891.20 ✓
N 2	2	Rear Boot Lid Hinge <i>2 H</i>	\$99.10	\$198.20 x
N 3	2	Rear Boot Lid Shock Absorber <i>2 H</i>	\$184.60	\$369.20 x
N 4	1	Rear Boot Lid Emblem Logo <i>2</i>		\$64.60 ✓
N 5	1	Rear Boot Lid Nv200 Logo <i>new</i>		\$151.50 ✓
N 6	1	Rear Boot Lid Vanette Logo <i>1</i>		\$77.40 ✓
N 8	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$261.00 ✓
N 9	1	Rear Boot Lid Inner Rubber <i>new</i>		\$133.80 ✓
L 10	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$152.50 +
N 11	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 30
N 13	1	Rear R/H Tail Lamp <i>1st</i>		\$258.70 ✓
N 14	2	Rear R/H Tail Lamp Clip <i>new</i>	\$8.00	\$16.00 ✓
L 15	1	Rear R/H Tail Lamp Panel <i>Rear</i>		\$277.20 x
L 16	1	Rear Bumper <i>Dented</i>		\$490.80 ✓
L 17	1	Rear R/H Bumper Side Retainer <i>new</i>		\$53.50 ✓
N 18	1	Rear Bumper Towing Cover <i>Dented</i>		\$38.60 ✓
L 20	1	Rear End Panel Outer <i>Dented</i>		\$464.10 ✓
L 21	1	Rear R/H Fender <i>Rear</i>		\$1,709.70 x
L 22	1	Rear End Panel Inner <i>Dented</i>		247.50 ✓
N 23	2	Rear Bumper Inner Sponge <i>new</i>		110.20 ✓
N 24	1	Tailgate Side Side Catch Latch <i>Dented</i>	71.50	Subtotal:- \$5,819.00
N 25	1	Tailgate Maximum Weight Sticker <i>new</i>	45.20	

S/N	QTY	ITEMS / Special Nett	U/PRICE	AMOUNT
1	1	Rear Boot Lid 70km/H Sticker <i>new</i>		\$30.00 <i>15(20)</i>
2	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$205.00 <i>60(20)</i>
3	1	Rear Bumper Reverse Sensor <i>Blurred</i>		\$294.00 <i>200(20)</i>
4	1	Rear R/H Fender Glass Seal <i>new</i>		\$195.00 x
5	1	Rear End Panel Sealant <i>new</i>		\$60 ✓
			335	Subtotal:- \$724.00

List 3147-10

Len 30%: 2202-97

Nett: 1258.50

Len 10%: 113301