

Kj

**Cheng Hoe Motor Pte Ltd**

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SJL 6300M  
 TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 07/12/2017

TP Veh Reg No: SKS7475L

Estimate No: ES1991031/YISHUN

Date: 31 Jan 2018

Policy No: 5045152097

Veh Reg No: SJL6300M

Make/Model: TOYOTA COROLLA

AXIO 1.5X A

Chassis No: NZE1416095465

Engine No: 1N2D178732

Reg. Date: 04/12/2008

Not Notified

L1 Reg B7

Recovery After Paint

2 days

**Estimate Repair Cost to Vehicle No :SJL6300M**

| Description                                                                    | U/Price | Quantity | List Price                  | Amount              |
|--------------------------------------------------------------------------------|---------|----------|-----------------------------|---------------------|
|                                                                                |         |          | <u>S\$</u>                  | <u>S\$</u>          |
| <b>List Price</b>                                                              |         |          |                             |                     |
| 1 REAR BUMPER                                                                  | 483.20  | 1 PC     | 483.20                      | ✓                   |
| 2 REAR BUMPER CLIPS                                                            | 3.50    | 6 PCS    | 21.00                       | ✓                   |
|                                                                                |         |          | 504.20                      |                     |
|                                                                                |         | Less 25% | 126.05                      | 378.15              |
| <b>Labour</b>                                                                  |         |          |                             |                     |
| 3 REMOVE & REFIX REAR BUMPER,KNOCK & REPAIR REAR PANEL,BOOT & REALIGN THE SAME | 350.00  | 1 LA     | 350.00                      | 200                 |
| 4 PUTTY & RESPRAY PAINTING ON REAR BUMPER,REAR PANEL,BOOT                      | 480.00  | 1 LA     | 480.00                      | 220                 |
|                                                                                |         |          | 830.00                      | 830.00              |
|                                                                                |         |          | <b>Total</b>                | <b>S\$ 1,208.15</b> |
|                                                                                |         |          | Add GST @ 7%                | 84.57               |
|                                                                                |         |          | <b>Total Amount Payable</b> | <b>S\$ 1,292.72</b> |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE