

ASS. REC. BY:

REF: CS/FCI/7024303/TIVd3<sup>n2</sup>

Special Instruction:

Survivor:

Taufik

ASSIGNMENT (Office)

CWS

From (Person): Sifheer

of FCI

Date/Time: 12.41pm @ 22/12/17

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 9209P

Insured: SHB 3721C

at Workshop m/s Reliable Carz

Tel: 816 69797

of 8 kelki Bukit Ave 4 #05-50

Policy No:

Claim No: D17011691MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/12/17

CA / REV / REP. / REV 24 HRS

lwp

26/11/17

H.O.D. Endorsement:

Date/Time: 2.06pm @ 22/12/17

Person Contacted:

Jason

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate	
	SLS 9209P - NS/INC17024158 / K1tb	D.O.A : 19/12/17
	SHB 3721C - NS/INC17024158 / K1tb	D.O.A : 19/12/17
22/1/18	Send preli revised to FCI	

REF: FCI

Surveyor

call before going

## ASSIGNMENT

From: Date: 26/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 9209P

at Workshop m/s Reliable Carz

of 8kaki Bkt Ave 4 #05-50

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Jason @ 816 69797

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLS 9209P Yr Regn: 2017 Oct.

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota C-HR Hybrid. 1797.Colour: Black A/O: Insured / Std / NI / NASp. Reading: 16887 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17R: 215/60R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mmL/Bal. 6 mm

D.O.I.

Survey held at: Reliable Carz

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S, UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4583500, 4 days. email to Jason.  
(Red 7467.90, 816)

RECEIVED 22 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Date/Time, File Return to?

22 p- typist

Report Format: CWS

Lump Sum / I.B.I: (\$ 3500p)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + PS \$:

Photo:

Others:

TOTAL

170
50
50
47
317

# Survey Department Check List (Case Handler)

Reference No.: CS/ FCI 17024303/ Tivd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin ( ): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor ( ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: VERON 22/5/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024303/T1vd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-12-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3721C	Veh. Inspected	SLS 9209P
Policy No.		Coverage (\$)	0.00
Claim No.	D17011691MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/12/2017	Inspection Date
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011691MFSH  
Our ref: CS/FC117024303/T1vd3

Date: 22/1/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 9209P**


We thank you for your instruction on 22/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/12/2017 at the premises of M/s RELIABLE CARZ PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,967.90
Revised Estimate Amount	: S\$3,927.18
"Check" Items Amount	: S\$1,261.43
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front o/s portion and undercarriage



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date	20-12-2017	Our Ref No. D17011691MFSH
Accident Date	19-12-2017	Claim Type. Third Party
Insured Vehicle	SHB3721C	Third Party Vehicle. SLS9209P
Survey Location	8 KAKI BUKIT AVENUE 4#05-50	
Contact Person.	JASON LEE	
Contact No.	81669797/ 81669797	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	RELIABLE CARZ PTE LTD	Attention. NIL
Cc : TP Solicitor	CROSSBORDERS LLC	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232152)



PRI Documents



Close



## PRI Header Details

Claim No	D17011691MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CROSS BC
Workshop Name	RELIABLE CARZ PTE LTD (Contact Person : JASON LEE)	Survey Location & Contact Details	8 KAKI BUKIT AVENUE 4#05-50 Mobile: 81669797 , Phone: 81669797 , Fax: 0 EmailId: HUITING@CROSSBORDERSLLC.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3721C	TP Vehicle No	SLS9209P
PRI Recieved Date	20-12-2017 04:50:39 PM	Surveyor Appointed Date	22-12-2017 12:39:51 PM	Surveyor Accept Date	22-12-2017 0

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	22-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 22 January 2018 8:48 AM  
**To:** 'Claim Workflow System'  
**Cc:** SITHARA@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17011691MFSH/1, SLS 9209P  
**Attachments:** SLS 9209P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLS 9209P  
Date of survey: 26/12/2017  
Number of days:4 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 22 December 2017 2:10 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D17011691MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

*"Wishes you a Merry Christmas & Happy New Year 2018"*

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Friday, 22 December, 2017 12:39 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [SITHARA@FIRST-INSURANCE.COM.SG](mailto:SITHARA@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17011691MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5094910330	RELIABLE RIDES PTE LTD	201611527N	GPC	drive CLASSIC	SLS9209P	SLS9209P	11/10/2017	10/10/2018



譚保險經紀有限公司  
TAN INSURANCE BROKERS PTE LTD  
34/5A Alwal Street, Chenn Leonn Building  
Singapore 199896  
www.tib.com.sg  
Tel: (65) 6742 6766 Fax: (65) 6742 6669

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5094910330 **Cover :** drivo CLASSIC

1. Index mark and Registration Number of Vehicle : SLS9209P  
Chassis Number : ZYX102042593

2. Name of Policyholder : RELIABLE RIDES PTE LTD

3. Effective Date of Insurance : 11 Oct 2017

4. Expiry Date of Insurance : 10 Oct 2018

5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

**This Policy does not cover**  
(a) Use for racing, pace-making, reliability trial or speed-testing.  
(b) Use for the carriage of goods (other than samples) in connection with any trade or business.  
(c) Use for any purpose in connection with the Motor Trade.  
# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$1,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DICKSON CAPITAL PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TAN INSURANCE BROKERS PTE LTD (00000690287)  
Date of Issue : 09 Oct 2017 13:33 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7702200G



Name

PANG HEE JIT LATVAIN  
(FENG QIRI)

馮 啓 日

Race

CHINESE

Date of birth

18-01-1977

Sex

M

Country/Place of birth  
SINGAPORE

5350034



NRIC No. S7702200G



Date of issue

08-09-2014

APT BLK 31 TRANSIT ROAD #05-23  
SINGAPORE 778893

NRIC No: S7702200G

Date: 05/06/2018

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S7702200G

Name

PANG HEE JIT LATVAIN  
(FENG QIRI)

Birth Date 18 Jan 1977

Issue Date 26 Feb 2014



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 26 Feb 2014

NP 428A



# RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875  
Contact No.: +65 8166 9797

Vehicle No.: SLS 9209P

Model: TOYOTA CHR

Tanpin 97495749  
- WP 62563561  
26/12/17 @ 1625.  
4 days lumpsum  
Resurvey after paint  
Sub @ Thkauto.com

## QTY DESCRIPTION

### List Items:

- 1 Front headlamp - LED
- 1 Front headlamp lower bracket
- 1 Front bumper
- 1 Front bumper lower grille
- 1 Front bumper lower side garnish
- 1 Front bumper reinforcement
- 1 Front bumper side retainer
- 1 Front fender - R/H
- 1 Front fender inner shield
- 1 Front fender "HYBRID" emblem
- 1 Front fender wheel arch garnish
- 1 Front wheel rim - R/H
- 1 Front wheel hub - R/H
- 1 Front wheel bearing - R/H
- 1 Front shock absorber - R/H
- 1 Front knuckle arm
- 1 Front tie rod
- 1 Front lower arm
- 1 Front drive shaft - R/H

## AMOUNT (S\$)

nn x 1798.00	
nn x 75.30	
de ✓ 1085.40	
nn x 385.00	
cut ✓ 285.00	
nn x 321.40	
nei ✓ 60.30	
bl ✓ 580.40	
de ✓ 155.50	
nei ✓ 78.00	
cut ✓ 488.30	
cut ✓ 1050.00	
wt ✓ 299.70	
wt ✓ 181.50	
nn x 501.20	
X ✓ 600.70	
X x 120.50	
nn x 426.00	
X x 985.00	
9477.20	4264.00
Less 25 % (2369.30)	
Subtotal	7107.90 3198.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### Special Nett Items:

- 1 Front bumper clip (1 set)
- 1 Front fender inner shield clip (1 set)
- 1 Front tyre

nei ✓ 50.00	30
nei ✓ 50.00	30
nn x 350.00	60
Subtotal	450.00

### Labour Charges:

- To check wiring and reset headlamp focussing
- To remove and refit front undercarriage
- To conduct wheel alignment
- To apply undercoating
- Panel beating, remove and replacing above parts
- To respray painting

80.00	20.
photo 450.00	120?
180.00	80.
100.00	30.
1400.00	500
1200.00	400
Subtotal	3410.00 1150

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

10967.90

3198.08  
60  
1150  
4408.08  
4543500, 4 days




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024303/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-02-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 3721C	Veh. Inspected	SLS 9209P	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011691MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	22/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA C-HR HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102042593	Colour	BLACK	
Odometer	16887	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	MICHELIN	6 mm	
L/H Front Tyre	215/60 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/12/2017	Inspection Date	26/12/2017	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 9209P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT HEADLAMP-LED	NOT NECESSARY	1,798.00	-
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	75.30	-
1	FRONT BUMPER	DEFORMED	1,085.40	1,085.40
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	385.00	-
1	FRONT BUMPER LOWER SIDE GARNISH	CUT	285.00	285.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	321.40	-
1	FRONT BUMPER SIDE RETAINER	NECESSARY	60.30	60.30
1	FRONT FENDER-R/H	BENT	580.40	580.40
1	FRONT FENDER INNER SHIELD	DEFORMED	155.50	155.50
1	FRONT FENDER "HYBRID" EMBLEM	NECESSARY	78.00	78.00
1	FRONT FENDER WHEEL ARCH GARNISH	CUT	488.30	488.30
1	FRONT WHEEL RIM-R/H	CUT	1,050.00	1,050.00
1	FRONT WHEEL BEARING-R/H	BENT	181.50	181.50
1	FRONT SHOCK ABSORBER-R/H	NOT NECESSARY	501.20	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	600.70	-
1	FRONT TIE ROD	NOT NECESSARY	120.50	-
1	FRONT LOWER ARM	NOT NECESSARY	426.00	-
1	FRONT DRIVE SHAFT-R/H	NOT NECESSARY	985.00	-
1	FRONT WHEEL HUB-R/H	BENT	299.70	299.70
	LESS 25% DISCOUNT		-2,369.30	-1,066.02
			7,107.90	3,198.08
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT TYRE (SN)	NOT NECESSARY	350.00	-
			450.00	60.00
<b>LABOUR</b>				
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		450.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	80.00

Report Ref No. CS/FCI17024303/T1vd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING.		100.00	30.00
	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS.		1,400.00	500.00
	TO RESPRAY PAINTING.		1,200.00	400.00
			3,410.00	1,150.00
GRAND TOTAL			10,967.90	4,408.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FCI17024303/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.