

INS. CASE OWNER:

Jony

CC6 / EQ1170 2 4304 / U093

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

26/12/17

Date / Time:

22/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GT 8896R

Claim No.:

DM17H002958/JT

Name of Insured:

VENDA ENGINEERING & TRADING PTE LTD

Policy No.:

DMCPHQ17-001787

Insured Tel No.:

HP:

Make / Model:

TOYOTA DYNA 1500

Excess Sec II :SS

D.O.A.:

21/12/17

Place of Accident:

BLK 181 ANG MO KEO AVE 5
1st OPEN CARPARK

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LOW SEW ONN

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

9632 4503

(V/L: YES / NO)

Insured Liability:

%

Final? Yes / No

SDP 47161C



INSRS:

WSP: Syntech Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

29/01/18 (THU THU)

SDP 47161C - X; GT 8896R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 041021/19-01C

OI report no accident.

request evidence from TP. pending for
PIR.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: NO DV

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA/LIA:

Medical Bill:

PIR: - REQUEST OIO

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

26/01/18

Sent By:

Shirley

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

H9

S\$ 3,000.00

(4 days)

Reduction:

G1

%

Email

Call

FINAL SETTLEMENT

Date/Time:

041021/19

Confirm with:

WINSTON

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

(w/950)

S\$ 3,210.00

Loss of Rental (LOR):

S\$

300.00

(3 days)

x 4100

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost:

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

5400.00

Total:

S\$

3,777.45

Global Sum S\$:

3,700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,700.00

Name 1:

SYNTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

Wang and Li

Veh No: SD74716K Yr Regn: 6 16

Type: ☒ Car / ☐ Motorcycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or ☒ Car

Make: Honda vereel cc: 1496

Colour: silver A/C: ☐ Insured / ☐ Std / ☐ Nil / ☐ NA

Sp. Reading: 28456 T/Radio: ☐ Insured / ☐ Std / ☐ Nil / ☐ NA

Eng/No: _____

C/No: RU 111 / 7659

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Independent / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____

Brake: ☒ Independent / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____

Modl: Nil / ☒ S/S / ☐ STD A/Rim or _____

Tyre Size: F: 215/60R16 R: _____

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or _____

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A: 21.12.17 D.O.I: 26.12.17

Survey held at: _____

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or ☒ O/S & U/C

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI17024304/Uus3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 22-12-2017	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 8896R	Veh. Inspected	SDP 4716K	
Policy No.	DMCPHQ17-001787	Coverage (\$)	0.00	
Claim No.	DM17HO02958/JT	Excess (\$)	0.00	
Assign From		Assign Date	22/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/12/2017	Inspection Date	26/12/2017	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9430F
Vehicle Details	
Vehicle No.:	SDP4716K
Vehicle to be Exported:	No
Intended De-registration Date:	27 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4037664
Chassis No.:	RU11117659
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,704.00
Original Registration Date:	14 Jun 2016
First Registration Date:	14 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$9,704.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2026
PARF Rebate Amount:	\$7,278.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$45,444.00

<https://vrl.lta.gov.sg/lta/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTI...> 27/12/2017

Honda Vezel SDP 4716K

- 1) RL F Door — 3d300 ✓
- 2) RL R Door — 3d300 ✓
- 3) RL F Door Black sticker — nr ✓
- 4) RL R Door Black sticker — nr ✓
- 5) Rear Fender — 2x 70.1 ✓
- 6) " " Arc garnish (F) — nr ✓
- 7) " " Arc garnish (R) — 70.1 ✓
- 8) " " Corner garnish — 2d712 ✓
- 9) " " garnish clip (3x) — nr ✓
- 10) " " Closing shield — 11x ✓
- 11) " " " clip — 11x ✓
- 12) " " mudflap — 11x ✓
- 13) Rear Bumper — 11x ✓
- 14) " " clip — nr ✓

labour! -

- 1) Transfer Fr R Door fitting — 60 120
- 2) Anti Rust Prepping — 100v 80
- 3) Check Wreap — 120v 30
- 4) Fabricator Upholstery — 200v 80
- 5) Remove & refit Roof lining — 150v 11x
- 6) Panel Beating — 150v 600
- 7) Paintwork — 1200v 900

26/12/11 4 day.

Let A. is Consultants hence notify the Repairer of the following:

- To identify areas with spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and approved by the Insurance Company

Acknowledged by Repairer

Signature: 240v. 120

Date:

Honda Vezel SDP 4716K

- 1) RL F Door ——— 5.4300 — \$965.40
- 2) RL R Door ——— 3.4300 — \$968.10
- 3) RL F Door Black sticker — nr — \$38.50
- 4) RL R Door Black sticker — nr — \$38.50
- 5) Rear fender — 2x — \$972.50
- 6) " " Arc garnish (F) — nr — \$180.60
- 7) " " Arc garnish (R) — nr — \$192.10
- 8) " " Corner garnish — 2x — \$38.20
- 9) " " garnish clip (3x) — nr — \$30.00 ea
- 10) " " clamping shield — 11x — \$136.46
- 11) " " " clip — 11x — \$30.00 ea
- 12) " " mudflap — 11x — \$88.00
- 13) Rear Bumper — 11x — \$610.20
- 14) " " clip — nr — \$30.00 ea

labour! -

- 1) Transfer Fr R Door fitting — 5x120 = 240h. 120
- 2) Anti rust Prepping — 100h 50
- 3) Check wiring — 120h 30
- 4) Exterior Upholstery — 200h 50
- 5) Remove & refit roof lamp — 150h 11x
- 6) Panel Beating — 150h 600
- 7) Paintwork — 120h 900

26/12/11 4 day.

u

Estimate

Not Authorized

T. Khan

1/5 @ 30000/-

4 days

Take photo After repair

Vehicle: SDP 4716KMake & Model: Honda verei

Year: _____

Chassis No: _____

Parts / Labour	Condition	Price	recommend
Front door o/s	205.00	965.40	✓
Rear door o/s	205.00	968.10	✓
Front door frame black sticker o/s	nu	38.50	✓
Rear door frame black sticker o/s	nu	38.50	✓
Rear fender o/s	R	972.50	X
Rear fender outer protector garnish (F) o/s	MIS	180.60	✓
Rear fender outer protector garnish o/s (R)	T-1	192.80	✓
Rear fender corner garnish o/s	Deepen?	38.20	✓
1 set Rear fender corner garnish clips o/s	nu	30.00	✓
Rear fender inner clowing o/s	11	136.40	X
Rear fender inner clwing clips.	11	30.00	X
Rear mud flap o/s	11	88.00	X
Rear bumper	11	610.20	X
1 set Rear bumper clips	20% nu	30.00	✓
		4319.20	2482.1

To dismantle & refix both o/s door components 240.00 + 120

To spray anti rust proofing 100.00 - 80

To check wiring 120.00 - 30

To Dismantle & Replacing upholstery 200.00 - 80

To Dismantle & refix roof lining 150.00 - 111X

labour for panel beating & replacing parts 1500.00 - 600

To putty & spray painting 1200.00 - 900

3795.60

TOTAL \$ 7829.20

Auto Consultants hence notify

the Reparer of the following:

- Insures before after spray painting
- To apply for repair parts during warranty
- Parts prices are subject to confirmation
- This estimate is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary estimate must be resurveyed and
- Is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408953 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQ117024304/Uus3

Date: 26.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SDP 4716K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.12.2017 at the premises of M/s Stytech Auto Pte Ltd (Kaki Bukit) and have the following to report:-

Workshop Estimate Amount	: S\$	7,829.20
Revised Estimate Amount	: S\$	3,795.68
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Shirley Hiew (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 26 January 2018 3:23 PM
To: Shirley Hiew (LKK Auto)
Cc: Thin Thin (LKKAuto)
Subject: FW: Direct Settlement - Accident Involving GT8896R (OI : EQI - DM17HO02958/JT AND SDP4716K (TP : LKK REF - CC6/EQI17024304/Uus3) on 21/12/2017
Attachments: TP GIA REPORT.pdf; TP ESTIMATE- MARKED.pdf; Preliminary Advice.pdf; LKK SURVEYOR PHOTO.pdf; EQIC-MARS00002054-GT8896R-GIA.PDF

Dear Shirley/Thin Thin,

Attach OI report

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road, #27-00, Tower Block, MND Compline, Singapore 069110
dtd 1/1/2018 10:12 | tel 65 6223 9433 ext 032 | fax 65 6223 8190
www.eqinsurancelimited.com.sg

A Member of Citistate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, January 26, 2018 9:23 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GT8896R (OI : EQI - TBA) AND SDP4716K (TP : LKK REF - CC6/EQI17024304/Uus3) on 21/12/2017

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

We have inspected TP vehicle SDP 4716K at M/s Stytech Auto Pte Ltd – Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Monday, 15 January 2018 2:01 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GT8896R (OI : EQI - TBA) AND SDP4716K (TP : LKK REF - CC6/EQI17024304/Uus3) on 21/12/2017

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

Meanwhile, Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Friday, 29 December 2017 9:48 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GT8896R (OI : EQI - TBA) AND SDP4716K (TP : LKK REF - CC6/EQI17024304/Uus3) on 21/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Meanwhile, Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]

Sent: Tuesday, 26 December, 2017 10:44 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving GT8896R (OI : EQI - TBA) AND SDP4716K (TP : LKK REF - CC6/EQI17024304/us3) on 21/12/2017

Dear all,

Involved driver in hospital due to sickness. We are following up on reporting.

Regards,

Janet Tan

Service Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 64964032 | tel 65 6223 9433 ext 082 | fax 65 6223 4150

www.eqinsurance.com.sg



A Member of Crayfish



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Friday, December 22, 2017 5:04 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GT8896R (OI : EQI - TBA) AND SDP4716K (TP : LKK REF - CC6/EQI17024304/us3) on 21/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Stytech Auto Pte Ltd – Kaki Bukit.

Enclosed for your perusal is:

- TP's GIA report

We have not authorized repairs.

We will revert preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To check availability of the case handler , you may contact the undersigned.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0955 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 26 January 2018 3:57 PM
To: Shirley Hiew (LKK Auto)
Subject: FW: GT8896R - Parking Lot Accident
Attachments: ATT00001.htm; GT8896R.pdf

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 059110
did 65 6286 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4180
www.eqinsurance.com.sg

 A Member of Citistate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Nicole Cheong [mailto:account@vendaengrg.com.sg]
Sent: Friday, December 22, 2017 6:16 PM
To: group@ajaxmars.com
Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Meilin <meilin@ajaxmars.com>
Subject: Re: GT8896R - Parking Lot Accident

Dear Elizabeth,

As mention, please find the attach picture provided by third party for your info.

--
Thanks & Best Regards,
Nicole Cheong
Venda Engineering & Trading Pte Ltd
Tel: 6355 9015
Fax: 6254 0424

On 22/12/2017 11:51 AM, Janet Tan wrote:

Dear all,

Accident on 21/12/17 0830hr
Involving GT8896R and SDP4716K

Please contact Ms Nicole for further details as it is unlikely for driver to report as yet.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete the message.

From: Nicole Cheong [<mailto:account@vendaengrg.com.sg>]

Sent: Friday, December 22, 2017 11:41 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Subject: GT8896R - Parking Lot Accident

Hi Janet,

As spoken, vehicle GT8896R is under our company **Venda Engineering Pte Ltd** care which involving in a parking lot accident.

But we have no witness and evidence proven that is our fault.

For our understanding third party already reported to the insurance and traffic police, at the same time traffic police came on the spot and reporting was done.

We had called our driver on yesterday morning once we received call from the reporter as to verify, but due to he is not feeling well and even cannot stand, so the case was still pending.

Our driver is now admitted to hospital and thus reporting was not done, could your please assists to arrange in-charge personnel go to the address as below to take a picture of our vehicle crashing site and reporting if needed.

Kindly refer our details as below.

Driver Name : Low Siew Onn

Driver Address : Blk 181 Ang Mo Kio Ave 5 Singapore 560181

--

Thanks & Best Regards,
Nicole Cheong

Venda Engineering & Trading Pte Ltd
Tel: 6355 9015
Fax: 6254 0424



Virus-free. www.avast.com



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98807/01/18

Date : 18/1/2018

To : M/S EQ Insurance Company Ltd.
5 Maxwell Rd #17-00
Tower Block MND Complex
S'pore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re : Claim of repair cost & loss of use for veh no. SDP 4716-K

<u>NO</u>	<u>PRICE</u>
1. Lump Sum Repair Cost For Veh No. SDP 4716-K.....	S\$ 3,210.00
2. Loss Of Use For Rental Bill No: 1164(25/12/17 to 30/12/17)	600.00
3. LTA Search Fee.....	S\$ 7.49

TOTAL : S\$ 3,817.49

=====



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/EQI17024304/Uhb3

04 MARCH 2019

VENDA ENGINEERING & TRADING PTE LTD
174 WESTWOOD CRESCENT
SINGAPORE 648541
ATTN: TO THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GT 8896R AND SDP 4716K ON 21/12/2017

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh
Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

Date: 25/12/17

M/S Chen Ling Min
Bik 179 Ang Mo Kio Ave 5
09-2878 S'pore (560179)

To: M/S STYTECH AUTO PTE LTD
2 Kaki Bukit Avenue 2, #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Mdm,

Repair Cost for Vehicle Number SOP 4716K
Caused by accident dated on 21/12/17 involving vehicle/s number SOP 4716K
X GT8896R at Ang Mo Kio Ave 5.

Our Company / I, Chen Ling Min
vehicle number SOP 4716K hereby authorized you to liaise with the insurance
company and undertake all repairs & any other damages incurred as I am involved in the accident dated
on 21/12/17.

All legal & repair costs will be deducted from the proceeds of my claim and be released to M/S STYTECH
AUTO PTE LTD.

Thank you.

Yours Faithfully

last



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98807/01/18

Date : 18/1/2018

To : M/S EQ Insurance Company Ltd.
5 Maxwell Rd #17-00
Tower Block MND Complex
S'pore 069110
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re : Accident on 21/12/2017 involving veh nos. SDP 4716-K & GT 8896-R
Along Ang Mo Kio Ave 5.

FINAL BILL FOR VEH NO. SDP 4716-K

DESCRIPTION

PRICE

Lump Sum Repair Cost For Veh No. SDP 4716-K..... S\$3000.00
7% GST..... S\$ 210.00

TOTAL : S\$3210.00

Yours Faithfully
STYTECH AUTO PTE. LTD.


.....
Mr. Winston Teo
9685-8843

WTM AUTOMOBILE

Reg. No. 53309501L

2 KAKI BUKIT AVENUE 2 #01-02 KAKI BUKIT AUTOHUB SINGAPORE 417921

Mobile No. : 69280881

email: wtm_automobile@singnet.com.sg

M/s Chen Ling Min

INVOICE :

1164

Vehicle No. : SGX1534K
Make : HONDA STREAM
Agreement No. :

Date : 30th Dec 2017
Terms :
Yours Ref :

S/No.			Amount
	(SGX1534K) Rental for 5 days 25/12/17 - 30/12/17 Ref: SDP4716K	\$ 120.00	\$ 600.00
			\$ 600.00

All Cheques should be crossed and made payable to WTM AUTOMOBILE

WTM AUTOMOBILE

Thank you for your business !

WTM AUTOMOBILE

2 KAKI BUKIT AVENUE 2 #01-02 KAKI BUKIT AUTOHUB SINGAPORE 417921

Tel: 69280881

email: wtm_automobile@singnet.com.sg

Co. Reg. No. 53309501L

SDP4716K

VEHICLE RENTAL AGREEMENT

No. 1164

HIRER'S PARTICULARS Name: <u>Chen Ling Min</u> Address: <u>Blk 174 Ang Mo Kio Ave 5 #09-387</u> <u>21560197</u> Contact Person: _____ Tel: _____		Vehicle No: <u>S6X1534K</u> Replace Veh No: _____ Mileage Out: _____ Mileage Out: _____ Make & Model: <u>HONDA</u> Make & Model: _____ Auto / Manual: <u>STREAM</u> Auto / Manual: _____ OUT: Date <u>25/12/17</u> OUT: Time <u>4.00pm</u> HIRE EXPIRY _____ TIME EXPIRY _____																															
DRIVER'S PARTICULARS Name: _____ Address: _____ Tel No: _____ H/P No: <u>97468745</u> P.P./I.C. No.: <u>S8109430F</u> D/L No: <u>S8109430F</u> Date of Birth: <u>02/02/81</u> Date of Issue / Expiry: <u>14/05/05</u> Nationality: _____ Pl. Of Issue: _____ Occupation: _____ Driving Exp: _____		<table border="1"> <thead> <tr> <th colspan="3">RENTAL CHARGES</th> </tr> </thead> <tbody> <tr> <td>Daily</td> <td><u>5</u> @ \$ <u>120</u></td> <td><u>600/-</u></td> </tr> <tr> <td>Weekly</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Monthly</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Hours</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Others</td> <td>@ \$</td> <td></td> </tr> <tr> <td>CDW</td> <td>@ \$</td> <td></td> </tr> <tr> <td>PAI</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Delivery Service</td> <td></td> <td></td> </tr> <tr> <td colspan="2">SUB-TOTAL \$</td> <td><u>600/-</u></td> </tr> </tbody> </table>		RENTAL CHARGES			Daily	<u>5</u> @ \$ <u>120</u>	<u>600/-</u>	Weekly	@ \$		Monthly	@ \$		Hours	@ \$		Others	@ \$		CDW	@ \$		PAI	@ \$		Delivery Service			SUB-TOTAL \$		<u>600/-</u>
RENTAL CHARGES																																	
Daily	<u>5</u> @ \$ <u>120</u>	<u>600/-</u>																															
Weekly	@ \$																																
Monthly	@ \$																																
Hours	@ \$																																
Others	@ \$																																
CDW	@ \$																																
PAI	@ \$																																
Delivery Service																																	
SUB-TOTAL \$		<u>600/-</u>																															
Refundable Deposits: _____ Cash/Nets/Cheque No.: _____ (A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES FRONT LEFT RIGHT REAR		EXTENSION _____ Collection Service _____ Misc. _____ ESTIMATED TOTAL RENTAL \$ _____ Sales Person Code: _____ Hirer is responsible for the first \$ <u>2000/-</u> excess for collision / damage to first party. (i.e) WTM AUTOMOBILE Vehicles (including windscreen) and also first \$ <u>2000/-</u> excess for collision/damage to third party's vehicles for each and every accident / damage HIRER's Signature _____ Additional Driver's Signature _____																															
ACCESSORIES CHECK ☐ Ashtray ☐ Cig Lighter ☐ S / Tyre ☐ STD Tools ☐ Jack ☐ Hub Caps ☐ Radio / Cass ☐ CD / Cartridges ☐ S / RIM																																	

I/We agree to the terms and conditions above, overleaf and that all information given is true and correct in all respect. My/Our Driving licence(s) is/are current and not disqualified from driving.

IMPORTANT

1. IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORISED DRIVER:

- shall report all accidents involving the said vehicle to the Owner immediately
- shall take immediate steps to complete and sign Form Mar 1 (Motor Accident Report form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is reported to the owner)
- shall report to the police within 24 hours from the occurrence, the following types of accidents:-
 - injury case;
 - non-injury case involving a Government vehicles or damage to Government property;
 - non-injury case involving a foreign vehicle (to obtain their motor insurance, policy, Passport No./Name of the driver, Vehicle number, Log card and Vehicle road tax information);
 - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE - THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WTM AUTOMOBILE AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	DEPOSIT REFUND	SIGNATURE OF HIRER/DRIVER
<u>30/12/17</u>	<u>5.10pm</u>					



Land Transport Authority

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 21 Dec 2017 / 16:04:23

Receipt Date/Time : 21 Dec 2017 / 16:04:23

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171221-001528

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GT8896R				
As at 21 Dec 2017/08:30:00				
Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - GT8896R			
	Enquiry Fee	7.00	0.49	7.49
	20171221160320968831			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	20171221160332674	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408663
Tel: +65 6547 0000
Fax: +65 6547 8258
www.police.gov.sg

Our Ref : TP/IP/67553/2017
Date : 9 February, 2018

TOH BOON PING
BLK 179 ANG MO KIO AVENUE 5
#09-2878
SINGAPORE 560179

Dear Sir/Madam

**ACCIDENT INVOLVING SDP4716K / GT8896R ON 21/12/2017 AT 0837 HRS ALONG
BLK 181 ANG MO KIO AVENUE 5 CARPARK**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of GT8896R has committed the following offences;

- a. Fail to stop after an accident under Section 84(1) RTA, Chapter 276
- b. Fail to lodge report within 24 hours after accident under Section 84(2) RTA, Chapter 276
- c. Careless Driving under Rule 29 Road Traffic Rules

Action has been initiated against the driver for the said offences.

3. If you have any queries, please contact the Investigation Officer, SHAIFUL NEEZAM at telephone number 6547 6180 or email Shaiful_Neezam_ABDUL_SAMAD@spf.gov.sg.

Yours faithfully


Roslan Ahmad, Stn Insp
For Head Investigation
Traffic Police
Singapore Police Force

Vic (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 1 November, 2018 8:37 AM
To: Thin Thin (LKKAUTO)
Cc: Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: Our ref:DM17HO02958/JT: GT8896R - Parking Lot Accident
Attachments: PIR sdp 4716k.jpg

Dear Thin Thin

Please proceed to direct settle.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]
Sent: Wednesday, October 31, 2018 7:51 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>; Justin Wong <justin.wong@eqinsurance.com.sg>; Joel Goh <joel.goh@eqinsurance.com.sg>
Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: GT8896R - Parking Lot Accident
Importance: High

Dear Sir / Madam,

We refer to the below matter.

Enclosed herewith PIR result for your perusal. Based on PIR, OID was charge by traffic police.

In view of the above, kindly let us have your further instruction as TP is chasing us for settlement.

Best Regards,

Thin Thin Hlaing | Case Handler



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 07/03/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GT 8896R	(Insd Veh)	Your Ref. No. : DM17HO02958/JT
	SDP 4716K	(TP Veh)	Our Ref. No. : CC6/EQ117024304/Uhb3q2
Date of Accident	21/12/2017		

Liability	100%	
Final Repair Cost	: \$ 3,210.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 500.00	5 days
Others:	: \$ 7.45	
	: \$	
	3,717.45	
Final Settlement Sum	: \$ 3,700.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	STYTECH AUTO PTE LTD	: \$ 3,700.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ117024304/Uhb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 07-03-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 8896R	Veh. Inspected	SDP 4716K	
Policy No.	DMCPHQ17-001787	Coverage (\$)	0.00	
Claim No.	DM17HO02958/JT	Excess (\$)	0.00	
Assign From		Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11117659	Colour	SILVER	
Odometer	28456	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2017	Inspection Date	26/12/2017	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDP 4716K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR O/S	BADLY DENTED	965.40	965.40
1	REAR DOOR O/S	BADLY DENTED	968.10	968.10
1	FRONT DOOR FRAME BLACK STICKER O/S	NECESSARY	38.50	38.50
1	REAR DOOR FRAME BLACK STICKER O/S	NECESSARY	38.50	38.50
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	972.50	-
1	REAR FENDER OUTER PROTECTOR GARNISH O/S (F)	MISSING	180.60	180.60
1	REAR FENDER OUTER PROTECTOR GARNISH O/S (R)	TORN	192.80	192.80
1	REAR FENDER CORNER GARNISH O/S	DEEP CUT	38.20	38.20
1	SET REAR FENDER CORNER GARNISH CLIPS O/S	NECESSARY	30.00	30.00
1	REAR FENDER INNER CLOWING O/S	NOT NECESSARY	136.40	-
1	REAR FENDER INNER CLOWING CLIPS	NOT NECESSARY	30.00	-
1	REAR MUDFLAP O/S	NOT NECESSARY	88.00	-
1	REAR BUMPER	NOT NECESSARY	610.20	-
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
	LESS 20% DISCOUNT		-	-496.42
			4,319.20	1,985.68
LABOUR				
	TO DISMANTLE & REFIX BOTH O/S DOOR COMPONENTS.		240.00	120.00
	TO SPRAY ANTI RUST PROOFING.		100.00	80.00
	TO CHECK WIRING.		120.00	30.00
	TO DISMANTLE & REPLACING UPHOLSTERY.		200.00	80.00
	TO DISMANTLE & REFIX ROOF LINING.	NOT NECESSARY	150.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	900.00
			3,510.00	1,810.00
GRAND TOTAL			7,829.20	3,795.68

Report Ref No. CC6/EQ117024304/Uhb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	----------

Report Ref No. CC6/EQ117024304/Uhb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 8 March 2019 4:00 PM
To: 'janet.tan@eqinsurance.com.sg'
Subject: TP Direct Settlement - Accident Involving GT 8896R (OI) and SDP 4716K (TP) on 21/12/2017
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933