Sketch Plan Pg. 2

Refer	42	police	report		
				vojih marakana se	
	-				
-1-1-					
	77.11				
		PUNCTURE -		2003-0	

Declaration

tWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time 2 p.p.c. 2017

2 0 DEC 2017

Driver's Signature (If driver is not the policyholder) / Date & Time

METINA CHIA SAN SAN Purformance Motors Limited 303 Alazarrana Road Stipp Darty Parformance Centre Singspore 159341

Witnessed by Reporting Centre Personnel 2 0 DEC 2017

Sketch Plan Pg. 3





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 4 Report No. T/20171219/2170

REPORT O	F A TRAF	FIC ACCIDENT
----------	----------	--------------

Date/Time Report Made: 19/12/2017 21:49			Vide Report No.:	Station Diary No.	
Informar	t's Partic	ulars			
Name of HAN MEI	Informant: LIN		Address: 767A MOUNTBATTEN F	RD SINGAPORE 437767	
ID Type / ID No.: NRIC NO / S2195456Z			Contact No.: Home/Office:	TITE (1887) - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887 - 1887	
Nationality: SINGAPORE CITIZEN		EN	Email:		
Sex: Age: Date of Birth: Female 64 10/05/1953			Type of Informant: Driver		
Race: Chinese			Language: Institution / School Na		
Occupation: Retiree			Driving Licence Information: Class: 3 Date of Expiry:		

General Infor	mation of the Accid	ent			LUATE OF SUPER-SIZE OF
Type of Accident:	Non-Injury	Drink Drive No	: /	Date/Time of Accident: 19/12/2017 17:25	Type of Location: Car Park
Along Road 1 ANG MO KIO BLOCK 202					
Weather: Clear		Road Surface Dry	9.	R	load Speed Limit:
Traffic Flow:	Traffic Contro	affic Control:		Traffic Volume: No Traffic	
Type of Collis Moving Vehic	ilon: le Against - Parked V	ehicle		1000	nyone conveyed by mbulance: lo

Vahiala Ma	Tunn	5.4-lan	Madel	Cale	615.40	11 cm
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
MBU5353	Car				Seriously	0
					Damaged	
SBV3366K	Car				Seriously	1
					Damaged	
SGA7323J	Car				Slightly	0
					Damaged	100

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

Report No. T/20171219/2170

Tel No: 65470000

CONTINUATION OF REPORT

Name	NGAU CHUNG KEONG	ID N	0.	87041405209
Related Vehicle	MBU5353 (Car)	Cont	act No.	81317977
Hospital/Clinic	NIL	Class Drivin Licer Expir	ng	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	charge NIL	
No. of Days gran	ted Medical Leave NIL	Degree of Injury	NIL	
Driver				
Name	HAN MEI LIN	ID No).	S2195456Z
Related Vehicle	SBV3366K (Car)	Cont	act No.	96289655
Hospital/Clinic	NIL	Class Drivir Licer Expir	ng	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
	ted Medical Leave NIL	Degree of Injury	NIL	
Driver				
Name	CHUA BOON KIN	ID No	j.	S1454802E
Related Vehicle	SGA7323J (Car)	Cont	act No.	97842013
Hospital/Clinic	NIL	Class Drivis Licer Expir	ng	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
	ted Medical Leave NIL	Degree of Injury	NIL	

Brief Details.

AT THE ABOVE MENTIONED TIME, DATE AND LOCATION.

I WAS PARKING MY CAR AT AMK AVE 3 BLOCK 202. I PUT MY CAR GEAR TO REVERSE, AS I WAS ATTEMPTING TO REVERSE PARK, BUT WHEN I PRESSED ON THE ACCELERATOR, THE CAR MOVED FORWARD INSTEAD OF BACKWARDS AND I WAS SHOCKED. MY CAR COLLIDED INTO THE MALAYSIAN CAR WITH THE REGISTRATION NUMBER: MBU5353 (VEHICLE NO.1) AND THEN I TRIED TO STOP MY CAR BUT IT COULD NOT STOP AND IT KEEP COLLIDING WITH THAT VEHICLE IN FRONT OF ME, AS A RESULT THE VEHICLE SHIFTED AND WENT UP THE CURB AND GLIDED AGAINST THE OTHER CAR WITH THE REGISTRATION NUMBER: SGA7323J (VEHICLE NUMBER 2). I WAS PANICKING BUT I EVENTUALLY TURNED OFF MY CAR ENGINE AND IT FINALLY STOPPED. I DO NOT KNOW WHY MY CAR HAD SUCH A MALFUNCTION. MY CAR

Sketch Plan Pg. 5



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 4 Report No. T/20171219/2170

CONTINUATION OF REPORT

SUFFERED SOME SERIOUS DAMAGES AT THE FRONT SIDE AND MY LICENCE PLATE ALSO FELL OFF. VEHICLE NUMBER MBU5353 ALSO HAD SOME DAMAGES AT THE FRONT. VEHICLE SGA7323J HAD VERY MINOR DAMAGES AT THE LEFT SIDE, JUST A SMALL SCRATCH. AFTER THE INCIDENT, VEHICLE NO 1 ALARM WENT OFF AND THE DRIVER CAME TO THE SCENE. HE ASKED ME TO KEEP MY VEHICLE THERE. THEN SOMEONE CALLED THE POLICE, A TOW TRUCK AND POLICE ARRIVED AT THE SCENE. THE TOW TRUCK MOVED VEHICLE NO 1 AS IT WAS LEANING AGAINST VEHICLE NO 2. THEN ALL OF US EXCHANGED PARTICULARS AND I WAS THEN ADVISED TO HEAD DOWN TO TRAFFIC POLICE HQ TO MAKE A REPORT AND MEET IO

Sketch Plan Pg. 6



Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

4 of 4 Report No. T/20171219/2170

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Informant:

Signature Of Officer Recording The Report: KHALED AMR HASSAN MOHSSEN Date/Time: Signature Of Interpreter: 19/12/2017 21:49 Not applicable Classification Of Case: Officer In Charge Of Case: TP/GIA/ SIMEASURE Staff Sgt TANG SIEW PING ASSA, FOLICE FORCE Contact No.: 65476430 Genziure: Authentication Stamp NP168


Enquire PARF/COE Rebate for Registered Vehicle


Owner ID Type:	Singapore NRIC
The state of the s	01922
Owner ID:	5456Z
/ehicle Details	
/ehicle No.:	SBV3366K
/ehicle to be Exported:	Yes
ntended De-registration Date:	22 Dec 2017
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON
0.3010.00730.003.00.000	HEADLAMP
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	A779I100N46B20BE
Chassis No.:	WBANT12020CX29080
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$45,018.00
Original Registration Date:	26 Feb 2008
First Registration Date:	26 Feb 2008
Transfer Count:	0
Actual ARF Paid:	\$49,520.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2018
PARF Rebate Amount:	\$24,760.00
Intended COE Rebate Details	

25 Feb 2018
B - Car (1601cc & above)
10
\$13,289.00
\$233.00
\$24,993.00

The information contained herein is correct as at 21 Dec 2017

ок





Recommended for you



[Help] Selling price for almost 2 years old BMW



24 car-related fees to rise from December



Techron D Concentrate for a superior clean



Big features in the Pioneer DEH-S5050BT



BMW 5 series get new turbocharged engines



BMW 520i for long term rent / takeover

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, CPC cars. vans, luxury cars, sports cars, SUV, MIV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, low mileage cars, car brands, car insurance, carpanir rates, car audio, car gracming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings. Singapore jobs, real estate properties for sale. Facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on spCarMart.com are gathered from sources and based on algorithms that are believed by spCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
 New Car
- Used Car
 Sell Car
- Motoring Directory
- Products Guide
 Article
- Forum
 Tool & Tip
- © 2004-2017 sgCarMart. All rights reserved.

- About Us
- Contact Us
 Sitemap

- Privacy Policy
 Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
wner ID:	5456Z
ehicle Details	
ehicle No.:	SBV3366K
ehicle to be Exported:	No
ntended De-registration Date:	26 Dec 2017
ehicle Make:	B.M.W.
ehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
rimary Colour:	White
Manufacturing Year:	2007
Engine No.:	A779I100N46B20BE
Chassis No.:	WBANT12020CX29080
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$45,018.00
Original Registration Date:	26 Feb 2008
First Registration Date:	26 Feb 2008
Transfer Count:	0
Actual ARF Paid:	\$49,520.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2018
PARF Rebate Amount:	\$24,760.00

COE Expiry Date:	25 Feb 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$13,289.00
COE Rebate Amount:	\$227.00
Total Rebate Amount:	\$24,987.00

The information contained herein is correct as at 26 Dec 2017

ОК

Performance Motors Limited BMW Dealer Co. Reg. No. 197401559W UST Reg. No M2-0020081-x 203, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel: 63190100 (Sales & Admin) 63190111 (AfterSales) Fax: 64747770

280. Kampong Arang Road Bast Coast Centre Singapore 435180 Tel. 62190555 AfterSales) Fax 63449773

LKK Auto Consultants hence notify 315, Alexa Sime Darby Bothe Repairer of the following: 10 resurvey before/after spray painting 13 a 10 digital barraged part(s) during resurvey Fax. 6479 6601 Arts prices are subject to confirmation

a Third party survey is on a "Without Prejudice" basis

GST REG. NO: M2 - 0020081 llegal mx ification(s) is allowed Supplementary item(s) must be resurveyed and

E S T I M A T E is subject to final approval from Insurance Company

Acknowledged by Repairer

Page No. : 2 of 2 Date:

Estimate No. Date Estimated

45253 : b1 : 21/12/2017

Prepared By

: Merina Chia San San

MILEAGE REGN. DATE MODEL CHASSIS NO. REGN. NO. 0 520iA 26/02/2008 CX29080 SBV3366K

DECORTEMION 0	ΓY	PRIC	VALUE
DESCRIPTION 3 BONNET LH HINGE 3	1	74.05	74.05
BONNET RH HINGE	1	74.05	74.05
	1	86.95	86.95
FRT BUMPER SUPPORT LEDGE V Deform	1	25.00	25.00
FRT BUMPER LOWER SPOILER V DE FARM	1	25.00	25.00
FRT BUMPER LOWER SPOILER	1	38.35	38.35
FRI BUMPER CHIFLAP COVERING PRIMED V DISG	1	38.35	38.35
FRT BUMPER RH FLAP COVERING PRIMED V DEG	1	18.15	18.15
FRT BUMPER LH SIDE SUPPORT BKT V NEC	1	18.15	18.15
FRT BUMPER RH SIDE SUPPORT BKT V NEC	1	1,121.75	1,121.75
FRT BUMPER (PDC) So Octor vomg	4	641.40	641.40
FRT BUMPER CARRIER A Octor	1	53.40	53.40
FRT BUMPER LH ABSORBER ?	1	53.40	53.40
FRT BUMPER RH ABSORBER ?	1	65.85	65.85
FRT BUMPER LH GRID LATERAL ?	1	65.85	65.85
FRT BUMPER RH GRID LATERAL ?	1	54.20	54.20
FRT BUMPER CTR GRID	1	29.35	29.35
FRT BUMPER SPOILER	2	0.80	1.60
EMBLEM GROMMET	1	67.80	67.80
BMW EMBLEM V NEC	4	23.10	23.10
BONNET UPPER CATCH BKT 7 3M	4	37.55	37.55
BONNET HOOD CATCH VIM	4	57.50	57.50
BONNET CENTER SEALING V NEC	2	19.55	39.10
DOINTE I SIDE SEALING	1	162.70	162.70
FRT BUMPER LH NOZZLE JET ?	4	162.70	162.70
FRT BUMPER RH NOZZLE JET ?	4	2,514.05	2.514.0
LH BI-XENON HEADLIGHT 7.	4	2,514.05	2,514.0
RH BI-XENON HEADLIGHT V CON+	4	251.85	251.8
FOG LAMP LEFT :	- 2	251.85	251.8
FOG LAMP RIGHT ?	- 1	1.003.35	1.003.3
A/C CONDENSER 7.	- 1		19.8
DECOUPLING RING PDC TORQUE CONVERTE :	4	4.95	1,452.2
	4	363.05	1,402.2
Sebassian. 22/12/2017 Photo Before Paint.	To	tal Parts	: 14,087.7
PDC sensor: Sebastion . 22/12/2017 Photo Before Paint. - Part by part repair Repair Subject To Market Value. - Guestion Mark Item Photo			
- Grustian Mark Item			

Dain & Time	130 130	Labour 1 Parts	1	12,395.00 14,087.75
Europora Harra Schastian Surveyora Tol 90036124	11.4	Labour 2 Excess	:	0.00 0.00
		Total GST @ 7%	:	1,853.79
		Grand Total	1	28,336.54

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

BMW Dooser

Performance Motors Limited

Co. Reg. No. 197401559W OST Reg. Bo M2-0010081-x

303, Alexandra Boad Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64247770

(Per panel).

BONNET

107

280, Eampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315. Alexandra EDAG Sime Darby Business Centre Singapore 159944 Tel 63150528 [AfterSales] 63190533/530 [Motorrad] Fax 64796601 [AfterSales] 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

21 DEC 2017

ESTIMATE

Page No. : 1 of 2 45253 : b1 Estimate No. Date Estimated : 21/12/2017 : Merina Chia San San Prepared By - ACCOUNT -- ESTIMATE REPAIR FOR -MSIG Insurance (S) Pte Ltd Han Mei Lin 4 Shenton Way 767A Mountbatten Road #21-01 SGX Centre 2 Singapore 068807 Singapore 437767 MILEAGE REGN. DATE MODEL REGN. NO. CHASSIS NO. 0 520iA 26/02/2008 CX29080 SBV3366K VALUE DESCRIPTION 4,675,00 850 /day To replace front bumper, front wall, bonnet including 3400 attachments etc and to knock out dented area caused by accident 3695 4.106.00 To paint front bumper, bonnet, front right fender and front left fender 195.00 To tow accident vehicle to PML workshop. 83.00 To supply front emboss number plate. 826.00 To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct checks for

leak. (For all models except 7 series). 150 177.00 To check electrical wiring systems at the front section for proper function including adjustments of headlights. 1,062.00 To replace both left and right headlights including program and conduct tests for proper function. 1,003.00 To replace air con condenser and air con hose including to

vacuum system, top up freon gas and check for leak. (For all models except for 7 series). 100 118:00 To carry out body cavity preservation.

150.00 Sundries.

PRIC 896.60 896.60 RADIATOR

Total Labour 1:

2,148.70

12,395.00

2,148.70

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submi	tted Status		
Main	20 Dec 2017	Lat Dublinged	22 Dec 2017 10:1 Edit Adj Rpt		S\$0.00 View Rpt	Pending f	or Survey Report	
	Main	Refere	ence	Claim Details		ocuments	Show All	
CLAIM S	UBFOLDER DET	AILS	THE RESERVE TO SHARE SHARE			[Created by ins	urer]	
Insured:		HAN MEI LIN	N, ID: S2195456Z,	Tel: +6596289655,	Email: NOEM/	AIL		
Vehicle Re	g. No.:	SBV3366K		Date of Loss:		19/12/2017 17:00) - :59	
Claim Typ	e;	OD / 54181	19	Policy/Cover Note	Policy/Cover Note No.: 10112761 (Comprel Coverage: 26/02/20			
				Excess:		S\$750.00		
Repairer:		Alexandra - T	el: 63190172/63190		250.00002335200			
Handling	Insurer:	Singam - 659	942471]	te. Ltd. (HQ) - Tel: +6				
Adjuster:		[Final Rpt	due 21/01/2018]				g Wai Keen]	
Driver/Cu	stodian:			IC: S2195456Z, Tel: +				
Adj Asg. F	Remarks:	also the steer value, rebates	ing wheel system if t s and net value to de	survey by today. Survey they are in efficient cond termine if it is economic m Performance Motors 8	fitions. Old ca cal to repair a	r (year 2008). Plea: nd also get a copy (se check market of the latest	
ASSOCIA	ATED MAIL REC	EIVED				View All	Compose Case Mail	
	ec (02/01/2010)	Alort - Adi Mano	date Revoked - SBV	/3366K - Claim Handle	er: Vimmala	D/O Raja Singam	r	
MSIG_	56 (03/01/2016)	. Alert - Auj Plant						
01120375-55	OCIATED TASK			View All	Search T	asks Create New		

Claim Documents

*SBV3366K (541819)
OD
Dec 19 2017 5:00PM
[HAN MEI LIN]
Performance Motors Limited

_		pload Photos Compose New Letter	1 per	page 🗸	✓
sse	ssment Reports	Performance Motors Limited (Alexandra)		Thumbnail	Print
0	Finalized On	Accident Statement	0	Load HTM	
	20/12/17 18:17	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
10	Finalized On 26/12/17 16:41	Adjuster Immediate Advice	6	Load HTM	
	20/12/17 10:41			- paring	-
hot	tos/Images		3 pe	r page 💙	N
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Prin
1	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	<u>N</u>
2	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	A
3	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	6	Load JPG	<u>N</u>
4	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
5	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	\mathbf{Z}
6	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
7	20/12/17 17:39	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
8	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
9	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
10	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
11	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Z
12	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	<u> </u>
13	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	0.000000	S
14	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		<u>~</u>
15	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		✓
16	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		Z
17	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
18	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		$\overline{\Delta}$
19	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	-	Z
20	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		✓
21	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		Z
22	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		✓
23	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0		V
24	20/12/17 17:40	Accident Photo	€	Load JPG	

		[Linked Accident Report Documents]			✓
25	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	~
26	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
27	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
8	20/12/17 17:40	Accident Photo [Unked Accident Report Documents]	0	Load JPG	✓
9	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
30	20/12/17 17:40	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
	03/01/18 12:11	General View	0	Load JPG	✓
2	03/01/18 12:11	General View	0	Load JPG	✓
3	03/01/18 12:11	General View	0	Load JPG	V
1	03/01/18 12:11	General View	0	Load JPG	✓
5	03/01/18 12:11	General View	0	Load JPG	~
5	03/01/18 12:11	General View	0	Load JPG	V
7	03/01/18 12:11	General View	0	Load JPG	V
3	03/01/18 12:11	General View	0	Load JPG	V
,		General View	0	Load JPG	V
	03/01/18 12:11	General View	0	Load JPG	V
10	03/01/18 12:11	General View	0	Load JPG	V
11	03/01/18 12:11		0	Load JPG	V
12	03/01/18 12:11	General View	0	Load JPG	3
3	03/01/18 12:11	General View	0		A
4	03/01/18 12:11	General View		Load JPG	-
15	03/01/18 12:11	General View	0	Load JPG	✓
16	03/01/18 12:11	General View	0	Load JPG	V
17	03/01/18 12:11	General View	0	Load JPG	✓
18	03/01/18 12:11	General View	0	Load JPG	⊻
19	03/01/18 12:11	General View	0	Load JPG	✓
20	03/01/18 12:11	General View	0	Load JPG	V
21	03/01/18 12:11	General View	0	Load JPG	✓
22	03/01/18 12:11	General View	0	Load JPG	✓
23	03/01/18 12:11	General View	0	Load JPG	4
24	03/01/18 12:11	General View	0	Load JPG	V
25	03/01/18 12:11	General View	0	Load JPG	✓
26	03/01/18 12:11	General View	0	Load JPG	V
27	03/01/18 12:11	General View	0	Load JPG	$\overline{\mathbf{A}}$
28	03/01/18 12:11	General View	0	Load JPG	$\overline{\mathbf{A}}$
29	03/01/18 12:11	General View	0	Load JPG	☑
30	03/01/18 12:11	General View	0	Load JPG	V
31	03/01/18 12:11	General View	0	Load JPG	V
32	03/01/18 12:11	General View	0	Load JPG	✓
33	03/01/18 12:11	General View	0	Load JPG	V
34	03/01/18 12:11	General View	0	Load JPG	V
		General View	0	Load JPG	V
35	03/01/18 12:11		0	Load JPG	₩.
36	03/01/18 12:11	General View	0	Load JPG	N N
37	03/01/18 12:11	General View	0		✓
38	03/01/18 12:11	General View		Load JPG	-
39	03/01/18 12:11	General View	0	Load JPG	A
40	03/01/18 12:11	General View	0	Load JPG	V

41	03/01/18 12:11	General View	0	Load JPG	$\overline{\mathbf{v}}$
	03/01/10 12:11	700	0	Load JPG	✓
42	03/01/18 12:11	General View	0	Load JPG	V
43	03/01/18 12:11	General View	0	Load JPG	▼
44	03/01/18 12:11	General View		Load JPG	₹
45	03/01/18 12:11	General View	0	1000000000	N N
46	03/01/18 12:11	Odometer Reading	0	Load JPG	-
47	03/01/18 12:11	General View	0	Load JPG	✓
48	03/01/18 12:11	Chassis Number	0	Load JPG	✓
49	03/01/18 12:11	General View	0	Load JPG	V
-0.50		General View	0	Load JPG	V
50	03/01/18 12:11	Constant of Francisco	0	Load JPG	V
51	03/01/18 12:11	General View	Õ	Load JPG	✓
52	03/01/18 12:11	General View	0	Load JPG	V
53	03/01/18 12:11	General View			₩.
54	03/01/18 12:11	General View	0	Load JPG	_
55	03/01/18 12:11	General View	0	Load JPG	✓
56	03/01/18 12:11	General View	0	Load JPG	✓
			1 pe	er page V	V
Do	cumentation	(a) and (HO)	house	Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	0	Load PDF	1
1	21/12/17 09:20	PARF/COE rebate details	Ō	Load PDF	
2	21/12/17 09:21	Road tax expiry date - 25/02/2018	ō	Load PDF	
3	22/12/17 10:09	Estimate from Performance Motors	0	Load PDF	
4	05/01/18 16:42	Discharge form to be sign by OI for CTL	0	Load PDF	
5	05/01/18 16:42	Email to OI - Acceptance Discharge form		Thumbnail	Print
No	Finalized On	Performance Motors Limited (Alexandra)	0	Load TIF	
1	20/12/17 17:38	Sketch Plan [Linked Accident Report Documents]	U		D. Just
No	Relabel/Reorde	Marie and the second se		Thumbnail	Print
1	26/12/17 16:28	Log card (if available)	6	Load PDF	
2	26/12/17 16:28	WORKSHOP ESTIMATE	0	Load PDF	-
3	28/12/17 10:34	MAINTENANCE SERVICING RECORD	0	Load PDF	-
4	08/01/18 09:06	LTA REBATE 26 DEC 2017	0	Load PDF	

Linked Accident Report Documents

			V	iew View in Bro	wser V
	Danaste		1 pe	r page 🔻	V
-	ssment Reports	Performance Motors Limited (Alexandra)		Thumbnail	
No 1	Finalized On 20/12/17 18:17	Accident Statement	6 Load HTM		
Dh.o	tos/Images		3 pe	r page 🔻	☑
No.	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	20/12/17 17:39	Accident Photo	0	Load JPG	✓
	20/12/17 17:39	Accident Photo	0	Load JPG	\square
2		Accident Photo	0	Load JPG	✓
3	20/12/17 17:39	Accident Photo	0	Load JPG	V
4	20/12/17 17:39		0	Load JPG	$\overline{\mathbf{A}}$
5	20/12/17 17:39	Accident Photo	0	Load JPG	V
6	20/12/17 17:39	Accident Photo	0	Load JPG	V
7	20/12/17 17:39	Accident Photo	0	Load JPG	V
8	20/12/17 17:40	Accident Photo			V
9	20/12/17 17:40	Accident Photo	0	Load JPG	-
10	20/12/17 17:40	Accident Photo	0	Load JPG	V
11	20/12/17 17:40		0	Load JPG	☑
12	20/12/17 17:40		0	Load JPG	

	1				V
13	20/12/17 17:40	Accident Photo	0	Load JPG	✓
14	20/12/17 17:40	Accident Photo	0	Load JPG	✓
15	20/12/17 17:40	Accident Photo	0	Load JPG	\checkmark
16	20/12/17 17:40	Accident Photo	0	Load JPG	V
17	20/12/17 17:40	Accident Photo	0	Load JPG	\checkmark
18	20/12/17 17:40	Accident Photo	0	Load JPG	\checkmark
19	20/12/17 17:40	Accident Photo	0	Load JPG	V
20	20/12/17 17:40	Accident Photo	0	Load JPG	V
21	20/12/17 17:40	Accident Photo	0	Load JPG	4
22	20/12/17 17:40	Accident Photo	0	Load JPG	V
23	20/12/17 17:40	Accident Photo	0	Load JPG	V
24	20/12/17 17:40	Accident Photo	0	Load JPG	\checkmark
25	20/12/17 17:40	Accident Photo	6	Load JPG	V
26	20/12/17 17:40	Accident Photo	0	Load JPG	✓
27	20/12/17 17:40	Accident Photo	0	Load JPG	V
28	20/12/17 17:40	Accident Photo	0	Load JPG	✓
29	20/12/17 17:40	Accident Photo	0	Load JPG	\mathbf{Z}
30	20/12/17 17:40	Accident Photo	0	Load JPG	Y
Do	cumentation		1 pe	r page	V
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	20/12/17 17:38	Sketch Plan	0	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	^			
	~			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG17024309/SQD3S2

Date:

08/01/2018

REFERENCE

Date of Loss:

Insured/Claimant:

HAN MEI LIN 19/12/2017

Policy No:

Nature of Claim:

10112761 OD

Engine No:

Odometer:

Chassis No:

Claim No:

68426 km

A779I100N46B20BE

WBANT12020CX29080

541819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Colour:

Reg. Date:

Make & Model:

BMW 5201, 2.0 (A)

26/02/2008 (Man. Year: 2007)

White

Engine Capacity: Market Value/New Car Price: 1995 cc \$\$28,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/55 R16

Rear Tyre Size:

225/55 R16

Front Left Side: Front Right Side: Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
	0.00	0.00	0.00	
Parts Miscellaneous Items	0.00	0.00	0.00	
MATERIAL	0.00	0.00	0.00	
Labour Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	-750.00	-750.00	0.00	0.00

INSPECTION

Date of Assignment:

22/12/2017

Date Inspected:

22/12/2017 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

0.0 days

Sebastian Yeang Wai Keen Adjuster:

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$28,000.00 OMV : \$45,018.00

PARF Rebate (1): \$24,760.00 Quota Premium Paid: \$13,289.00 COE Rebate (2): \$ 227.00

Total Rebate (1) + (2) =: \$24,987.00

The total amount incurred will be Market Value \$28,000.00 minus Total Rebate \$24,987.00 = \$3,013.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 08 Jan 2018)

Parts:

143

BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBV3366K)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >