

QTY	DESCRIPTION - SPECIAL NETT	LEFT	RIGHT	PRICE
1	TAILGATE WINDSCREEN SEALANT / <i>na</i>			60 120 ✓
1	TAILGATE CARPLATE X <i>su</i>			80 ✓
1	TAILGATE STICKER (70KM/H) / <i>na</i>			20 ✓
1	TAILGATE STICKER (5PAX) / <i>alc</i>			20 ✓
2	REAR BUMPER REVERSE SENSOR / <i>slab</i>	1	1	200 ✓
1	REAR FENDER SEALANT X <i>on</i>			120
1	REAR FLOOR PANEL TOP COVER X <i>su</i>			180
QTY	DESCRIPTION - LABOUR	LEFT	RIGHT	PRICE
1	TO RNR AND ACCIDENT AFFECTED BACK			800 2200 ✓
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED BACK			800 1500 ✓
1	TO RUST PROOF ACCIDENT AFFECTED BACK			50 80 ✓
1	TO RNR REVERSE SENSOR AND CHECK FUNCTION			30 120 ✓
1	TO RNR EXHAUST PIPE ASSY			180 ✓
1	TO RNR TAILGATE WINDSCREEN			180 120 ✓
1	TO CHECK WATER SEEPAGE			80 50 ✓
1	TO RNR LUGGAGE COMPARTMENTS			120 ✓
1	TO RNR TAILGATE MECHNISM			120 50 ✓
PARTS SUBTOTAL : \$5001.37				
LESS 250% : (\$1250.34)				
PARTS TOTAL : \$3751.03				
SPECIAL NETT TOTAL : \$380				
LABOUR TOTAL : \$1900				
GROSS REPAIR : \$6031.03				
LESS 20% : (\$1206.21)				
NETT REPAIR COST : \$4850				

Kalan 10/11/14

22/12/17 1820km

It 4 Pays

L/S

After Repair photo

19345.63

3750.58
2600