

SURVEYOR

Meimen

Kalin

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time

22/12/17 @ 9.49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GU6123X

Insured:

GBB 1176K

at Workshop m/s

Ethicarz

Tel:

G384 4404

of

56 Layang way # 04-04, 508775

Policy No:

27940957 MKC

Claim No:

542082

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

20/12/2017

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11.55am @ 22/12/17

Person Contacted:

John

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GU6123X - N/A / INC 09 002672 / y 1
	GBB 1176K - X
26/12/17 @ 5.30p	revised to Catherine Thia via Meimen.
29/1/18 @ 10.55am	2001 revised to Catherine Thia via Meimen.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____ 0200
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / FR Seen: _____ Consistent? Yes or No
 Est. Repair: 5 days Res: Yes or No
 Lump Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

N/S	O/S

Veh No: 64 6123x 18 Apr 201
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Litae 2184
 Colour: Silver A/C Insured / Std / NI / NA
 So Reading: 344251 T-Ratio: Insured / Std / NI / NA
 Eng No: _____
 C No: CR 420018505
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inok / Jammed / Leaked / Burnt or
 Brake: Inok / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / 6 SD A/Rim or
 Tyre Size: F: 16+ R12C
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 7 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 7 mm
 D/OA: 20/12/17 D/OI: 24/12/17
 Survey held at: Ethicon
 Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
 Pen
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
 26/1/18 a. Called 4644850 / 5 Mr. (Ref B 14495.43, 75%)

MSA

29/1/2018

RECEIVED 31 JAN 2018

Date/Time File Pass to: ☐ Preli. Report
 31/1/18 ☐ Final Report
 Date/Time File Return to:

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$
☐ Inter. Insp \$
☐ Tech. Insp \$
☐ Weekend \$

Report Format: MER-TP
 Lump Sum / I.B. 4850

Subs. Fee: 300
 Other Fee: _____
 Total: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024313/K1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 1176K	Veh. Inspected	GU 6123X
Policy No.	27940957MKC	Coverage (\$)	0.00
Claim No.	542082	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/12/2017	Inspection Date	22/12/2017
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: CA/MSK/170243131/14683
 Policy Type: OD/TP/TP RES/TL/EVA

GA 6123x

Case Handler

Typist

Admin (Niraj): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Calvin): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			
✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Calvin 29/1/18
 Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		22 Dec 2017 09:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	S.S. Kim Enterprise Pte Ltd, Co. Reg. No.: 200105920Z		
Main Claimant:	Pan Seas Enterprise (Pte) Ltd, Co. Reg. No.: 196600200W		
Vehicle Reg. No.:	GU6123X	Date of Loss:	20/12/2017 09:00 - :59
Claim Type:	TP / 542082	Policy/Cover Note No.:	27940957MKC Coverage: 07/08/2017 - 06/08/2018
Vehicle Reg. No. (Insured):	GBB1176K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 29 Jan 2018

Preliminary Advice

Insured Vehicle No	: GBB1176K	Accident Date	: 20/12/2017
TP Vehicle No	: GU6123X	Assignment Date	: 22/12/2017
Make	: TOYOTA LITEACE	Est. Duration of Repair	: 5.00
Date of Inspection	: 22/12/2017		
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,345.63
Revised Amount	:S\$	6,431.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,431.03
Lump Sum Repair	:S\$	4,850.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

12/26/2017

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 26 Dec 2017

Preliminary Advice

Insured Vehicle No	: GBB1175K	Accident Date	: 20/12/2017
TP Vehicle No	: GU6123X	Assignment Date	: 22/12/2017
Make	: TOYOTA LITEACE	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/12/2017		
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,320.00 (SN + LABOUR)
Revised Amount	:S\$	2,200.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,200.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
PENDING FOR PARTS PRICES.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0200W
Vehicle Details	
Vehicle No.:	GU6123X
Vehicle to be Exported:	No
Intended De-registration Date:	26 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACEDAUTO
Primary Colour:	White
Manufacturing Year:	2001
Engine No.:	3C3906064
Chassis No.:	CR420018505
Maximum Power Output:	-
Open Market Value:	\$24,614.00
Original Registration Date:	18 Apr 2001
First Registration Date:	18 Apr 2001
Transfer Count:	1
Actual ARF Paid:	\$1,231.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,394.00
COE Rebate Amount:	\$20,800.00
Total Rebate Amount:	\$20,800.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2017 15:15
Date Of Accident	20/12/2017 09:55
Exact Location Of Accident	KALLANG RD/CAVENDER ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU6123X
Insured/Policyholder	
Name Of Registered Owner	PAN SEAS ENTERPRISE (PTE) LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81669518
Alternative Phone No	OFFICE-81669518

Vehicle Particulars

Manufacturer	TOYOTA
Model	VAN
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DHOM110155851700
Cover Note Number	

Driver

Name of Driver	FANG JIALONG
Passport No/FIN	G8101938Q
Date Of Birth	02/05/1969
Occupation	INDOOR
Date Of Driving Pass	06/05/2008
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81669518
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	35B FISHERY PORT RD JURONG CENTRAL FISH MARKET
Postcode	619744
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHEN APPROACH TRAFFIC LIGHT JUNCTION OF KALLANG RD/CAVENDER ST. THE LIGHT TURN RED SO I QUICKLY APPLIED BRAKE AND MANAGE TO STOP IN TIME. ABOUT 2-3 SEC LATER, A VEHICLE CAME FROM BEHIND HIT ONTO THE REAR PORTION OF MY VEHICLE. ATTENDED BY LYNDIA

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB1176K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZIN HTET OO
NRIC/Passport Number	G3172828U
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Reporting Centre
Name: Tel: 6560 3312 Fax: 6568 0722
Email: vacbb@singnet.com.sg
NRIC/IN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

UDAC BUKIT BAI (UK) (VAC)

511 12 18 2304 11 23

Due: 4/16/25

Reporting Centre Personnel's Signature _____

Name: _____
Email: vachb@singnet.com.sg
NRIC/PR No. _____



United Overseas Insurance Limited
3 Anson Road #28-01 Springvale Tower Singapore 079909
Tel: (65) 6221 7723 Fax: (65) 6327 3886 / 6327 3670
Email: ContactUs@uoi.com.sg
uoi.com.sg
Co. Reg. No. 197100152R

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)

Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1958 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DH0M110155851700	Excess:	\$0/-NOT APPLICABLE
Type of Cover	THIRD PARTY		
Vehicle Number	GU6123X		
Name of Insured	PAN SEAS ENTERPRISES (PTE) LTD		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 18 April 2017 to 31 March 2018

Engine# 3C3906084
Chassis# CR420018505

Goods carrying - Private Type [MZ 500]

AUTHORISED DRIVER

Any person who is driving on the Insured's order or with their permission

LIMITATIONS AS TO USE

- (1) Use in connection with the Insured's business
- (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business
- (3) Use for social domestic and pleasure purposes

THE POLICY DOES NOT COVER

- (1) Use for hire or reward or for racing pace-making reliability trial or speed-testing
- (2) Use whilst drawing a trailer except the towing of any disabled mechanically propelled vehicle


Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

*Limitation rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia)

UNITED OVERSEAS INSURANCE LTD

FCZAH Date : 14/03/2017


For the Company

REPUBLIC OF SINGAPORE - DRIVING LICENCE

08101938Q

FANG JIALONG

Date of Birth: 02 May 1969
 Valid Till: 10 Apr 2013
 Valid Till: 05 May 2013

002169700K



Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer:
PAN SEAS ENTERPRISES PRIVATE LIMITED

Sector: **MANUFACTURING**

Name:
FANG JIALONG

Occupation:
LOGISTICS SUPERVISOR


S Pass No.
S 578078ES

Date of Application:
19-04-2017

Date of Issue:
11-05-2017

Date of Expiry:
21-05-2018





L7920114

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 06 May 2008

NP 428A

Licence No: 08101938Q



VISIT PASS
 Immigration Regulations

Name:
FANG JIALONG

Date of Birth: 02-05-1969 Sex: M Nationality: CHINESE

Pin: 08101938Q Date of Issue: 11-05-2017 Date of Expiry: 21-05-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.






Ethicarz Pte. Ltd, 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:	GU6123X
MAKE & MODEL:	TOYOTA VAN
MILEAGE:	344251
TYRE:	YOKOHAMA 165/R13C P15
CHASSIS NUM:	CR420018505

ATTN:				
QTY	DESCRIPTION - PARTS	LEFT	RIGHT	PRICE
1	TAILGATE /			
1	TAILGATE WINDSCREEN GLASS MOULD /			
1	TAILGATE WIPER ARM /			
1	TAILGATE WIPER MOTOR X			
1	TAILGATE OPENER /			
1	TAILGATE GARNISH HANDLE /			
1	TAILGATE CARPLATE LAMP X			
1	TAILGATE LOCK /			
1	TAILGATE WEATHER STRIP X			
1	TAILGATE HINGE X			
1	TAILGATE DAMPER X			
1	TAILGATE BOARD /			
1	TAILGATE BOARD CLIP /			
2	TAILLAMP X	1	1	
2	TAILLAMP GARNISH X	1	1	
2	TAILLAMP CLIP X	1	1	
1	REAR BUMPER /			
2	REAR BUMPER RETAINER /	1	1	
2	REAR BUMPER BRACKET /	1	1	
2	REAR BUMPER REFLECTOR X	1	1	
2	REAR BUMPER CLIP /	1	1	
2	REAR FENDER X <i>regr</i>	1	1	
2	REAR FENDER COWLING X	1	1	
2	REAR FENDER COWLING CLIP X	1	1	
2	REAR FENDER MUDFLAP X	1	1	
2	REAR FENDER SEALANT X	1	1	
1	REAR END PANEL <i>(flame panel)</i> X			
1	REAR END PANEL TOP GANISH ?			
1	EXHAUST PIPE X			
1	EXHAUST PIPE MOUNTING X			
1	EXHAUST PIPE HEAT SEAL X			
1	EXHAUST PIPE GASKET X			



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844484, FAX: 63840444

VEHICLE NUM:	GU6123X
MAKE & MODEL:	TOYOTA VAN
MILEAGE:	344251
TYRE:	YOKOHAMA 165/R13C P15
CHASSIS NUM:	CR420018505

ATTN:				
QTY	DESCRIPTION - PARTS	LEFT	RIGHT	PRICE
1	TAILGATE <i>del</i>			1213.4
1	TAILGATE WINDSCREEN GLASS MOULD <i>del</i>			181.4
1	TAILGATE WIPER ARM <i>del</i>			121.5
1	TAILGATE WIPER MOTOR <i>X</i> <i>sm</i>			386.4
1	TAILGATE OPENER <i>del</i> <i>sm</i>			260.71
1	TAILGATE GARNISH HANDLE <i>del</i> <i>sm</i>			406.40
1	TAILGATE CARPLATE LAMP <i>X</i> <i>sm</i>			140 x 2 pcs
1	TAILGATE LOCK <i>del</i> <i>sm</i>			289.90
1	TAILGATE WEATHER STRIP <i>X</i> <i>sm</i>			287.75
1	TAILGATE HINGE <i>X</i> <i>sm</i>			262.7 x 2 pcs
1	TAILGATE DAMPER <i>X</i> <i>sm</i>			566.4 x 2 pcs
1	TAILGATE BOARD <i>del</i> <i>sm</i>			387.50
1	TAILGATE BOARD CLIP <i>del</i> <i>sm</i>			10 x 10 pcs
2	TAILLAMP <i>X</i> <i>sm</i>	1	1	404.20 x 2
2	TAILLAMP GARNISH <i>X</i> <i>sm</i>	1	1	186.9 x 2 pcs
2	TAILLAMP CLIP <i>X</i> <i>sm</i>	1	1	10 x 10 pcs
1	REAR BUMPER <i>del</i>			481.7
2	REAR BUMPER RETAINER <i>del</i> <i>sm</i>	1	1	36.3 x 2 pcs
2	REAR BUMPER BRACKET <i>del</i> <i>sm</i>	1	1	266.48 x 2 pcs
2	REAR BUMPER REFLECTOR <i>X</i> <i>sm</i>	1	1	123.1 x 2 pcs
2	REAR BUMPER CLIP <i>del</i> <i>sm</i>	1	1	10 x 10 pcs
2	REAR FENDER <i>X</i> <i>sm</i>	1	1	1817.20
2	REAR FENDER COWLING <i>X</i> <i>sm</i>	1	1	-
2	REAR FENDER COWLING CLIP <i>X</i> <i>sm</i>	1	1	-
2	REAR FENDER MUDFLAP <i>X</i> <i>sm</i>	1	1	141.33 x 2 pcs
2	REAR FENDER SEALANT <i>X</i> <i>sm</i>	1	1	-
1	REAR END PANEL <i>(flam panel)</i> <i>del</i> <i>sm</i>			672.90
1	REAR END PANEL TOP GANISH <i>del</i> <i>sm</i>			180
1	EXHAUST PIPE <i>X</i> <i>sm</i>			783.20
1	EXHAUST PIPE MOUNTING <i>X</i> <i>sm</i>			78
1	EXHAUST PIPE HEAT SEAL <i>X</i> <i>sm</i>			121.30
1	EXHAUST PIPE GASKET <i>X</i> <i>sm</i>			51.5

QTY	DESCRIPTION - SPECIAL NETT	LEFT	RIGHT	PRICE
1	TAILGATE WINDSCREEN SEALANT / <i>na</i>			60 120 ✓
1	TAILGATE CARPLATE <i>X</i> <i>na</i>			80 ✓
1	TAILGATE STICKER (70KM/H) / <i>na</i>			20 ✓
1	TAILGATE STICKER (5PAX) / <i>na</i>			20 ✓
2	REAR BUMPER REVERSE SENSOR / <i>slab</i>	1	1	900 ✓
1	REAR FENDER SEALANT <i>X</i> <i>na</i>			120
1	REAR FLOOR PANEL TOP COVER <i>X</i> <i>na</i>			180
QTY	DESCRIPTION - LABOUR	LEFT	RIGHT	PRICE
1	TO RNR AND ACCIDENT AFFECTED BACK			800 2200 ✓
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED BACK			800 1500 ✓
1	TO RUST PROOF ACCIDENT AFFECTED BACK			50 80 ✓
1	TO RNR REVERSE SENSOR AND CHECK FUNCTION			30 120 ✓
1	TO RNR EXHAUST PIPE ASSY			180 <i>X</i> <i>na</i>
1	TO RNR TAILGATE WINDSCREEN			180 720 ✓
1	TO CHECK WATER SEEPAGE			80 50 ✓
1	TO RNR LUGGAGE COMPARTMENTS			120 <i>X</i> <i>na</i>
1	TO RNR TAILGATE MECHNISM			120 50 ✓
PARTS SUBTOTAL : \$5001.37				
LESS 250% : (\$1250.34)				
PARTS TOTAL : \$3751.03				
SPECIAL NETT TOTAL : \$380				
LABOUR TOTAL : \$1900				
GROSS REPAIR : \$6031.03				
LESS 20% : (\$1206.21)				
NETT REPAIR COST : \$4824.82				

Kalon 16/11/14

22/12/17 1820

It 4 Pays

L/S

After Repair photo

19345.63

7250.58
2600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		22 Dec 2017 09:49 Edit Adj Rpt	S\$4,850.00 Edit Estimates	S\$4,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	S.S. Kim Enterprise Pte Ltd, Co. Reg. No.: 200105920Z								
Main Claimant:	Pan Seas Enterprise (Pte) Ltd, Co. Reg. No.: 196600200W								
Vehicle Reg. No.:	GU6123X	Date of Loss:	20/12/2017 09:00 - :59						
Claim Type:	TP / 542082	Policy/Cover Note No.:	27940957MKC Coverage: 07/08/2017 - 06/08/2018						
Vehicle Reg. No. (Insured):	GBB1176K	Policy No. (Claimant):							
		Excess:							
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 21/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GU6123X (542082)

[GBB1176K]

TP

Pan Seas Enterprise (Pte) Ltd

Dec 20 2017 9:00AM

[S.S. Kim Enterprise Pte Ltd]

Ethicarz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	26/12/17 17:30	Adjuster Immediate Advice							1	Load HTM	
2	29/01/18 10:52	Adjuster Immediate Advice							1	Load HTM	
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	22/12/17 17:48	General View							1	Load JPG	☒
2	22/12/17 17:48	General View							1	Load JPG	☒
3	22/12/17 17:48	General View							1	Load JPG	☒
4	22/12/17 17:48	General View							1	Load JPG	☒
5	22/12/17 17:48	General View							1	Load JPG	☒
6	22/12/17 17:48	General View							1	Load JPG	☒
7	22/12/17 17:48	General View							1	Load JPG	☒
8	22/12/17 17:48	General View							1	Load JPG	☒
9	22/12/17 17:48	General View							1	Load JPG	☒
10	22/12/17 17:48	General View							1	Load JPG	☒
11	22/12/17 17:48	General View							1	Load JPG	☒
12	22/12/17 17:48	General View							1	Load JPG	☒
13	22/12/17 17:48	General View							1	Load JPG	☒
14	22/12/17 17:48	General View							1	Load JPG	☒
15	22/12/17 17:48	General View							1	Load JPG	☒
16	22/12/17 17:48	General View							1	Load JPG	☒
17	22/12/17 17:48	General View							1	Load JPG	☒
18	22/12/17 17:48	General View							1	Load JPG	☒
19	22/12/17 17:48	General View							1	Load JPG	☒
20	22/12/17 17:48	General View							1	Load JPG	☒
21	22/12/17 17:48	General View							1	Load JPG	☒
22	22/12/17 17:48	General View							1	Load JPG	☒
23	22/12/17 17:48	General View							1	Load JPG	☒
24	22/12/17 17:48	General View							1	Load JPG	☒
25	22/12/17 17:48	General View							1	Load JPG	☒
26	22/12/17 17:48	General View							1	Load JPG	☒
27	29/12/17 17:41	Reinspection Photo							1	Load JPG	☒
28	29/12/17 17:41	Reinspection Photo							1	Load JPG	☒
29	29/12/17 17:41	Reinspection Photo							1	Load JPG	☒
30	29/12/17 17:41	Reinspection Photo							1	Load JPG	☒
31	29/12/17 17:41	Reinspection Photo							1	Load JPG	☒

32	29/12/17 17:41	Reinspection Photo	1	Load JPG	☒
33	29/12/17 17:41	Reinspection Photo	1	Load JPG	☒
34	29/12/17 17:41	Reinspection Photo	1	Load JPG	☒
35	29/12/17 17:41	Reinspection Photo	1	Load JPG	☒
36	29/12/17 17:41	Reinspection Photo	1	Load JPG	☒
37	26/01/18 18:00	Reinspection Photo	1	Load JPG	☒
38	26/01/18 18:00	Reinspection Photo	1	Load JPG	☒
39	26/01/18 18:00	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 10:59	SUPPLEMENTARY PART	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024313/K1QD3

Date: 01/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27940957MKC

Claimant Vehicle No : GU6123X

Insured Vehicle No : GBB1176K

Date of Loss: 20/12/2017

Nature of Claim:

TP

Claim No: 542082

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GU6123X

Make & Model: TOYOTA LITEACE, 2.2 D (A)

Engine No: 3C3906064

Reg. Date: 18/04/2001 (Man. Year: 2001)

Chassis No: CR420018505

Colour: Silver

Odometer: 344251 km

Engine Capacity: 2184 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165 R13C

Rear Tyre Size: 165 R13C

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,465.98	4,131.03	9,334.95	69.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,880.00	2,300.00	3,580.00	60.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,345.98	6,431.03	12,914.95	66.76
Approved Total (Overridden) (S\$)		4,850.00		
Nett Amount (S\$)	19,345.98	4,850.00	14,495.98	74.93

INSPECTION

Date of Assignment: 22/12/2017

Date Inspected: 22/12/2017 Inspected At:

Ethicarz Pte Ltd (HQ)
56 LOYANG WAY #04-04 LOYANG
ENTERPRISE BUILDING
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Feb 2018)	
Parts:	N/A	TOYOTA LITEACE 2.2 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GU6123X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,213.80 F	*1,213.80 FL
2	1		*TAILGATE WINDSCREEN GLASS MOULD	Necessary	181.40 F	*181.40 FL
3	1		*TAILGATE WIPER ARM	Missing	121.50 F	*121.50 FL
4	1		*TAILGATE WIPER MOTOR	Serviceable	386.40 F	*- FL
5	1		*TAILGATE OPENER	Cracked	260.71 F	*260.71 FL
6	1		*TAILGATE GARNISH HANDLE	Cracked	406.40 F	*406.40 FL
7	1		*TAILGATE CARPLATE LAMP	Serviceable	280.00 F	*- FL
8	1		*TAILGATE LOCK	Jammed	289.90 F	*289.90 FL
9	1		*TAILGATE WEATHER STRIP	Serviceable	287.75 F	*- FL
10	2		*TAILGATE HINGE	Serviceable	525.40 F	*- FL
11	2		*TAILGATE DAMPER	Serviceable	1,132.80 F	*- FL
12	1		*TAILGATE BOARD	Torn	387.50 F	*387.50 FL
13	10		*TAILGATE BOARD CLIP	Necessary	100.00 F	*100.00 FL
14	2		*TAILLAMP	Serviceable	808.40 F	*- FL
15	2		*TAILLAMP GARNISH	Serviceable	373.80 F	*- FL
16	10		*TAILLAMP CLIP	Not Necessary	100.00 F	*- FL
17	1		*REAR BUMPER	Deformed	481.70 F	*481.70 FL
18	2		*REAR BUMPER RETAINER	Cracked	72.60 F	*72.60 FL
19	2		*REAR BUMPER BRACKET	Bent	532.96 F	*532.96 FL
20	2		*REAR BUMPER REFLECTOR	Serviceable	246.20 F	*- FL
21	10		*REAR BUMPER CLIP	Necessary	100.00 F	*100.00 FL
22	2		*REAR FENDER	Repair	1,817.20 F	*- FL
23	2		*REAR FENDER COWLING (NPA)	Serviceable	0.00 F	*- FL
24	2		*REAR FENDER COWLING CLIP (NPA)	Not Necessary	0.00 F	*- FL
25	2		*REAR FENDER MUDFLAP	Serviceable	282.66 F	*- FL
26	2		*REAR FENDER SEALANT (NPA)	Not Necessary	0.00 F	*- FL
27	1		*REAR END PANEL (FLOOR PANEL)	Dented	672.90 F	*672.90 FL
28	1		*REAR END PANEL TOP GARNISH	Cracked	180.00 F	*180.00 FL
29	1		*EXHAUST PIPE	Serviceable	783.20 F	*- FL
30	1		*EXHAUST PIPE MOUNTING	Serviceable	78.00 F	*- FL
31	1		*EXHAUST PIPE HEAT SEAL	Serviceable	171.30 F	*- FL
32	1		*EXHAUST PIPE GASKET	Serviceable	51.50 F	*- FL
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
34	1		*TAILGATE CARPLATE	Necessary	80.00 FS	*80.00 FS
35	1		*TAILGATE STICKER (70KM/H)	Necessary	20.00 FS	*20.00 FS
36	1		*TAILGATE STICKER (5PAX)	Necessary	20.00 FS	*20.00 FS
37	2		*REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
38	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
39	1		*REAR FLOOR PANEL TOP COVER	Serviceable	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 F	*- FL
41	1		*REAR FLOOR PANEL TOPBOARD	Repair	400.00 F	*- FL
					Sub Total (S\$)	13,465.98
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	4,131.03

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR AND ACCIDENT AFFECTED BACK	New	2,200.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED BACK	New	1,500.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED BACK	New	80.00	50.00
4	TO RNR REVERSE SENSOR AND CHECK FUNCTION	New	120.00	30.00
5	TO RNR EXHAUST PIPE ASSY	New	180.00	0.00
6	TO RNR TAILGATE WINDSCREEN	New	180.00	120.00
7	TO CHECK WATER SEEPAGE	New	80.00	50.00
8	TO RNR LUGGAGE COMPARTMENTS	New	120.00	0.00
9	TO RNR TAILGATE MECHNISM	New	120.00	50.00
10	TO RNR REAR FLOOR PANEL	New	900.00	200.00
11	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA (REAR FLOOR PANEL)	New	400.00	200.00
Gross Labour Cost (\$\$)			5,880.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >