

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD464D - AXA**AAD1712-208**

Not Authorised
Running B4 policy 85181-82

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD464D - JHOW
VF1ABL15AUC283247
RENAULT
LATITUDE
19.12.2017
AXA

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>SL</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97
5	1	BUMEPR RETAINER LH REAR	\$	<i>SL</i> 44.99
6	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97
8	1	BUMEPR RETAINER LH REAR	\$	<i>SL</i> 44.99
9	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49
10	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
11	1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47
12	1	TAILLAMP LH	\$	<i>SL</i> 552.55
13	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
14	1	EXHAUST REAR	\$	<i>R</i> 7,489.05
15	1	EXHAUST CAP REAR	\$	<i>SL</i> 230.49
16	1	DOOR PANEL REAR LH	\$	<i>Bu</i> 2,844.66 ✓
17	1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82
18	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
19	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
20	1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06
21	1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75
22	1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75
23	1	DOOR GRAB HANDLE REAR LH	\$	<i>SL</i> 210.96
24	1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49
25	1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52
26	1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89
27	1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22
28	1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60
29	1	DOOR REGULATOR REAR LH	\$	<i>SL</i> 1,135.10
30	1	DOOR REGUALTOR MOTOR REAR LH	\$	<i>SL</i> 893.75
31	1	DOOR FINISHER REAR LH	\$	<i>SL</i> 423.10
32	1	DOOR WHEATHESTRIIP REAR LH	\$	<i>SL</i> 410.66
33	1	DOOR SEAL REAR LH	\$	<i>SL</i> 162.02
34	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>SL</i> 334.69

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-208**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD464D - AXA

35	1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82 X
36	1	DOOR PANEL FRT LH	\$	<i>n</i> 2,844.66 X

TOTAL	\$	29,010.76
10%	\$	2,901.08
	\$	26,109.68

Special Nett

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00 —
4	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00
5	1SET	BUMEPR RETAINER LH CLIP RR	\$	<i>nn</i> 20.00
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00
8	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82
9	1	TAILLAMP CLIP LH	\$	<i>nn</i> 5.00
10	1SET	WHEELARCH CLIP RR LH	\$	<i>nn</i> 66.00
11	2	REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00
12	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00
14	1	CAP HUB LH RR	\$	<i>nd</i> 35.00 ✓
15	1	RIM LH RR	\$	<i>Sn</i> 385.00 X
16	1	TYRE LH RR	\$	<i>Sn</i> 330.00 X
17	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
18	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X
19	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>born</i>

TOTAL	\$	2,225.82
TOTAL PARTS	\$	28,335.50

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *6601*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *301*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,800.00 *5001*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-208

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD464D - AXA

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
Towing Fees	\$	120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 601
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 601
To transfer of tire, rim and on wheel balancing.	\$	170.00 X

TOTAL	\$	7,710.00
Over All Total	\$	36,045.50

(PARTS BY PARTS)**Repair Days**~~10~~Days

3days