

INS. CASE OWNER:

Bennie

CC 6 / AIG17024341 / Uus39

LIX:

DIAC:

Surveyor:

Marcus

DOI:

ASSIGNMENT

26/12/17

Date / Time:

26/12/17

Registered in Merimen:

26/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 6140L

Name of Insured:

LIM HON YUN

Insured Tel No.:

HP: 98460817

Excess Sec II: SS

D.O.A: 21/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

703613814656

Policy No.:

2100464769-01

Make / Model:

MAZDA 3.1.5 SKYACTIV

Place of Accident:

JALAN BESAR, INFRONT OF
STN LIM TOWER

If NO, Driver Name / Age:

Driver Tel No.:

(V/ YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLF 8435C



INSRS:

WSP: Syntech Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

27/12/17 (THUR THUR)

SLF 8435C - X ; SLB 6140L - X

28/12/17 9:35

spoke to OI, she confirmed the accident
details, informed ID claim and she agree
to settle.

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

> THH By Email

After call 1st to OI:

28/12

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

5/2/18

Confirm with Winston

Email

Call

Final Liability:

%

100

(Assessed)

Assessed) BOLA S/N No.: 29

Repair Cost: (Inc/Est)

S\$ 3959.00

Loss of Rental (LOR):

S\$ 535.00

(5 days) x 100/wgst

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

S\$

7.49

Medical:

S\$

Disbursement:

S\$

Legal Cost:

S\$

(e.g. Tow/Independent)

Total:

S\$ 4501.49

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 4501.49

Name 1:

SYNTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

RECEIVED 2 FEB 2018

COPY SENT
22/02/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CCG/AIG17024341/Uus3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 26-12-2017	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 6140L	Veh. Inspected	SLF 8435C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/12/2017	Inspection Date	26/12/2017	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

u

1 not Adm
hr
1/5 \$3700
4dy.

Estimate

Vehicle: SLF 8438C

Make & Model: Honda Jazz

Year: _____

Chassis No: JHM6K38

	Parts / Labour	Condition	Price	recommend
	Tailgate	so/gd	\$9.50	✓
	Tailgate outer handle	11	123.60	X
	Tailgate outer top garnish	one	258.80	✓
	Tailgate outer top garnish emblem	11	34.40	X
	Tailgate inner lock	1w1	220.90	✓
	Tailgate licence plate lamp	11	52.10	X
	Tailgate Rear windscreen sealant	rec	60.00	40s.w
	Tailgate Rear windscreen moulding	rec	58.00	✓
	Tailgate Rear wiper motor	11	286.30	X
	Tailgate 'Jazz' emblem	rec	38.30	✓
	Tailgate rear licence plate w/holder	11	45.00	5s.w X
	Tailgate rear reverse camera	11	944.60	X
1set	Rear reverse sensor 4pcs	shld	250.00	5s.w ✓
	Rear end panel	so/gd	548.50	✓
	Rear end panel top garnish	De/10.11	102.50	✓
1set	Rear end panel top garnish clips	11	10.00	5s.w X
	Rear end panel rubber	11	122.30	X
	Rear end panel striker	11	35.80	X
2pc's	taillamps @ 314.70	n/cru	629.40	1pc
2pc's	taillamp housing panels @ 167.60	n/sd	335.60	1pc
	Rear bumper 492.70	no/de	929.60	✓
1set	Rear bumper clips	rec	30.00	✓
2pc's	Rear bumper retainers @ 22.60	Recf	45.20	✓
2pc's	Rear bumper side grilles @ 38.60	11	77.60	X
2pc's	Rear fender inner shield clips @ 20.00	11	20.00	X
	Rear end panel sealant	rec	80.00	50s.w
			207	
			8940.60	

3137.3
2609.84

Estimate

Vehicle: SLF 8435C Make & Model: _____

Year: _____ Chassis No: _____

Parts / Labour	Condition	Price	recommend
To transfer tailgate components		120.00	60
To Dismantle & refix rear windscreen		120.00	✓
To check wiring		100.00	30
To spray anti. rust proofing		80.00	40
To dismantle & refix upholstery		100.00	60
labour for panel beating & replacing parts		750.00	720
To partly & spray painting		950.00	800

TOTAL £160.60

4679.80

KK Auto Consultants hence notify
the Repairer of the following:
• To resurvey vehicle after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Honda Jaff SLF 8435 C


- 1) Rear Buckled — Solids —
- 2) " " Handle — 11 X
- 3) " " Top Garment — CHE ✓
- 4) " " " " Rubber — 11 X
- 5) " " " " Lock — 7m1 —
- 6) " " " " plate lamp — 11 X
- 7) " " " " glass sealant — ne
- 8) " " " " Rubber — ne —
- 9) " " " " upper motor — 11 X
- 10) " " " " JAZZ' plate — ne —
- 11) " " " " " " — 11 X
- 12) Rear Reverse Camera —
- 13) Rear Reverse Sensor (X) — chet 2505. w
- 14) Rear Panel — Solids ✓
- 15) " " " " " " — De/torn ✓
- 16) 16) Rear Panel Rubber — 11 X
- 17) " " " " Stricker — 11 X
- 18) Rear Taillamp (X) — 11 X
- 19) Rear Taillamp Panel (X) — 11 X
- 20) Rear Bumper — 11 X
- 21) " " " " " " — 11 X
- 22) " " " " " " — 11 X
- 23) " " " " " " — 11 X
- 24) Rear fender fender shield clip (X) — 11 X

SLF 8435C Honda Jaff

(Labour):-

1) Transfer Boddled fitting — 120	60
2) " " glass — 120	✓
3) Check wiring — 100	30
4) Anti Rust Proofing — 80	40
5) Rear Panel Joint Sealant — 80	ALL SUS. W
6) Interior Upolstery — 100	60
7) Panel Beating — 750	720
8) Paintwork — 950	800

26/12/11 4 day.



Flouder Jaff SLF 8435 C

- | Q | Part | Qty | Unit Price | Total Price |
|-----|-------------------------------------|-----|------------|-------------|
| 1) | Rear Bootlid | 1 | \$859.50 | \$859.50 |
| 2) | " Handle | 11 | \$123.60 | \$123.60 |
| 3) | " " Top Garnish | 11 | \$258.80 | \$258.80 |
| 4) | " " " Emblem | 11 | \$34.40 | \$34.40 |
| 5) | " " " Taper Lock | 7 | \$220.90 | \$220.90 |
| 6) | " " " no plate lamp | 11 | \$52.10 | \$52.10 |
| 7) | " " " glass sealant | 1 | \$60.00 SW | \$60.00 |
| 8) | " " " Rubber | 1 | \$58.00 | \$58.00 |
| 9) | " " " wiper motor | 1 | \$286.30 | \$286.30 |
| 10) | " " " 'JAZZ' plate | 1 | \$38.30 | \$38.30 |
| 11) | Rear no plate Assy | 11 | \$45.00 SW | \$45.00 |
| 12) | Rear Reverse Camera | 11 | \$944.60 | \$944.60 |
| 13) | Rear Reverse Sensor (FR) | 2 | \$548.90 | \$548.90 |
| 14) | Rear Panel | 1 | \$102.50 | \$102.50 |
| 15) | " " " Taper garnish | 11 | \$10.00 SW | \$10.00 |
| 16) | Rear Panel Rubber | 11 | \$122.30 | \$122.30 |
| 17) | " " " Stricker | 1 | \$35.80 | \$35.80 |
| 18) | Rear Tail Lamp | 1 | \$314.70 | \$314.70 |
| 19) | Rear Tail Lamp Panel (FR) | 1 | \$167.80 | \$167.80 |
| 20) | Rear Bumper | 1 | \$929.80 | \$929.80 |
| 21) | " " " clips | 1 | \$30.00 SW | \$30.00 |
| 22) | " " " Retainer (FR) | 1 | \$45.20 | \$45.20 |
| 23) | " " " Grille Garnish (FR) | 1 | \$38.80 | \$38.80 |
| 24) | Rear fender Taper shield clips (FR) | 1 | \$20.00 SW | \$20.00 |

SLF 8435 C Honda Jaff

Labour:-

1) Transfer Bootled fitting	— 120/	60
2) " " plan	— 120/	✓
3) check wiring	— 100/	30
4) Anti Rust proofing	— 80/	40
5) Rew Panel Joint Sealant	— 80/	?
6) Interior Upolstery	— 100/	60
7) Panel Beating	— 750/	?
8) Paintwork	— 950/	800

26/12/11 4 day.

Honda Jaff SLF 8435 C

- 1) Rear Booled — Solids —
- 2) " " Handle — 11 X
- 3) " " Top Garnish — ch 2 ✓
- 4) " " " " Emblem — 11 X
- 5) " " Inner Lock — 7m1 —
- 6) " " no plate lamp — 11 X
- 7) " " glass Seclant — m
- 8) " " " Rubber — m ✓
- 9) " " wiper motor — 1 ✓
- 10) " " 'JAZZ' plate — m ✓
- 11) " " " " — 11 X
- 12) Rear Reverse Camera — 11 X
- 13) Rear Reverse Sensor (2x) — ch 2505. ✓
- 14) Rear Panel — Solids ✓
- 15) " " Inner garnish — De/ton ✓
- 16) " " Panel Rubber — 11 X
- 17) " " Stricker — 11 X
- 18) Rear Taillamp (2x) — MS 12 C
- 19) Rear Taillamp Panel (4x) — 11 X
- 20) Rear Bumper — 11 X
- 21) " " clip — m
- 22) " " Retainer (2x) — 11 X
- 23) " " Grille Garnish (2x) — 11 X
- 24) Rear fender Inner shield clip (2x) — 11 X

SLF 8435C Honda Jaff

Labour:-

1) Transfer Bottled filler	— 120	60
2) " " plan	— 120	✓
3) check wiring	— 100	30
4) Anti Rust Proofing	— 80	40
5) Rear Panel Joint Sealant	— 80	700 SUS. W
6) Interior Upolstery	— 100	60
7) Panel Beating	— 750	720
8) Paintwork	— 950	800

26/12/11 4 day.

LK5 Auto Consultants hereby notify
the Regulator of the following:

- To remedy the defect(s) identified
- To display details of the defect(s) on a sign
- To provide a written statement of the defect(s)
- To provide a written statement of the defect(s)
- To provide a written statement of the defect(s)
- To provide a written statement of the defect(s)
- To provide a written statement of the defect(s)

Acknowledged by Regulator

Signature

Date

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2077G
Vehicle Details	
Vehicle No.:	SLF8435C
Vehicle to be Exported:	No
Intended De-registration Date:	27 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L13B11010317
Chassis No.:	JHMGK3850GX241018
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,594.00
Original Registration Date:	13 Sep 2016
First Registration Date:	13 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$10,594.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2026
PARF Rebate Amount:	\$7,945.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$46,457.00



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref:SAPL/98809/01/18

Date :18/1/2018

To :M/S AIG Asia Pacific Insurance Pte.Ltd.
AIG Building 78 Shenton Way
#07-16,
S'pore 079120
Attn:Motor Claim Dept

Dear Sir/Mdm,

Re :Claim of repair cost & loss of use for veh no.SLF 8435-C

<u>NO</u>	<u>PRICE</u>
1.Lump Sum Repair Cost For Veh No.SLF 8435-C.....	S\$3,959.00
2.Loss Of Use For Rental Bill NR:33753(100X7Days)..... (Plus Waiting Day)	S\$ 749.00
3.LTA Search Fee.....	S\$ 7.49

TOTAL : S\$4,715.49

=====

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Thursday, 28 December 2017 4:39 PM
To: honyun@gmail.com
Subject: ACCIDENT INVOLVING SLB 6140L & SLF 8435C ON 21/12/2017



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG17024341/us3

28 DECEMBER 2017

LIM HON YUN
1 ANG MO KIO AVE 9
#09-03
SINGAPORE 569758

Dear Sir/Madam,

ACCIDENT INVOLVING SLB 6140L & SLF 8435C ON 21/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Car Club Pte Ltd ("the third party claimant")
of 60, Paya Lebar Road # 06-43 S'pore 409051 (address),
owner of SLF8435C (vehicle no.) hereby authorize
Stytech Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLF8435C that was
damaged pursuant to the accident which occurred on 21/12/17 (date) along
Jalan Besar Road Infront of Sim Lim Tower (location)
involving vehicle no/s SLB 6140 L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 30th day of Dec (month) 20 17 (year)





Signed by "the third party claimant"





Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Stytech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 3,959.00 (repair costs), S\$ 535.00 (loss of use/rental) S\$ 7.49 (search fees) for vehicle no. SLF8435C that was damaged pursuant to the accident which occurred on 21/12/17 (date) along Jalan Besar Road Infront of Sim Line Tower (location) involving vehicle no/s SLB 6140L.

This is pursuant to the inspection conducted on 26/12/17 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Car Club Pte Ltd ("third party claimant") of vehicle no. SLF8435C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLB 6140L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9 day of 2 (month) 2018 (year)

MCF



Signed by AIG appointed surveyor

Winston



Chopped & Signed by "the workshop"



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref:SAPL/98809/01/18

Date :18/1/2018

To :M/S AIG Asia Pacific Insurance Pte.Ltd.
AIG Building 78 Shenton Way
#07-16,
S'pore 079120
Attn:Motor Claim Dept

Dear Sir/Mdm,

Re :Accident on 21/12/2017 involving veh nos.SLF 8435-C & SLB6140-L
Along Jalan Besar Rd Infront Of Sim Lim Tower.

FINAL BILL FOR VEH NO.SLF 8435-C

DESCRIPTION

PRICE

Lump Sum Repair Cost For Veh No.SLF 8435-C.....	S\$3,700.00
7% GST.....	S\$ 259.00

TOTAL : S\$3,959.00

Yours Faithfully
STYTECH AUTO PTE.LTD.

.....
Mr.Winston Teo
9685-8843



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
 TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
 GST REG. NO: 201601539K CO. REG. NO: 201601539K

NR No: 33753

Vehicle No: SKW 5080JMake and Type MAZDA 3Date/Time Out 22/12/17 9.30amDate/Time In 30/12/17 10.00amFuel Gauge

F	1/4	1/2	3/4	F

EXTENSION CHARGES IS \$12.00 PER HOUR (SINGAPORE USE)
 DEPOSIT WILL BE FORFEITED IN ANY ACCIDENT/DAMAGE/FIRE & THEFT
 *NO RETURNING OF VEHICLE AFTER 6 PM & EVE / PUBLIC HOLIDAY

Hirer's Name: Car Club Pte Ltd

KM OUT												KM IN								
--------	--	--	--	--	--	--	--	--	--	--	--	-------	--	--	--	--	--	--	--	--

Hirer's Address: 60, Paya Lebar Road #06-43Paya Lebar Square - S(409501)Tel: 67881511

I/C:

H/P:

Age:

Driver's Name: Khee Quek KhiongDriver's Address: BK123 Simei St 1 #08-404

Tel:

I/C: 57129716JAge: 1971Driving Licence Date: 16/5/03 Class: 3

Additional Driver's Name:

Driver's Address:

Tel:

I/C:

Age:

Driving Licence Date: Class:

Guarantor's Name:

Guarantor's Address:

Tel:

I/C:

Occupation:

Age:

IMPORTANT NOTES

- * This vehicle is restricted to SINGAPORE only.
- * No refund will be given for early return or fuel left in vehicle.
- * Hirer is liable to pay all parking fees, traffic summons & other claims.
- * Hirer who carries the number of passengers or load exceeding the MPC label will have to take their own responsibilities & LTA summons.
- * In the event of vehicle breakdown due to no fuel, hirer is liable to pay \$50 service charge plus cost of fuel/diesel.
- * No replacement of vehicle in any accident, damage or loss.
- * Hirer is responsible for the first \$ 2000 excess for collision/damage/ fire or theft to first party (i.e. STYTECH AUTO PTE LTD) vehicle (including windscreen) and also first \$ 2000 excess for collision/damage/fire & theft to third party's vehicle for each and every accident & damage.

RENTALS CHARGES

7 Days at S\$ 100 per day \$ 700.00

Week at S\$ per week

Month at S\$ per mth

Insurance fee to cover hired vehicle only

Delivery/Collection fee

Petrol/Diesel

Others

Sub-Total

Add GST

Total Nett Charges

*Less Total Prepayment/Deposit Received

Balance Amount Due/Refundable

Add : EXTENSION CHARGES

METHOD OF PAYMENT

☐ Cash ☐ Cheque No: ☐ Visa ☒ Bill Co.

Refund

Received \$ _____ By Hirer x _____

* In the event of the rental vehicle is not return on the date due & no contact is made to inform our company of any changes & payment after one week due. Our Company will take action & repossess the vehicle & a service charge of \$120.00 are subject to the Hirer inclusive of the overdue charges with an additional interest of 3% per month.

I/We have read the terms and conditions of the rental agreement and agree thereto:-

Hirer's Signature

Guarantor's Signature

STYTECH AUTO PTE LTD
Signed By



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 23 Dec 2017 / 17:29:32

Receipt Date/Time : 23 Dec 2017 / 17:29:32

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171223-000912

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLB6140L (SLF8435C)				
As at 21 Dec 2017/19:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLB6140L Enquiry Fee 20171223172820459809	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - GBD9215T (GBB842)				
As at 18 Dec 2017/14:10:00				
Insurance Co: AXA INSURANCE PTE LTD				
2	Insurance Enquiry - GBD9215T Enquiry Fee 20171223172820518057	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		14.00	0.98	14.98
Rounding Difference				0.03
Total Amount Payable				14.95
Paid By				
	20171223172838881	Direct Debit: eNETS Debit (Internet Banking)		14.95
Total				14.95
Cash Change				0.00
Tendered Amount				14.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017 Edit Reg		26 Dec 2017 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LIM HON YUN , ID: S8400895H		
Main Claimant:	CAR CLUB PTE LTD , Co. Reg. No.: 200912077G		
Vehicle Reg. No.:	SLF8435C	Date of Loss:	21/12/2017 19:00 - :59
Claim Type:	TP / 7036138146SG	Policy/Cover Note No.:	2100464769 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB6140L	Policy No. (Claimant):	MSD/VCC/17-000024-00
	Excess:		
Repairer:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 64448125		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/01/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF8435C (7036138146SG)
[SLB6140L]
TP
CAR CLUB PTE LTD
Dec 21 2017 7:00PM
[LIM HON YUN]
Stytech Auto Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Letters/Correspondences					1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit		

Assessment Reports					1 per page v	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	27/12/17 11:48	Accident Statement From: SC - Reg. No: SLB6140L, Claimant: LIM HON YUN	1	Load HTM		

Photos/Images					3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	19/01/18 08:57	Chassis Number	1	Load JPG	☒	
2	19/01/18 08:57	General View	1	Load JPG	☒	
3	19/01/18 08:57	Odometer Reading	1	Load JPG	☒	
4	19/01/18 08:57	General View	1	Load JPG	☒	
5	19/01/18 08:57	General View	1	Load JPG	☒	
6	19/01/18 08:57	General View	1	Load JPG	☒	
7	19/01/18 08:57	General View	1	Load JPG	☒	
8	19/01/18 08:57	General View	1	Load JPG	☒	
9	19/01/18 08:57	General View	1	Load JPG	☒	
10	19/01/18 08:57	General View	1	Load JPG	☒	
11	19/01/18 08:57	General View	1	Load JPG	☒	
12	19/01/18 08:57	General View	1	Load JPG	☒	
13	19/01/18 08:57	General View	1	Load JPG	☒	
14	19/01/18 08:57	General View	1	Load JPG	☒	
15	19/01/18 08:57	General View	1	Load JPG	☒	
16	19/01/18 08:57	General View	1	Load JPG	☒	
17	19/01/18 08:57	General View	1	Load JPG	☒	
18	19/01/18 08:57	General View	1	Load JPG	☒	
19	19/01/18 08:57	General View	1	Load JPG	☒	
20	19/01/18 08:57	General View	1	Load JPG	☒	
21	19/01/18 08:57	General View	1	Load JPG	☒	
22	19/01/18 08:57	General View	1	Load JPG	☒	
23	19/01/18 08:57	General View	1	Load JPG	☒	
24	19/01/18 08:57	General View	1	Load JPG	☒	
25	19/01/18 08:57	General View	1	Load JPG	☒	
26	19/01/18 08:57	General View	1	Load JPG	☒	
27	19/01/18 08:57	General View	1	Load JPG	☒	
28	19/01/18 08:57	General View	1	Load JPG	☒	

29	19/01/18 08:57	General View	1	Load JPG	☒
30	19/01/18 08:57	General View	1	Load JPG	☒
31	19/01/18 08:57	General View	1	Load JPG	☒
32	19/01/18 08:57	General View	1	Load JPG	☒
33	19/01/18 08:57	General View	1	Load JPG	☒
34	19/01/18 08:57	General View	1	Load JPG	☒
35	19/01/18 08:57	General View	1	Load JPG	☒
36	19/01/18 08:57	General View	1	Load JPG	☒
37	19/01/18 08:57	General View	1	Load JPG	☒
38	19/01/18 08:57	General View	1	Load JPG	☒
39	19/01/18 08:57	General View	1	Load JPG	☒
40	19/01/18 08:57	General View	1	Load JPG	☒
41	19/01/18 08:57	General View	1	Load JPG	☒
42	19/01/18 08:57	General View	1	Load JPG	☒
43	19/01/18 08:57	General View	1	Load JPG	☒
44	19/01/18 08:57	General View	1	Load JPG	☒
45	19/01/18 08:57	General View	1	Load JPG	☒
46	19/01/18 08:57	General View	1	Load JPG	☒
47	19/01/18 08:57	General View	1	Load JPG	☒
48	19/01/18 08:57	General View	1	Load JPG	☒
49	19/01/18 08:57	General View	1	Load JPG	☒
50	19/01/18 08:57	General View	1	Load JPG	☒
51	19/01/18 08:57	General View	1	Load JPG	☒
52	19/01/18 08:57	General View	1	Load JPG	☒
53	19/01/18 08:57	General View	1	Load JPG	☒
54	19/01/18 08:57	General View	1	Load JPG	☒
55	19/01/18 08:57	Reinspection Photo	1	Load JPG	☒
56	19/01/18 08:57	Reinspection Photo	1	Load JPG	☒
57	19/01/18 08:57	Reinspection Photo	1	Load JPG	☒
58	19/01/18 08:57	Reinspection Photo	1	Load JPG	☒
59	19/01/18 08:57	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/17 11:11	TP GIA REPORT	1	Load PDF	
2	03/01/18 12:17	TP ESTIMATE- INCOMPLETE	1	Load PDF	
3	25/01/18 09:43	TP ESTIMATE- MARKED	1	Load PDF	
4	26/02/18 09:18	WORKSHOP INVOICE	1	Load PDF	
5	26/02/18 09:18	AUTHORISATION TO ACT FORM	1	Load PDF	
6	26/02/18 09:18	Release Voucher	1	Load PDF	
7	26/02/18 09:18	RENTAL RECEIPT	1	Load PDF	
8	26/02/18 09:18	LTA SEARCH	1	Load PDF	
9	26/02/18 09:18	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLB6140L (Insd veh)	Model:	HONDA JAZZ 1.3 CVT (A)
	SLF8435C (TP veh)		
Date of Accident:	21/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,007.90
Final Repair Cost	:	\$	3,959.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	535.00 5 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,501.49

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Stytech Auto Pte Ltd	:	\$ 4,501.49
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

26 Feb
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024341/UUS3Q2

Date: 26/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100464769
 Claimant Vehicle No: SLF8435C Insured Vehicle No: SLB6140L
 Date of Loss: 21/12/2017 Nature of Claim: TP Claim No: 7036138146SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF8435C
 Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11010317
 Reg. Date: 13/09/2016 (Man. Year: 2016) Chassis No: JHMGK3850GX241018
 Colour: Silver Odometer: 31368 km
 Engine Capacity: 1318 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,198.60	2,849.84	3,348.76	54.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,830.00	390.00	17.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,418.60	4,679.84	3,738.76	44.41
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	8,418.60	3,700.00	4,718.60	56.05
+ GST 7.00/7.00% (S\$)	589.30	259.00	330.30	56.05
Nett Amount (S\$)	9,007.90	3,959.00	5,048.90	56.05
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,501.49		

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 26/12/2017 Inspected At:

 Stytech Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit

Autohub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	859.50 F	*859.50 FL
2	1		*TAILGATE OUTER HANDLE	Not Necessary	123.60 F	*- FL
3	1		*TAILGATE OUTER TOP GARNISH	Cracked	258.80 F	*258.80 FL
4	1		*TAILGATE OUTER TOP GARNISH EMBLEM	Not Necessary	34.40 F	*- FL
5	1		*TAILGATE INNER LOCK	Twisted	220.90 F	*220.90 FL
6	1		*TAILGATE LICENCE PLATE LAMP	Not Necessary	52.10 F	*- FL
7	1		*TAILGATE REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
8	1		*TAILGATE REAR WINDSCREEN MOULDING	Necessary	58.00 F	*58.00 FL
9	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	286.30 F	*- FL
10	1		*TAILGATE JAZZ EMBLEM	Necessary	38.30 F	*38.30 FL
11	1		*TAILGATE REAR LICENCE PLATE W/HOLDER	Not Necessary	45.00 FS	*- FS
12	1		*TAILGATE REAR REVERSE CAMERA	Not Necessary	944.60 F	*- FL
13	1		*SET REAR REVERSE SENSOR	Shorted (4 PCS)	250.00 FS	*250.00 FS
14	1		*REAR END PANEL	Badly Dented	548.90 F	*548.90 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed / Torn	102.50 F	*102.50 FL
16	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	10.00 FS	*- FS
17	1		*REAR END PANEL RUBBER	Not Necessary	122.30 F	*- FL
18	1		*REAR END PANEL STRIKER	Not Necessary	35.80 F	*- FL
19	1		*TAILLAMPS	N/S Cracked	629.40 F	*314.70 FL
20	1		*TAILLAMP HOUSING PANELS	N/S Dented	335.60 F	*167.80 FL
21	1		*REAR BUMPER	Dented / Deformed	929.80 F	*492.70 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
23	2		*REAR BUMPER RETAINERS	Bent	45.20 F	*45.20 FL
24	2		*REAR BUMPER SIDE GRILLES	Not Necessary	77.60 F	*- FL
25	2		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	20.00 F	*- FL
26	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,198.60	3,477.30
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	627.46
Total Parts (S\$)	6,198.60	2,849.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO SPRAY ANTI RUST PROOFING	New	80.00	40.00
5	TO DISMANTLE & REFIX UPHOLSTERY	New	100.00	60.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	750.00	720.00
7	TO PUTTY & SPRAY PAINTING	New	950.00	800.00
Gross Labour Cost (\$\$)			2,220.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >