

u

Estimate

not added
 1/5 of \$3700
 467.

Vehicle: SLE 8438CMake & Model: Honda Jazz

Year: _____

Chassis No: JHM6K38

	Parts / Labour	Condition	Price	recommend
	Tailgate	As/gd	\$9.50	✓
	Tailgate outer handle	11	123.60	X
	Tailgate outer top garnish	one	258.80	✓
	Tailgate outer top garnish emblem	11	34.40	X
	Tailgate inner lock	1w1	220.90	✓
	Tailgate licence plate lamp	11	52.10	X
	Tailgate Rear windscreen sealant	rec	60.00	405.00
	Tailgate Rear windscreen moulding	rec	58.00	✓
	Tailgate Rear wiper motor	11	286.30	X
	Tailgate 'Jazz' emblem	rec	38.30	✓
	Tailgate rear licence plate w/holder	11	45.00	5.00 X
	Tailgate rear reverse camera	11	944.60	X
1set	Rear reverse sensor 4pcs	shld	250.00	5.00 ✓
	Rear end panel	As/gd	548.50	✓
	Rear end panel top garnish	De/10.11	102.50	✓
1set	Rear end panel top garnish clips	11	10.00	5.00 X
	Rear end panel rubber	11	122.30	X
	Rear end panel striker	11	35.80	X
2pcs	taillamps @ 314.70	N/s cr	629.40	12C
2pcs	taillamp housing panels @ 167.50	N/s cr	335.00	12C
	Rear bumper 492.70	as/de	929.60	✓
1set	Rear bumper clips	rec	30.00	✓
2pcs	Rear bumper retainers @ 22.60	Rec	45.20	✓
2pcs	Rear bumper side grilles @ 38.60	11	77.60	X
2pcs	Rear fender inner shield clips @ 20.00	11	20.00	X
	Rear end panel sealant	rec	80.00	50.00
			207	
			8940.60	

3137.3
 2609.54

Estimate

Vehicle: SLF 8435C

Make & Model:

Year: _____

Chassis No:

Parts / Labour	Condition	Price	recommend
To transfer tailgate components		120.00	60
To Dismantle & refix rear windscreen		120.00	✓
To check wiring		100.00	30
To spray anti rust proofing		80.00	40
To dismantle & refix upholstery		100.00	60
labour for panel beating & replacing parts		750.00	720
To partly & spray painting		950.00	800
		TOTAL £160.60	467

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Honda Jazz SLF 8435 C


- | | Part | Qty | Unit | Price | Total |
|-----|-------------------------------------|-----|------|-------|-------|
| 1) | Rear Bockled | 1 | pc | 11 X | 11 X |
| 2) | " Handle | 1 | pc | 11 X | 11 X |
| 3) | " Top Garnish | 1 | pc | 11 X | 11 X |
| 4) | " " " Emblem | 1 | pc | 11 X | 11 X |
| 5) | " Inner Lock | 1 | pc | 11 X | 11 X |
| 6) | " No plate Lamp | 1 | pc | 11 X | 11 X |
| 7) | " glass Sealant | 1 | pc | 11 X | 11 X |
| 8) | " " Rubber | 1 | pc | 11 X | 11 X |
| 9) | " wiper motor | 1 | pc | 11 X | 11 X |
| 10) | " 'JAZZ' plate | 1 | pc | 11 X | 11 X |
| 11) | Rear No plate Assy | 1 | pc | 11 X | 11 X |
| 12) | Rear Reverse Camera | 1 | pc | 11 X | 11 X |
| 13) | Rear Reverse Sensor (Ex) | 1 | pc | 11 X | 11 X |
| 14) | Rear Panel | 1 | pc | 11 X | 11 X |
| 15) | " " Inner garnish | 1 | pc | 11 X | 11 X |
| 16) | Rear Panel Rubber | 1 | pc | 11 X | 11 X |
| 17) | " " Stricker | 1 | pc | 11 X | 11 X |
| 18) | Rear Taillamp (Ex) | 1 | pc | 11 X | 11 X |
| 19) | Rear Taillamp Panel (Fu) | 1 | pc | 11 X | 11 X |
| 20) | Rear Bumper | 1 | pc | 11 X | 11 X |
| 21) | " clip | 1 | pc | 11 X | 11 X |
| 22) | " Retainer (Ex) | 1 | pc | 11 X | 11 X |
| 23) | " Grille Garnish (Ex) | 1 | pc | 11 X | 11 X |
| 24) | Rear fender fender shield clip (Ex) | 1 | pc | 11 X | 11 X |

SLF 8435C Honda Jaff

Ques:-

1) Transfer Boddled fitting	— 120	60
2) " " glass	— 120	✓
3) Check wiring	— 100	30
4) Anti Rust protection	— 80	40
5) Rear Panel Joint Sealant	— 80	Per 505.2
6) Interior Upolstery	— 100	60
7) Panel Beating	— 750	720
8) Paintwork	— 950	800

26/12/11 4 day.



Honda Jazz SLF 8435. C

- | | | | | | |
|-----|------|---------|------------------------------|--------------|------------|
| 1) | Rear | Bolted | _____ | Sel. m | \$859.50 |
| 2) | " | " | Handle _____ | 11 X | \$123.60 |
| 3) | " | " | " Top Garnish _____ | 11 X ? | \$258.80 |
| 4) | " | " | " " Emblem _____ | 11 X | \$34.40 |
| 5) | " | " | Tuner Lock _____ | 7m1 | \$220.90 |
| 6) | " | " | no plate lamp _____ | 11 X | \$52.10 |
| 7) | " | " | glass sealant _____ | m | \$60.00 SV |
| 8) | " | " | " Rubber _____ | m | \$58.00 |
| 9) | " | " | wiper motor _____ | X 1 A ? | \$286.30 |
| 10) | " | " | 'JAZZ' Plate _____ | m | \$38.30 |
| 11) | Rear | no | plate Assy _____ | 11 X | \$45.00 SV |
| 12) | Rear | Reverse | Camera _____ | 11 X | \$944.60 |
| 13) | Rear | Reverse | Scum (ex) _____ | shot 2505. w | |
| 14) | Rear | Panel | _____ | ? \$548.90 | |
| 15) | " | " | Tuner garnish _____ | ? \$102.50 | |
| 16) | Rear | Panel | Rubber _____ | 11 q | \$10.00 SV |
| 17) | " | " | Stricker _____ | 11 X | \$122.30 |
| 18) | Rear | Tailamp | (ex) \$314.70 | N/S C = | \$314.70 |
| 19) | Rear | Tailamp | Panel (Fu) _____ | 2 X | \$167.80 |
| 20) | Rear | Bumper | _____ | 700/22 | \$929.80 |
| 21) | " | " | clip _____ | m | \$30.00 SV |
| 22) | " | " | Retainer (2x) \$22.60 | sl | \$45.20 |
| 23) | " | " | Grille Garnish (2x) _____ | 17 X | \$38.80 |
| 24) | Rear | fender | Tuner shield clip (ex) _____ | 11 X | \$20.00 SV |

SLF 8435-C Honda Jaff

(Labour):-

1) Transfer Bootled fitting	— 120/	60
2) " " plan	— 120/	✓
3) Check wiring	— 100/	30
4) Anti Rust proofing	— 80/	40
5) Rear Panel Joint Sealant	— 80/	?
6) Interior Upolstery	— 100/	60
7) Panel Beating	— 750/	?
8) Paintwork	— 950/	800

26/12/11 4 day.