

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg1

AIG Asia Pacific Insurance Pte Ltd

Date: 26.12.2017

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

DOA: 21.12.2017

No	Description	Unit	List (\$)
1	FRONT BONNET	1	\$ <i>bt</i> 1,290.00
2	FRONT BONNET HINGE	2	\$ <i>bt</i> 196.00
3	FRONT BONNET LOCK	1	\$ <i>?</i> 265.94
4	FRONT FENDER RH	1	\$ <i>bt</i> 699.00
5	FRONT FENDER SHIELD RH	1	\$ <i>de</i> 208.00
6	FRONT HEADLAMP LH	1	\$ <i>x</i> 2,700.00
7	FRONT HEADLAMP RH	1	\$ <i>Cna</i> 2,700.00
8	FRONT HEADLAMP LOWER BRACKET RH	1	\$ <i>neu</i> 110.00
9	FRONT FENDER INNER PANEL RH	1	\$ <i>Rx</i> 800.00
10	FRONT FENDER TOP GARNISH RH	1	\$ <i>de</i> 75.00
11	RH ROOF MOULDING / GARNISH	1	\$ <i>?</i> 728.02
12	FRONT REINFORCEMENT	1	\$ <i>bt</i> 380.00
13	FRONT BUMPER SPONGE	1	\$ <i>?</i> 240.00
14	FRONT BUMPER SIDE RETAINER <i>LH-x RM-de</i>	2	\$ <i>neu</i> 230.00
15	FRONT FOGLAMP GARNISH <i>LH-x, RM-dis</i>	2	\$ 250.00
16	FRONT BUMPER TOW COVER	1	\$ <i>de</i> 65.00
17	FRONT ABSORBER LH	1	\$ <i>?</i> 695.00
18	FRONT ABSORBER RH	1	\$ <i>?</i> 695.00
19	FRONT ABSORBER MOUNTING RH	1	\$ <i>?</i> 270.00
20	FRONT ABSORBER MOUNTING LH	1	\$ <i>?</i> 270.00
21	FRONT ABSORBER STOPPER RH	1	\$ <i>?</i> 80.00
22	FRONT ABSORBER STOPPER LH	1	\$ <i>?</i> 80.00
23	FRONT ABSORBER DUST COVER LH	2	\$ <i>?</i> 156.00
24	FRONT ABSORBER BALL BEARING	2	\$ <i>?</i> 150.00
25	FRONT LOWER ARM RH	1	\$ <i>?</i> 580.00
Total (A) :			\$ 13,912.96
Less 10% :			\$ 1,391.30
Total :			\$ 12,521.66

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg2

AIG Asia Pacific Insurance Pte Ltd

Date: 26.12.2017

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Claim Type: Third Party Claim

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Chassis No: WDD1173422N575979

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

DOA: 21.12.2017

[illegible]

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg3

AIG Asia Pacific Insurance Pte Ltd

Date: 26.12.2017

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Claim Type: Third Party Claim

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Chassis No: WDD1173422N575979

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

DOA: 21.12.2017

No	Description	Unit	List (\$)
	Special Nett		
1	CAR PLATE NUMBER WITH HOLDER	1	\$ 50.00 ? 50.00
2	FRONT BUMPER SENSOR	2	\$ 376.00 376.00
3	BONNET INSULATOR CLIPS	19	\$ 76.00 76.00
4	FRONT FENDER SHIELD CLIPS	10	\$ 40.00 40.00
5	FRONT BUMPER	1	\$ 3,650.00 3,650.00
6	FRONT BUMPER CLIPS	15	\$ 82.50 82.50
7	FRONT BUMPER LOWER SPOILER (After Market)	1	\$ 680.00 680.00
8	FRONT LOWER GRILLE	1	\$? 105.80
9	FRONT LOWER GRILLE SIDE GARNISH	2	\$ 170.00 170.00
10	FRONT GRILLE (After Market)	1	\$ 880.00 880.00
11	FROM LOGO	1	\$ 120.00 120.00
12	FRONT GRILLE CHROME SET	1	\$ 220.00 220.00
13	FRONT LOGO AMG	1	\$? 135.00
14	FRONT FOGLAMP TOP GARNISH (After Market)	SET	\$ 260.00 260.00
15	FRONT TYRE	1	\$ 320.00 320.00
16	TYRE RIM	SET	\$ 2,800.00 2,800.00
Total (C) :			\$ 9,965.30

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg4

AIG Asia Pacific Insurance Pte Ltd

Date: 26.12.2017

Owner's Name : Joey Teo CaiYi

Vehicle No : SJT9191Z

Vehicle Make & Model : Mercedes Benz CLA 180 AMG

Claim Type: Third Party Claim

Chassis No: WDD1173422N575979

Registration Date : 22 Nov 2017 (YOM 2017) COE Expiry Date 21 Nov 2027

DOA: 21.12.2017

No	Description	Unit	List (\$)
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 600 1,200.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 1000 2,000.00
3	Check Wiring System & Light	1	\$ 50. 100.00
4	Anti Rust Treatment	1	\$ 40. 120.00
5	To Check & Adjust Wheel Aligment	1	\$ 80. 100.00
6	To Remove / Refix Front Bonnet Attachment	1	\$ X 200.00
7	To Check Water Leaking	1	\$ 30. 120.00
8	To Remove/ Refix Bumper Sensor	1	\$ 30. 120.00
9	To Remove / Refix Front Under Carriage photo.	1	\$ 120 250.00
10	To Remove / Replace Tyre & Rim	1	\$ 40. 250.00
11	To Remove / Replace Outer Roof Moulding	1	\$ 40.? 250.00
	Tanpin 97495749		
	27/12/17 @ 1745		
	Resurvey before paint.		
	Baby's		
	sur@lkhauto.com.		
	LKK Auto Consultants hence notify the Repairer of the following:		
	• To resurvey before/after spray painting		
	• To display damaged part(s) during resurvey		
	• Parts prices are subject to confirmation		
	• Third party survey is on a "Without Prejudice" basis		
	• No illegal modification(s) is allowed		
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer	Total (D) :	\$ 4,710.00
		Grand Total:	\$ 28,650.81