

INS. CASE OWNER:

CC 6 / AIG170

24355,

Uua3

LKK:
IDAC

Survevor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merlion:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/1/18
RM

SJH 45720 - X; SKW 13727 - X

TP change lane.

Based on footage, OI driving straight
TP change lane.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3320.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Singapore Motor


REF:

A16

24528 / UMG - GIX

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TR / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: 5JH 4572D
 at Workshop m/s: hockeuh 3pm
 of: _____
 Insured: SKW 1372T
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 12
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS 8229+
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: 5JH 4572D Yr Regn: 8 of
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Honda Jazz CC: 1339
 Colour: white A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 120522 T. Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: JHMGD185085216611
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / A/Rim or
 Tyre Size: F: 185/55-R15
 R: _____
 SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal: _____ mm R/Bal: _____ mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 23/12/17 D.O.I: 5/1/18
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S H.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 7827

\$ 2234.16 (Red: \$ 2181.22 / 49-1.)
 check item - \$ 114.50
 Not finalize

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2) _____

Add Fee: ☐ Site Insp. (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Insp. (\$ _____)

☐ Weekend (\$ _____)

Photo: _____

Chart: _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC8/AIG17024355/ua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 26-12-2017		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 1372T	Veh. Inspected	SJH 4572D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/12/2017	Inspection Date		
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8229Z
Vehicle Details	
Vehicle No.:	5JH4572D
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A55001170
Chassis No.:	JHMGD18508S216611
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,951.00
Original Registration Date:	08 Aug 2008
First Registration Date:	08 Aug 2008
Transfer Count:	1
Actual ARF Paid:	\$13,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2018
PARF Rebate Amount:	\$6,975.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,685.00
COE Rebate Amount:	\$852.00
Total Rebate Amount:	\$7,827.00

The information contained herein is correct as at 08 Jan 2018

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S0268229Z
YEOW HOR KEE
BLK 51 CHAI CHEE STREET
06-316
SINGAPORE 460051
TEL : FAX :
PH : 97211630
ATTN :

ESTIMATE BILL

Number : EB00004698
Date : 26/12/2017
Case No : AD00009466
Vehicle No : SJH4572D
Chassis : JHMGD18508S216611
Year of Mfr : 2008
Policy No : 5080484130-01
Model : HONDA JAZZ 1.4A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT FENDER LH <i>ss/ant</i>	1.0	375.60	20	300.48
2	FRONT FENDER SHIELD LH <i>tan</i>	1.0	70.20	20	56.16
3	FRONT FENDER SHIELD CHIPS <i>neu</i>	8.0	3.70	20	23.68
4	FRONT BUMPER <i>de/repair</i>	1.0	505.50	20	404.40
5	FRONT BUMPER SIDE RETAINER LH <i>set</i>	1.0	13.10	20	10.48
6	FRONT HEADLIGHT LH <i>scr</i>	1.0	486.20	20	388.96
7	FRONT WHEEL BEARING LH	1.0	119.20	20	95.36
8	FRONT LOWER ARM LH	1.0	237.90	20	190.32
9	FRONT KNUCKLE ARM LH	1.0	228.70	20	182.96
10	FRONT SHOCK ABSORBER LH	1.0	228.70	20	182.96
11	FRONT ENGINE LOWER DUST COVER <i>an</i>	1.0	72.90	20	58.32
List Price - Parts Sub Total					1,894.08
12	FRONT TYRE LH <i>su</i>	1.0	380.00	0	380.00
13	FRONT RIM LH <i>cu</i>	1.0	601.30	0	601.30
Special Nett Price - Parts Sub Total					981.30
Parts Total					2,875.38
14	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
15	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
16	ANTI-RUST COATING	1.0	100.00	0	100.00
17	TO REMOVE & REFIT UNDERCARRIAGE	1.0	300.00	0	300.00
18	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,540.00
SINGAPORE DOLLARS : FOUR THOUSAND SEVEN HUNDRED TWENTY-FOUR AND CENTS FORTY-SIX ONLY			Less Excess		0.00
			SUBTOTAL		4,415.38
			GST 7.00%		309.08
			TOTAL		4,724.46

Date of accident : 26/12/2017 02:12 PM, Place : ALONG CHAI CHEE STREET

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

CUSTOMER SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD



AUTHORISED SIGNATURE

Printed/signed by: [Signature]

Page 1 of 1

* N = Item not subjected to GST

Issued by : MAVIS

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Friday, 12 January 2018 1:21 PM
To: 'Hock Wah Motor Pte Ltd'
Subject: RE: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017 *** LKK REF: CC6/AIG17024355/ua3
Attachments: VID-20180111-WA0003.mp4

Dear Mavis,

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Your client's accident statement clearly stated that he turn his car to the left.

Based on footage, our insured vehicle was travelling straight within the lane and your client encroached into our insured lane and collided onto our insured vehicle.

Attached herewith our insured's video footage for your perusal.

Under such a circumstances, we are denying liability and unable to look into your client's claim.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Wah Motor Pte Ltd [mailto:motor@hockwah.com.sg]
Sent: Tuesday, 9 January 2018 9:43 AM
To: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Subject: RE: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017 *** LKK REF: CC6/AIG17024355/ua3

Dear Thin Thin

Our client do not have any video footage or scene photo.

Any updates regarding the case liability?

Thank you.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Thin Thin (LKKAuto) [<mailto:thinthin@lkkauto.com>]

Sent: Thursday, 28 December, 2017 10:49 AM

To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>

Subject: RE: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017 *** LKK REF: CC6/AIG17024355/ua3

"Without Prejudice"

Dear Sir / Madam,

We refer to the below matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence to substantiate either party's version. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage as stated in order to seek further instruction from our principal.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]

Sent: Thursday, 28 December, 2017 10:12 AM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Subject: RE: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017 *** LKK REF: CC6/AIG17024355/ua3

Dear Thin Thin

Has your insured reported? Please revert the liability.

Thank you.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, 26 December, 2017 2:48 PM
To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017 *** LKK REF: CC6/AIG17024355/ua3

Dear Mavis,

We refer to the below email.

Please be informed that we are currently **pending for our insured's report.**

Kindly note that for liability, claim negotiation and settlement, please contact Thin Thin at 6841 2360.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]
Sent: Tuesday, 26 December, 2017 11:34 AM
To: Admin A <admin-a@lkkauto.com>
Subject: TP CLAIM_SJH4572D & SKW1372T (AIG)_DOA:23/12/2017

Dear sir/madam

Attached herewith our client's GIA report that claim against your insured SKW1372T.

The above mention vehicle not in Bedok workshop, please assist to make necessary arrangement.

Please revert the liability of the above case.

Best Regards

Mavis Er

Customer Service Executive

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Thin Thin (LKKAUTO)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Thursday, 11 January 2018 3:19 PM
To: Thin Thin (LKKAUTO)
Subject: RE: ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D | 8417114319SG-003

Dear Thin Thin,

Please proceed to reject the claim as per your proposal.

Fyi, TP did not turn on indication light when turning.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]
Sent: Thursday, January 11, 2018 2:54 PM
To: Ler, Bernard-JQ
Subject: ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D
Importance: High

Your Ref: 8417114319SG
Our Ref: CC6/AIG17024355/Uua3

Dear Bernard,

ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D

We refer to the above matter.

We have spoken to OI and she mention that she was travelling straight along left lane and TP vehicle encroached into her lane and collided onto her vehicle. Enclosed herewith CCTV footage for your perusal.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

Thin Thin Hlaing | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Thin Thin (LKKAuto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Thursday, 11 January 2018 3:19 PM
To: Thin Thin (LKKAuto)
Subject: RE: ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D | 8417114319SG-003

Dear Thin Thin,

Please proceed to reject the claim as per your proposal.

Fyi, TP did not turn on indication light when turning.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Thin Thin (LKKAuto) [mailto:thinthin@lkkauto.com]
Sent: Thursday, January 11, 2018 2:54 PM
To: Ler, Bernard-JQ
Subject: ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D
Importance: High

Your Ref: 8417114319SG
Our Ref: CC6/AIG17024355/Uua3

Dear Bernard,

ACCIDENT ON 23/12/2017 INVOLVING VEHICLES SKW 1372T AND SJH 4572D

We refer to the above matter.

We have spoken to OI and she mention that she was travelling straight along left lane and TP vehicle encroached into her lane and collided onto her vehicle. Enclosed herewith CCTV footage for your perusal.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

Thin Thin Hlaing | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017 Edit Reg		05 Jan 2018 00:00 Edit Adj Rpt	S\$2,234.16 Edit Estimates	S\$2,234.16 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		LIM LUAN KEE, ID: S0065050A							
Main Claimant:		YEOW HOR KEE, ID: S0268229Z							
Vehicle Reg. No.:		SJH4572D	Date of Loss:	23/12/2017 16:00 - :59					
Claim Type:		TP / 8417114319SG	Policy/Cover Note No.:	2100432972					
Vehicle Reg. No. (Insured):		SKW1372T	Policy No. (Claimant):	5080484130-01					
		Excess:							
Repairer:		Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/01/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH4572D (8417114319SG)

[SKW1372T]

TP

YEOW HOR KEE

Dec 23 2017 4:00PM

[LIM LUAN KEE]

Hock Wah Motor Workshop Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video												1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	11/01/18 15:20	Video - Accident											Load MP4				
Assessment Reports												1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	26/12/17 15:31	Accident Statement <small>From: SC - Reg. No: SKW1372T, Claimant: LIM LUAN KEE</small>											Load HTM				
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
2	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
3	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
4	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
5	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
6	06/01/18 11:14	General View											Load JPG	<input checked="" type="checkbox"/>			
7	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
8	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
9	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
10	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
11	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
12	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
13	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
14	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
15	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
16	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
17	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
18	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
19	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
20	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
21	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
22	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
23	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
24	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
25	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
26	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
27	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			
28	06/01/18 11:15	General View											Load JPG	<input checked="" type="checkbox"/>			

29	06/01/18 11:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	06/01/18 11:15	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	06/01/18 11:15	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
32	06/01/18 11:15	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/17 14:46	TP GIA REPORT	1	Load PDF	
2	09/01/18 10:50	TP ESTIMATE - MARKED	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024355/UUA3Q2

Date: 23/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100432972
 Claimant Vehicle No: SJH4572D Insured Vehicle No: SKW1372T
 Date of Loss: 23/12/2017 Nature of Claim: TP Claim No: 8417114319SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH4572D**
 Make & Model: HONDA JAZZ, 1.4 (A) Engine No: L13A55001170
 Reg. Date: 08/08/2008 (Man. Year: 2008) Chassis No: JHMGD18508S216611
 Colour: White Odometer: 120522 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,875.38	1,484.16	1,391.22	48.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	750.00	790.00	51.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,415.38	2,234.16	2,181.22	49.40
+ GST 7.00/7.00% (S\$)	309.08	156.39	152.69	49.40
Nett Amount (S\$)	4,724.46	2,390.55	2,333.91	49.40
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/01/2018
 Date Inspected: 05/01/2018 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented / Bent	375.60 FL	*375.60 FL
2	1		*FRONT FENDER SHIELD LH	Torn	70.20 FL	*70.20 FL
3	8		*FRONT FENDER SHIELD CLIPS	Necessary	29.60 FL	*29.60 FL
4	1		*FRONT BUMPER	Deformed / Warped	505.50 FL	*505.50 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Bent	13.10 FL	*13.10 FL
6	1		*FRONT HEADLIGHT LH	Scratched	486.20 FL	*486.20 FL
7	1		*FRONT WHEEL BEARING LH	*Check	119.20 FL	*- FL
8	1		*FRONT LOWER ARM LH	*Check	237.90 FL	*- FL
9	1		*FRONT KNUCKLE ARM LH	*Check	228.70 FL	*- FL
10	1		*FRONT SHOCK ABSORBER LH	*Check	228.70 FL	*- FL
11	1		*FRONT ENGINE LOWER DUST COVER	Not Necessary	72.90 FL	*- FL
12	1		*FRONT TYRE LH	Serviceable	380.00 FS	*- FS
13	1		*FRONT RIM LH	Cut	601.30 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	3,348.90	1,780.20
- List Item Discount on L Items 20.00/20.00% (S\$)	473.52	296.04
Total Parts (S\$)	2,875.38	1,484.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
3	ANTI-RUST COATING	New	100.00	30.00
4	TO REMOVE & REFIT UNDERCARRIAGE (*Check)	New	300.00	0.00
5	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			1,540.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >