

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT17005170	Page	1
	8 SHENTON WAY	Date	: 21. Dec 2017		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SKA4947G	Engine No	: R20A15700002		
Chassis No	: JHLRE2850BC200002	Date Time	: 21. Dec 2017 8:14:04 AM		
Model	: CRV 2.0L 2011 MODEL SUNROOF	Surveyor Name	:		
Owner's Name	: RENTAL CARS	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 20/12/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: KAH MOTOR CO SDN BHD						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 20/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SHC5463D						
74895-SWA-A01ZJ	GARNISHTAILGATE LOWER <i>DD/AE</i>	1	381.80	35	248.17	17.37	265.54
74800-SMG-G02	LOCKTAILGATE <i>11</i>	1	234.80	35	152.62	10.68	163.30
74440-SWA-003	W/STRIPTAILGATE	1	140.00	35	91.00	6.37	97.37
75722-SWA-003	EMBLEMREAR CRV <i>11</i>	1	29.60	35	19.24	1.35	20.59
04715-SWA-A00ZZ	FACEREAR BUMPER <i>DD/AE</i>	1	436.50	35	283.72	19.86	303.58
33505-SWA-J01	REFLECTORR.RR. <i>11</i>	1	20.50	35	13.32	0.93	14.25
33555-SWA-J01	REFLECTORL.RR. <i>11</i>	1	20.50	35	13.32	0.93	14.25
71502-SWA-A00	FACEREAR BUMPER LOWER <i>AE</i>	1	367.90	35	239.13	16.74	255.87
71593-SWA-A01	SPACERR.RR.BUMPER <i>11</i>	1	17.30	35	11.24	0.79	12.03
71598-SWA-A01	SPACERL.RR.BUMPER <i>11</i>	1	17.30	35	11.24	0.79	12.03
91505-S9A-003	CLIP ABUMPER <i>11</i>	4	3.90	35	10.14	0.71	10.85
91506-S9A-003	CLIP BBUMPER <i>11</i>	2	2.40	35	3.12	0.22	3.34
Sum Item					1096.26	76.74	1,173.00
BOSUN	SUNDRIES	1 <i>11</i>	30.00	10	30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00	✓	80.00	5.60	85.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	100.00	✓	100.00	7.00	107.00
BKBU02R	REPLACE RR BUMPER, REPAIR TAILGATE, RR PANEL &	1	1400.00	900	1400.00	98.00	1498.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1200.00	1050	1200.00	84.00	1284.00



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKA4947G
Chassis No : JHLRE2850BC200002
Model : CRV 2.0L 2011 MODEL SUNROOF
Owner's Name : RENTAL CARS
Ins Policy No. :
Date of Accident : 20/12/2017

Document No. : SQT17005170 Page 2
Date : 21. Dec 2017
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R20A15700002
Date | Time : 21. Dec 2017 8:14:04 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
Sum Labor					2810.00	196.70	3,006.70

Survey By

Date & Time

Excess

Status

Signature

mercus klu
27/12/17 @ 3.15pm
not a fault
take photo before repair.
4dy.

Total Amount 3,906.26 273.44 4,179.70
Total (Inclusive of GST) 4,179.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/12/2017 11:38:49 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)