

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

LKK

Vehicle Insured : SKV4209T (AXA)

Date : 22-12-2017

Accident Date : 22-12-2017

Our Ref : SKB7907Y / CHAN 21799

2 <sup>KSA</sup> Accident

ROSLI BIN MOHAMED YUSOF  
C/O ALAN'S UNITED AUTO PTE LTD  
BLK 7 SIN MING IND.EST. SECTOR C  
# 01-76  
SINGAPORE 575642

## ESTIMATE COST OF REPAIR FOR BMW 320I SKB7907Y

TO REMOVE FRONT BUMPER FOR REPAIR , ADJUST ,ALIGN AND TO REFIX FRONT BUMPER

\$200.00 12d

TO PUTTY AND SPRAY FRONT BUMPER

\$250.00 22d  
\$450.00

Not Authorized  
\$340

1 day

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Singapore Dollars Four Hundred Fifty Only